

Appendices

The following documents have been published in a separate volume of this study.

- Elementary Schools – M/E/P/FP Report *GGD*
- Elementary Schools – Cost Estimates *Essential Design*
- Elementary Schools – Structural Report
for the Hastings School *Lim Consultants, Inc.*
- High School – E/P/FP Report *G/G/D*
- High School – Base renovation cost Estimate *Essential Design*
- High School – Food Service Report *Crabtree McGrath Associates*
- High School – Site Scope Memo *Warner Larson Associates*

The following documents are not included but are frequently referenced in this report and should be considered “incorporated by reference”:

- High School – HVAC Systems Report-2008 *GGD*
- Elementary Schools – Master Plan—2006 *DPC*
- Enrollment Projections –12.2008 *Superintendent Paul Ash*

Elementary Schools - Cost Estimates

**Lexington Elem. Schools
Master Plan Study**

Bowman Elementary School

Executive Summary – Electrical

The existing electrical systems in general, although functioning, are at the end or have exceeded their useful life. Even with regular maintenance systems do deteriorate over the years. The life safety systems, due to code changes over the years, are not in compliance with current codes.

Existing Conditions

- The primary service runs overhead and feeds a 300 kva Utility Co. owned pad mounted transformer. Secondary service runs underground in one (1) 4" conduit. The secondary electrical service consists of a main switch rated at 400amp, 277/480 volt, 3Ø, 4wire, a C/T cabinet and meter with a distribution panel. The equipment is located in the custodian's work room. Lighting and power panels are circuit breaker type and are rated at 120/208 volt and 277/480 volt, 3Ø, 3wire. The existing panels do not appear to have spare circuit breakers for the addition of new lighting and power circuits. Dry type transformers are used for receptacle power. Most equipment was manufactured by General Electric. Various panels do not have required working clearance. The condition of the equipment is poor and has exceeded its useful life.
- Existing classroom lighting consists of (3) continuous rows of wraparound fixtures parallel with the exterior wall. Lights are controlled with one switch. No occupancy sensor exists.
Stage lighting comprises of floor lights in front and track fixtures at stage.
2 x 4 recessed fixtures are used in the Gymnasium with four (4) T5HO lamps and are in good condition.
Kitchen lighting is through vaportight 4' fluorescent fixtures.
Corridor lighting consists of wall mounted 1 x 4 surface wraparound fixtures. Corridors are controlled with local switches.
Although lighting has been retrofitted with T8 lamps and electronic ballasts, fixtures are generally old and in poor condition.
- Existing site lighting consists of cobra heads on utility poles. The site appears to be dark. Building mounted metal halide floods also exist on photocell. Surface canopy lights of compact fluorescent exist at front and rear entrances.
- The existing emergency lighting system is through a LP gas generator rated at 12.5KW, 277/480v, 3Ø, 4W and is manufactured by Onan. One automatic transfer switch manufactured by Onan is present. The system is not code compliant and the equipment is in poor condition. Retrofitted LED exit signs exist. There is inadequate coverage of exit signs.

- Generally classrooms have one receptacle per interior wall. One double duplex has been recently provided from computer grade panel to serve computer equipment. Several extension cords are being used. Outlets in kindergarten are not tamper resistant type. Kitchen floor receptacles not GFI type.
Computer lab has extension cords running on floor to feed center tables.
Receptacles are currently sparsely located and additional receptacles should be provided.
- The building is equipped throughout with an automatic fire alarm system. Existing strobes do not meet ADA. Notification to the fire department is by a Sigcom radio master box with exterior antenna, box #2725. Toilets do not have ADA Strobes.
Strobe lights are mounted higher than 80" above floor as is required by ADA.
The fire alarm control panel is manufactured by Simplex model 4002, 8 zone conventional (non-addressable). Pull stations exceed 48"-54" as required by ADA.
Typical classroom has one smoke detector, no horn/strobes.
Building is not sprinklered and does not have full coverage of smoke and heat detectors and does not have adequate coverage of horn/strobes.
- The existing classroom intercom consists of a Rauland Telecenter TC 2100. Classrooms have a wall phone and 2-way speaker for communications with Administration office. No paging speakers in corridors.
- Classroom clocks are manufactured by Simplex. A master time clock is present and is manufactured by Simplex.
- Classrooms do have a Category 5 computer network installed. Classrooms have 4 data drops for students and 1 and 1 CATV data for teacher. Computer lab has inadequate quantity of data drops for computers. School has cable TV and fiber optic services.
- Front and back entrances have an AIPHONE LEF-5 system with intercom/camera at each door with master at administration with door release.
- Security/intrusion consists of a NAPCO magnum alert 800 control panel connected to a remote central station. Infrared sensors exist in corridors, media center. Exterior doors not alarmed.
- No card access or Closed Circuit TV exists.
- No lightning protection exists.
- Portable classroom building is in good condition. Building is interconnected with main building for fire alarm system. Emergency lighting and exit signs are with battery back-up.

Proposed System Priorities

Priority 1: Immediate Needs and Requirements:

- Hood fire suppression system fire alarm conduit broken.
» **\$300.00**
- Exposed wiring in freezer provide box and cover.
» **\$300.00**
- Various kitchen receptacles not GFI. Provide GFI receptacles or GFI breakers.
» **\$1,500.00**
- Exterior core classroom, receptacle cover missing.
» **\$50.00**
- Portable classroom, men toilet, receptacle not GFI.
» **\$100.00**
- Service electrode requires jumper around water meter for proper grounding.
» **\$500.00**
- Electrical items under kitchen hood are required to shutdown upon activation of hood's suppression system.
» **\$2,500.00**
- Add horn/strobes in cafeteria and library, currently none exist. Add strobes in toilets.
» **\$7,500.00**
- One (1) wire guard for smoke detector on gym ceiling is loose and ready to drop.
» **\$100.00**
- Add receptacles to eliminate extension cord use.
» **\$10,000.00**
- Add fire alarm pull station at gymnasium.
» **\$750.00**

Priority 2: 1 - 5 Year Expected Life:

- The existing fire alarm control panel, Simplex 4002, 1980's vintage, has reached the end of its life. Although some replacement parts are still available, other parts are not. Detectors compatible with this panel are still available. Should the panel fail and the replacement part not be available it would force the school to be under a fire watch. We recommend replacing the 4002 control panel with a current Simplex zoned 4006 panel on a one for one swap. This will allow existing wiring and devices to remain and allow additional devices to be provided. In light of the building not being sprinklered it is

recommended that additional smoke and heat detectors be provided for full coverage of the facility.

» ***\$1.00/s.f. = \$63,434.00***

- The normal/emergency lighting system should be tested by simulating a power failure and confirming that adequate emergency lighting exists in egress ways and other large spaces where required. Additional emergency lighting should be added where required including on the exterior at exit discharge doors.
» ***\$.25/s.f. = \$15,859.00***
- Provide full coverage of exit signs where required for safe egress out of the facility.
» ***\$.10/s.f. = \$6,343.00***

Priority 3: 5 – 10 Year Expected Life:

- Provide occupancy sensors to turn lights off in classroom, toilets, offices, gym, etc. to save energy when spaces are unoccupied. Utility Co. rebates may be available for energy conservation measures.
» ***50 @ \$200.00/unit = \$10,000.00***

Priority 4 – Full Renovation of Systems (Gut Rehab)

» ***\$25.00/s.f. = \$1,585,850.00***

- New construction service ratings are designed for a demand load of 10 watts/s.f. The service capacity will be sized for 1200 amperes at 277/480 volt, 3Ø, 4wire. New lighting and power panels will be provided to accommodate respective loads and located in electric rooms. A system of computer grade panelboards with double neutrals and integral surge suppressors fed from k-rated transformers will be utilized to mitigate the harmonic effects caused by computers and other electronics.
- Classroom lighting fixtures will consist of pendant mounted indirect fluorescent luminaries with T5HO lamps and electronic ballasts. The fixtures will be pre-wired for automatic dimming control where natural daylight is available and also for multi-level switching.
- Office lighting fixtures will consist of acrylic recessed direct fixtures with (2) T5 lamps and electronic ballasts. Two step ballasts will be provided for dual-level switching. Fully dimmable ballasts will be provided where natural daylight is available. Lighting levels will be approximately 30-50 foot candles in classrooms and offices.
- Gymnasium lighting will be comprised of direct fluorescent fixtures with T5HO lamps and electronic ballasts. The fixtures will be provided with protective wire guards. The light level will be designed for approximately 30 foot candles. Occupancy sensors will be provided to turn lights off when unoccupied. Theatrical lights with a dimming system will be provided for performances.

- Corridor lighting will be comprised of recessed acrylic fixtures with (2) T5 lamps & 2 step dimming electronic ballasts for dual level switching. The corridor light level will be designed for approximately 20-foot candles.
- Cafeteria lighting will be pendant indirect fluorescent fixtures with Biax lamps & electronic ballasts. The light levels will be designed for approximately 30 foot candles with dual level switching.
- Kitchen and servery lighting will consist of recessed 2'x4' acrylic lensed troffers with aluminum frame doors with T5 lamps and electronic ballasts. Light levels will be approximately 50-75 foot candles.
- Each area will be locally switched and designed for multi-level controls. Each classroom, office space and toilet rooms will have an occupancy sensor to turn lights off when unoccupied. Daylight sensors will be installed in each classroom and perimeter spaces for automatic dimming of light fixtures.
- The entire school will be controlled with an automatic lighting control system using the lighting panelboards with programmable breakers for programming lights on & off.
- Exterior site lighting fixtures for area lighting will be pole mounted long life, energy efficient LED luminaries in the parking area and roadways. Building perimeter fixtures will be wall mounted compact fluorescent over exterior doors. The exterior lighting will be connected to the automatic lighting control system for photocell on and timed off operation.
- An exterior natural gas emergency generator with a sound attenuated aluminum enclosure will be provided. Light fixtures and LED exit signs will be installed to serve all egress areas such as corridors, intervening spaces, toilets, and exit discharge exterior doors. The administration area lighting will be connected to the emergency generator. The generator will be sized to include life safety systems, boilers and circulating pumps, communications systems, kitchen refrigeration, etc.
- Each classroom will have a minimum of (2) duplex receptacles per teaching wall and (2) double duplex receptacles on dedicated circuits at classroom computer workstations. The teacher's workstation will have a double duplex receptacle also on a dedicated circuit.
- Office areas will generally have (1) duplex outlet per wall. At each workstation a double duplex receptacle will be provided.
- Corridors will have a cleaning receptacle at approximately 30-40 foot intervals.
- Exterior weatherproof GFI receptacles will be installed at exterior doors.
- A fire alarm and detection system in compliance with ADA will be provided with battery back-up. The system will be of the addressable type where each device will be identified at the control panel and remote annunciator by device type and location to facilitate search for origin of alarms. Smoke detectors will be provided in open areas, corridors,

and other egress ways. The sprinkler system will be supervised for water flow and tampering with valves. Speaker/strobes will be provided in egress ways, classrooms, assembly spaces, open areas and other large spaces. Strobe only units will be provided in single toilets and conference rooms.

- Manual pull stations will be provided at exit discharge doors.
- The system will be remotely connected to automatically report alarms to fire department via the radio master box.
- A three phase centralized uninterruptible power supply (UPS) system will be provided with battery back up. The system will provide conditioned power to sensitive electronic loads, telecommunication systems, bridge over power interruptions of short duration and allow an orderly shutdown of servers, communication systems, etc. during a prolonged power outage. The UPS system will also be connected to the stand-by generator.
- A system of lightning protection will be provided. The system will be installed in compliance with the provisions of the latest “Code for Protection Against Lightning” for buildings as adopted by the National Fire Protection Association and the Underwriters’ Laboratories, Inc. for a UL Master Label System.
- The lightning protection equipment will include air terminals, conductors, conduits, fasteners, connectors, ground rods, etc.
- A Closed Circuit TV system will consist of computer servers with image software, computer monitors and IP based closed circuit TV cameras. The head end server will be located in the head end MDF room and will be rack mounted. The system can be accessed from any PC within the facility or externally via an IP address. Each camera can be viewed independently. The network video recorders NVR’s will record all cameras and store this information for 21days at 15 images per second (virtual real time).

The location of the cameras is generally in corridors and exterior building perimeter. The exterior cameras are pan-tilt-zoom type.

The system will fully integrate with the access control system to allow viewing of events from a single alarm viewer. Camera images and recorded video will be linked to the access system to allow retrieval of video that is associated with an event.

- An intrusion system will consists of security panel, keypads, motion detectors and door contacts. The system is addressable which means that each device will be identified when an alarm occurs. The system is designed so that each perimeter classroom with grade access will have dual tech sensors along the exterior wall and corridors, door contacts at each exterior door.

The system can be partitioned into several zones. Therefore, it is possible to use the Gym area while the remainder of the school remains alarmed.

The system will include a digital transmitter to summons the local police department in the event of an alarm condition

The intrusion system will be connected to the automated lighting control system to automatically turn on lighting upon an alarm.

- A card access system includes a card access controller, door controllers and proximity readers/keypads. Proximity readers will be located at various locations. Each proximity reader will have a distinctive code to identify the user and a log will be kept in memory. The log within the panel can be accessed through a computer.

The alarm condition will also initiate real time recording on the integrated CCTV System. The system may be programmed with graphic maps allowing the end-user to quickly identify alarm conditions and lock/unlock doors.

The system is modular and may be easily expanded to accommodate any additional devices.

- A renewable energy system will consist of a grid connected photovoltaic PV system intended to reduce the facilities demand for power. The photovoltaic system will operate in conformance with the green schools initiative. System will consist of roof mounted photovoltaic modules, weather station, data acquisition system and inverters. Interactive display terminals will be provided for students and for public awareness of the benefits of renewable energy.
- The data system infrastructure will consist of fiber optic backbone cabling. Horizontal wiring will consist of Category 6 UTP Plenum rated cabling for both data and telephone system for gigabit connectivity. The telephone infrastructure will accommodate Centrex, PBX or VOIP based phone systems.
- Each classroom will have 4 data outlets for student computers. Two data, one voice and CATV with video and audio connections to a ceiling projector will be provided at teacher's station with interconnectivity to a smartboard. A wall phone outlet with 2 way ceiling speaker will be provided for communications with administration. Clock will be wireless, part of a GPS/LAN based centralized clock system. Wireless access points with spare fibre will be provided on selected classrooms and other spaces.
- The cafeteria and gymnasium will each have a local sound system with assistive listening devices.
- A central paging system will be provided and integrated with the telephone system.

Bowman Elementary School

Executive Summary - HVAC

The Bowman Elementary School has received below average maintenance of the HVAC systems over its occupied years. Even with adequate maintenance, through normal operation systems do gradually deteriorate due to scale, poor water conditions, and lack of preventive maintenance. Systems will gradually deteriorate to a point of exceeding their maximum serviceable life. This building is a typical example of one such project. While generally speaking, most systems are operating and maintaining reasonable space temperature control, but due to the extreme antiquated nature of the mechanical systems and their gradual scaling of the various piping systems, heat transfer rates have become reduced and the overall system is taxed to a point of inefficiency being created by the slowly depreciating system. While there are no catastrophic failures obvious with the present systems, the systems could continuously be repaired and modified on a sectional basis that will keep the systems operating maintaining acceptable space temperature control however, continued operation will be at the expense of increased operating costs due to inefficiency in heat transfer and through the generally antiquated nature of the systems themselves. The systems installed within this building are approaching their maximum serviceable life. With overall maintenance, cleaning and calibrating of the system, a continued limited service could be achieved however, unpredictable at best. At this time it is not necessary that the systems be modified to prevent a near catastrophic failure, but a continued reuse of the systems will continue to produce unsatisfactory results in terms of overall air quality, temperature control and operating costs.

Existing Conditions:

- The boiler room is provided with two (2) individual HB Smith 450 MILS cast iron sectional boilers generating low-pressure steam. Each boiler is provided with dual low water cut-offs as well as all operating and safety controls and a firematic switch. It was noted that there was surface contamination on the mud drums adjacent to the cast iron sectional nipples indicating that the nipples could be leaking. Each boiler is provided with a single no. 2 fuel oil burner and generates low-pressure steam for distribution. Considering the age of approximately forty-five (45) years, each boiler would suggest that it has approximately five (5) years of usable life.
- The breeching from each boiler appears to be welded black steel and is insulated with what appears to be calcium silicate insulation with a canvas jacket. Each boiler is provided with an individual induced draft fan located at the rear of each boiler which conveys combustion gases from each boiler to a masonry chimney. The induced draft fans are contaminated with soot and are reaching the end of their serviceable life.
- No. 2 fuel oil is recirculated from a buried 10,000 gallon double wall tank installed in 1993. It is provided with leak containment, leak monitoring, double wall piping and fluid level controls. Also provided is a central monitoring panel to detect the presence of fluid within the containment vessels which is not operating. Fuel oil is distributed throughout

- the boiler room through a duplex gear driven fuel oil transfer set which includes pumps, strainers, and isolation valves. It appears that this pumping system is original to the building of approximately 1965 and the fuel oil pumps are showing signs of leakage and are slightly contaminated in the area of the pump bases and consideration should be given to a generalized upgrade. Also located within the pump area are two (2) steam shell and tube heat exchangers for the heating of the original no. 6 fuel oil. No. 6 fuel oil has been discontinued in use and no. 2 fuel oil has replaced it however, custodial personnel continue to use the heating system to preheat the no. 2 fuel oil. This does no harm in the overall operation however, is an energy waste.
- Condensate is returned to the boiler room from the building through a schedule 80 black steel condensate return system. Condensate is returned to the boiler room to a central condensate receiver system which is located on the floor of the boiler room. The floor mounted receiver is provided with two (2) individual boiler feed pumps which appear to be of primary and standby arrangement each of which pumps to a common distribution feed water piping to each boiler. Considering the overall age of the condensate system consideration should be given to an overall upgrade.
 - Low-pressure steam and condensate is distributed through a series of tunnels which feed throughout the building. Steam piping appears to be schedule 40 black steel and condensate appears to be schedule 80 black steel both of which are insulated with what appears to be fiberglass insulation with an all service jacket. It was not possible to evaluate the piping located within these tunnels nor was it possible to determine the condition of the insulation however, considering its age of approximately forty-five (45) years and the noticeable steam leaks consideration should be given to a generalized upgrade of all piping.
 - The automatic temperature control system is of the pneumatic type and is provided with a single storage tank with duplex compressors and motors. It does appear that these compressors are operating correctly but not maintaining adequate compressed air flow to the entire control system. The system was recently provided with a refrigerated air dryer which eliminates moisture within the pneumatic lines. Some corrosion was noted on the pneumatic lines resulting from moisture within the tubing. Consideration for upgrading should be considered.
 - The kitchen is provided with a single wall stainless steel exhaust hood located over the cooking area. This exhaust hood is provided with an individual exhaust system through a welded steel exhaust ductwork system which connects to a roof mounted exhaust fan. The exhaust hood was noted to have vapor tight incandescent lights. The fire suppression system currently installed is not compatible with the installed sprinkler head located in the hood.
 - Make-up air for the kitchen and its associated hood is through an air-handling unit located at the ceiling. This air-handling unit is of the return air/outside air design and is provided with a steam heating coil with valve control, supply fan, and filters. Sidewall diffusers provide supply air to the entire kitchen area and generally are exhausted 100% through the associated exhaust hood.

- Heating of the entire kitchen area is through two (2) individual ceiling mounted classroom unit ventilators which are designed to introduce one hundred percent (100%) outside air for a source of make-up for the kitchen hood.
- The cafeteria is provided with a single air-handling unit which distributes to wall mounted supply registers located along one wall of the cafeteria. Galvanized sheet metal ductwork provides heated and ventilation air which is noted to be uninsulated. A source of outside air ventilation is provided for this air-handling unit to meet code requirements and the unit is provided with a low-pressure steam heating coil, supply fan, and filters. Return air is drawn through a return air opening at the base of the air-handling unit. Also located within the space are two (2) individual wall mounted exhaust registers that communicate to a roof mounted exhaust fan through a galvanized sheet metal exhaust system. The air-handling unit is controlled through a wall mounted pneumatic thermostat which is noted to be antiquated. Considering the overall age of all equipment and systems within the space consideration should be given to an overall upgrade.
- The building classrooms are provided with a wall mounted classroom unit ventilator. The unit ventilators are all of the low-pressure steam design and are provided with automatic control valves, outside air intake louver for the introduction of outside ventilation air, as well as filters, a supply fan, and automatic temperature controls. It was noted that each of the unit ventilators were extremely antiquated many of which were slightly damaged on the surface, loud and many of which were not operating. The classrooms were also provided with individual exhaust registers. These exhaust grills communicate through a galvanized sheet metal exhaust system to roof mounted exhaust fan and it does appear that this system does operate in a satisfactory manner however, consideration should be given to an upgrade.
- Each classroom space is also provided with a wall mounted pneumatic thermostat which controls the unit's ventilator control valve as well as the outside air dampers.
- The corridor areas throughout the building were provided with exhaust ventilation air however, supply air was not provided which is non-code compliant and should be upgraded.
- The corridor's were also provided with individual wall mounted convectors which were of the low pressure steam design and provide heating through the control of wall mounted pneumatic thermostats.
- The art/teachers work room area is provided with an individual air-handling unit located above the ceiling of the art room. This unit is provided with a source of outside ventilation air, low pressure steam heating coil, supply fan and filters. Considering the generalized age of all equipment consideration should be given to an upgrade.
- The media center is provided with an air-handling unit located above the ceiling. This area is provided with an individual air-handling unit located above the ceiling. This air-handling unit is provided with a source of outside ventilation air, low-pressure steam

- heating coil, supply fan and filters. Considering the generalized age of all equipment consideration should be given to an upgrade.
- The media center is also provided with an individual exhaust system which is made up of two (2) individual exhaust registers generally located in the wall. These exhaust registers communicate to a galvanized sheet metal exhaust system to a roof mounted exhaust fan. Generally considering the age of the equipment consideration should be given to a generalized upgrade.
 - The administration area is provided with a single roof mounted air conditioning unit. This unit is of the single zone design and provides air-conditioned as well as ventilation air through one single zone throughout individual administration areas. Each occupied room is provided with a ceiling mounted supply diffuser which was noted to be slightly dirty. Considering its general age consideration should be given to an upgrade.
 - Also located within the various offices of the administration area were varying lengths of fintube radiation located along the exterior wall. The fintube radiation was noted to be dirty and in many instances it was damaged with various end covers missing and slight surface contamination. The fintube radiation is controlled through an individual wall mounted pneumatic thermostats all of which were noted to be antiquated. Considering its general appearance and age consideration should be given to an upgrade.
 - The interior classrooms were provided with ceiling suspended classroom unit ventilators which free blow into the occupied space through a single discharge grill horizontally located on the unit ventilator. Each unit ventilator is provided with an outside air intake duct which communicates to a roof mounted hood which was insulated with what appears to be fiberglass insulation. The unit ventilators were very typical to those of a typical classroom which include a steam heating coil, filters, and supply fan. The unit is provided with a wall mounted pneumatic thermostat for control and it also was antiquated.
 - The individual classrooms were also provided with fintube radiation located under the clear story glass on the exterior wall. This fintube radiation was noted to be slightly dirty and slightly damaged.
 - Also located within these classrooms was a wall mounted exhaust register. It was noted that these exhaust registers communicate to roof mounted exhaust fans through a galvanized sheet metal exhaust system. As we understand it, all systems do operate in a satisfactory manner however, considering the age of all equipment consideration should be given to an upgrade.
 - The portable classrooms are each provided with a single roof mounted heating and ventilating and air conditioning unit. Each rooftop unit is provided with electric cooling and propane heating. The rooftop units are controlled through individual electric wall mounted thermostats. There is an offensive odor present in the portable classrooms which could relate to excessive vapor pressure resulting in mold formation. Further investigation should be considered to determine the contributing conditions.

- The building public toilets were provided with wall mounted exhaust registers that were noted to be slightly dirty however, as we understand it do operate. These exhaust registers communicate to roof mounted exhaust fans through a galvanized sheet metal exhaust system.
- Make-up air for the individual toilets was through the use of louvers located within the doors.
- Heating of the toilet spaces is through the use of wall mounted convection heating. It was noted that the heating elements were slightly damaged with surface contamination. The individual radiation elements were controlled by wall mounted pneumatic thermostats which were noted to be antiquated. Consideration should be given to an upgrade based purely on age and the antiquated nature of all equipment.

Proposed System Priorities

Priority 1 – Immediate Needs and Requirements

- Veeder Root oil tank monitoring system is not operating
» **\$2,000.00**
- Wasted energy resulting from pre-heating No.2 fuel oil
» **\$2,000.00**
- Steam leaks in steam tunnels
» **\$25,000.00**
- Fire suppression system in Kitchen is not compatible with sprinkler head in hood
» **\$250.00**
- Code required ventilation air not provided in corridors
» **\$44,000.00**
- Calibration of the pneumatic temperature controls
» **\$31,500.00**
- CO2 Demand ventilation control in Classroom unit ventilators
» **\$27,000.00**
- Verify shaft trueness on all unit ventilators, exhaust fans and air handling units and replace if necessary
» **\$13,000**
- Verify conditions of shaft bearings on all unit ventilators, exhaust fans and air handling units and replace if necessary
» **\$13,000**

- Clean fan wheels, coils, dampers, and outside air louvers on all unit ventilators, exhaust fans and air handling units
» **\$13,000**

Priority 2 – Five Year Needs

- In approximately five years the heating plant will be at the end of its serviceable life therefore, within that time frame we recommend the installation of (2) new gas fired steam boilers with modulating gas for energy savings.
» **\$250,000**
- All air handling units and classroom unit ventilators would remain as is and be reused to accommodate desired room temperatures.

Priority 3 – Ten Year Needs

- The recently installed heating plant will be reused and converted from steam to hot water while reusing the modulating gas burners and adding boiler water reset for additional energy savings.
» **\$3,500**
- All unit ventilators will be replaced with hot water unit ventilators reusing CO2 demand ventilation controls.
» **\$202,500**
- All steam piping will be removed and a new schedule 40 black steel hot water system will be installed.
» **\$252,000**
- Provide a direct digital control system with internet access and colored graphics.
» **\$315,000**
- Replace all air handling units serving the Kitchen, Cafeteria, Art/Teachers Work Room, Media Center and Administration Area.
» **\$135,000**
- Replace all exhaust fans and internally clean exhaust ductwork.
» **\$68,000**

Priority 4 – Full Renovation of Systems

Regarding the HVAC systems, the projection will be limited to repairing the necessary systems incorporated in the ten year needs.

Bowman Elementary School

Executive Summary - Plumbing/Fire Protection

The Bowman Elementary School has received minimal maintenance on the plumbing systems and equipment over its occupied years. Even with adequate maintenance, systems will gradually deteriorate due to scale and poor water conditions. Although most of the systems are working adequately at this time, the major equipment and systems are near the end of their useful life. Along with aging systems, many of the systems are not up to current codes.

Fixtures:

- Fixtures are generally original indicating the time of their original installation.
- The water closets are generally wall hung vitreous china, flush valve type with siphon jet action. The flush valves do not appear meet water conservation requirements.
- The urinals are wall hung vitreous china, flush valve type with blow out action. The flush valves do not appear to meet water conservation requirements.
- The lavatories are wall hung vitreous china. The faucets are hot and cold water type and do not meet the water conservation requirements. The piping is standard p-trap and is not insulated to meet the accessibility codes.
- The classroom sinks are single bowl, stainless steel sinks with single lever faucets and drinking fountains as part of the sink. The sinks and faucets are in fair condition but do not appear to meet accessibility requirements.
- The drinking fountains are generally wall hung stainless with single lever controls. Fixtures appear to be in fair condition. The fixture and controls do not meet accessibility codes.

Water System:

- The domestic water service enters the building in the Boiler Room. The service entering the building is 4 in. and is complete with a water meter as well as a pressure reducing valve with by-pass. The pressure reducing valve pressure is set to reduce the incoming 100 psi down to the set pressure 60 psi. There is no backflow preventer on the municipal water supply.
- The domestic water heater is supplied from a storage tank with a steam shell and tube heat exchanger supplied from the heating boilers. This type of set up requires the heating boilers to run when there is a need for domestic hot water resulting in an excessive amount of wasted energy.

- There is a master thermostatic mixing valve on the domestic hot water system prior to being distributed to the building hot water system. The domestic hot water is distributed at 130 degrees F. There is no separate 140 degree F. hot water supplied to the Kitchen.

Drainage System:

- The sanitary and storm drainage systems are piped with cast iron. The exposed piping is visibly in good condition.
- The sanitary drainage system is piped to a municipal sewer system.
- The roof is generally flat and is drained by roof drains and a roof drainage system, which exits the building and connects to a municipal storm drainage system.

Natural Gas System:

- The building has no natural gas service at this time.
- There are four individual propane tanks on site that provide fuel for heating of the portable classrooms and fuel for the generator.

Kitchen:

- The kitchen equipment is all generally original and indicates the vintage of the time of installation.
- The cooking equipment is all electric and in fair condition.
- There is a grease trap in the kitchen that appears to be dedicated for the 3-pot sink. All other fixtures appear to go to the sanitary drainage system. There is no dedicated kitchen waste system or an exterior grease trap.

Fire Protection:

- There is no Fire Protection Sprinkler System installed in this school.

Proposed System Priorities

Priority 1 – Immediate Needs and Requirements:

- There are no immediate needs or requirements for this building. All equipment appears to be operating properly.

Priority 2 – 5 Year Requirements:

- A new gas fired water heater along with a thermostatic mixing valve that will supply 120 degree F. hot water to the building.
» **\$15,000.00**
- A new natural gas service will be installed to the building to provide fuel for heating and domestic hot water. Natural gas will also be provided to a generator if one is provided as part of the design.
» **\$5,000.00**

Priority 3 – 10 Year Requirements:

- The domestic water heater installed under Priority 2 will be utilized.
- The gas service installed under Priority 2 will be utilized.
- A new domestic 140 degree F. hot water and hot water recirculating piping system will be included to supply the kitchen needs.
» **\$5,000.00**
- All plumbing fixtures will be replaced with new water conserving type fixtures capable of saving approximately 30% of overall water usage of the building.
» **\$40,000.00**

Priority 4 – Full Renovation of Systems:

- All plumbing fixtures will be replaced with new water conserving type fixtures capable of saving approximately 30% of overall water usage of the building.
- The existing domestic water service appears to be sufficient for the existing building as well as any additions that may be incorporated into the design. A new gas fired water heater along with a thermostatic mixing valve that will supply 120 degree F. hot water to the building as well as 140 degree F hot water to the Kitchen.
- A new domestic cold, hot and hot water recirculating piping system will be included as part of the new domestic water systems.
- The existing drainage systems will be modified and reused as possible to accommodate the modifications to the existing building and any additions.
- A new natural gas service will be installed to the building to provide fuel for heating, domestic hot water and cooking. Natural gas will also be provided to a generator if one is provided as part of the design.

- Kitchen design will be based on the equipment provided by the kitchen equipment consultant including domestic hot and cold water, gas for cooking and drainage of all equipment. A dedicated kitchen waste system will be installed to convey all kitchen waste to an exterior grease trap prior to being discharged into the site sewer system.
- A new fire protection sprinkler system will be installed to provide 100% coverage of the entire existing building as well as all additions. This will include a new fire service to the building and distribution system with quick response sprinklers and fire department valves where required.

DRAFT

**Lexington Elem. Schools
Master Plan Study**

Bridge Elementary School

Executive Summary – Electrical

The existing electrical systems in general, although functioning, are at the end or have exceeded their useful life. Even with regular maintenance systems do deteriorate over the years. The life safety systems, due to code changes over the years, are not in compliance with current codes.

Existing Conditions

- The primary service runs overhead and feeds a 300 kva Utility Co. owned pad mounted transformer. Secondary service runs underground in one (1) 4" conduit. The secondary electrical service consists of a main switch rated at 400amp, 277/480 volt, 3Ø, 4wire, a C/T cabinet and meter with a distribution panel. The equipment is located in the custodian's work room. Lighting and power panels are circuit breaker type and are rated at 120/208 volt and 277/480 volt, 3Ø, 3wire. The existing panels do not appear to have spare circuit breakers for the addition of new lighting and power circuits. Dry type transformers are used for receptacle power. Most equipment was manufactured by General Electric. Various panels do not have required working clearance. The condition of the equipment is poor and has exceeded its useful life.
- Existing classroom lighting consists of (3) continuous rows of wraparound fixtures parallel with the exterior wall. Lights are controlled with one switch. No occupancy sensor exists.
Stage lighting comprises of spot lights in front and track fixtures at stage.
1 x 4 surface fixtures are used in the Gymnatorium with four (4) T5HO lamps and are in good condition.
Kitchen lighting is through vaportight 4' fluorescent fixtures.
Corridor lighting consists of wall mounted 1 x 4 surface wraparound fixtures. Corridors are controlled with local switches.
Although lighting has been retrofitted with T8 lamps and electronic ballasts, fixtures are generally old and in poor condition.
- Existing site lighting consists of floods on utility poles. The site appears to be dark. Building mounted metal halide floods also exist on photocell. Surface canopy lights of compact fluorescent exist at front and rear entrances.
- The existing emergency lighting system is through a LP gas generator rated at 12.5KW, 277/480v, 3Ø, 4W and is manufactured by Onan. Generator does not currently start automatically. One automatic transfer switch manufactured by Onan is present. The system is not code compliant and the equipment is in poor condition. Retrofitted LED exit signs exist. There is inadequate coverage of exit signs.

- Generally classrooms have one receptacle per interior wall. One double duplex has been recently provided from computer grade panel to serve computer equipment. Several extension cords are being used. Outlets in kindergarten are not tamper resistant type. Kitchen floor receptacles not GFI type.
Computer lab has extension cords running on floor to feed center tables.
Receptacles are currently sparsely located and additional receptacles should be provided.
- The building is equipped throughout with an automatic fire alarm system. Existing strobes do not meet ADA. Notification to the fire department is by a Sigcom radio master box with exterior antenna, box #4532. Toilets do not have ADA Strobes.
Strobe lights are mounted higher than 80" above floor as is required by ADA.
The fire alarm control panel is manufactured by Spectronics 641 Series, 8 zone conventional (non-addressable). Pull stations exceed 48"-54" as required by ADA.
Typical classroom has one smoke detector, no horn/strobes.
Building is not sprinklered and does not have full coverage of smoke and heat detectors and does not have adequate coverage of horn/strobes.
- The existing classroom intercom consists of a Rauland Telecenter TC 2100. Classrooms have a wall phone and 2-way speaker for communications with Administration office. No paging speakers in corridors.
- Classroom clocks are manufactured by Simplex. A master time clock is present and is manufactured by Simplex.
- Classrooms do have a Category 5 computer network installed. Classrooms have 4 data drops for students and 1 data and 1 CATV for teacher. Computer lab has inadequate quantity of data drops for computers. School has cable TV and fiber optic services.
- Front and back entrances have an AIPHONE LEF-5 system with intercom/camera at each door with master at administration with door release.
- Security/intrusion consists of a NAPCO magnum alert 800 control panel connected to a remote central station. Infrared sensors exist in corridors, media center. Exterior doors not alarmed.
- No card access or Closed Circuit TV exists.
- No lightning protection exists.

Proposed System Priorities:

Priority 1 - Immediate Needs

- Generator does not start automatically upon normal power failure. Generator is currently started manually. Code requires generator to start automatically and assume load within 10 seconds.
» **\$2,500.00**
- Various kitchen receptacles not GFI.
» **\$1,500.00**
- Portable men toilet, receptacle not GFI.
» **\$100.00**
- Service electrode requires jumper around water meter for proper grounding.
» **\$500.00**
- Electrical items under kitchen hood are required to shutdown upon activation of hood's suppression system.
» **\$2,500.00**
- Add horn/strobes in kitchen, cafeteria and library, currently none exist. Add strobes in toilets.
» **\$7,500.00**
- Add receptacles to eliminate extension cord use.
» **\$10,000.00**
- No pull station at gym exterior door.
» **\$750.00**

Priority 2: 1 – 5 Year Expected Life:

- The existing fire alarm control panel, Spectronics 641 Series, late 1980's vintage, is still a current panel for this manufacturer with available parts. Detectors compatible with this panel are still available. This will allow existing wiring and devices to remain and allow additional devices to be provided. In light of the building not being sprinklered it is recommended that additional smoke and heat detectors be provided for full coverage of the facility.
» **\$1.00/s.f. = \$63,434.00**

- The normal/emergency lighting system should be tested by simulating a power failure and confirming that adequate emergency lighting exists in egress ways and other large spaces where required. Additional emergency lighting should be added where required including on the exterior at exit discharge doors.
» ***\$.25/s.f. = \$15,859***
- Provide full coverage of exit signs where required for safe egress out of the facility.
» ***\$.10/s.f. = \$6,343.00***

Priority 3: 5 – 10 Year Expected Life:

- Provide occupancy sensors to turn lights off in classroom, toilets, offices, gym, etc. to save energy when spaces are unoccupied. Utility Co. rebates may be available for energy conservation measures.
» ***50 @ \$200.00/unit = \$10,000.00***

Priority 4 – Full Renovation of Systems (Gut Rehab)

- » ***\$25.00/s.f. = \$1,585,850.00***
- New construction service ratings are designed for a demand load of 10 watts/s.f. The service capacity will be sized for 1200 amperes at 277/480 volt, 3Ø, 4wire. New lighting and power panels will be provided to accommodate respective loads and located in electric rooms. A system of computer grade panelboards with double neutrals and integral surge suppressors fed from k-rated transformers will be utilized to mitigate the harmonic effects caused by computers and other electronics.
- Classroom lighting fixtures will consist of pendant mounted indirect fluorescent luminaries with T5HO lamps and electronic ballasts. The fixtures will be pre-wired for automatic dimming control where natural daylight is available and also for multi-level switching.
- Office lighting fixtures will consist of acrylic recessed direct fixtures with (2) T5 lamps and electronic ballasts. Two step ballasts will be provided for dual-level switching. Fully dimmable ballasts will be provided where natural daylight is available. Lighting levels will be approximately 30-50 foot candles in classrooms and offices.
- Gymnasium lighting will be comprised of direct fluorescent fixtures with T5HO lamps and electronic ballasts. The fixtures will be provided with protective wire guards. The light level will be designed for approximately 30 foot candles. Occupancy sensors will be provided to turn lights off when unoccupied. Theatrical lights with a dimming system will be provided for performances.
- Corridor lighting will be comprised of recessed acrylic fixtures with (2) T5 lamps & 2 step dimming electronic ballasts for dual level switching. The corridor light level will be designed for approximately 20-foot candles.

- Cafeteria lighting will be pendant indirect fluorescent fixtures with Biax lamps & electronic ballasts. The light levels will be designed for approximately 30 foot candles with dual level switching.
- Kitchen and servery lighting will consist of recessed 2'x4' acrylic lensed troffers with aluminum frame doors with T5 lamps and electronic ballasts. Light levels will be approximately 50-75 foot candles.
- Each area will be locally switched and designed for multi-level controls. Each classroom, office space and toilet rooms will have an occupancy sensor to turn lights off when unoccupied. Daylight sensors will be installed in each classroom and perimeter spaces for automatic dimming of light fixtures.
- The entire school will be controlled with an automatic lighting control system using the lighting panelboards with programmable breakers for programming lights on & off.
- Exterior site lighting fixtures for area lighting will be pole mounted long life, energy efficient LED luminaries in the parking area and roadways. Building perimeter fixtures will be wall mounted compact fluorescent over exterior doors. The exterior lighting will be connected to the automatic lighting control system for photocell on and timed off operation.
- An exterior natural gas emergency generator with a sound attenuated aluminum enclosure will be provided. Light fixtures and LED exit signs will be installed to serve all egress areas such as corridors, intervening spaces, toilets, and exit discharge exterior doors. The administration area lighting will be connected to the emergency generator. The generator will be sized to include life safety systems, boilers and circulating pumps, communications systems, kitchen refrigeration, etc.
- Each classroom will have a minimum of (2) duplex receptacles per teaching wall and (2) double duplex receptacles on dedicated circuits at classroom computer workstations. The teacher's workstation will have a double duplex receptacle also on a dedicated circuit.
- Office areas will generally have (1) duplex outlet per wall. At each workstation a double duplex receptacle will be provided.
- Corridors will have a cleaning receptacle at approximately 30-40 foot intervals.
- Exterior weatherproof GFI receptacles will be installed at exterior doors.
- A fire alarm and detection system in compliance with ADA will be provided with battery back-up. The system will be of the addressable type where each device will be identified at the control panel and remote annunciator by device type and location to facilitate search for origin of alarms. Smoke detectors will be provided in open areas, corridors, and other egress ways. The sprinkler system will be supervised for water flow and tampering with valves. Speaker/strobes will be provided in egress ways, classrooms,

assembly spaces, open areas and other large spaces. Strobe only units will be provided in single toilets and conference rooms.

- Manual pull stations will be provided at exit discharge doors.
- The system will be remotely connected to automatically report alarms to fire department via the radio master box.
- A three phase centralized uninterruptible power supply (UPS) system will be provided with battery back up. The system will provide conditioned power to sensitive electronic loads, telecommunication systems, bridge over power interruptions of short duration and allow an orderly shutdown of servers, communication systems, etc. during a prolonged power outage. The UPS system will also be connected to the stand-by generator.
- A system of lightning protection will be provided. The system will be installed in compliance with the provisions of the latest “Code for Protection Against Lightning” for buildings as adopted by the National Fire Protection Association and the Underwriters’ Laboratories, Inc. for a UL Master Label System.
- The lightning protection equipment will include air terminals, conductors, conduits, fasteners, connectors, ground rods, etc.
- Closed Circuit TV system will consist of computer servers with image software, computer monitors and IP based closed circuit TV cameras. The head end server will be located in the head end MDF room and will be rack mounted. The system can be accessed from any PC within the facility or externally via an IP address. Each camera can be viewed independently. The network video recorders NVR’s will record all cameras and store this information for 21days at 15 images per second (virtual real time). The location of the cameras is generally in corridors and exterior building perimeter. The exterior cameras are pan-tilt-zoom type.
The system will fully integrate with the access control system to allow viewing of events from a single alarm viewer. Camera images and recorded video will be linked to the access system to allow retrieval of video that is associated with an event.
- An intrusion system will consists of security panel, keypads, motion detectors and door contacts. The system is addressable which means that each device will be identified when an alarm occurs. The system is designed so that each perimeter classroom with grade access will have dual tech sensors along the exterior wall and corridors, door contacts at each exterior door.
The system can be partitioned into several zones. Therefore, it is possible to use the Gym area while the remainder of the school remains alarmed.
The system will include a digital transmitter to summons the local police department in the event of an alarm condition
The intrusion system will be connected to the automated lighting control system to automatically turn on lighting upon an alarm.

- A card access system includes a card access controller, door controllers and proximity readers/keypads. Proximity readers will be located at various locations. Each proximity reader will have a distinctive code to identify the user and a log will be kept in memory. The log within the panel can be accessed through a computer.
The alarm condition will also initiate real time recording on the integrated CCTV System. The system may be programmed with graphic maps allowing the end-user to quickly identify alarm conditions and lock/unlock doors.
The system is modular and may be easily expanded to accommodate any additional devices.
- A renewable energy system will consist of a grid connected photovoltaic PV system intended to reduce the facilities demand for power. The photovoltaic system will operate in conformance with the green schools initiative. System will consist of roof mounted photovoltaic modules, weather station, data acquisition system and inverters. Interactive display terminals will be provided for students and for public awareness of the benefits of renewable energy.
- The data system infrastructure will consist of fiber optic backbone cabling. Horizontal wiring will consist of Category 6 UTP Plenum rated cabling for both data and telephone system for gigabit connectivity. The telephone infrastructure will accommodate Centrex, PBX or VOIP based phone systems.
- Each classroom will have 4 data outlets for student computers. Two data, one voice and CATV with video and audio connections to a ceiling projector will be provided at teacher's station with interconnectivity to a smartboard. A wall phone outlet with 2 way ceiling speaker will be provided for communications with administration. Clock will be wireless, part of a GPS/LAN based centralized clock system. Wireless access points with spare fibre will be provided on selected classrooms and other spaces.
- The cafeteria and gymnasium will each have a local sound system with assistive listening devices.
- A central paging system will be provided and integrated with the telephone system.

Bridge Elementary School

Executive Summary - HVAC

The Bridge Elementary School has received below average maintenance of the HVAC systems over its occupied years. Even with adequate maintenance, through normal operation systems do gradually deteriorate due to scale, poor water conditions, and lack of preventive maintenance. Systems will gradually deteriorate to a point of exceeding their maximum serviceable life. This building is a typical example of one such project. While generally speaking, most systems are operating and maintaining reasonable space temperature control, but due to the extreme antiquated nature of the mechanical systems and their gradual scaling of the various piping systems, heat transfer rates have become reduced and the overall system is taxed to a point of inefficiency being created by the slowly depreciating system. While there are no catastrophic failures obvious with the present systems, the systems could continuously be repaired and modified on a sectional basis that will keep the systems operating maintaining acceptable space temperature control however, continued operation will be at the expense of increased operating costs due to inefficiency in heat transfer and through the generally antiquated nature of the systems themselves. The systems installed within this building are approaching their maximum serviceable life. With overall maintenance, cleaning and calibrating of the system, a continued limited service could be achieved however, unpredictable at best. At this time it is not necessary that the systems be modified to prevent a near catastrophic failure, but a continued reuse of the systems will continue to produce unsatisfactory results in terms of overall air quality, temperature control and operating costs.

Existing Conditions:

- The boiler room is provided with two (2) individual HB Smith 450 MILS cast iron sectional boilers generating low-pressure steam. Each boiler is provided with dual low water cut-offs as well as all operating and safety controls and a firematic switch. It was noted that there was surface contamination on the mud drums adjacent to the cast iron sectional nipples indicating that the nipples could be leaking. Each boiler is provided with a single no. 2 fuel oil burner and generates low-pressure steam for distribution. Considering the age of approximately forty-five (45) years, each boiler would suggest that it has approximately five (5) years of usable life.
- The breeching from each boiler appears to be welded black steel and is insulated with what appears to be calcium silicate insulation with a canvas jacket. Each boiler is provided with an individual induced draft fan located at the rear of each boiler which conveys combustion gases from each boiler to a masonry chimney. The induced draft fans are contaminated with soot and are reaching the end of their serviceable life.
- No. 2 fuel oil is recirculated from a buried 10,000 gallon double wall tank installed in 1993. It is provided with leak containment, leak monitoring, double wall piping and fluid level controls. Also provided is a central monitoring panel to detect the presence of fluid within the containment vessels which is not operating. Fuel oil is distributed throughout

- the boiler room through a duplex gear driven fuel oil transfer set which includes pumps, strainers, and isolation valves. It appears that this pumping system is original to the building of approximately 1965 and the fuel oil pumps are showing signs of leakage and are slightly contaminated in the area of the pump bases and consideration should be given to a generalized upgrade. Also located within the pump area are two (2) steam shell and tube heat exchangers for the heating of the original no. 6 fuel oil. No. 6 fuel oil has been discontinued in use and no. 2 fuel oil has replaced it however, custodial personnel continue to use the heating system to preheat the no. 2 fuel oil. This does no harm in the overall operation however, is an energy waste.
- Condensate is returned to the boiler room from the building through a schedule 80 black steel condensate return system. Condensate is returned to the boiler room to a central condensate receiver system which is located on the floor of the boiler room. The floor mounted receiver is provided with two (2) individual boiler feed pumps which appear to be of primary and standby arrangement each of which pumps to a common distribution feed water piping to each boiler. Considering the overall age of the condensate system consideration should be given to an overall upgrade.
 - Low-pressure steam and condensate is distributed through a series of tunnels which feed throughout the building. Steam piping appears to be schedule 40 black steel and condensate appears to be schedule 80 black steel both of which are insulated with what appears to be fiberglass insulation with an all service jacket. It was not possible to evaluate the piping located within these tunnels nor was it possible to determine the condition of the insulation however, considering its age of approximately forty-five (45) years and the noticeable steam leaks consideration should be given to a generalized upgrade of all piping.
 - The automatic temperature control system is of the pneumatic type and is provided with a single storage tank with duplex compressors and motors. It does appear that these compressors are operating correctly but not maintaining adequate compressed air flow to the entire control system. The system was recently provided with a refrigerated air dryer which eliminates moisture within the pneumatic lines. Some corrosion was noted on the pneumatic lines resulting from moisture within the tubing. Consideration for upgrading should be considered.
 - The kitchen is provided with a single wall stainless steel exhaust hood located over the cooking area. This exhaust hood is provided with an individual exhaust system through a welded steel exhaust ductwork system which connects to a roof mounted exhaust fan. The exhaust hood was noted to have vapor tight incandescent lights. The fire suppression system currently installed does not have a sprinkler head located in the hood.
 - Make-up air for the kitchen and its associated hood is through an air-handling unit located at the ceiling. This air-handling unit is of the return air/outside air design and is provided with a steam heating coil with valve control, supply fan, and filters. Sidewall diffusers provide supply air to the entire kitchen area and generally are exhausted 100% through the associated exhaust hood.

- Heating of the entire kitchen area is through two (2) individual ceiling mounted classroom unit ventilators which are designed to introduce one hundred percent (100%) outside air for a source of make-up for the kitchen hood.
- The cafeteria is provided with a single air-handling unit which distributes to wall mounted supply registers located along one wall of the cafeteria. Galvanized sheet metal ductwork provides heated and ventilation air which is noted to be uninsulated. A source of outside air ventilation is provided for this air-handling unit to meet code requirements and the unit is provided with a low-pressure steam heating coil, supply fan, and filters. Return air is drawn through a return air opening at the base of the air-handling unit. Also located within the space are two (2) individual wall mounted exhaust registers that communicate to a roof mounted exhaust fan through a galvanized sheet metal exhaust system. The air-handling unit is controlled through a wall mounted pneumatic thermostat which is noted to be antiquated. Considering the overall age of all equipment and systems within the space consideration should be given to an overall upgrade.
- The building classrooms are provided with a wall mounted classroom unit ventilator. The unit ventilators are all of the low-pressure steam design and are provided with automatic control valves, outside air intake louver for the introduction of outside ventilation air, as well as filters, a supply fan, and automatic temperature controls. It was noted that each of the unit ventilators were extremely antiquated many of which were slightly damaged on the surface, loud and many of which were not operating. The classrooms were also provided with individual exhaust registers. These exhaust grills communicate through a galvanized sheet metal exhaust system to roof mounted exhaust fan and it does appear that this system does operate in a satisfactory manner however, consideration should be given to an upgrade.
- Each classroom space is also provided with a wall mounted pneumatic thermostat which controls the unit's ventilator control valve as well as the outside air dampers.
- The corridor areas throughout the building were provided with exhaust ventilation air however, supply air was not provided which is non-code compliant and should be upgraded.
- The corridor's were also provided with individual wall mounted convectors which were of the low pressure steam design and provide heating through the control of wall mounted pneumatic thermostats.
- The art/teachers work room area is provided with an individual air-handling unit located above the ceiling of the art room. This unit is provided with a source of outside ventilation air, low pressure steam heating coil, supply fan and filters. Considering the generalized age of all equipment consideration should be given to an upgrade.

- The media center is provided with an air-handling unit located above the ceiling. This area is provided with an individual air-handling unit located above the ceiling. This air-handling unit is provided with a source of outside ventilation air, low-pressure steam heating coil, supply fan and filters. Considering the generalized age of all equipment consideration should be given to an upgrade.
- The media center is also provided with an individual exhaust system which is made up of two (2) individual exhaust registers generally located in the wall. These exhaust registers communicate to a galvanized sheet metal exhaust system to a roof mounted exhaust fan. Generally considering the age of the equipment consideration should be given to a generalized upgrade.
- The administration area is provided with a single roof mounted air conditioning unit. This unit is of the single zone design and provides air-conditioned as well as ventilation air through one single zone throughout individual administration areas. Each occupied room is provided with a ceiling mounted supply diffuser which was noted to be slightly dirty. Considering its general age consideration should be given to an upgrade.
- Also located within the various offices of the administration area were varying lengths of fintube radiation located along the exterior wall. The fintube radiation was noted to be dirty and in many instances it was damaged with various end covers missing and slight surface contamination. The fintube radiation is controlled through an individual wall mounted pneumatic thermostats all of which were noted to be antiquated. Considering its general appearance and age consideration should be given to an upgrade.
- The interior classrooms were provided with ceiling suspended classroom unit ventilators which free blow into the occupied space through a single discharge grill horizontally located on the unit ventilator. Each unit ventilator is provided with an outside air intake duct which communicates to a roof mounted hood which was insulated with what appears to be fiberglass insulation. The unit ventilators were very typical to those of a typical classroom which include a steam heating coil, filters, and supply fan. The unit is provided with a wall mounted pneumatic thermostat for control and it also was antiquated.
- The individual classrooms were also provided with fintube radiation located under the clear story glass on the exterior wall. This fintube radiation was noted to be slightly dirty and slightly damaged.
- Also located within these classrooms was a wall mounted exhaust register. It was noted that these exhaust registers communicate to roof mounted exhaust fans through a galvanized sheet metal exhaust system. As we understand it, all systems do operate in a satisfactory manner however, considering the age of all equipment consideration should be given to an upgrade.

- The portable classrooms are each provided with a single roof mounted heating and ventilating and air conditioning unit. Each rooftop unit is provided with electric cooling and propane heating. The rooftop units are controlled through individual electric wall mounted thermostats. There is an offensive odor present in the portable classrooms which could relate to excessive vapor pressure resulting in mold formation. Further investigation should be considered to determine the contributing conditions.
- The building public toilets were provided with wall mounted exhaust registers that were noted to be slightly dirty however, as we understand it do operate. These exhaust registers communicate to roof mounted exhaust fans through a galvanized sheet metal exhaust system.
- Make-up air for the individual toilets was through the use of louvers located within the doors.
- Heating of the toilet spaces is through the use of wall mounted convection heating. It was noted that the heating elements were slightly damaged with surface contamination. The individual radiation elements were controlled by wall mounted pneumatic thermostats which were noted to be antiquated. Consideration should be given to an upgrade based purely on age and the antiquated nature of all equipment.

Proposed System Priorities

Priority 1 – Immediate Needs and Requirements

- Veeder Root oil tank monitoring system is not operating
» **\$2,000.00**
- Wasted energy resulting from pre-heating No.2 fuel oil
» **\$2,000.00**
- Steam leaks in steam tunnels
» **\$25,000.00**
- Sprinkler head in kitchen hood is not installed
» **\$250.00**
- Code required ventilation air not provided in corridors
» **\$44,000.00**
- Calibration of the pneumatic temperature controls
» **\$31,500.00**
- CO2 Demand ventilation control in Classroom unit ventilators
» **\$27,000.00**

- Verify shaft trueness on all unit ventilators, exhaust fans and air handling units and replace if necessary
» **\$13,000**
- Verify conditions of shaft bearings on all unit ventilators, exhaust fans and air handling units and replace if necessary
» **\$13,000**
- Clean fan wheels, coils, dampers, and outside air louvers on all unit ventilators, exhaust fans and air handling units
» **\$13,000**

Priority 2 – Five Year Needs

- In approximately five years the heating plant will be at the end of its serviceable life therefore, within that time frame we recommend the installation of (2) new gas fired steam boilers with modulating gas for energy savings.
» **\$250,000**
- All air handling units and classroom unit ventilators would remain as is and be reused to accommodate desired room temperatures.

Priority 3 – Ten Year Needs

- The recently installed heating plant will be reused and converted from steam to hot water while reusing the modulating gas burners and adding boiler water reset for additional energy savings.
» **\$3,500**
- All unit ventilators will be replaced with hot water unit ventilators reusing CO2 demand ventilation controls.
» **\$202,500**
- All steam piping will be removed and a new schedule 40 black steel hot water system will be installed.
» **\$252,000**
- Provide a direct digital control system with internet access and colored graphics.
» **\$315,000**
- Replace all air handling units serving the Kitchen, Cafeteria, Art/Teachers Work Room, Media Center and Administration Area.
» **\$135,000**
- Replace all exhaust fans and internally clean exhaust ductwork.
» **\$68,000**

Priority 4 – Full Renovation of Systems

Regarding the HVAC systems, the projection will be limited to repairing the necessary systems incorporated in the ten year needs.

DRAFT

Bridge Elementary School

Executive Summary - Plumbing/Fire Protection

The Bridge Elementary School has received minimal maintenance on the plumbing systems and equipment over its occupied years. Even with adequate maintenance, systems will gradually deteriorate due to scale and poor water conditions. Although most of the systems are working adequately at this time, the major equipment and systems are near the end of their useful life. Along with aging systems, many of the systems are not up to current codes.

Fixtures:

- Fixtures are generally original indicating the time of their original installation.
- The water closets are generally wall hung vitreous china, flush valve type with siphon jet action. The flush valves do not appear meet water conservation requirements.
- The urinals are wall hung vitreous china, flush valve type with blow out action. The flush valves do not appear to meet water conservation requirements.
- The lavatories are wall hung vitreous china. The faucets are hot and cold water type and do not meet the water conservation requirements. The piping is standard p-trap and is not insulated to meet the accessibility codes.
- The classroom sinks are single bowl, stainless steel sinks with single lever faucets and drinking fountains as part of the sink. The sinks and faucets are in fair condition but do not appear to meet accessibility requirements.
- The drinking fountains are generally wall hung stainless with single lever controls. Fixtures appear to be in fair condition. The fixture and controls do not meet accessibility codes.

Water System:

- The domestic water service enters the building in the Boiler Room. The service entering the building is 4 in. and is complete with a water meter as well as a pressure reducing valve with by-pass. The pressure reducing valve pressure is set to reduce the incoming 100 psi down to the set pressure 60 psi. There is no backflow preventer on the municipal water supply.
- The domestic water heater is supplied from a storage tank with a steam shell and tube heat exchanger supplied from the heating boilers. This type of set up requires the heating boilers to run when there is a need for domestic hot water resulting in an excessive amount of wasted energy.

- There is a master thermostatic mixing valve on the domestic hot water system prior to being distributed to the building hot water system. The domestic hot water is distributed at 130 degrees F. There is no separate 140 degree F. hot water supplied to the Kitchen.

Drainage System:

- The sanitary and storm drainage systems are piped with cast iron. The exposed piping is visibly in good condition.
- The sanitary drainage system is piped to a municipal sewer system.
- The roof is generally flat and is drained by roof drains and a roof drainage system, which exits the building and connects to a municipal storm drainage system.

Natural Gas System:

- The building has no natural gas service at this time.

Kitchen:

- The kitchen equipment is all generally original and indicates the vintage of the time of installation.
- The cooking equipment is all electric and in fair condition.
- There is a grease trap in the kitchen that appears to be dedicated for the 3-pot sink. All other fixtures appear to go to the sanitary drainage system. There is no dedicated kitchen waste system or an exterior grease trap.

Fire Protection:

- There is no Fire Protection Sprinkler System installed in this school.

Proposed System Priorities

Priority 1 – Immediate Needs and Requirements:

- There are no immediate needs or requirements for this building. All equipment appears to be operating properly.

Priority 2 – 5 Year Requirements:

- A new gas fired water heater along with a thermostatic mixing valve that will supply 120 degree F. hot water to the building.
» **\$15,000.00**

- A new natural gas service will be installed to the building to provide fuel for heating and domestic hot water. Natural gas will also be provided to a generator if one is provided as part of the design.
» **\$5,000.00**

Priority 3 – 10 Year Requirements:

- The domestic water heater installed under Priority 2 will be utilized.
- The gas service installed under Priority 2 will be utilized.
- A new domestic 140 degree F. hot water and hot water recirculating piping system will be included to supply the kitchen needs.
» **\$5,000.00**
- All plumbing fixtures will be replaced with new water conserving type fixtures capable of saving approximately 30% of overall water usage of the building.
» **\$40,000.00**

Priority 4 – Full Renovation of Systems:

- All plumbing fixtures will be replaced with new water conserving type fixtures capable of saving approximately 30% of overall water usage of the building.
- The existing domestic water service appears to be sufficient for the existing building as well as any additions that may be incorporated into the design. A new gas fired water heater along with a thermostatic mixing valve that will supply 120 degree F. hot water to the building as well as 140 degree F hot water to the Kitchen.
- A new domestic cold, hot and hot water recirculating piping system will be included as part of the new domestic water systems.
- The existing drainage systems will be modified and reused as possible to accommodate the modifications to the existing building and any additions.
- A new natural gas service will be installed to the building to provide fuel for heating, domestic hot water and cooking. Natural gas will also be provided to a generator if one is provided as part of the design.
- Kitchen design will be based on the equipment provided by the kitchen equipment consultant including domestic hot and cold water, gas for cooking and drainage of all equipment. A dedicated kitchen waste system will be installed to convey all kitchen waste to an exterior grease trap prior to being discharged into the site sewer system.

- A new fire protection sprinkler system will be installed to provide 100% coverage of the entire existing building as well as all additions. This will include a new fire service to the building and distribution system with quick response sprinklers and fire department valves where required.

DRAFT

**Lexington Elem. Schools
Master Plan Study**

Estabrook Elementary School

Executive Summary - Electrical:

- The existing electrical systems in general, although functioning, are at the end or have exceeded their useful life. Even with regular maintenance systems do deteriorate over the years. The life safety systems, due to code changes over the years, are not in compliance with current codes.

Existing Conditions:

- The existing electrical service consists of an original switchboard with a fusible main device and fusible branches located in the basement main electric room. The service rating is 1,200 amp, 120/208 volt, 3Ø, 4wire manufactured by General Electric. The condition of the equipment is poor.
The main electric room does not have two entrances with panic hardware as currently required by code. The transformer feeding the building is located in a vault with exterior grate access. Primary service runs underground.
Existing lighting and power panels are circuit breaker type and are rated at 120/208 volt, 3Ø, 4wire. The existing panels generally do not have spare circuit breakers for the addition of new lighting and power circuits. The existing panels are in poor condition. A panel with a surge suppressor was recently added for classroom computer receptacles.
- Existing classroom lighting consists of 2' x 4' acrylic lensed fixtures with T8 lamps and electronic ballasts, parallel with the exterior wall. The existing lighting system contributes substantial glare onto computer screens present in classrooms. Controls are with 3 switches. There are no occupancy sensors.
Lighting in the corridors is with 2' x 2' recessed acrylic fixtures with T8 lamps and electronic ballasts. Corridor light levels are moderate. Lights are locally controlled with switches.
The stage has no theatrical lighting.
Gymnasium lighting is with 1 x 4 lensed high bay with three (3) T5HO lamps and wireguards in good condition.
- Existing site roadway lighting is by concrete poles with cobra heads. Exterior building mounted metal halide flood lights also exist. Rear parking has wooden poles with cobra heads. Front canopy has recessed square fixtures with incandescent lamps.
- The emergency lighting system is through self contained emergency battery units. The system does not meet present code due to the lack of coverage. A minimum of one-foot candle is required at the floor. No emergency lights at exterior doors.
- Existing classrooms have approximately one receptacle per wall. A double duplex has been added for computer power. Computer lab is equipped with wiremold at each bench.

- The building is equipped throughout with an automatic fire alarm system in the corridors. While some existing strobes meet ADA for intensity others do not. Most strobes exceed ADA height and are not synchronized. The fire alarm control panel is conventional (non-addressable) and is manufactured by Gamewell Flex 300 and has 18 zones. Notification to the fire department is by a radio master box #5656. Pull stations exceed ADA height. Classrooms have smokes but no horn/strobe. Heats exist in boiler room.
- The telephone service is located outside of the main electric room. The Administration area has telephone handsets. Classrooms also have handsets. The paging/intercom system is a Bogen C-100 utilizing an old console for classroom speakers. There are classroom panels with integral clock/speaker. The stage does have a local sound system.
There is a local area network present. Typically five data drops are present per classroom. The distribution frame is located in the computer lab.
There is a master time clock. The clock appears to be in fair condition.
There is a security system present with infrared detectors in the corridor and classrooms. Control panel was manufactured by Maxsys PC4020.
No door entry system with door release.
No card access or CCTV systems.
No lightning protection system.

Proposed System Priorities

Priority 1: Immediate Needs

- Receptacles in kitchen not GFI.
» **\$1,500.00**
- Provide lens in light fixture over server counter.
» **\$100.00**
- Electrical items under kitchen hood are required to shutdown upon activation of hood suppression system.
» **\$2,500.00**
- Add fire alarm strobe to toilets.
» **\$5,000.00**
- Add pull station at toilet exterior door.
» **\$750.00**

Priority 2: 1 – 5 Year Expected Life:

- The existing fire alarm control panel, Gamewell Flex 300, 1980's vintage has reached the end of its life. Replacement parts are still available until they run out. New parts are no longer manufactured. Replacement smoke detectors are still available although UL Listed smoke detectors may not be. Existing panel is not expandable. In light of the building not being sprinklered it is recommended that a replacement panel be provided

with expansion capability for full coverage of smokes and heats. Strobes visible within the same space are required to be synchronized.

» **$\$1.00/s.f. = \$65,000.00$**

- Provide additional self contained battery units in egress ways and other large spaces. Provide emergency lighting over exterior doors.

» **$\$.20/s.f. = \$13,000.00$**

- Provide full coverage of exit signs where required for safe egress out of the facility.

» **$\$.10/s.f. = \$6,500.00$**

Priority 3: 5 – 10 Year Expected Life:

- Provide occupancy sensors to turn lights off in classroom, toilets, offices, gym, etc. to save energy when spaces are unoccupied. Utility Co. rebates may be available for energy conservation measures.

» **$55 @ \$200/unit = \$11,000.00$**

Priority 4 – Full Renovation of Systems (Gut Rehab)

» **$\$25.00/s.f. = \$1,625,000.00$**

- New construction service ratings are designed for a demand load of 10 watts/s.f. The service capacity will be sized for 1200 amperes at 277/480 volt, 3Ø, 4wire. New lighting and power panels will be provided to accommodate respective loads and located in electric rooms. A system of computer grade panelboards with double neutrals and integral surge suppressors fed from k-rated transformers will be utilized to mitigate the harmonic effects caused by computers and other electronics.
- Classroom lighting fixtures will consist of pendant mounted indirect fluorescent luminaries with T5HO lamps and electronic ballasts. The fixtures will be pre-wired for automatic dimming control where natural daylight is available and also for multi-level switching.
- Office lighting fixtures will consist of acrylic recessed direct fixtures with (2) T5 lamps and electronic ballasts. Two step ballasts will be provided for dual-level switching. Fully dimmable ballasts will be provided where natural daylight is available. Lighting levels will be approximately 30-50 foot candles in classrooms and offices.
- Gymnasium lighting will be comprised of direct fluorescent fixtures with T5HO lamps and electronic ballasts. The fixtures will be provided with protective wire guards. The light level will be designed for approximately 30 foot candles. Occupancy sensors will be provided to turn lights off when unoccupied. Theatrical lights with a dimming system will be provided for performances.
- Corridor lighting will be comprised of recessed acrylic fixtures with (2) T5 lamps & 2 step dimming electronic ballasts for dual level switching. The corridor light level will be designed for approximately 20-foot candles.

- Cafeteria lighting will be pendant indirect fluorescent fixtures with Biax lamps & electronic ballasts. The light levels will be designed for approximately 30 foot candles with dual level switching.
- Kitchen and servery lighting will consist of recessed 2'x4' acrylic lensed troffers with aluminum frame doors with T5 lamps and electronic ballasts. Light levels will be approximately 50-75 foot candles.
- Each area will be locally switched and designed for multi-level controls. Each classroom, office space and toilet rooms will have an occupancy sensor to turn lights off when unoccupied. Daylight sensors will be installed in each classroom and perimeter spaces for automatic dimming of light fixtures.
- The entire school will be controlled with an automatic lighting control system using the lighting panelboards with programmable breakers for programming lights on & off.
- Exterior site lighting fixtures for area lighting will be pole mounted long life, energy efficient LED luminaries in the parking area and roadways. Building perimeter fixtures will be wall mounted compact fluorescent over exterior doors. The exterior lighting will be connected to the automatic lighting control system for photocell on and timed off operation.
- An exterior natural gas emergency generator with a sound attenuated aluminum enclosure will be provided. Light fixtures and LED exit signs will be installed to serve all egress areas such as corridors, intervening spaces, toilets, and exit discharge exterior doors. The administration area lighting will be connected to the emergency generator. The generator will be sized to include life safety systems, boilers and circulating pumps, communications systems, kitchen refrigeration, etc.
- Each classroom will have a minimum of (2) duplex receptacles per teaching wall and (2) double duplex receptacles on dedicated circuits at classroom computer workstations. The teacher's workstation will have a double duplex receptacle also on a dedicated circuit.
- Office areas will generally have (1) duplex outlet per wall. At each workstation a double duplex receptacle will be provided.
- Corridors will have a cleaning receptacle at approximately 30-40 foot intervals.
- Exterior weatherproof GFI receptacles will be installed at exterior doors.
- A fire alarm and detection system in compliance with ADA will be provided with battery back-up. The system will be of the addressable type where each device will be identified at the control panel and remote annunciator by device type and location to facilitate search for origin of alarms. Smoke detectors will be provided in open areas, corridors, and other egress ways. The sprinkler system will be supervised for water flow and tampering with valves. Speaker/strobes will be provided in egress ways, classrooms,

assembly spaces, open areas and other large spaces. Strobe only units will be provided in single toilets and conference rooms.

- Manual pull stations will be provided at exit discharge doors.
- The system will be remotely connected to automatically report alarms to fire department via the radio master box.
- A three phase centralized uninterruptible power supply (UPS) system will be provided with battery back up. The system will provide conditioned power to sensitive electronic loads, telecommunication systems, bridge over power interruptions of short duration and allow an orderly shutdown of servers, communication systems, etc. during a prolonged power outage. The UPS system will also be connected to the stand-by generator.
- A system of lightning protection will be provided. The system will be installed in compliance with the provisions of the latest “Code for Protection Against Lightning” for buildings as adopted by the National Fire Protection Association and the Underwriters’ Laboratories, Inc. for a UL Master Label System.
- The lightning protection equipment will include air terminals, conductors, conduits, fasteners, connectors, ground rods, etc.
- A Closed Circuit TV system will consist of computer servers with image software, computer monitors and IP based closed circuit TV cameras. The head end server will be located in the head end MDF room and will be rack mounted. The system can be accessed from any PC within the facility or externally via an IP address. Each camera can be viewed independently. The network video recorders NVR’s will record all cameras and store this information for 21days at 15 images per second (virtual real time). The location of the cameras is generally in corridors and exterior building perimeter. The exterior cameras are pan-tilt-zoom type.

The system will fully integrate with the access control system to allow viewing of events from a single alarm viewer. Camera images and recorded video will be linked to the access system to allow retrieval of video that is associated with an event.

- An intrusion system will consists of security panel, keypads, motion detectors and door contacts. The system is addressable which means that each device will be identified when an alarm occurs. The system is designed so that each perimeter classroom with grade access will have dual tech sensors along the exterior wall and corridors, door contacts at each exterior door.
The system can be partitioned into several zones. Therefore, it is possible to use the Gym area while the remainder of the school remains alarmed.
The system will include a digital transmitter to summons the local police department in the event of an alarm condition
The intrusion system will be connected to the automated lighting control system to automatically turn on lighting upon an alarm.

- A card access system includes a card access controller, door controllers and proximity readers/keypads. Proximity readers will be located at various locations. Each proximity reader will have a distinctive code to identify the user and a log will be kept in memory. The log within the panel can be accessed through a computer.
The alarm condition will also initiate real time recording on the integrated CCTV System. The system may be programmed with graphic maps allowing the end-user to quickly identify alarm conditions and lock/unlock doors.
The system is modular and may be easily expanded to accommodate any additional devices.
- A renewable energy system will consist of a grid connected photovoltaic PV system intended to reduce the facilities demand for power. The photovoltaic system will operate in conformance with the green schools initiative. System will consist of roof mounted photovoltaic modules, weather station, data acquisition system and inverters. Interactive display terminals will be provided for students and for public awareness of the benefits of renewable energy.
- The data system infrastructure will consist of fiber optic backbone cabling. Horizontal wiring will consist of Category 6 UTP Plenum rated cabling for both data and telephone system for gigabit connectivity. The telephone infrastructure will accommodate Centrex, PBX or VOIP based phone systems.
- Each classroom will have 4 data outlets for student computers. Two data, one voice and CATV with video and audio connections to a ceiling projector will be provided at teacher's station with interconnectivity to a smartboard. A wall phone outlet with 2 way ceiling speaker will be provided for communications with administration. Clock will be wireless, part of a GPS/LAN based centralized clock system. Wireless access points with spare fibre will be provided on selected classrooms and other spaces.
- The cafeteria and gymnasium will each have a local sound system with assistive listening devices.
- A central paging system will be provided and integrated with the telephone system.

Estabrook Elementary School

Executive Summary - HVAC

The Estabrook Elementary School has received average maintenance of the HVAC systems over its occupied years. Even with adequate maintenance, through normal operation systems do gradually deteriorate due to scale, poor water conditions, and lack of preventive maintenance. Systems will gradually deteriorate to a point of exceeding their maximum serviceable life. While generally speaking, most systems are operating and maintaining reasonable space temperature control, but due to the extreme antiquated nature of the mechanical systems and their gradual scaling of the various piping systems, heat transfer rates have become reduced and the overall system is taxed to a point of inefficiency being created by the slowly depreciating system. While there are no catastrophic failures obvious with the present systems, the systems could continuously be repaired and modified on a sectional basis that will keep the systems operating maintaining acceptable space temperature control however, continued operation will be at the expense of increased operating costs due to inefficiency in heat transfer and through the generally antiquated nature of the systems themselves. The systems installed within this building are approaching their maximum serviceable life. With overall maintenance, cleaning and calibrating of the system, a continued limited service could be achieved. At this time it is not necessary that the systems be modified to prevent a near catastrophic failure, but a continued reuse of the systems will continue to produce unsatisfactory results in terms of overall air quality, temperature control and operating costs.

Existing Conditions:

- The boiler room is provided with two individual HB Smith 440 MILS water tube boilers generating low pressure steam. Each boiler is provided with dual low water cut-offs as well as all operating and safety controls and a firematic switch. Each boiler is provided with a single fuel no. 2 fuel oil burner and generates low-pressure steam for distribution. The boiler room is provided with an emergency shut-off switch at the boiler room entrance and does operate. Considering the age of the boilers it would appear from an external standpoint that they should be replaced.
- The breeching from each boiler appears to be welded black steel and is insulated with what appears to be calcium silicate insulation with a canvas jacket. Each boiler is provided with an individual induced draft fan and barometric damper located at the rear of each boiler which conveys combustion gases from each boiler to a masonry chimney. The induced draft fans are contaminated with soot and reaching the end of their serviceable life.
- No. 2 fuel oil is recirculated from a buried 10,000 gallon double wall underground storage tank. Fuel oil is distributed throughout the boiler room through a duplex gear driven fuel oil transfer set which includes pumps, strainers, and isolation valves. It appears that this pumping system is original and the fuel oil pumps are showing signs of leakage and are contaminated in the area of the pump bases and should be replaced.

- Condensate is returned to the boiler room through a schedule 80 black steel condensate return system. Condensate is returned to the boiler room to a return system which is located on the floor of the boiler room. The floor mounted receivers are provided with positive discharge pumps which act as boiler feed pumps to the boilers. The original condensate tank is no longer operational and three new tanks have been installed.
- Low-pressure steam and condensate is distributed through the crawl space which travels throughout the building. Steam piping appears to be schedule 40 black steel and condensate appears to be schedule 80 black steel both of which are insulated with what appears to be fiberglass insulation.
- Combustion air is provided through two individual ducts which originate at wall mounted louvers. One duct terminates at approximately twelve inches above the floor and a second duct terminates at approximately three feet above the floor. Per code one of the ducts must terminate at approximately eight to ten feet above the floor. The other duct at approximately twelve inches above the floor can remain. No motor operated damper was provided in one of the combustion air ducts. This condition is non-code compliant and should be upgraded.
- The automatic temperature control system is of the pneumatic type and is provided with a single storage tank with duplex compressors and motors. It does appear that these compressors are operating correctly but not maintaining adequate compressed air flow to the entire control system. The system is provided with a refrigerated air dryer as well as an oil and water separators. Consideration for upgrading should be considered.
- The kitchen is provided with a single wall stainless steel exhaust hood located over the cooking area. The exhaust hood was noted to have vapor tight incandescent lighting, fire protection, and washable replaceable filters.
- Make-up air for the kitchen and its associated hood is through an air-handling unit located at the ceiling of an adjacent storage room. This air-handling unit is provided with a steam heating coil with valve control, supply fan, and filters. Ventilation air is distributed through a galvanized sheet metal distribution system. Side wall diffusers provide supply air to the entire kitchen area and generally are exhausted 100% through the associated exhaust hood.
- The cafeteria area is a large area adjacent to the entrance lobby which has been assigned to use as an eating area. This space is not provided with any means of ventilation control nor is it provided with the air changes required for total air and outside air to meet the building code requirements. This entire condition is non-code compliant and should be upgraded.
- The cafeteria area is also provided with individual wall mounted convectors for space heating.

- The gymnasium is provided with two individual air handling units located high at the ceiling within an adjacent storage room. Galvanized sheet metal travels between each air handling unit to a single side wall diffuser located high within the space. The air handling units each are typical and are each provided with a source of outside air to a wall louver and the outside air duct is insulated. Each air handling unit is provided with a low pressure steam heating coil, supply fan, and filters. We were advised that the systems cannot be operated because of the noise generated makes them nearly impossible to use. Based on the above comments it is recommended that the systems be replaced entirely.
- Return air and exhaust air from the space are drawn through individual wall mounted registers which travel below the slab within the crawl space to remote exhaust fans and discharge the exhaust air out through louvers.
- Also located within the gymnasium was a length of fintube radiation located along the exterior wall. This fintube radiation is of the low pressure steam design and it was noted to be damaged and dirty and in need of upgrading.
- The air handling units and fintube radiation are controlled through individual wall mounted pneumatic thermostats.
- Each classroom is provided with a wall mounted classroom unit ventilator located on the exterior wall of each classroom. The unit ventilators are provided with a low pressure steam heating coil with a modulating automatic control valve. The unit ventilators are provided with an outside air intake louver as well as filters, supply fan. In each case the units were extremely antiquated many of which were slightly damaged on the surface and noisy. These spaces were also provided with individual exhaust registers. These exhaust grills communicate through a galvanized sheet metal exhaust system which are ventilated through a utility type exhaust fan which discharges to a wall mounted louver at the ceiling of the crawl space. All exhaust systems are extremely antiquated and considering their age should be replaced at this time.
- The computer classroom was provided with an air handling unit located overhead within the space itself. This air handling unit distributes heated and air conditioned air through an overhead galvanized sheet metal duct distribution system. It does appear that no ventilation is provided to this internal space and consideration should be given to upgrading this condition. Also located within this space was an exhaust register located approximately twelve inches above the floor. It appears that this exhaust register communicates through the central exhaust system located within the crawl space.
- The corridors located within the building were all provided with wall mounted convectors for generalized space heating. The individual convectors were controlled through individual pneumatic wall mounted thermostats.
- It was noted that there was a limited amount of exhaust ventilation located throughout the corridor areas however, no supply ventilation was provided. This condition is non-code compliant and should be upgraded.

- The music/lecture area is provided with heated and ventilation air which originates in an air handling unit located within the crawl space. This air handling unit is provided with a source of outside air for ventilation as well as a low pressure steam heating coil, supply fan, and filters. Also located within the space was various return air registers located above the floor. These registers return to the ceiling of the crawl space to provide return air back to the air handling unit. Also located at the ceiling of the space was an exhaust fan with limited amount of exhaust ductwork and registers. It was noted that all systems were slightly dirty and this exhaust system was extremely noisy.
- The media center is provided with three individual wall mounted classroom unit ventilators located along the exterior wall. Each unit ventilator is very similar in design and size to the individual classrooms and each are provided with a low pressure steam heating coil which is controlled through a modulating steam control valve, outside air louver for the introduction of ventilation air, supply fans, and filter. Each unit ventilator is controlled through a wall mounted pneumatic thermostat and it was noted to be antiquated and in need of replacement.
- Exhaust ventilation is through individual wall mounted exhaust registers located along the corridor wall of the space.
- The administration area is heated and ventilated through a centrally installed air handling unit located within the crawl space. This air handling unit is of the single zone design and distributes heating and ventilated air through a galvanized sheet metal supply system located at the ceiling of the crawl space. Supply air for the individual office areas is through a series of ceiling mounted diffusers located throughout each occupied area. This air handling unit is provided with a low pressure steam heating coil, filters, supply fans, and a source of outside ventilation air. Considering the overall age and condition consideration should be given to an upgrade.
- Also located within each occupied area were varying lengths of fin tube radiation and/or convectors. Each heating element is of the low pressure steam design and is controlled through individual wall mounted pneumatic thermostats.
- Within the office administration area was a window mounted air conditioning unit which discharges condenser air into the entrance vestibule. This overall condition should be upgraded.
- The portable classroom building is provided with three individual classrooms each controlled through an individual rooftop unit. Each roof top unit is provided with electric heat and electric cooling and distributes heated, ventilation, and air conditioned air through an overhead galvanized sheet metal duct distribution system. Considering the source of electric heat consideration should be given to upgrading. There is an offensive odor present in the portable classrooms which could relate to excessive vapor pressure resulting in mold formation. Further investigation should be considered to determine the contributing conditions.

- Also located within the portable classrooms were ceiling mounted exhaust registers and a fan which is controlled through a wall mounted switch. It does appear that minimum ventilation is not being provided through this air handling unit and consideration should be given to upgrading the control system.
- The building gang toilets were provided with wall mounted exhaust registers which were extremely antiquated and dirty. These exhaust registers communicate to centrally located exhaust fans within the crawl space and through a galvanized sheet metal exhaust system discharge to wall mounted louvers.
- Make-up air for the individual toilets was through the use of louvers located within the doors.
- Heating of the toilet spaces were through the use of wall mounted fintube radiation which was controlled through the use of a pneumatic thermostat. It was noted that this radiation was slightly damaged with surface contamination and the pipe feeding the fintube radiation was damaged and the insulation was severely compromised.

Proposed System Priorities

Priority 1 – Immediate Needs and Requirements

- No actuator on one of the combustion air ducts in the boiler room. Duct termination heights are not code compliant.
» **\$3,000.00**
- Code required ventilation air not provided in corridors/café
» **\$32,000.00**
- Calibration of the pneumatic temperature controls
» **\$32,500.00**
- CO2 Demand ventilation control in the classroom and media center unit ventilators
» **\$21,000.00**
- Verify shaft trueness on all unit ventilators, exhaust fans and air handling units and replace if necessary.
» **\$13,000.00**
- Verify conditions of shaft bearings on all unit ventilators, exhaust fans and air handling units and replace if necessary.
» **\$13,000.00**
- Clean fan wheels, coils, dampers, and outside air louvers on all unit ventilators, exhaust fans and air handling units.
» **\$13,000.00**

Priority 2 – Five Year Needs

- In approximately five years the heating plant will be at the end of its serviceable life therefore, within that time frame we recommend the installation of (2) new gas fired steam boilers with modulating gas for energy savings.
» **\$250,000.00**
- All air handling units and classroom unit ventilators would remain as is and be reused to accommodate desired room temperatures.

Priority 3 – Ten Year Needs

- The recently installed heating plant will be reused and converted from steam to hot water while reusing the modulating gas burners and adding boiler water reset for additional energy savings.
» **\$3,500.00**
- All unit ventilators will be replaced with hot water unit ventilators reusing CO2 demand ventilation controls.
» **\$157,500.00**
- All steam piping will be removed and a new schedule 40 black steel hot water system will be installed.
» **\$260,000.00**
- Provide a direct digital control system with internet access and colored graphics.
» **\$325,000.00**
- Replace all air handling units serving the gym, computer classroom, administration area, music/lecture area and kitchen.
» **\$98,000.00**
- Replace all exhaust fans and internally clean exhaust ductwork.
» **\$67,500.00**

Priority 4 – Full Renovation of Systems

Regarding the HVAC systems, the projection will be limited to repairing the necessary systems incorporated in the 10 year needs.

Estabrook Elementary School

Executive Summary - Plumbing/Fire Protection

The Estabrook Elementary School has received minimal maintenance on the plumbing systems and equipment over its occupied years. Even with adequate maintenance, systems will gradually deteriorate due to scale and poor water conditions. Although most of the systems are working adequately at this time, the major equipment and systems are near the end of their useful life. Along with aging systems, many of the systems are not up to current codes.

Fixtures:

- Fixtures are generally original indicating the time of their original installation. Some attempts have been made to try and provide accessible toilet rooms.
- The water closets are generally wall hung vitreous china, flush valve type with siphon jet action. The flush valves do not appear meet water conservation requirements.
- The urinals are wall hung vitreous china, flush valve type with blow out action. The flush valves do not appear to meet water conservation requirements.
- The lavatories are wall hung vitreous china. The faucets are hot and cold water type and do not meet the water conservation requirements. The piping is standard p-trap and is not insulated to meet the accessibility codes.
- The classroom sinks are single bowl, stainless steel sinks with single lever faucets and drinking fountains as part of the sink. The sinks and faucets are in fair condition but do not appear to meet accessibility requirements.
- The drinking fountains are generally wall hung stainless with single lever controls. Fixtures appear to be in fair condition. The fixture and controls do not meet accessibility codes.

Water System:

- The domestic water service enters the building in the Boiler Room. The service entering the building is 3 in. and is complete with a water meter as well as a pressure reducing valve with by-pass. The pressure reducing valve pressure is set to reduce the incoming 100 psi down to the set pressure 60 psi. There is no backflow preventer on the municipal water supply.
- The domestic hot water is supplied from a tank type oil fired water heater. The water heater was installed in 2004 and is in good condition.

- There is a master thermostatic mixing valve on the domestic hot water system prior to being distributed to the building hot water system. There is no separate 140 degree F. hot water supplied to the Kitchen.

Drainage System:

- The sanitary and storm drainage systems are piped with cast iron. The exposed piping is visibly in good condition.
- The sanitary drainage system is piped to a municipal sewer system.
- The roof is generally flat and is drained by roof drains and a roof drainage system, which exits the building and connects to a municipal storm drainage system.
- There is a simplex sump pump located in the Boiler Room which appears to lift ground water as well as overflow from the condensate receivers.

Natural Gas System:

- There is no natural gas service supplied to the building.

Kitchen:

- The kitchen equipment is all generally original and indicates the vintage of the time of installation.
- The cooking equipment is all electric and in fair condition.
- There is a grease trap in the kitchen that appears to be dedicated for the 3-pot sink. All other fixtures appear to go to the sanitary drainage system. There is no dedicated kitchen waste system or an exterior grease trap.

Fire Protection:

- There is no Fire Protection Sprinkler System installed in this school.

Proposed System Priorities

Priority 1 – Immediate Needs and Requirements:

- There are no immediate needs or requirements for this building. All equipment appears to be operating properly.

Priority 2 – 5 Year Requirements:

- A new gas fired water heater along with a thermostatic mixing valve that will supply 120 degree F. hot water to the building.
» **\$15,000.00**
- A new natural gas service will be installed to the building to provide fuel for heating and domestic hot water. Natural gas will also be provided to a generator if one is provided as part of the design.
» **\$5,000.00**

Priority 3 – 10 Year Requirements:

- The domestic water heater installed under Priority 2 will be utilized.
- The gas service installed under Priority 2 will be utilized.
- A new domestic 140 degree F. hot water and hot water recirculating piping system will be included to supply the kitchen needs.
» **\$5,000.00**
- All plumbing fixtures will be replaced with new water conserving type fixtures capable of saving approximately 30% of overall water usage of the building.
» **\$40,000.00**

Priority 4 – Full Renovation of Systems:

- All plumbing fixtures will be replaced with new water conserving type fixtures capable of saving approximately 30% of overall water usage of the building.
- A new domestic water service will be provided, sized based on the building demand. A new gas fired water heater along with a thermostatic mixing valve that will supply 120 degree F. hot water to the building as well as 140 degree F hot water to the Kitchen.
- A new domestic cold, hot and hot water recirculating piping system will be included as part of the new domestic water systems.
- The existing drainage systems will be modified and reused as possible to accommodate the modifications to the existing building and any additions.
- A new natural gas service will be installed to the building to provide fuel for heating, domestic hot water and cooking. Natural gas will also be provided to a generator if one is provided as part of the design.

- Kitchen design will be based on the equipment provided by the kitchen equipment consultant including domestic hot and cold water, gas for cooking and drainage of all equipment. A dedicated kitchen waste system will be installed to convey all kitchen waste to an exterior grease trap prior to being discharged into the site sewer system.
- A new fire protection sprinkler system will be installed to provide 100% coverage of the entire existing building as well as all additions. This will include a new fire service to the building and distribution system with quick response sprinklers and fire department valves where required.

DRAFT

**Lexington Elem. Schools
Master Plan Study**

Hastings Elementary School

Executive Summary – Electrical

- The existing electrical systems in general, although functioning, are at the end or have exceeded their useful life. Even with regular maintenance systems do deteriorate over the years. The life safety systems, due to code changes over the years, are not in compliance with current codes.
- The facility has two (2) electrical services, one for the main building and a second service for the portables.
- The primary service runs underground into a transformer vault with exterior grate access. The vault transformer is a 225kva. The access into the vault below grade has experienced water seepage. The switchboard rated at 800 amperes, 120/208V, 3Ø, 4W has a fusible main with fusible branch devices. The switchboard was manufactured by Frank Adam and appears to be of the original vintage. The installation does not meet current code which required two entrances into the electric room with panic door hardware. Remote panels in general have no spare capacity for additional devices. Equipment condition is poor.
- Classroom lighting consists of two (2) rows, except Kindergarten end classrooms which have three (3) rows of suspended direct/indirect fixtures with parabolic baffles with two (2) T8 lamps and magnetic ballasts. Fixtures are suspended with 12" threaded rods on lower level. Corridor lights are 2 x 4 recessed acrylic troffers with two (2) T8 lamps and electronic ballasts. Corridors are locally switched. Cafeteria and kitchen have 1 x 4 surface wraparounds with two (2) T8 lamps and electronic ballasts. Kitchen hood has vaportight globes some without lens.
- Gymnasium has 1 x 4 fluorescent high bays with four (4) T5HO lamps with lens & wireguard. Stage has no theatrical lighting. There are no occupancy sensors in the facility.
- Exterior lighting consists of building mounted metal halide floods. There is no pole mounted parking lot fixtures.
- Emergency lighting system consists of an exterior generator diesel fired with an integral base mounted tank. The manufacturer is Onan/Cummings. The unit was locked but appears to be in good condition, installed approximately 15 years ago. One 225A, 3 pole automatic transfer switch exists in a separate emergency room. Switch and panel does not meet code for required working clearance. Current code requires electrical separation of emergency and non-emergency loads requiring two (2) transfer switches. Lower level corridor has battery units, lights are not on generator. Inadequate coverage of exit signs.

- Classrooms typically have four to six receptacles. Wiremold exists in classrooms.
- The fire alarm system consists of an Edwards EST Model LSS1 conventional (non-addressable) with 8 zones. System is approximately 15 years old. Transmission to fire department is via a radio master box #4221. Existing pedestal master box has been abandoned in place. Most horn/strobes are ADA type except height exceeds ADA guidelines. Some strobes are wall mounted tight to ceiling where minimum 6" below ceiling is required. Corridors and classrooms have smokes. No horn/strobes in classrooms. Toilets have strobes. Strobes are not synchronized.
- Building has a master clock system. Classrooms have a wall clock/speaker with a wall phone. The administration area has a phone for paging/intercom. The intercom was manufactured by Dukane Macs.
- Classrooms have a Category 5 computer network. Classrooms have 3 data drops and 1 CATV drop. Fiber optic service exists in server room.
- Security system is a Magnum Alert 1000 Series control panel connected to a remote central station. Exterior doors not alarmed except kitchen. Corridors and cafeteria have infrared sensors. Remote keypad exists at loading dock entrance.
- Stage has a local sound system.
- No door entry system with door release.
- No card access or closed circuit TV systems.
- No lightning protection system.
- Portable building \pm 12 years old is in good condition. Portables have a second 200 ampere, 120/208V, 3Ø, 4W electrical service. Building is interconnected with main building for fire alarm system. Smokes and horn/strobes exist in corridors and classrooms. Self contained emergency battery units and exit signs exist.

Proposed System Priorities:

Priority 1: Immediate Needs

- Receptacles in kitchen not GFI.
» ***\$1,500.00***
- Add pull station and exit sign at lower level stairwell exterior door.
» ***\$1,500.00***

- Add pull stations at lower level classroom exterior doors, 1960 addition.
» **\$5,000.00**
- Add horn/strobe in library.
» **\$1,000.00**
- Add globes to kitchen hood fixtures.
» **\$500.00**
- Add exit signs at all exterior doors.
» **\$5,000.00**

Priority 2: 1 – 5 Year Expected Life:

- The existing fire alarm control panel, Edwards EST LSS1, early 1990's vintage, has reached the end of its life. Although some replacement parts are still available, other parts are not. Replacement detectors compatible with this panel are still available. Should the panel fail and the replacement part not be available it would force the school to be under a fire watch. We recommend replacing the existing control panel with a current EST addressable panel on a one for one swap. This will allow existing wiring to remain and allow new addressable devices to be added. In light of the building not being sprinklered it is recommended that additional smoke and heat detectors be provided for full coverage of the facility. Strobes should be synchronized to meet ADA.
» **\$1.00/s.f. = \$67,540.00**
- The normal/emergency lighting system should be tested by simulating a power failure and confirming that adequate emergency lighting exists in egress ways and other large spaces where required. Additional emergency lighting should be added where required including on the exterior at exit discharge doors.
» **\$.25/s.f. = \$16,885.00**
- Provide full coverage of exit signs where required for safe egress out of the facility.
» **\$.10/s.f. = \$6,754.00**

Priority 3: 5 – 10 Year Expected Life:

- Provide occupancy sensors to turn lights off in classroom, toilets, offices, gym, etc. to save energy when spaces are unoccupied. Utility Co. rebates may be available for energy conservation measures.
» **60 @ \$200/unit = \$12,000.00**

Priority 4 – Full Renovation of Systems (Gut Rehab)

- » **\$25.00/s.f. = \$1,688,500.00**
- New construction service ratings are designed for a demand load of 10 watts/s.f. The service capacity will be sized for 1200 amperes at 277/480 volt, 3Ø, 4wire. New lighting and power panels will be provided to accommodate respective loads and located in electric rooms. A system of computer grade panelboards with double neutrals and

integral surge suppressors fed from k-rated transformers will be utilized to mitigate the harmonic effects caused by computers and other electronics.

- Classroom lighting fixtures will consist of pendant mounted indirect fluorescent luminaries with T5HO lamps and electronic ballasts. The fixtures will be pre-wired for automatic dimming control where natural daylight is available and also for multi-level switching.
- Office lighting fixtures will consist of acrylic recessed direct fixtures with (2) T5 lamps and electronic ballasts. Two step ballasts will be provided for dual-level switching. Fully dimmable ballasts will be provided where natural daylight is available. Lighting levels will be approximately 30-50 foot candles in classrooms and offices.
- Gymnasium lighting will be comprised of direct fluorescent fixtures with T5HO lamps and electronic ballasts. The fixtures will be provided with protective wire guards. The light level will be designed for approximately 30 foot candles. Occupancy sensors will be provided to turn lights off when unoccupied. Theatrical lights with a dimming system will be provided for performances.
- Corridor lighting will be comprised of recessed acrylic fixtures with (2) T5 lamps & 2 step dimming electronic ballasts for dual level switching. The corridor light level will be designed for approximately 20-foot candles.
- Cafeteria lighting will be pendant indirect fluorescent fixtures with Biax lamps & electronic ballasts. The light levels will be designed for approximately 30 foot candles with dual level switching.
- Kitchen and server lighting will consist of recessed 2'x4' acrylic lensed troffers with aluminum frame doors with T5 lamps and electronic ballasts. Light levels will be approximately 50-75 foot candles.
- Each area will be locally switched and designed for multi-level controls. Each classroom, office space and toilet rooms will have an occupancy sensor to turn lights off when unoccupied. Daylight sensors will be installed in each classroom and perimeter spaces for automatic dimming of light fixtures.
- The entire school will be controlled with an automatic lighting control system using the lighting panelboards with programmable breakers for programming lights on & off.
- Exterior site lighting fixtures for area lighting will be pole mounted long life, energy efficient LED luminaries in the parking area and roadways. Building perimeter fixtures will be wall mounted compact fluorescent over exterior doors. The exterior lighting will be connected to the automatic lighting control system for photocell on and timed off operation.

- An exterior natural gas emergency generator with a sound attenuated aluminum enclosure will be provided. Light fixtures and LED exit signs will be installed to serve all egress areas such as corridors, intervening spaces, toilets, stairwells and exit discharge exterior doors. The administration area lighting will be connected to the emergency generator. The generator will be sized to include life safety systems, boilers and circulating pumps, communications systems, kitchen refrigeration, elevator, etc.
- Each classroom will have a minimum of (2) duplex receptacles per teaching wall and (2) double duplex receptacles on dedicated circuits at classroom computer workstations. The teacher's workstation will have a double duplex receptacle also on a dedicated circuit.
- Office areas will generally have (1) duplex outlet per wall. At each workstation a double duplex receptacle will be provided.
- Corridors will have a cleaning receptacle at approximately 30-40 foot intervals.
- Exterior weatherproof GFI receptacles will be installed at exterior doors.
- A fire alarm and detection system in compliance with ADA will be provided with battery back-up. The system will be of the addressable type where each device will be identified at the control panel and remote annunciator by device type and location to facilitate search for origin of alarms. Smoke detectors will be provided in open areas, corridors, and other egress ways. The sprinkler system will be supervised for water flow and tampering with valves. Speaker/strobes will be provided in egress ways, classrooms, assembly spaces, open areas and other large spaces. Strobe only units will be provided in single toilets and conference rooms.
- Manual pull stations will be provided at exit discharge doors.
- The system will be remotely connected to automatically report alarms to fire department via the radio master box.
- A three phase centralized uninterruptible power supply (UPS) system will be provided with battery back up. The system will provide conditioned power to sensitive electronic loads, telecommunication systems, bridge over power interruptions of short duration and allow an orderly shutdown of servers, communication systems, etc. during a prolonged power outage. The UPS system will also be connected to the stand-by generator.
- A system of lightning protection will be provided. The system will be installed in compliance with the provisions of the latest "Code for Protection Against Lightning" for buildings as adopted by the National Fire Protection Association and the Underwriters' Laboratories, Inc. for a UL Master Label System.
- The lightning protection equipment will include air terminals, conductors, conduits, fasteners, connectors, ground rods, etc.

- A Closed Circuit TV system will consist of computer servers with image software, computer monitors and IP based closed circuit TV cameras. The head end server will be located in the head end MDF room and will be rack mounted. The system can be accessed from any PC within the facility or externally via an IP address. Each camera can be viewed independently. The network video recorders NVR's will record all cameras and store this information for 21 days at 15 images per second (virtual real time). The location of the cameras is generally in corridors and exterior building perimeter. The exterior cameras are pan-tilt-zoom type.
The system will fully integrate with the access control system to allow viewing of events from a single alarm viewer. Camera images and recorded video will be linked to the access system to allow retrieval of video that is associated with an event.
- An intrusion system will consist of security panel, keypads, motion detectors and door contacts. The system is addressable which means that each device will be identified when an alarm occurs. The system is designed so that each perimeter classroom with grade access will have dual tech sensors along the exterior wall and corridors, door contacts at each exterior door.
The system can be partitioned into several zones. Therefore, it is possible to use the Gym area while the remainder of the school remains alarmed.
The system will include a digital transmitter to summons the local police department in the event of an alarm condition
The intrusion system will be connected to the automated lighting control system to automatically turn on lighting upon an alarm.
- A card access system includes a card access controller, door controllers and proximity readers/keypads. Proximity readers will be located at various locations. Each proximity reader will have a distinctive code to identify the user and a log will be kept in memory. The log within the panel can be accessed through a computer.
The alarm condition will also initiate real time recording on the integrated CCTV System. The system may be programmed with graphic maps allowing the end-user to quickly identify alarm conditions and lock/unlock doors.
The system is modular and may be easily expanded to accommodate any additional devices.
- A renewable energy system will consist of a grid connected photovoltaic PV system intended to reduce the facilities demand for power. The photovoltaic system will operate in conformance with the green schools initiative. System will consist of roof mounted photovoltaic modules, weather station, data acquisition system and inverters. Interactive display terminals will be provided for students and for public awareness of the benefits of renewable energy.
- The data system infrastructure will consist of fiber optic backbone cabling. Horizontal wiring will consist of Category 6 UTP Plenum rated cabling for both data and telephone system for gigabit connectivity. The telephone infrastructure will accommodate Centrex, PBX or VOIP based phone systems.

- Each classroom will have 4 data outlets for student computers. Two data, one voice and CATV with video and audio connections to a ceiling projector will be provided at teacher's station with interconnectivity to a smartboard. A wall phone outlet with 2 way ceiling speaker will be provided for communications with administration. Clock will be wireless, part of a GPS/LAN based centralized clock system. Wireless access points with spare fibre will be provided on selected classrooms and other spaces.
- The cafeteria and gymnasium will each have a local sound system with assistive listening devices.
- A central paging system will be provided and integrated with the telephone system.

Hastings Elementary School

Executive Summary - HVAC

The Hastings Elementary School has received below average maintenance of the HVAC systems over its occupied years. Even with adequate maintenance, through normal operation systems do gradually deteriorate due to scale, poor water conditions, and lack of preventive maintenance. Systems will gradually deteriorate to a point of exceeding their maximum serviceable life. This building is a typical example of one such project. While generally speaking, most systems are operating and maintaining reasonable space temperature control, but due to the extreme antiquated nature of the mechanical systems and their gradual scaling of the various piping systems, heat transfer rates have become reduced and the overall system is taxed to a point of inefficiency being created by the slowly depreciating system. While there are no catastrophic failures obvious with the present systems, the systems could continuously be repaired and modified on a sectional basis that will keep the systems operating maintaining acceptable space temperature control however, continued operation will be at the expense of increased operating costs due to inefficiency in heat transfer and through the generally antiquated nature of the systems themselves. The systems installed within this building are approaching their maximum serviceable life. With overall maintenance, cleaning and calibrating of the system, a continued limited service could be achieved however, unpredictable at best. At this time it is not necessary that the systems be modified to prevent a near catastrophic failure, but a continued reuse of the systems will continue to produce unsatisfactory results in terms of overall air quality, temperature control and operating costs.

Existing Conditions:

- The boiler room is provided with two individual Weil McLain cast iron sectional boilers generating low pressure steam. Each boiler is provided with dual low water cut-offs as well as all operating and safety controls and a firematic switch. Each boiler is provided with a single fuel no. 2 fuel oil burner and generates low-pressure steam for distribution. One of the boilers does not have a control panel located on the burner. Considering the age of the boilers it would appear from an external standpoint that they should be replaced since they are reaching the end of their serviceable life.
- The breeching from each boiler appears to be welded black steel and is insulated with what appears to be calcium silicate insulation with a canvas jacket. Each boiler is provided with an individual induced draft fan and barometric damper located at the rear of each boiler which conveys combustion gases from each boiler to a masonry chimney. The induced draft fans are contaminated with soot, corrosion and are reaching the end of their serviceable life.

- No. 2 fuel oil is recirculated from a buried 10,000 gallon double wall underground storage tank. The oil system has a Veeder Root oil monitoring system. Fuel oil is distributed throughout the boiler room through a trench which travels from the oil filters to the boiler burners. It appears that this system is original to the building and is showing signs of leakage and should be replaced.
- Condensate is returned to the boiler room through a schedule 80 black steel condensate return system. Condensate is returned to the boiler room to a return system which is located on the floor of the boiler room. The floor mounted receiver is provided with positive discharge pumps which act as boiler feed pumps to the boilers.
- Low-pressure steam and condensate is distributed through a trench system which travels throughout the building. Steam piping appears to be schedule 40 black steel and condensate appears to be schedule 80 black steel both of which are insulated with what appears to be fiberglass insulation.
- Combustion air is provided through an indoor air handler which has a steam heating coil, supply fan, filters and outside air ductwork associated with it, all of which have reached the end of their serviceable life.
- The automatic temperature control system is of the pneumatic type and is provided with a recently installed single storage tank with duplex compressors and motors. It does appear that these compressors are operating correctly but not maintaining adequate compressed air flow to the entire control system. The system is provided with a refrigerated air dryer as well as an oil and water separators and blow down.
- The kitchen is provided with a single wall stainless steel exhaust hood located over the cooking area. The exhaust hood was noted to have vapor tight incandescent lighting, fire protection, and washable replaceable filters.
- Make-up air for the kitchen and its associated hood is through an air-handling unit located at the ceiling of an adjacent storage room. This air-handling unit is provided with a steam heating coil with valve control, supply fan, and filters. Ventilation air is distributed through a galvanized sheet metal distribution system. Side wall diffusers provide supply air to the entire kitchen area and generally are exhausted 100% through the associated exhaust hood.
- The cafeteria area is provided with one individual air handling unit located high at the ceiling within the boiler room. Galvanized sheet metal ductwork travels through the wall and discharges to multiple side wall diffusers. The air handling unit is provided with a source of outside air to a wall louver and the outside air duct is insulated but the supply and return are not. Each air handling unit is provided with a low pressure steam heating coil, supply fan, and filters. Return ductwork is associated with a return grille located low on the wall. Considering the age of the system an upgrade should be considered.

- The cafeteria area is also provided with individual wall mounted convectors for space heating. Also located within the cafe was a length of fintube radiation located along the exterior wall. This fintube radiation as well as the convector is of the low pressure steam design and it was noted to be damaged and dirty and in need of upgrading.
- The gymnasium is provided with one individual air handling unit located high at the ceiling within the boiler room. Galvanized sheet metal ductwork travels through the wall and into the stage area where it discharges to a single side wall diffuser the length of the entire stage. The air handling unit is provided with a source of outside air to a wall louver and the outside air duct is insulated but the supply and return are not. Each air handling unit is provided with a low pressure steam heating coil, supply fan, and filters. Return ductwork is associated with a single return grille located under the stage. Considering the age of the system an upgrade should be considered.
- Also located within the gymnasium was a length of fintube radiation located along the exterior wall within casework. This fintube radiation is of the low pressure steam design and it was noted to be damaged and dirty and in need of upgrading.
- The air handling units and fintube radiation are controlled through individual wall mounted pneumatic thermostats.
- Each classroom is provided with a wall mounted classroom unit ventilator located on the exterior wall of each classroom as well as fintube incased within casework along the entire exterior wall. The unit ventilators and fintube are provided with a low pressure steam heating coil with a modulating automatic control valve controlled through a wall mounted pneumatic thermostat. The unit ventilators are provided with an outside air intake louver as well as filters and supply fan. In each case the units were extremely antiquated many of which were slightly damaged on the surface and noisy.
- These classrooms were also provided with individual exhaust registers integrated into the cabinetry. These exhaust grills communicate through a galvanized sheet metal exhaust system which are ventilated through a utility type exhaust fan located above the corridor ceiling. All exhaust systems are extremely antiquated and considering their age should be replaced at this time.
- Also located in the classrooms were window air condition units for summer use. These units were dirty and in need of replacement.
- An addition was done to the school where additional kindergarten classrooms were installed. This addition was originally fed by the steam heating plant through underground direct buried steam pipe. Over time there was a pipe burst therefore, a secondary boiler room was added to this addition near the stairwell.

- Located in the boiler room is a gas fired Weil McLain cast iron hot water atmospheric boiler with mechanical combustion air through the use of a combustion air fan. The hot water is sent to a main header where four different zones are fed. Each zone is provided with a circulator to distribute the hot water to wall mounted classroom unit ventilators located on the exterior wall of each classroom as well as fin tube along the entire exterior wall. The unit ventilators and fin tube are provided with hot water heating coil with a modulating control valve controlled through a wall mounted thermostat. The unit ventilators are provided with an outside air intake louver as well as filters and supply fan. In each case the units were extremely antiquated many of which were slightly damaged on the surface.
- The corridors located within the building were all provided with wall mounted convectors for generalized space heating. The individual convectors were controlled through individual pneumatic wall mounted thermostats.
- It was noted that there was exhaust ventilation located throughout the corridor areas however, no supply ventilation was provided. This condition is non-code compliant and should be upgraded.
- Located above the corridor ceilings is an attic space which is utilized for mechanical space to allow exhaust ductwork to travel to and from classrooms and corridors. There are two different systems associated with the corridors and classrooms. The classrooms are handled through the use of a centrifugal exhaust fan and the corridors utilize a typical roof mounted mushroom fan. Also located within this attic space is a row of bare fin tube element utilized to heat the space and an exhaust system to keep the space from overheating however, the controllability of the exhaust fan has been through a reverse acting thermostat which is not operating at this time.
- The teachers work room is provided with two wall mounted classroom unit ventilators located on the exterior wall. The unit ventilators are provided with a low pressure steam heating coil with a modulating automatic control valve. The unit ventilators are provided with an outside air intake louver as well as filters, supply fan. In each case the units were extremely antiquated many of which were slightly damaged on the surface and noisy.
- This space was not provided with exhaust register which is non code compliant. The unit ventilators are controlled through a wall mounted pneumatic thermostat.
- The media center is provided with fin tube radiation located at the exterior wall within casework. Each heating element is of the low pressure steam design and is controlled through individual wall mounted pneumatic thermostats. Code required ventilation air is through the use of operable windows. There is no sign of exhaust for this area which is not code compliant and should be upgraded. Considering the overall age and condition consideration should be given to an upgrade.
- Also located in the media center were window air condition units for summer use. These units were dirty and in need of replacement.

- The administration area is heated through varying lengths of fintube radiation located in all occupied areas. Each heating element is of the low pressure steam design and is controlled through individual wall mounted pneumatic thermostats. Code required ventilation air is through the use of operable windows. There is no exhaust for this area which is not code compliant and should be upgraded. Considering the overall age and condition consideration should be given to an upgrade.
- The portable classroom building is provided with individual classrooms each controlled through an individual rooftop unit. Each roof top unit is provided with electric heat and electric cooling and distributes heated, ventilation, and air conditioned air through an overhead galvanized sheet metal duct distribution system. Considering the source of electric heat consideration should be given to upgrading. There is an offensive odor present in the portable classrooms which could relate to excessive vapor pressure resulting in mold formation. Further investigation should be considered to determine the contributing conditions.
- Also located within the portable classrooms were ceiling mounted exhaust registers and a fan which is controlled through a wall mounted switch. It does appear that minimum ventilation is not being provided through this air handling unit and consideration should be given to upgrading the control system.
- The building gang toilets were provided with wall mounted exhaust registers which were extremely antiquated and dirty. These exhaust registers communicate to a centrally located exhaust fan.
- Make-up air for the individual toilets was through the use of louvers located within the doors.
- Heating of the toilet spaces were through the use of wall mounted fintube radiation which was controlled through the use of a pneumatic thermostat. It was noted that this radiation was slightly damaged with surface contamination.

Proposed System Priorities

Priority 1 – Immediate Needs and Requirements

- Boiler #2 burner control panel needs to be replaced.
» **\$2,500.00**
- Teachers work room/General classroom has no exhaust system.
» **\$3,500.00**
- Room #10's unit ventilator steam valve was not operating.
» **\$600.00**

- The computer room has no exhaust or ventilation air also the wall mounted cooling unit is not operating correctly and has a tendency to allow the room to over heat.
» **\$8,500.00**
- The library thermostat is located within the corridor next to the main entrance rather than within the space.
» **\$1,000.00**
- Code required ventilation air not provided in corridors
» **\$24,000.00**
- Calibration of the pneumatic temperature controls
» **\$33,500.00**
- Installing CO2 demand ventilation control in classroom unit ventilators.
» **\$24,000.00**
- Verify shaft trueness on all unit ventilators, exhaust fans and air handling units and replace if necessary.
» **\$17,000.00**
- Verify conditions of shaft bearings on all unit ventilators, exhaust fans and air handling units and replace if necessary.
» **\$17,000.00**
- Clean fan wheels, coils, dampers, and outside air louvers on all unit ventilators, exhaust fans and air handling units.
» **\$17,000.00**

Priority 2 – Five Year Needs

- In approximately five years the heating plant will be at the end of its serviceable life therefore, within that time frame we recommend the installation of (2) new gas fired steam boilers with modulating gas for energy savings.
» **\$250,000.00**
- All air handling units and classroom unit ventilators would remain as is and be reused to accommodate desired room temperatures.

Priority 3 – Ten Year Needs

- The recently installed heating plant will be reused and converted from steam to hot water while reusing the modulating gas burners and adding boiler water reset for additional energy savings.
» **\$3,500.00**

- All unit ventilators will be replaced with hot water unit ventilators reusing CO2 demand ventilation controls.
» ***\$180,000.00***
- All steam piping will be removed and a new schedule 40 black steel hot water system will be installed.
» ***\$268,000.00***
- Provide a direct digital control system with internet access and colored graphics.
» ***\$335,000.00***
- Replace all air handling units serving the gym, computer classroom, administration area, music/lecture area and kitchen.
» ***\$100,000.00***
- Replace all exhaust fans and internally clean exhaust ductwork.
» ***\$70,000.00***

Priority 4 – Full Renovation of Systems

Regarding the HVAC systems, the projection will be limited to repairing the necessary systems incorporated in the ten year needs.

Hasting Elementary School

Executive Summary - Plumbing/Fire Protection

The Hasting Elementary School has received minimal maintenance on the plumbing systems and equipment over its occupied years. Even with adequate maintenance, systems will gradually deteriorate due to scale and poor water conditions. Although most of the systems are working adequately at this time, the major equipment and systems are near the end of their useful life. Along with aging systems, many of the systems are not up to current codes.

Fixtures:

- Fixtures are generally original indicating the time of their original installation. Some attempts have been made to try and provide accessible toilet rooms.
- The water closets are generally wall hung vitreous china, flush valve type with siphon jet action. The flush valves do not appear meet water conservation requirements.
- The urinals are wall hung vitreous china, flush valve type with blow out action. The flush valves do not appear to meet water conservation requirements.
- The lavatories are wall hung vitreous china. The faucets are hot and cold water type and do not meet the water conservation requirements. The piping is standard p-trap and is not insulated to meet the accessibility codes.
- The classroom sinks are single bowl, stainless steel sinks with single lever faucets and drinking fountains as part of the sink. The sinks and faucets are in fair condition but do not appear to meet accessibility requirements.
- The drinking fountains are generally wall hung stainless with single lever controls. Fixtures appear to be in fair condition. The fixture and controls do not meet accessibility codes.

Water System:

- The domestic water service enters the building in the Boiler Room. The service entering the building is 2½ in. and is complete with a water meter as well as a pressure reducing valve with by-pass. The pressure reducing valve pressure is set to reduce the incoming 100 psi down to the set pressure 60 psi. There is no backflow preventer on the municipal water supply. The water service may be undersized for the building water requirements.
- The domestic hot water is supplied from a tank type gas fired water heater. The water heater was installed in 1995 and is in good condition.

- There is no master thermostatic mixing valve on the domestic hot water system prior to being distributed to the building hot water system. There is no separate 140 degree F. hot water supplied to the Kitchen.

Drainage System:

- The sanitary and storm drainage systems are piped with cast iron. The exposed piping is visibly in good condition.
- The sanitary drainage system is piped to a municipal sewer system.
- The roof is generally flat and is drained by roof drains and a roof drainage system, which exits the building and connects to a municipal storm drainage system.
- There is a duplex sewage ejector in the building which lifts the sewage from the building up to the municipal sewer system located in School Street. There is a very strong sewer smell in the room that the ejector is located in.

Natural Gas System:

- A small natural gas service is supplied to the building. The service was installed to provide fuel for the domestic water heater.

Kitchen:

- The kitchen equipment is all generally original and indicates the vintage of the time of installation.
- The cooking equipment is all electric and in fair condition. The kitchen appears to be a warming kitchen with no cooking or grease producing equipment.
- There is a grease 3-pot sink in the kitchen. There is no grease trap associated with this fixture. All other fixtures appear to go to the sanitary drainage system. There is no dedicated kitchen waste system or an exterior grease trap.

Fire Protection:

- There is no Fire Protection Sprinkler System installed in this school.

Proposed System Priorities

Priority 1 – Immediate Needs and Requirements:

- Repair seals and venting of the sewage ejector to eliminate the sewer smell in the building.
 - » **\$2,500.00**

Priority 2 – 5 Year Requirements:

- A new gas fired water heater along with a thermostatic mixing valve that will supply 120 degree F. hot water to the building.
» **\$15,000.00**
- A new natural gas service will be installed to the building to provide fuel for heating and domestic hot water. Natural gas will also be provided to a generator if one is provided as part of the design.
» **\$5,000.00**

Priority 3 – 10 Year Requirements:

- The domestic water heater installed under Priority 2 will be utilized.
- The gas service installed under Priority 2 will be utilized.
- A new domestic 140 degree F. hot water and hot water recirculating piping system will be included to supply the kitchen needs.
» **\$5,000.00**
- All plumbing fixtures will be replaced with new water conserving type fixtures capable of saving approximately 30% of overall water usage of the building.
» **\$40,000.00**

Priority 4 – 25 Year Term:

- All plumbing fixtures will be replaced with new water conserving type fixtures capable of saving approximately 30% of overall water usage of the building.
- The existing domestic water service appears to be insufficient for the existing building as well as any additions that may be incorporated into the design. A new domestic water service will be provided, sized based on the building demand. A new gas fired water heater along with a thermostatic mixing valve that will supply 120 degree F. hot water to the building as well as 140 degree F hot water to the Kitchen.
- A new domestic cold, hot and hot water recirculating piping system will be included as part of the new domestic water systems.
- The existing drainage systems will be modified and reused as possible to accommodate the modifications to the existing building and any additions.
- A new natural gas service will be installed to the building to provide fuel for heating, domestic hot water and cooking. Natural gas will also be provided to a generator if one is provided as part of the design.

- Kitchen design will be based on the equipment provided by the kitchen equipment consultant including domestic hot and cold water, gas for cooking and drainage of all equipment. A dedicated kitchen waste system will be installed to convey all kitchen waste to an exterior grease trap prior to being discharged into the site sewer system.
- A new fire protection sprinkler system will be installed to provide 100% coverage of the entire existing building as well as all additions. This will include a new fire service to the building and distribution system with quick response sprinklers and fire department valves where required.

DRAFT

Elementary Schools - M/E/P/FP Report

**BOWMAN ELEMENTARY SCHOOL RENOVATION
STUDY ESTIMATE - 11-22-08
LEXINGTON, MA**

Project name **Bowman E.S.**
Lexington
MA

Architect **TDPC**

Estimator *Essential Estimating*

| Location | Labor Amount | Material Amount | Equip Amount | Total Amount |
|-----------------|--------------|-----------------|--------------|--------------|
| 1 LIFE SAFETY | 1,060 | 3,626 | | 4,686 |
| 2 BUILDING CODE | 20,346 | 12,576 | 45 | 32,967 |
| 3 EXTERIOR | 160,456 | 268,572 | 5,204 | 434,232 |
| 5 HC ACCESS | 215,110 | 278,220 | 6,338 | 499,667 |
| 6 FINISHES GEN | 290,493 | 206,220 | 16,698 | 513,412 |

Estimate Totals

| | | | |
|--------------|------------------|------------------|-----|
| Labor | 687,465 | 7,273.709 | hrs |
| Material | 769,214 | | |
| Equipment | 28,284 | 1,297.452 | hrs |
| | 1,484,963 | 1,484,963 | |
| Total | 1,484,963 | | |

| Location | Bid Item | Description | Labor Amount | Material Amount | Equip Amount | Total Amount |
|------------------------|------------|------------------------|----------------|-----------------|---------------|----------------|
| 1 LIFE SAFETY | | | | | | |
| | <u>1A</u> | | <u>247</u> | <u>16</u> | | <u>262</u> |
| | <u>1D</u> | | <u>814</u> | <u>3,610</u> | | <u>4,424</u> |
| | | 1 LIFE SAFETY | 1,060 | 3,626 | | 4,686 |
| 2 BUILDING CODE | | | | | | |
| | <u>2G</u> | | <u>19,986</u> | <u>12,576</u> | <u>32</u> | <u>32,594</u> |
| | <u>2H</u> | | <u>360</u> | | <u>12</u> | <u>373</u> |
| | | 2 BUILDING CODE | 20,346 | 12,576 | 45 | 32,967 |
| 3 EXTERIOR | | | | | | |
| | <u>3A</u> | | <u>131,430</u> | <u>250,330</u> | <u>279</u> | <u>382,039</u> |
| | <u>3B</u> | | <u>8,049</u> | <u>14,782</u> | <u>279</u> | <u>23,109</u> |
| | <u>3C</u> | | <u>874</u> | <u>3,461</u> | | <u>4,334</u> |
| | <u>3E</u> | | <u>20,104</u> | | <u>4,646</u> | <u>24,750</u> |
| | | 3 EXTERIOR | 160,456 | 268,572 | 5,204 | 434,232 |
| 5 HC ACCESS | | | | | | |
| | <u>5A</u> | | <u>13,491</u> | <u>6,139</u> | <u>639</u> | <u>20,269</u> |
| | <u>5B</u> | | <u>20,327</u> | <u>35,903</u> | <u>256</u> | <u>56,486</u> |
| | <u>5C</u> | | <u>1,866</u> | <u>5,297</u> | <u>24</u> | <u>7,187</u> |
| | <u>5D</u> | | <u>168</u> | | <u>1</u> | <u>169</u> |
| | <u>5E</u> | | <u>843</u> | | | <u>843</u> |
| | <u>5F</u> | | <u>696</u> | <u>888</u> | <u>27</u> | <u>1,611</u> |
| | <u>5G</u> | | <u>1,927</u> | <u>6,010</u> | <u>7</u> | <u>7,944</u> |
| | <u>5H</u> | | <u>124,119</u> | <u>76,692</u> | <u>3,234</u> | <u>204,044</u> |
| | <u>5K</u> | | <u>17,681</u> | <u>10,604</u> | <u>1,746</u> | <u>30,030</u> |
| | <u>5L</u> | | <u>3,566</u> | <u>15,347</u> | <u>271</u> | <u>19,184</u> |
| | <u>5N</u> | | <u>2,003</u> | <u>1,532</u> | <u>72</u> | <u>3,608</u> |
| | <u>5P</u> | | <u>543</u> | <u>2,407</u> | | <u>2,949</u> |
| | <u>5Q</u> | | <u>962</u> | | <u>27</u> | <u>989</u> |
| | <u>5T</u> | | <u>26,918</u> | <u>117,402</u> | <u>35</u> | <u>144,354</u> |
| | | 5 HC ACCESS | 215,110 | 278,220 | 6,338 | 499,667 |
| 6 FINISHES GEN | | | | | | |
| | <u>6A</u> | | <u>1,761</u> | <u>1,225</u> | <u>22</u> | <u>3,008</u> |
| | <u>6B</u> | | <u>28,228</u> | <u>663</u> | <u>5,465</u> | <u>34,356</u> |
| | <u>6C</u> | | <u>2,028</u> | <u>1,830</u> | | <u>3,858</u> |
| | <u>6D</u> | | <u>34,479</u> | <u>584</u> | <u>7,347</u> | <u>42,409</u> |
| | <u>6E</u> | | <u>2,152</u> | <u>1,126</u> | <u>5</u> | <u>3,283</u> |
| | <u>6G</u> | | <u>153</u> | <u>14</u> | | <u>167</u> |
| | <u>6GG</u> | | <u>3,458</u> | <u>479</u> | <u>242</u> | <u>4,179</u> |
| | <u>6KK</u> | | <u>21,201</u> | <u>8,804</u> | | <u>30,006</u> |
| | <u>6L</u> | | <u>776</u> | <u>180</u> | <u>73</u> | <u>1,029</u> |
| | <u>6LL</u> | | <u>196,258</u> | <u>191,317</u> | <u>3,544</u> | <u>391,119</u> |
| | | 6 FINISHES GEN | 290,493 | 206,220 | 16,698 | 513,412 |

Estimate Totals

Estimate Totals

| | | | |
|-----------|------------------|------------------|-----|
| Labor | 687,465 | 7,273.709 | hrs |
| Material | 769,214 | | |
| Equipment | 28,284 | 1,297.452 | hrs |
| | <u>1,484,963</u> | <u>1,484,963</u> | |
| | Total | 1,484,963 | |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|------------------------|-----------|----------|----------|------------------------------------|------------------|---------------|-----------------|-----------------|---------------|
| 1 LIFE SAFETY | | | | | | | | | |
| | 1A | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Door | 1.00 each | 32 | - | 32.11 /each | 32 |
| | | | | Demo: Doors & Windows | | 32 | | /each | 32 |
| | | | | DEMOLITION | | 32 | | /sqft | 32 |
| | | 8000.00 | | DOORS & WINDOWS | | | | | |
| | | | 8210.01 | Doors: Wood | | | | | |
| | | | | Rehang Door | 1.00 each | 130 | | 130.26 /each | 130 |
| | | | | Doors: Wood | | 130 | | /each | 130 |
| | | | | DOORS & WINDOWS | | 130 | | /sqft | 130 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Wd Door & Metal Frame & Prep | 1.00 each | 84 | 16 | 99.98 /each | 100 |
| | | | | Painting: Interior | | 84 | 16 | /sqft | 100 |
| | | | | FINISHES | | 84 | 16 | /sqft | 100 |
| | | | | 1A | | 247 | 16 | | 262 |
| | 1D | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Hardware | 3.00 each | 136 | - | 45.21 /each | 136 |
| | | | | Demo: Doors & Windows | | 136 | | /each | 136 |
| | | | | DEMOLITION | | 136 | | /sqft | 136 |
| | | 8000.00 | | DOORS & WINDOWS | | | | | |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Ext Budget | 3.00 each | 678 | 3,610 | 1,429.33 /each | 4,288 |
| | | | | Hardware: Finishing | | 678 | 3,610 | /set | 4,288 |
| | | | | DOORS & WINDOWS | | 678 | 3,610 | /sqft | 4,288 |
| | | | | 1D | | 814 | 3,610 | | 4,424 |
| | | | | 1 LIFE SAFETY | | 1,060 | 3,626 | | 4,686 |
| 2 BUILDING CODE | | | | | | | | | |
| | 2G | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 4.90 cuyd | 101 | - | 27.17 /cuyd | 133 |
| | | | | Demo: General | | 101 | | /cuyd | 133 |
| | | | 2084.50 | Demo: Misc Items | | | | | |
| | | | | Remove Stage Curtain | 528.00 sqft | 593 | - | 1.12 /sqft | 593 |
| | | | | Demo: Misc Items | | 593 | | /sqft | 593 |
| | | | | DEMOLITION | | 694 | | /sqft | 727 |
| | | 11000.00 | | EQUIPMENT | | | | | |
| | | | 11060.01 | Equip: Stage | | | | | |
| | | | | Curtain Track Med Duty | 44.00 lnft | 3,627 | 2,412 | 137.25 /lnft | 6,039 |
| | | | | Curtain Fireproof | 528.00 sqft | 15,665 | 10,164 | 48.92 /sqft | 25,829 |
| | | | | Equip: Stage | | 19,291 | 12,577 | /each | 31,868 |
| | | | | EQUIPMENT | | 19,291 | 12,577 | /sqft | 31,868 |
| | | | | 2G | | 19,986 | 12,577 | | 32,594 |
| | 2H | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 1.90 cuyd | 39 | - | 27.17 /cuyd | 52 |
| | | | | Demo: General | | 39 | | /cuyd | 52 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Door | 10.00 each | 321 | - | 32.11 /each | 321 |
| | | | | Demo: Doors & Windows | | 321 | | /each | 321 |
| | | | | DEMOLITION | | 360 | | /sqft | 373 |
| | | | | 2H | | 360 | | | 373 |
| | | | | 2 BUILDING CODE | | 20,346 | 12,577 | | 32,967 |
| 3 EXTERIOR | | | | | | | | | |
| | 3A | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 42.40 cuyd | 873 | - | 27.17 /cuyd | 1,152 |
| | | | | Demo: General | | 873 | | /cuyd | 1,152 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Metal Windows | 4,580.00 sqft | 14,339 | - | 3.13 /sqft | 14,339 |
| | | | | Demo: Doors & Windows | | 14,339 | | /each | 14,339 |
| | | | | DEMOLITION | | 15,213 | | /sqft | 15,491 |
| | | 4000.00 | | MASONRY | | | | | |
| | | | 4156.00 | Access: Wall Flashing | | | | | |
| | | | | Flash Head Lead Ct. Cop 5 oz. | 756.00 sqft | 3,457 | 3,476 | 9.17 /sqft | 6,933 |
| | | | | Flash Sill Lead Ct. Cop 5 oz. | 756.00 sqft | 3,152 | 3,265 | 8.49 /sqft | 6,417 |
| | | | | Access: Wall Flashing | | 6,609 | 6,741 | /sqft | 13,350 |
| | | | | MASONRY | | 6,609 | 6,741 | /sqft | 13,350 |
| | | 6000.00 | | WOOD & PLASTICS | | | | | |
| | | | 6015.00 | Fasteners: Frame Anchors | | | | | |
| | | | | Fastners & Misc | 1.00 lsum | - | 25 | 25.41 /lsum | 25 |
| | | | | Fasteners: Frame Anchors | | | 25 | /each | 25 |
| | | | 6113.40 | Blocking: Rough Bucks | | | | | |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|--------------------|----------|-------|----------|------------------------------------|------------------|----------------|-----------------|-----------------|----------------|
| | | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | | Rough Bucks 2 x 6 PT Windows | 2,240.00 Inft | 8,515 | 2,530 | 4.93 /Inft | 11,044 |
| | | | | Blocking: Rough Bucks | | 8,515 | 2,530 | /mbf | 11,044 |
| | | | | WOOD & PLASTICS | | 8,515 | 2,555 | /sqft | 11,070 |
| | 7000.00 | | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | | Backer Rod ½" | 2,240.00 Inft | 6,790 | 205 | 3.12 /Inft | 6,995 |
| | | | | Polyurethane Sealant 1/2" | 4,480.00 Inft | 42,679 | 2,228 | 10.02 /Inft | 44,907 |
| | | | | Sealant - Jt Filler Gaskt | | 49,469 | 2,433 | /Inft | 51,902 |
| | | | | THERMAL & MOISTURE PROT | | 49,469 | 2,433 | /sqft | 51,902 |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | | 8520.01 | Window: Aluminum | | | | | |
| | | | | Custom Proj 4" .125 w Ins Gl Kynar | 4,580.00 sqft | 51,625 | 238,600 | 63.37 /sqft | 290,225 |
| | | | | Window: Aluminum | | 51,625 | 238,600 | /sqft | 290,225 |
| | | | | DOORS & WINDOWS | | 51,625 | 238,600 | /sqft | 290,225 |
| | | | | 3A | | 131,430 | 250,330 | | 382,039 |
| 3B | | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 42.40 cuyd | 873 | - | 27.17 /cuyd | 1,152 |
| | | | | Demo: General | | 873 | | /cuyd | 1,152 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Window Treatment | 4,580.00 sqft | 2,206 | - | 0.48 /sqft | 2,206 |
| | | | | Demo: Doors & Windows | | 2,206 | | /each | 2,206 |
| | | | | DEMOLITION | | 3,079 | | /sqft | 3,358 |
| | 12000.00 | | | FURNISHINGS | | | | | |
| | | | 12520.01 | Shades | | | | | |
| | | | | Vinyl Heavy Wt | 4,580.00 sqft | 4,969 | 14,782 | 4.31 /sqft | 19,751 |
| | | | | Shades | | 4,969 | 14,782 | /sqft | 19,751 |
| | | | | FURNISHINGS | | 4,969 | 14,782 | /sqft | 19,751 |
| | | | | 3B | | 8,049 | 14,782 | | 23,109 |
| 3C | | | | | | | | | |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | | 8565.00 | Windows: Screens | | | | | |
| | | | | Window Screens/Wicket (Aluminum) | 464.00 sqft | 874 | 3,461 | 9.34 /sqft | 4,334 |
| | | | | Windows: Screens | | 874 | 3,461 | /each | 4,334 |
| | | | | DOORS & WINDOWS | | 874 | 3,461 | /sqft | 4,334 |
| | | | | 3C | | 874 | 3,461 | | 4,334 |
| 3E | | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2060.00 | Demo: Building | | | | | |
| | | | | Small Building Temp | 21,924.00 cuft | 5,132 | - | 0.36 /cuft | 7,923 |
| | | | | Disposal Building | 182.02 cuyd | 1,591 | - | 11.88 /cuyd | 2,162 |
| | | | | Demo: Building | | 6,722 | | /cuft | 10,085 |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 5.20 cuyd | 107 | - | 27.17 /cuyd | 141 |
| | | | | Demo: General | | 107 | | /cuyd | 141 |
| | | | 2075.00 | Demo: Concrete | | | | | |
| | | | | Remove Conc Walls 8" | 620.00 sqft | 10,348 | - | 18.26 /sqft | 11,321 |
| | | | | Remove Ramp | 280.00 sqft | 2,926 | - | 11.44 /sqft | 3,202 |
| | | | | Demo: Concrete | | 13,274 | | /cuyd | 14,523 |
| | | | | DEMOLITION | | 20,103 | | /sqft | 24,750 |
| | | | | 3E | | 20,103 | | | 24,750 |
| | | | | 3 EXTERIOR | | 160,456 | 268,572 | | 434,232 |
| 5 HC ACCESS | | | | | | | | | |
| 5A | | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 8.30 cuyd | 171 | - | 27.17 /cuyd | 225 |
| | | | | Demo: General | | 171 | | /cuyd | 225 |
| | | | 2076.00 | Demo: Masonry | | | | | |
| | | | | Sawcut 6" CMU | 24.00 Inft | 679 | - | 46.49 /Inft | 1,116 |
| | | | | Tooth Jamb's 1 Wythe | 24.00 Inft | 741 | - | 30.89 /Inft | 741 |
| | | | | Remove CMU 6" | 120.00 sqft | 438 | - | 3.97 /sqft | 476 |
| | | | | Demo: Masonry | | 1,858 | | /cuft | 2,333 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Door | 28.00 each | 899 | - | 32.11 /each | 899 |
| | | | | Remove Door & Frame Ext Double | 1.00 each | 150 | - | 170.04 /each | 170 |
| | | | | Demo: Doors & Windows | | 1,049 | | /each | 1,069 |
| | | | 2088.01 | Demo: Finishes, Floors | | | | | |
| | | | | Flash Patch @ Wall Removal | 10.00 sqft | 23 | 21 | 4.41 /sqft | 44 |
| | | | | Flash Patch @ Wall Removal | 4.00 sqft | 9 | 8 | 4.41 /sqft | 18 |
| | | | | Demo: Finishes, Floors | | 32 | 30 | /sqft | 62 |
| | | | 2088.21 | Demo: Finishes, Walls | | | | | |
| | | | | Remove Stud GWB Partition | 40.00 sqft | 150 | - | 3.75 /sqft | 150 |
| | | | | Demo: Finishes, Walls | | 150 | | /sqft | 150 |
| | | | | DEMOLITION | | 3,260 | 30 | /sqft | 3,839 |
| | 4000.00 | | | MASONRY | | | | | |
| | | | 4050.10 | Misc: Scaffold | | | | | |
| | | | | Interior Scaffold | 96.00 sqft | 107 | 40 | 1.77 /sqft | 170 |
| | | | | Misc: Scaffold | | 107 | 40 | /sqft | 170 |
| | | | 4050.15 | Misc: Material Handling | | | | | |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|-----------|----------|----------|--------------------------------------|------------------|---------------|-----------------|-----------------|---------------|
| | | | 4050.15 | Misc: Material Handling | | | | | |
| | | | | Concrete Block | 0.09 m | - | - | 262.78 /m | 24 |
| | | | | Misc: Material Handling | | | | /m | 24 |
| | | | 4105.00 | Mortar: All Types | | | | | |
| | | | | Mortar Type "N" | 0.17 cuyd | 21 | 37 | 338.00 /cuyd | 57 |
| | | | | Mortar: All Types | | 21 | 37 | /cuyd | 57 |
| | | | 4110.01 | Mortar: Grout Fill Conc | | | | | |
| | | | | Grout Fill 3000 psi, 1/2" Gravl | 0.09 cuyd | 25 | 17 | 495.44 /cuyd | 45 |
| | | | | Grout Double Door Frame | 1.00 each | 85 | 29 | 120.26 /each | 120 |
| | | | | Mortar: Grout Fill Conc | | 111 | 46 | /cuyd | 165 |
| | | | 4157.00 | Reinforce: Vertical Wall | | | | | |
| | | | | Re-Bar #5 & #6 | 20.86 lbs | 42 | 22 | 3.09 /lbs | 64 |
| | | | | Reinforce: Vertical Wall | | 42 | 22 | /lbs | 64 |
| | | | 4158.00 | Reinforce: Horizontl Wall | | | | | |
| | | | | Horiz Wall Reinf 6" Hot Dippd | 0.08 mlf | 36 | 14 | 615.60 /mlf | 49 |
| | | | | Reinforce: Horizontl Wall | | 36 | 14 | /mlf | 49 |
| | | | 4221.20 | Conc. Block: 6" | | | | | |
| | | | | Blk 6" Standard Face Reg Wt | 84.00 each | 1,027 | 189 | 14.47 /each | 1,216 |
| | | | | Conc. Block: 6" | | 1,027 | 189 | /each | 1,216 |
| | | | 4221.50 | Conc. Block: 6" Lintel | | | | | |
| | | | | Lintel 6" Stand Face Reg Wt | 6.00 each | 111 | 39 | 26.60 /each | 160 |
| | | | | Conc. Block: 6" Lintel | | 111 | 39 | /each | 160 |
| | | | | MASONRY | | 1,455 | 387 | /sqft | 1,905 |
| | | 5000.00 | | METALS | | | | | |
| | | | 5510.35 | Misc: Bolt On Material | | | | | |
| | | | | Angle Bolted To Masonry | 29.00 lb | 102 | 87 | 6.74 /lb | 195 |
| | | | | Misc: Bolt On Material | | 102 | 87 | /lbs | 195 |
| | | | | METALS | | 102 | 87 | /sqft | 195 |
| | | 6000.00 | | WOOD & PLASTICS | | | | | |
| | | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | | Rough Bucks 2 x 6 PT Doors | 20.00 lnft | 50 | 23 | 3.63 /lnft | 73 |
| | | | | Blocking: Rough Bucks | | 50 | 23 | /mbf | 73 |
| | | | | WOOD & PLASTICS | | 50 | 23 | /sqft | 73 |
| | | 7000.00 | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | | Backer Rod 1/2" | 20.00 lnft | 61 | 2 | 3.12 /lnft | 62 |
| | | | | Polyurethane Sealant 1/2" | 40.00 lnft | 381 | 20 | 10.02 /lnft | 401 |
| | | | | Sealant - Jt Filler Gaskt | | 442 | 22 | /lnft | 463 |
| | | | | THERMAL & MOISTURE PROT | | 442 | 22 | /sqft | 463 |
| | | 8000.00 | | DOORS & WINDOWS | | | | | |
| | | | 8210.01 | Doors: Wood | | | | | |
| | | | | Rehang Door | 28.00 each | 3,647 | | 130.26 /each | 3,647 |
| | | | | Doors: Wood | | 3,647 | | /each | 3,647 |
| | | | 8410.00 | Aluminum Doors & Frames | | | | | |
| | | | | Alum Frame 6' x 7' Bronze Fin | 1.00 each | 283 | 503 | 785.96 /each | 786 |
| | | | | Alum Door Med 3'-0 x 7'-0 Full Gl | 2.00 each | 513 | 2,104 | 1,308.63 /each | 2,617 |
| | | | | Aluminum Doors & Frames | | 796 | 2,607 | /each | 3,403 |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Ext Budget | 2.00 each | 452 | 2,407 | 1,429.34 /each | 2,859 |
| | | | | Hardware: Finishing | | 452 | 2,407 | /set | 2,859 |
| | | | | DOORS & WINDOWS | | 4,895 | 5,014 | /sqft | 9,909 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9210.01 | Lath/Plastr: Gyp Plaster | | | | | |
| | | | | Plaster Patch @ Wall Removal | 24.00 sqft | 400 | 43 | 18.82 /sqft | 452 |
| | | | | Plaster Patch @ Wall Removal | 20.00 sqft | 333 | 36 | 18.83 /sqft | 377 |
| | | | | Plaster Patch Ceiling @ Wall Removal | 14.00 sqft | 76 | 22 | 7.17 /sqft | 100 |
| | | | | Lath/Plastr: Gyp Plaster | | 809 | 100 | /sqft | 929 |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Wd Door & Metal Frame & Prep | 28.00 each | 2,358 | 441 | 99.97 /each | 2,799 |
| | | | | Paint Int CMU Spray p+2ct | 128.00 sqft | 121 | 36 | 1.22 /sqft | 156 |
| | | | | Painting: Interior | | 2,479 | 477 | /sqft | 2,956 |
| | | | | FINISHES | | 3,287 | 577 | /sqft | 3,884 |
| | | | | 5A | | 13,491 | 6,139 | | 20,269 |
| | 5B | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 38.90 cuyd | 801 | - | 27.17 /cuyd | 1,057 |
| | | | | Demo: General | | 801 | | /cuyd | 1,057 |
| | | | 2080.01 | Demo: Millwork | | | | | |
| | | | | Remove Casework | 146.00 lnft | 762 | - | 5.22 /lnft | 762 |
| | | | | Demo: Millwork | | 762 | | /sqft | 762 |
| | | | 2088.60 | Demo: Plumbing | | | | | |
| | | | | Remove Sink | 29.00 each | 3,562 | - | 122.84 /each | 3,562 |
| | | | | Demo: Plumbing | | 3,562 | | /sqft | 3,562 |
| | | | | DEMOLITION | | 5,125 | | /sqft | 5,381 |
| | | 6000.00 | | WOOD & PLASTICS | | | | | |
| | | | 6113.20 | Blocking: Misc. | | | | | |
| | | | | Blocking 2 x 6 R.L. | 146.00 lnft | 502 | 99 | 4.11 /lnft | 601 |
| | | | | Blocking: Misc. | | 502 | 99 | /mbf | 601 |
| | | | | WOOD & PLASTICS | | 502 | 99 | /sqft | 601 |
| | | 12000.00 | | FURNISHINGS | | | | | |
| | | | 12350.00 | Casework | | | | | |
| | | | | School Casework Base & Top | 146.00 lnft | 14,700 | 35,804 | 345.92 /lnft | 50,504 |
| | | | | Casework | | 14,700 | 35,804 | /lnft | 50,504 |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|----------|----------|-----------------------------------|------------------|---------------|-----------------|-----------------|---------------|
| | | | | FURNISHINGS | | 14,700 | 35,804 | /sqft | 50,504 |
| | | | | 5B | | 20,327 | 35,903 | | 56,486 |
| | 5C | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 3.60 cuyd | 74 | - | 27.17 /cuyd | 98 |
| | | | | Demo: General | | 74 | | /cuyd | 98 |
| | | | 2080.01 | Demo: Millwork | | | | | |
| | | | | Remove Casework | 16.00 Inft | 83 | - | 5.22 /Inft | 83 |
| | | | | Demo: Millwork | | 83 | | /sqft | 83 |
| | | | | DEMOLITION | | 158 | | /sqft | 181 |
| | | 6000.00 | | WOOD & PLASTICS | | | | | |
| | | | 6113.20 | Blocking: Misc. | | | | | |
| | | | | Blocking 2 x 6 R.L. | 16.00 Inft | 55 | 11 | 4.11 /Inft | 66 |
| | | | | Blocking: Misc. | | 55 | 11 | /mbf | 66 |
| | | | | WOOD & PLASTICS | | 55 | 11 | /sqft | 66 |
| | | 12000.00 | | FURNISHINGS | | | | | |
| | | | 12620.00 | Furniture | | | | | |
| | | | | Library Charge Desk | 16.00 Inft | 1,654 | 5,286 | 433.71 /Inft | 6,939 |
| | | | | Furniture | | 1,654 | 5,286 | /Inft | 6,939 |
| | | | | FURNISHINGS | | 1,654 | 5,286 | /sqft | 6,939 |
| | | | | 5C | | 1,866 | 5,297 | | 7,187 |
| | 5D | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 0.20 cuyd | 4 | - | 27.20 /cuyd | 5 |
| | | | | Demo: General | | 4 | | /cuyd | 5 |
| | | | 2088.60 | Demo: Plumbing | | | | | |
| | | | | Remove Drinking Fountain | 1.00 each | 164 | - | 163.75 /each | 164 |
| | | | | Demo: Plumbing | | 164 | | /sqft | 164 |
| | | | | DEMOLITION | | 168 | | /sqft | 169 |
| | | | | 5D | | 168 | | | 169 |
| | 5E | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2084.50 | Demo: Misc Items | | | | | |
| | | | | Remove TV | 14.00 each | 843 | - | 60.21 /each | 843 |
| | | | | Demo: Misc Items | | 843 | | /sqft | 843 |
| | | | | DEMOLITION | | 843 | | /sqft | 843 |
| | | | | 5E | | 843 | | | 843 |
| | 5F | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 0.10 cuyd | 2 | - | 27.20 /cuyd | 3 |
| | | | | Demo: General | | 2 | | /cuyd | 3 |
| | | | 2077.00 | Demo: Steel | | | | | |
| | | | | Remove Steel Rail | 9.00 Inft | 90 | - | 10.04 /Inft | 90 |
| | | | | Demo: Steel | | 90 | | /each | 90 |
| | | | | DEMOLITION | | 92 | | /sqft | 93 |
| | | 5000.00 | | METALS | | | | | |
| | | | 5510.80 | Stairs: Stair Parts | | | | | |
| | | | | Stair Railing Steel 1-1/2" 6 pipe | 9.00 Inft | 534 | 877 | 159.66 /Inft | 1,437 |
| | | | | Stairs: Stair Parts | | 534 | 877 | /flt | 1,437 |
| | | | | METALS | | 534 | 877 | /sqft | 1,437 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Int Pipe Rails | 54.00 Inft | 69 | 12 | 1.50 /Inft | 81 |
| | | | | Painting: Interior | | 69 | 12 | /sqft | 81 |
| | | | | FINISHES | | 69 | 12 | /sqft | 81 |
| | | | | 5F | | 696 | 888 | | 1,611 |
| | 5G | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 1.10 cuyd | 23 | - | 27.16 /cuyd | 30 |
| | | | | Demo: General | | 23 | | /cuyd | 30 |
| | | | 2084.50 | Demo: Misc Items | | | | | |
| | | | | Remove Toilet Partitions | 2.00 each | 161 | - | 80.28 /each | 161 |
| | | | | Remove Toilet Accessories | 9.00 each | 90 | - | 10.03 /each | 90 |
| | | | | Demo: Misc Items | | 251 | | /sqft | 251 |
| | | | | DEMOLITION | | 274 | | /sqft | 281 |
| | | 6000.00 | | WOOD & PLASTICS | | | | | |
| | | | 6113.20 | Blocking: Misc. | | | | | |
| | | | | Block Toilet Partition | 1.00 each | 30 | 12 | 42.06 /each | 42 |
| | | | | Block H.C. Toilet Partition | 2.00 each | 90 | 29 | 59.95 /each | 120 |
| | | | | Block Misc Toilet Accessories | 16.00 each | 289 | 80 | 23.10 /each | 370 |
| | | | | Blocking: Misc. | | 410 | 122 | /mbf | 532 |
| | | | | WOOD & PLASTICS | | 410 | 122 | /sqft | 532 |
| | | 10000.00 | | SPECIALTIES | | | | | |
| | | | 10160.02 | Toilet Partition Phenolic | | | | | |
| | | | | Toilet Partition HC Flr Mtd | 2.00 each | 424 | 3,342 | 1,882.83 /each | 3,766 |
| | | | | Urinal Screens Wall Hung | 1.00 each | 148 | 465 | 613.39 /each | 613 |
| | | | | Toilet Partition Phenolic | | 572 | 3,807 | /each | 4,379 |
| | | | 10800.01 | Toilet Accessories | | | | | |
| | | | | Grab Bar 1-1/4" S.S. 36" | 4.00 each | 145 | 156 | 75.11 /each | 300 |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|---------|----------|------------------------------------|------------------|--------------|-----------------|-----------------|--------------|
| | | | 10800.01 | Toilet Accessories | | | | | |
| | | | | Mirror 18" x 30" S.S. | 2.00 each | 94 | 160 | 127.26 /each | 255 |
| | | | | Sanitary Napkin Dispenser Recessed | 1.00 each | 48 | 1,036 | 1,083.76 /each | 1,084 |
| | | | | Clothes Hook Single | 2.00 each | 40 | 38 | 39.26 /each | 79 |
| | | | | Soap Dispenser | 2.00 each | 145 | 414 | 279.45 /each | 559 |
| | | | | Stainless Steel Shelf | 3.00 Inft | 49 | 114 | 54.51 /Inft | 164 |
| | | | | Toilet Tissue Disp Dbl | 2.00 each | 60 | 55 | 57.62 /each | 115 |
| | | | | Towel Dispenser Surface Mtd | 2.00 each | 90 | 108 | 99.02 /each | 198 |
| | | | | Toilet Accessories | | 672 | 2,081 | /each | 2,753 |
| | | | | SPECIALTIES | | 1,244 | 5,888 | /sqft | 7,132 |
| | | | | 5G | | 1,927 | 6,010 | | 7,944 |
| 5H | | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | 2071.01 | | Demo: General | | | | | |
| | | | | General Disposal | 68.90 cuyd | 1,419 | - | 27.17 /cuyd | 1,872 |
| | | | | Demo: General | | 1,419 | | /cuyd | 1,872 |
| | | 2075.00 | | Demo: Concrete | | | | | |
| | | | | Saw Concrete Slab to 6" | 138.00 Inft | 752 | - | 7.56 /Inft | 1,043 |
| | | | | Chip out Slab | 116.00 sqft | 1,434 | 10 | 14.12 /sqft | 1,637 |
| | | | | Demo: Concrete | | 2,186 | 10 | /cuyd | 2,681 |
| | | 2076.00 | | Demo: Masonry | | | | | |
| | | | | Remove CMU 6" | 1,750.00 sqft | 6,380 | - | 3.97 /sqft | 6,941 |
| | | | | Demo: Masonry | | 6,380 | | /cuft | 6,941 |
| | | 2084.50 | | Demo: Misc Items | | | | | |
| | | | | Remove Toilet Partitions | 12.00 each | 963 | - | 80.28 /each | 963 |
| | | | | Remove Toilet Accessories | 55.00 each | 552 | - | 10.04 /each | 552 |
| | | | | Demo: Misc Items | | 1,515 | | /sqft | 1,515 |
| | | 2088.01 | | Demo: Finishes, Floors | | | | | |
| | | | | Remove Ceramic Tile Floor | 1,096.00 sqft | 2,024 | - | 1.85 /sqft | 2,024 |
| | | | | Flash Patch @ Wall Removal | 175.00 sqft | 403 | 369 | 4.41 /sqft | 772 |
| | | | | Demo: Finishes, Floors | | 2,427 | 369 | /sqft | 2,796 |
| | | 2088.50 | | Demo: Finishes, Ceilings | | | | | |
| | | | | Remove Plaster Ceiling Metal Lath | 1,096.00 sqft | 2,464 | - | 2.25 /sqft | 2,464 |
| | | | | Demo: Finishes, Ceilings | | 2,464 | | /sqft | 2,464 |
| | | 2088.60 | | Demo: Plumbing | | | | | |
| | | | | Remove Sink | 13.00 each | 1,597 | - | 122.84 /each | 1,597 |
| | | | | Remove Water Closet | 17.00 each | 2,387 | - | 140.41 /each | 2,387 |
| | | | | Remove Urinal | 3.00 each | 737 | - | 245.68 /each | 737 |
| | | | | Demo: Plumbing | | 4,721 | | /sqft | 4,721 |
| | | | | DEMOLITION | | 21,112 | 379 | /sqft | 22,989 |
| | 3000.00 | | | CONCRETE | | | | | |
| | | 3310.01 | | Conc: Slabs On Grade | | | | | |
| | | | | Patch Conc. Slab Trench etc. | 138.00 sqft | 748 | 1,631 | 17.24 /sqft | 2,379 |
| | | | | Conc: Slabs On Grade | | 748 | 1,631 | /cuyd | 2,379 |
| | | | | CONCRETE | | 748 | 1,631 | /sqft | 2,379 |
| | 4000.00 | | | MASONRY | | | | | |
| | | 4050.10 | | Misc: Scaffold | | | | | |
| | | | | Interior Scaffold | 1,830.00 sqft | 2,035 | 767 | 1.77 /sqft | 3,238 |
| | | | | Misc: Scaffold | | 2,035 | 767 | /sqft | 3,238 |
| | | 4050.15 | | Misc: Material Handling | | | | | |
| | | | | Concrete Block | 3.00 m | - | - | 262.92 /m | 789 |
| | | | | Misc: Material Handling | | | | /m | 789 |
| | | 4105.00 | | Mortar: All Types | | | | | |
| | | | | Mortar Type "N" | 3.48 cuyd | 422 | 754 | 337.96 /cuyd | 1,176 |
| | | | | Mortar: All Types | | 422 | 754 | /cuyd | 1,176 |
| | | 4110.01 | | Mortar: Grout Fill Conc | | | | | |
| | | | | Grout Fill 3000 psi, 1/2" Gravl | 1.53 cuyd | 431 | 294 | 494.65 /cuyd | 757 |
| | | | | Grout Single Door Frame | 10.00 each | 636 | 204 | 88.73 /each | 887 |
| | | | | Mortar: Grout Fill Conc | | 1,067 | 498 | /cuyd | 1,644 |
| | | 4157.00 | | Reinforce: Vertical Wall | | | | | |
| | | | | Re-Bar #5 & #6 | 333.76 lbs | 674 | 356 | 3.09 /lbs | 1,030 |
| | | | | Reinforce: Vertical Wall | | 674 | 356 | /lbs | 1,030 |
| | | 4158.00 | | Reinforce: Horizontl Wall | | | | | |
| | | | | Horiz Wall Reinf 6" Hot Dippd | 1.47 mlf | 654 | 251 | 615.65 /mlf | 905 |
| | | | | Reinforce: Horizontl Wall | | 654 | 251 | /mlf | 905 |
| | | 4221.20 | | Conc. Block: 6" | | | | | |
| | | | | Blk 6" Standard Face Reg Wt | 1,922.00 each | 23,502 | 4,318 | 14.47 /each | 27,820 |
| | | | | Conc. Block: 6" | | 23,502 | 4,318 | /each | 27,820 |
| | | 4221.50 | | Conc. Block: 6" Lintel | | | | | |
| | | | | Lintel 6" Stand Face Reg Wt | 138.00 each | 2,564 | 906 | 26.60 /each | 3,671 |
| | | | | Conc. Block: 6" Lintel | | 2,564 | 906 | /each | 3,671 |
| | | | | MASONRY | | 30,919 | 7,850 | /sqft | 40,273 |
| | 5000.00 | | | METALS | | | | | |
| | | 5510.35 | | Misc: Bolt On Material | | | | | |
| | | | | Angle Bolted To Masonry | 658.00 lb | 2,325 | 1,981 | 6.74 /lb | 4,436 |
| | | | | Misc: Bolt On Material | | 2,325 | 1,981 | /lbs | 4,436 |
| | | | | METALS | | 2,325 | 1,981 | /sqft | 4,436 |
| | 6000.00 | | | WOOD & PLASTICS | | | | | |
| | | 6113.20 | | Blocking: Misc. | | | | | |
| | | | | Block Toilet Partition | 11.00 each | 331 | 131 | 42.05 /each | 463 |
| | | | | Block H.C. Toilet Partition | 4.00 each | 181 | 59 | 59.95 /each | 240 |
| | | | | Block Misc Toilet Accessories | 112.00 each | 2,025 | 562 | 23.10 /each | 2,587 |
| | | | | Blocking: Misc. | | 2,537 | 752 | /mbf | 3,290 |
| | | 6113.40 | | Blocking: Rough Bucks | | | | | |
| | | | | Rough Bucks 2 x 6 Doors | 170.00 Inft | 426 | 115 | 3.18 /Inft | 541 |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|-------|----------|---|------------------|----------------|-----------------|-----------------|----------------|
| | | | | Blocking: Rough Bucks | | 426 | 115 | /mbf | 541 |
| | | | | WOOD & PLASTICS | | 2,963 | 868 | /sqft | 3,831 |
| | 7000.00 | | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | | Polysulfide Sealant 1/4" Interior | 170.00 Inft | 1,595 | 38 | 9.61 /Inft | 1,633 |
| | | | | Sealant - Jt Filler Gaskt | | 1,595 | 38 | /Inft | 1,633 |
| | | | | THERMAL & MOISTURE PROT | | 1,595 | 38 | /sqft | 1,633 |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | | 8110.01 | Doors: Steel with Frames | | | | | |
| | | | | H.M. Frame 18ga Interior Single | 10.00 each | 989 | 1,728 | 271.73 /each | 2,717 |
| | | | | Doors: Steel with Frames | | 989 | 1,728 | /each | 2,717 |
| | | | 8210.01 | Doors: Wood | | | | | |
| | | | | Door M Core 3-0 x 7-0 Louver | 10.00 each | 1,380 | 4,981 | 636.05 /each | 6,360 |
| | | | | Doors: Wood | | 1,380 | 4,981 | /each | 6,360 |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Int Budget w Closure | 10.00 each | 1,356 | 7,980 | 933.58 /each | 9,336 |
| | | | | Hardware: Finishing | | 1,356 | 7,980 | /set | 9,336 |
| | | | | DOORS & WINDOWS | | 3,725 | 14,689 | /sqft | 18,414 |
| | 9000.00 | | | FINISHES | | | | | |
| | | | 9210.01 | Lath/Plastr: Gyp Plaster | | | | | |
| | | | | Plaster Patch @ Wall Removal | 200.00 sqft | 3,330 | 355 | 18.82 /sqft | 3,764 |
| | | | | Plaster Patch Ceiling @ Wall Removal | 175.00 sqft | 952 | 279 | 7.17 /sqft | 1,254 |
| | | | | Lath/Plastr: Gyp Plaster | | 4,282 | 634 | /sqft | 5,018 |
| | | | 9253.30 | GWB: Boards & Sheathing | | | | | |
| | | | | GWB 5/8" Water Resistant Clgs | 1,096.00 sqft | 1,016 | 475 | 1.36 /sqft | 1,491 |
| | | | | GWB: Boards & Sheathing | | 1,016 | 475 | /sqft | 1,491 |
| | | | 9254.00 | GWB: Finish Mud/Tape | | | | | |
| | | | | Labor GWB Ceiling Finish | 1,096.00 sqft | 1,221 | 84 | 1.19 /sqft | 1,304 |
| | | | | GWB: Finish Mud/Tape | | 1,221 | 84 | /sqft | 1,304 |
| | | | 9310.01 | Ceramic Tile | | | | | |
| | | | | Ceramic Tile Floor Grade 2 | 1,096.00 sqft | 15,267 | 6,656 | 20.00 /sqft | 21,923 |
| | | | | Ceramic Trim: Cove Base | 462.00 Inft | 11,837 | 2,013 | 29.98 /Inft | 13,850 |
| | | | | Ceramic Tile | | 27,104 | 8,669 | /sqft | 35,773 |
| | | | 9510.10 | Ceiling: Susp. System | | | | | |
| | | | | Susp Clg 1-1/2" Channel | 1,096.00 sqft | 3,680 | 1,713 | 4.92 /sqft | 5,393 |
| | | | | Ceiling: Susp. System | | 3,680 | 1,713 | /sqft | 5,393 |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Wd Door & Metal Frame | 10.00 each | 702 | 143 | 84.46 /each | 845 |
| | | | | Epoxy Paint GDW Clg | 1,096.00 sqft | 2,535 | 863 | 3.10 /sqft | 3,399 |
| | | | | Paint Int CMU Spray p+2ct | 2,630.00 sqft | 2,479 | 735 | 1.22 /sqft | 3,214 |
| | | | | Epoxy Paint Int CMU | 2,630.00 sqft | 6,084 | 2,206 | 3.15 /sqft | 8,289 |
| | | | | Epoxy Paint Exist Int CMU | 2,832.00 sqft | 4,125 | 1,583 | 2.02 /sqft | 5,708 |
| | | | | Painting: Interior | | 15,924 | 5,530 | /sqft | 21,454 |
| | | | | FINISHES | | 53,226 | 17,105 | /sqft | 70,433 |
| | 10000.00 | | | SPECIALTIES | | | | | |
| | | | 10160.02 | Toilet Partition Phenolic | | | | | |
| | | | | Toilet Partition Reg Flr Mtd | 8.00 each | 1,696 | 11,609 | 1,663.01 /each | 13,304 |
| | | | | Toilet Partition HC Flr Mtd | 4.00 each | 848 | 6,684 | 1,882.83 /each | 7,531 |
| | | | | Urinal Screens Wall Hung | 3.00 each | 445 | 1,395 | 613.39 /each | 1,840 |
| | | | | Toilet Partition Phenolic | | 2,988 | 19,687 | /each | 22,676 |
| | | | 10800.01 | Toilet Accessories | | | | | |
| | | | | Grab Bar 1-1/4" S.S. 36" | 20.00 each | 723 | 779 | 75.11 /each | 1,502 |
| | | | | Mirror 18" x 30" S.S. | 14.00 each | 658 | 1,123 | 127.26 /each | 1,782 |
| | | | | Sanitary Napkin Dispenser Recessed | 3.00 each | 145 | 3,107 | 1,083.76 /each | 3,251 |
| | | | | Clothes Hook Single | 12.00 each | 241 | 230 | 39.26 /each | 471 |
| | | | | Soap Dispenser | 14.00 each | 1,013 | 2,900 | 279.45 /each | 3,912 |
| | | | | Stainless Steel Shelf | 21.00 Inft | 346 | 799 | 54.51 /Inft | 1,145 |
| | | | | Toilet Tissue Disp Dbl | 18.00 each | 542 | 495 | 57.62 /each | 1,037 |
| | | | | Towel Dispenser Surface Mtd | 6.00 each | 271 | 323 | 99.02 /each | 594 |
| | | | | Towel Disp/Waste Recpt | 4.00 each | 579 | 2,709 | 821.92 /each | 3,288 |
| | | | | Toilet Accessories | | 4,517 | 12,465 | /each | 16,982 |
| | | | | SPECIALTIES | | 7,505 | 32,152 | /sqft | 39,658 |
| | | | | 5H | | 124,119 | 76,692 | | 204,044 |
| 5K | | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 2.20 cuyd | 45 | - | 27.17 /cuyd | 60 |
| | | | | Shore - Screw Jack | 7.00 each | 7,449 | 479 | 1,196.86 /each | 8,378 |
| | | | | Demo: General | | 7,494 | 479 | /cuyd | 8,438 |
| | | | 2076.00 | Demo: Masonry | | | | | |
| | | | | Cut Out Opng 6" CMU | 49.00 sqft | 1,397 | - | 31.02 /sqft | 1,520 |
| | | | | Sawcut 6" CMU | 56.00 Inft | 1,584 | - | 46.49 /Inft | 2,603 |
| | | | | Tooth Jamb 1 Wythe | 49.00 Inft | 1,514 | - | 30.89 /Inft | 1,514 |
| | | | | Demo: Masonry | | 4,495 | | /cuft | 5,637 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Door & Frame Int Single | 7.00 each | 787 | - | 127.51 /each | 893 |
| | | | | Demo: Doors & Windows | | 787 | | /each | 893 |
| | | | | DEMOLITION | | 12,776 | 479 | /sqft | 14,967 |
| | 4000.00 | | | MASONRY | | | | | |
| | | | 4110.01 | Mortar: Grout Fill Conc | | | | | |
| | | | | Grout Single Door Frame | 7.00 each | 445 | 143 | 88.72 /each | 621 |
| | | | | Mortar: Grout Fill Conc | | 445 | 143 | /cuyd | 621 |
| | | | | MASONRY | | 445 | 143 | /sqft | 621 |
| | 6000.00 | | | WOOD & PLASTICS | | | | | |
| | | | 6113.40 | Blocking: Rough Bucks | | | | | |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|-----------|----------|----------|----------|---|------------------|---------------|-----------------|-----------------|---------------|
| | | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | | Rough Bucks 2 x 6 Doors | 119.00 Inft | 298 | 81 | 3.18 /Inft | 379 |
| | | | | Blocking: Rough Bucks | | 298 | 81 | /mbf | 379 |
| | | | | WOOD & PLASTICS | | 298 | 81 | /sqft | 379 |
| | | 7000.00 | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | | Polysulfide Sealant 1/4" Interior | 119.00 Inft | 1,116 | 26 | 9.61 /Inft | 1,143 |
| | | | | Sealant - Jt Filler Gaskt | | 1,116 | 26 | /Inft | 1,143 |
| | | | | THERMAL & MOISTURE PROT | | 1,116 | 26 | /sqft | 1,143 |
| | | 8000.00 | | DOORS & WINDOWS | | | | | |
| | | | 8110.01 | Doors: Steel with Frames | | | | | |
| | | | | H.M. Frame 18ga Interior Single | 7.00 each | 692 | 1,210 | 271.73 /each | 1,902 |
| | | | | Doors: Steel with Frames | | 692 | 1,210 | /each | 1,902 |
| | | | 8210.01 | Doors: Wood | | | | | |
| | | | | Door M Core 3-0 x 7-0 Vision | 7.00 each | 912 | 2,980 | 555.93 /each | 3,891 |
| | | | | Doors: Wood | | 912 | 2,980 | /each | 3,891 |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Int Budget w Closure | 7.00 each | 949 | 5,586 | 933.58 /each | 6,535 |
| | | | | Hardware: Finishing | | 949 | 5,586 | /set | 6,535 |
| | | | | DOORS & WINDOWS | | 2,554 | 9,775 | /sqft | 12,329 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Wd Door & Metal Frame | 7.00 each | 491 | 100 | 84.46 /each | 591 |
| | | | | Painting: Interior | | 491 | 100 | /sqft | 591 |
| | | | | FINISHES | | 491 | 100 | /sqft | 591 |
| | | | | 5K | | 17,681 | 10,604 | | 30,030 |
| 5L | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 0.40 cuyd | 8 | - | 27.15 /cuyd | 11 |
| | | | | Demo: General | | 8 | | /cuyd | 11 |
| | | | 2075.00 | Demo: Concrete | | | | | |
| | | | | Saw Concrete Slab to 6" | 25.00 Inft | 136 | - | 7.56 /Inft | 189 |
| | | | | Chip out Slab | 35.00 sqft | 433 | 3 | 14.12 /sqft | 494 |
| | | | | Demo: Concrete | | 569 | 3 | /cuyd | 683 |
| | | | | DEMOLITION | | 577 | 3 | /sqft | 694 |
| | | 14000.00 | | CONVEYING SYSTEMS | | | | | |
| | | | 14405.00 | Lifts | | | | | |
| | | | | Lift Commercial | 1.00 each | 2,989 | 15,344 | 18,490.57 /each | 18,491 |
| | | | | Lifts | | 2,989 | 15,344 | /each | 18,491 |
| | | | | CONVEYING SYSTEMS | | 2,989 | 15,344 | /sqft | 18,491 |
| | | | | 5L | | 3,566 | 15,347 | | 19,184 |
| 5N | | | | | | | | | |
| | | 3000.00 | | CONCRETE | | | | | |
| | | | 3131.00 | Forms: Ramps | | | | | |
| | | | | Ramp Forms 2 use | 115.00 Inft | 910 | 205 | 9.69 /Inft | 1,114 |
| | | | | Forms: Ramps | | 910 | 205 | /Inft | 1,114 |
| | | | 3225.00 | Rebar: WWM @ Ramp/Misc | | | | | |
| | | | | Wiremesh - Ramp 6x6 6/6 | 4.08 sqs | 282 | 208 | 120.01 /sqs | 490 |
| | | | | Rebar: WWM @ Ramp/Misc | | 282 | 208 | /sqs | 490 |
| | | | 3309.50 | Conc: Ramps | | | | | |
| | | | | Ramp Conc 4000 psi | 7.56 cuyd | 348 | 1,072 | 197.31 /cuyd | 1,492 |
| | | | | Conc: Ramps | | 348 | 1,072 | /cuyd | 1,492 |
| | | | 3375.00 | Finish: Protect & Cure | | | | | |
| | | | | Cure Conc w/burlap Ramp | 4.08 sqs | 105 | 48 | 37.43 /sqs | 153 |
| | | | | Finish: Protect & Cure | | 105 | 48 | /sqs | 153 |
| | | | 3380.01 | Finish: General | | | | | |
| | | | | Broom/Float Finish Ramp | 408.00 sqft | 359 | - | 0.88 /sqft | 359 |
| | | | | Finish: General | | 359 | | /sqft | 359 |
| | | | | CONCRETE | | 2,003 | 1,532 | /sqft | 3,608 |
| | | | | 5N | | 2,003 | 1,532 | | 3,608 |
| 5P | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Hardware | 2.00 each | 90 | - | 45.21 /each | 90 |
| | | | | Demo: Doors & Windows | | 90 | | /each | 90 |
| | | | | DEMOLITION | | 90 | | /sqft | 90 |
| | | 8000.00 | | DOORS & WINDOWS | | | | | |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Ext Budget | 2.00 each | 452 | 2,407 | 1,429.34 /each | 2,859 |
| | | | | Hardware: Finishing | | 452 | 2,407 | /set | 2,859 |
| | | | | DOORS & WINDOWS | | 452 | 2,407 | /sqft | 2,859 |
| | | | | 5P | | 543 | 2,407 | | 2,949 |
| 5Q | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2075.00 | Demo: Concrete | | | | | |
| | | | | Remove Locker Base | 8.00 Inft | 136 | - | 20.38 /Inft | 163 |
| | | | | Demo: Concrete | | 136 | | /cuyd | 163 |
| | | | 2084.50 | Demo: Misc Items | | | | | |
| | | | | Relocate Lockers | 8.00 each | 826 | - | 103.24 /each | 826 |
| | | | | Demo: Misc Items | | 826 | | /sqft | 826 |
| | | | | DEMOLITION | | 962 | | /sqft | 989 |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|-----------------------|----------|-------|----------|---|------------------|----------------|-----------------|-----------------|----------------|
| | | | | | | 962 | | | 989 |
| 5T | | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 5.30 cuyd | 109 | - | 27.17 /cuyd | 144 |
| | | | | Demo: General | | 109 | | /cuyd | 144 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Hardware | 144.00 each | 6,510 | - | 45.21 /each | 6,510 |
| | | | | Demo: Doors & Windows | | 6,510 | | /each | 6,510 |
| | | | | DEMOLITION | | 6,619 | | /sqft | 6,654 |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Ext Budget | 16.00 each | 3,617 | 19,253 | 1,429.33 /each | 22,869 |
| | | | | Finishing Hardware Int Budget w Closure | 123.00 each | 16,682 | 98,149 | 933.58 /each | 114,831 |
| | | | | Hardware: Finishing | | 20,298 | 117,402 | /set | 137,700 |
| | | | | DOORS & WINDOWS | | 20,298 | 117,402 | /sqft | 137,700 |
| 5T | | | | | | 26,918 | 117,402 | | 144,354 |
| 5 HC ACCESS | | | | | | 215,110 | 278,220 | | 499,667 |
| 6 FINISHES GEN | | | | | | | | | |
| 6A | | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 3.30 cuyd | 68 | - | 27.17 /cuyd | 90 |
| | | | | Demo: General | | 68 | | /cuyd | 90 |
| | | | 2088.50 | Demo: Finishes, Ceilings | | | | | |
| | | | | Remove Acoust Tile | 360.00 sqft | 520 | - | 1.45 /sqft | 520 |
| | | | | Demo: Finishes, Ceilings | | 520 | | /sqft | 520 |
| | | | | DEMOLITION | | 588 | | /sqft | 610 |
| | 9000.00 | | | FINISHES | | | | | |
| | | | 9510.50 | Ceiling: 2x4 Tile | | | | | |
| | | | | MinFbr Tegulr Std 2x4 3/4" < 250 sf | 360.00 sqft | 1,173 | 1,225 | 6.66 /sqft | 2,398 |
| | | | | Ceiling: 2x4 Tile | | 1,173 | 1,225 | /sqft | 2,398 |
| | | | | FINISHES | | 1,173 | 1,225 | /sqft | 2,398 |
| 6A | | | | | | 1,761 | 1,225 | | 3,008 |
| 6B | | | | | | | | | |
| | 4000.00 | | | MASONRY | | | | | |
| | | | 4520.01 | Masonry Restoration | | | | | |
| | | | | Cut & Repoint CMU Hard Mortar | 90.00 Inft | 931 | 125 | 14.56 /Inft | 1,310 |
| | | | | Cut & Repoint Brick Soft Mortr | 40.00 sqft | 289 | 29 | 9.88 /sqft | 395 |
| | | | | Remove Individual Brick Allow | 270.00 each | 18,153 | - | 85.37 /each | 23,050 |
| | | | | Patch Individual Brick Allow | 270.00 each | 4,833 | 389 | 19.34 /each | 5,222 |
| | | | | Remove CMU 8" Allow | 45.00 each | 2,683 | - | 64.87 /each | 2,919 |
| | | | | Patch in 8" CMU Allow | 45.00 each | 1,339 | 120 | 32.42 /each | 1,459 |
| | | | | Masonry Restoration | | 28,228 | 663 | /m | 34,356 |
| | | | | MASONRY | | 28,228 | 663 | /sqft | 34,356 |
| 6B | | | | | | 28,228 | 663 | | 34,356 |
| 6C | | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2084.50 | Demo: Misc Items | | | | | |
| | | | | Remove Lockers Top | 24.00 each | 414 | - | 17.26 /each | 414 |
| | | | | Demo: Misc Items | | 414 | | /sqft | 414 |
| | | | | DEMOLITION | | 414 | | /sqft | 414 |
| | 10000.00 | | | SPECIALTIES | | | | | |
| | | | 10505.90 | Lockers | | | | | |
| | | | | Replace Locker Top | 24.00 each | 1,614 | 1,830 | 143.48 /each | 3,444 |
| | | | | Lockers | | 1,614 | 1,830 | /each | 3,444 |
| | | | | SPECIALTIES | | 1,614 | 1,830 | /sqft | 3,444 |
| 6C | | | | | | 2,028 | 1,830 | | 3,858 |
| 6D | | | | | | | | | |
| | 4000.00 | | | MASONRY | | | | | |
| | | | 4520.01 | Masonry Restoration | | | | | |
| | | | | Remove Individual Brick | 405.00 each | 27,229 | - | 85.37 /each | 34,576 |
| | | | | Patch Individual Brick | 405.00 each | 7,250 | 584 | 19.34 /each | 7,833 |
| | | | | Masonry Restoration | | 34,479 | 584 | /m | 42,409 |
| | | | | MASONRY | | 34,479 | 584 | /sqft | 42,409 |
| 6D | | | | | | 34,479 | 584 | | 42,409 |
| 6E | | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 0.80 cuyd | 16 | - | 27.18 /cuyd | 22 |
| | | | | Demo: General | | 16 | | /cuyd | 22 |
| | | | 2088.70 | Demo: Mechanical | | | | | |
| | | | | Remove Louvers | 21.00 sqft | 241 | - | 11.48 /sqft | 241 |
| | | | | Demo: Mechanical | | 241 | | /sqft | 241 |
| | | | | DEMOLITION | | 258 | | /sqft | 263 |
| | 5000.00 | | | METALS | | | | | |
| | | | 5510.05 | Misc: Lintels | | | | | |
| | | | | Stl Angles 1000 - 2000 lbs | 90.00 lb | 169 | 132 | 3.34 /lb | 300 |
| | | | | Misc: Lintels | | 169 | 132 | /lbs | 300 |
| | | | | METALS | | 169 | 132 | /sqft | 300 |
| | 6000.00 | | | WOOD & PLASTICS | | | | | |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|------------|----------|----------|----------|---------------------------------------|------------------|---------------|-----------------|-----------------|---------------|
| | | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | | 2 x 6 PT Louvers | 36.00 Inft | 97 | 41 | 3.82 /Inft | 137 |
| | | | | Blocking: Rough Bucks | | 97 | 41 | /mbf | 137 |
| | | | | WOOD & PLASTICS | | 97 | 41 | /sqft | 137 |
| | | 7000.00 | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | | Backer Rod ½" | 36.00 Inft | 109 | 3 | 3.12 /Inft | 112 |
| | | | | Polysulfide Sealant 1/4" Interior | 72.00 Inft | 676 | 16 | 9.61 /Inft | 692 |
| | | | | Sealant - Jt Filler Gaskt | | 785 | 19 | /Inft | 804 |
| | | | | THERMAL & MOISTURE PROT | | 785 | 19 | /sqft | 804 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Louvers | 21.00 sqft | 36 | 7 | 2.06 /sqft | 43 |
| | | | | Painting: Interior | | 36 | 7 | /sqft | 43 |
| | | | | FINISHES | | 36 | 7 | /sqft | 43 |
| | | 15500.00 | | HVAC SYSTEMS | | | | | |
| | | | 15856.00 | Louvers/Filters | | | | | |
| | | | | Fixed Blade Stormproof | 21.00 sqft | 808 | 927 | 82.62 /sqft | 1,735 |
| | | | | Louvers/Filters | | 808 | 927 | /sqft | 1,735 |
| | | | | HVAC SYSTEMS | | 808 | 927 | /sqft | 1,735 |
| | | | | 6E | | 2,152 | 1,126 | | 3,283 |
| 6G | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2079.00 | Demo: Exterior Finishes | | | | | |
| | | | | Remove Soffit & Trim | 10.00 sqft | 90 | - | 8.99 /sqft | 90 |
| | | | | Demo: Exterior Finishes | | 90 | | /sqft | 90 |
| | | | | DEMOLITION | | 90 | | /sqft | 90 |
| | | 6000.00 | | WOOD & PLASTICS | | | | | |
| | | | 6450.30 | X Trim: Soffit & Eave | | | | | |
| | | | | Soffit 1/2" AC | 10.00 sqft | 53 | 12 | 6.53 /sqft | 65 |
| | | | | X Trim: Soffit & Eave | | 53 | 12 | /each | 65 |
| | | | | WOOD & PLASTICS | | 53 | 12 | /sqft | 65 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9910.01 | Painting: Exterior | | | | | |
| | | | | Paint Ext Soffit 3 ct | 10.00 sqft | 10 | 1 | 1.16 /sqft | 12 |
| | | | | Painting: Exterior | | 10 | 1 | /sqft | 12 |
| | | | | FINISHES | | 10 | 1 | /sqft | 12 |
| | | | | 6G | | 153 | 14 | | 167 |
| 6GG | | | | | | | | | |
| | | 3000.00 | | CONCRETE | | | | | |
| | | | 3328.00 | Conc: Restoration | | | | | |
| | | | | Patch Concrete Wall | 20.00 sqft | 271 | 479 | 37.50 /sqft | 750 |
| | | | | Pressure Injected Grout | 1.00 dy | 3,187 | - | 3,428.98 /dy | 3,429 |
| | | | | Conc: Restoration | | 3,458 | 479 | /sqft | 4,179 |
| | | | | CONCRETE | | 3,458 | 479 | /sqft | 4,179 |
| | | | | 6GG | | 3,458 | 479 | | 4,179 |
| 6KK | | | | | | | | | |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Exist Int CMU Spray 2 ct | 49,493.00 sqft | 21,201 | 8,804 | 0.61 /sqft | 30,006 |
| | | | | Painting: Interior | | 21,201 | 8,804 | /sqft | 30,006 |
| | | | | FINISHES | | 21,201 | 8,804 | /sqft | 30,006 |
| | | | | 6KK | | 21,201 | 8,804 | | 30,006 |
| 6L | | | | | | | | | |
| | | 4000.00 | | MASONRY | | | | | |
| | | | 4155.00 | Access: Control Joint | | | | | |
| | | | | Control Jnt Rubber 8" Wall | 40.00 Inft | 156 | 148 | 7.59 /Inft | 304 |
| | | | | Access: Control Joint | | 156 | 148 | /Inft | 304 |
| | | | | MASONRY | | 156 | 148 | /sqft | 304 |
| | | 7000.00 | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | | Backer Rod ½" | 40.00 Inft | 121 | 4 | 3.12 /Inft | 125 |
| | | | | Polyurethane Sealant 1/2" | 40.00 Inft | 381 | 20 | 10.02 /Inft | 401 |
| | | | | Rake Out Masonry Jt. Filler | 40.00 Inft | 118 | 8 | 4.98 /Inft | 199 |
| | | | | Sealant - Jt Filler Gaskt | | 620 | 32 | /Inft | 725 |
| | | | | THERMAL & MOISTURE PROT | | 620 | 32 | /sqft | 725 |
| | | | | 6L | | 776 | 180 | | 1,029 |
| 6LL | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 539.30 cuyd | 11,107 | - | 27.17 /cuyd | 14,652 |
| | | | | Demo: General | | 11,107 | | /cuyd | 14,652 |
| | | | 2088.50 | Demo: Finishes, Ceilings | | | | | |
| | | | | Rem. Acoust Tile & Grid | 58,240.00 sqft | 70,131 | - | 1.20 /sqft | 70,131 |
| | | | | Demo: Finishes, Ceilings | | 70,131 | | /sqft | 70,131 |
| | | | | DEMOLITION | | 81,238 | | /sqft | 84,783 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9510.50 | Ceiling: 2x4 Tile | | | | | |
| | | | | MinFbr Tegulr Std 2x4 3/4" 250-500 sf | 58,240.00 sqft | 115,019 | 191,317 | 5.26 /sqft | 306,336 |
| | | | | Ceiling: 2x4 Tile | | 115,019 | 191,317 | /sqft | 306,336 |
| | | | | FINISHES | | 115,019 | 191,317 | /sqft | 306,336 |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------------|----------|-------|-------|-------------|------------------|----------------|-----------------|-----------------|----------------|
| | | | | | | <u>196,258</u> | <u>191,317</u> | | <u>391,119</u> |
| 6 FINISHES GEN | | | | | | 290,493 | 206,220 | | 513,412 |

Estimate Totals

| | | | |
|-----------|------------------|------------------|-----|
| Labor | 687,465 | 7,273.709 | hrs |
| Material | 769,215 | | |
| Equipment | <u>28,284</u> | 1,297.452 | hrs |
| | <u>1,484,964</u> | <u>1,484,964</u> | |
| Total | | <u>1,484,964</u> | |

BRIDGE ELEMENTARY SCHOOL RENOVATION
STUDY ESTIMATE - 11-14-08
LEXINGTON, MA

Project name **Bridge E.S.**
Lexington
MA

Architect **TDPC**

Estimator *Essential Estimating*

| Location | Labor Amount | Material Amount | Equip Amount | Total Amount |
|-----------------|--------------|-----------------|--------------|--------------|
| 1 LIFE SAFETY | 925 | 3,220 | | 4,145 |
| 2 BUILDING CODE | 23,625 | 15,978 | 87 | 39,690 |
| 3 EXTERIOR | 173,935 | 337,975 | 688 | 512,597 |
| 5 HC ACCESS | 212,973 | 280,733 | 7,401 | 501,107 |
| 6 FINISHES GEN | 340,590 | 214,463 | 23,758 | 578,811 |

Estimate Totals

| | | | |
|--------------|------------------|------------------|-----|
| Labor | 752,048 | 7,905.513 | hrs |
| Material | 852,369 | | |
| Equipment | 31,934 | 1,566.307 | hrs |
| | 1,636,351 | 1,636,351 | |
| Total | 1,636,351 | | |

| Location | Bid Item | Description | Labor Amount | Material Amount | Equip Amount | Total Amount |
|------------------------|------------|------------------------|----------------|-----------------|---------------|----------------|
| 1 LIFE SAFETY | | | | | | |
| | <u>1A</u> | | <u>247</u> | <u>16</u> | | <u>262</u> |
| | <u>1D</u> | | <u>678</u> | <u>3,205</u> | | <u>3,883</u> |
| | | 1 LIFE SAFETY | 925 | 3,220 | | 4,145 |
| 2 BUILDING CODE | | | | | | |
| | <u>2C</u> | | <u>372</u> | <u>1,341</u> | <u>1</u> | <u>1,715</u> |
| | <u>2D</u> | | <u>181</u> | <u>49</u> | | <u>230</u> |
| | <u>2F</u> | | <u>90</u> | <u>53</u> | | <u>144</u> |
| | <u>2G</u> | | <u>19,987</u> | <u>12,577</u> | <u>32</u> | <u>32,596</u> |
| | <u>2H</u> | | <u>431</u> | | <u>14</u> | <u>445</u> |
| | <u>2I</u> | | <u>2,565</u> | <u>1,958</u> | <u>39</u> | <u>4,561</u> |
| | | 2 BUILDING CODE | 23,625 | 15,978 | 87 | 39,690 |
| 3 EXTERIOR | | | | | | |
| | <u>3A</u> | | <u>162,796</u> | <u>314,829</u> | <u>351</u> | <u>477,975</u> |
| | <u>3B</u> | | <u>9,736</u> | <u>17,881</u> | <u>337</u> | <u>27,954</u> |
| | <u>3C</u> | | <u>1,326</u> | <u>5,251</u> | | <u>6,577</u> |
| | <u>3D</u> | | <u>77</u> | <u>14</u> | | <u>91</u> |
| | | 3 EXTERIOR | 173,935 | 337,975 | 688 | 512,597 |
| 5 HC ACCESS | | | | | | |
| | <u>5A</u> | | <u>8,642</u> | <u>474</u> | <u>532</u> | <u>9,647</u> |
| | <u>5B</u> | | <u>18,364</u> | <u>32,216</u> | <u>231</u> | <u>50,810</u> |
| | <u>5C</u> | | <u>1,866</u> | <u>5,297</u> | <u>24</u> | <u>7,187</u> |
| | <u>5D</u> | | <u>336</u> | | <u>3</u> | <u>338</u> |
| | <u>5E</u> | | <u>723</u> | | | <u>723</u> |
| | <u>5F</u> | | <u>696</u> | <u>888</u> | <u>27</u> | <u>1,611</u> |
| | <u>5G</u> | | <u>4,257</u> | <u>13,505</u> | <u>16</u> | <u>17,778</u> |
| | <u>5H</u> | | <u>111,253</u> | <u>62,863</u> | <u>3,205</u> | <u>177,321</u> |
| | <u>5K</u> | | <u>30,374</u> | <u>18,178</u> | <u>3,003</u> | <u>51,555</u> |
| | <u>5L</u> | | <u>3,565</u> | <u>15,348</u> | <u>270</u> | <u>19,183</u> |
| | <u>5N</u> | | <u>2,165</u> | <u>953</u> | <u>29</u> | <u>3,147</u> |
| | <u>5P</u> | | <u>543</u> | <u>2,407</u> | | <u>2,949</u> |
| | <u>5Q</u> | | <u>962</u> | | <u>27</u> | <u>989</u> |
| | <u>5T</u> | | <u>29,229</u> | <u>128,604</u> | <u>36</u> | <u>157,869</u> |
| | | 5 HC ACCESS | 212,973 | 280,733 | 7,401 | 501,107 |
| 6 FINISHES GEN | | | | | | |
| | <u>6A</u> | | <u>4,308</u> | <u>2,995</u> | <u>54</u> | <u>7,357</u> |
| | <u>6B</u> | | <u>103,984</u> | <u>2,226</u> | <u>19,976</u> | <u>126,187</u> |
| | <u>6E</u> | | <u>629</u> | <u>306</u> | <u>1</u> | <u>937</u> |
| | <u>6H</u> | | <u>454</u> | <u>188</u> | | <u>642</u> |
| | <u>6J</u> | | <u>4,855</u> | <u>2,343</u> | | <u>7,198</u> |
| | <u>6KK</u> | | <u>25,476</u> | <u>10,579</u> | | <u>36,055</u> |
| | <u>6L</u> | | <u>699</u> | <u>162</u> | <u>66</u> | <u>926</u> |
| | <u>6LL</u> | | <u>198,785</u> | <u>193,595</u> | <u>3,647</u> | <u>396,028</u> |
| | <u>6M</u> | | <u>475</u> | <u>1,622</u> | <u>14</u> | <u>2,111</u> |
| | <u>6T</u> | | <u>925</u> | <u>446</u> | | <u>1,371</u> |
| | | 6 FINISHES GEN | 340,590 | 214,463 | 23,758 | 578,811 |

Estimate Totals

| | | | |
|--------------|------------------|------------------|-----|
| Labor | 752,048 | 7,905.513 | hrs |
| Material | 852,369 | | |
| Equipment | 31,934 | 1,566.307 | hrs |
| | <u>1,636,351</u> | <u>1,636,351</u> | |
| Total | 1,636,351 | | |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|------------------------|-----------|-------|----------|---|------------------|---------------|-----------------|-----------------|---------------|
| 1 LIFE SAFETY | | | | | | | | | |
| | 1A | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Door | 1.00 each | 32 | - | 32.11 /each | 32 |
| | | | | Demo: Doors & Windows | | 32 | | /each | 32 |
| | | | | DEMOLITION | | 32 | | /sqft | 32 |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | | 8210.01 | Doors: Wood | | | | | |
| | | | | Rehang Door | 1.00 each | 130 | 0 | 130.27 /each | 130 |
| | | | | Doors: Wood | | 130 | | /each | 130 |
| | | | | DOORS & WINDOWS | | 130 | | /sqft | 130 |
| | 9000.00 | | | FINISHES | | | | | |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Wd Door & Metal Frame & Prep | 1.00 each | 84 | 16 | 99.99 /each | 100 |
| | | | | Painting: Interior | | 84 | 16 | /sqft | 100 |
| | | | | FINISHES | | 84 | 16 | /sqft | 100 |
| | | | | 1A | | 247 | 16 | | 262 |
| | 1D | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Hardware | 2.00 each | 90 | - | 45.21 /each | 90 |
| | | | | Demo: Doors & Windows | | 90 | | /each | 90 |
| | | | | DEMOLITION | | 90 | | /sqft | 90 |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Ext Budget | 2.00 each | 452 | 2,407 | 1,429.40 /each | 2,859 |
| | | | | Finishing Hardware Int Budget w Closure | 1.00 each | 136 | 798 | 933.64 /each | 934 |
| | | | | Hardware: Finishing | | 588 | 3,205 | /set | 3,792 |
| | | | | DOORS & WINDOWS | | 588 | 3,205 | /sqft | 3,792 |
| | | | | 1D | | 678 | 3,205 | | 3,883 |
| | | | | 1 LIFE SAFETY | | 925 | 3,220 | | 4,145 |
| 2 BUILDING CODE | | | | | | | | | |
| | 2C | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 0.20 cu yd | 4 | - | 27.15 /cu yd | 5 |
| | | | | Demo: General | | 4 | | /cu yd | 5 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Door | 1.00 each | 32 | - | 32.11 /each | 32 |
| | | | | Demo: Doors & Windows | | 32 | | /each | 32 |
| | | | | DEMOLITION | | 36 | | /sqft | 38 |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | | 8210.01 | Doors: Wood | | | | | |
| | | | | Birch Solid Core 3-0 x 7-0 Vision | 1.00 each | 130 | 529 | 658.87 /each | 659 |
| | | | | Doors: Wood | | 130 | 529 | /each | 659 |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Int Budget w Closure | 1.00 each | 136 | 798 | 933.64 /each | 934 |
| | | | | Hardware: Finishing | | 136 | 798 | /set | 934 |
| | | | | DOORS & WINDOWS | | 266 | 1,327 | /sqft | 1,593 |
| | 9000.00 | | | FINISHES | | | | | |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Wd Door & Metal Frame | 1.00 each | 70 | 14 | 84.46 /each | 84 |
| | | | | Painting: Interior | | 70 | 14 | /sqft | 84 |
| | | | | FINISHES | | 70 | 14 | /sqft | 84 |
| | | | | 2C | | 372 | 1,341 | | 1,715 |
| | 2D | | | | | | | | |
| | 7000.00 | | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7270.00 | Firestopping | | | | | |
| | | | | Firesafing | 50.00 lnft | 181 | 49 | 4.60 /lnft | 230 |
| | | | | Firestopping | | 181 | 49 | /lnft | 230 |
| | | | | THERMAL & MOISTURE PROT | | 181 | 49 | /sqft | 230 |
| | | | | 2D | | 181 | 49 | | 230 |
| | 2F | | | | | | | | |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Smoke Seal | 1.00 each | 90 | 53 | 143.80 /each | 144 |
| | | | | Hardware: Finishing | | 90 | 53 | /set | 144 |
| | | | | DOORS & WINDOWS | | 90 | 53 | /sqft | 144 |
| | | | | 2F | | 90 | 53 | | 144 |
| | 2G | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 4.90 cu yd | 101 | - | 27.17 /cu yd | 133 |
| | | | | Demo: General | | 101 | | /cu yd | 133 |
| | | | 2084.50 | Demo: Misc Items | | | | | |
| | | | | Remove Stage Curtain | 528.00 sqft | 593 | - | 1.12 /sqft | 593 |
| | | | | Demo: Misc Items | | 593 | | /sqft | 593 |
| | | | | DEMOLITION | | 694 | | /sqft | 727 |
| | 11000.00 | | | EQUIPMENT | | | | | |
| | | | 11060.01 | Equip: Stage | | | | | |
| | | | | Curtain Track Med Duty | 44.00 lnft | 3,627 | 2,413 | 137.26 /lnft | 6,039 |
| | | | | Curtain Fireproof | 528.00 sqft | 15,666 | 10,165 | 48.92 /sqft | 25,830 |
| | | | | Equip: Stage | | 19,292 | 12,577 | /each | 31,869 |
| | | | | EQUIPMENT | | 19,292 | 12,577 | /sqft | 31,869 |
| | | | | 2G | | 19,987 | 12,577 | | 32,596 |
| | 2H | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|-----------|-------|---------|---|------------------|---------------|-----------------|-----------------|---------------|
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 2.20 cuyd | 45 | - | 27.17 /cuyd | 60 |
| | | | | Demo: General | | 45 | | /cuyd | 60 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Door | 12.00 each | 385 | - | 32.11 /each | 385 |
| | | | | Demo: Doors & Windows | | 385 | | /each | 385 |
| | | | | DEMOLITION | | 431 | | /sqft | 445 |
| | | | | 2H | | 431 | | | 445 |
| | 2I | | | | | | | | |
| | 4000.00 | | | MASONRY | | | | | |
| | | | 4050.10 | Misc: Scaffold | | | | | |
| | | | | Interior Scaffold | 96.00 sqft | 107 | 40 | 1.77 /sqft | 170 |
| | | | | Misc: Scaffold | | 107 | 40 | /sqft | 170 |
| | | | 4050.15 | Misc: Material Handling | | | | | |
| | | | | Concrete Block | 0.01 m | - | - | 264.00 /m | 2 |
| | | | | Misc: Material Handling | | | | /m | 2 |
| | | | 4105.00 | Mortar: All Types | | | | | |
| | | | | Mortar Type "N" | 0.15 cuyd | 18 | 32 | 337.93 /cuyd | 51 |
| | | | | Mortar: All Types | | 18 | 32 | /cuyd | 51 |
| | | | 4110.01 | Mortar: Grout Fill Conc | | | | | |
| | | | | Grout Fill 3000 psi, 1/2" Gravl | 0.17 cuyd | 48 | 33 | 495.12 /cuyd | 84 |
| | | | | Grout Single Door Frame | 1.00 each | 64 | 20 | 88.72 /each | 89 |
| | | | | Mortar: Grout Fill Conc | | 112 | 53 | /cuyd | 173 |
| | | | 4157.00 | Reinforce: Vertical Wall | | | | | |
| | | | | Re-Bar #5 & #6 | 25.03 lbs | 51 | 27 | 3.09 /lbs | 77 |
| | | | | Reinforce: Vertical Wall | | 51 | 27 | /lbs | 77 |
| | | | 4158.00 | Reinforce: Horizontl Wall | | | | | |
| | | | | Horiz Wall Reinf 6" Hot Dippd | 0.06 mlf | 27 | 10 | 615.50 /mlf | 37 |
| | | | | Reinforce: Horizontl Wall | | 27 | 10 | /mlf | 37 |
| | | | 4221.20 | Conc. Block: 6" | | | | | |
| | | | | Blk 6" Stand Face Reg Wt - Infill | 75.00 each | 1,362 | 178 | 20.53 /each | 1,540 |
| | | | | Conc. Block: 6" | | 1,362 | 178 | /each | 1,540 |
| | | | 4221.50 | Conc. Block: 6" Lintel | | | | | |
| | | | | Lintel 6" Stand Face Lt Wt | 6.00 each | 14 | 8 | 3.63 /each | 22 |
| | | | | Conc. Block: 6" Lintel | | 14 | 8 | /each | 22 |
| | | | | MASONRY | | 1,689 | 349 | /sqft | 2,071 |
| | 5000.00 | | | METALS | | | | | |
| | | | 5510.35 | Misc: Bolt On Material | | | | | |
| | | | | Angle Bolted To Masonry | 29.00 lb | 102 | 87 | 6.74 /lb | 196 |
| | | | | Misc: Bolt On Material | | 102 | 87 | /lbs | 196 |
| | | | | METALS | | 102 | 87 | /sqft | 196 |
| | 6000.00 | | | WOOD & PLASTICS | | | | | |
| | | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | | Rough Bucks 2 x 6 PT Doors | 17.00 lnft | 43 | 19 | 3.63 /lnft | 62 |
| | | | | Blocking: Rough Bucks | | 43 | 19 | /mbf | 62 |
| | | | | WOOD & PLASTICS | | 43 | 19 | /sqft | 62 |
| | 7000.00 | | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | | Polysulfide Sealant 1/4" Interior | 17.00 lnft | 160 | 4 | 9.61 /lnft | 163 |
| | | | | Sealant - Jt Filler Gaskt | | 160 | 4 | /lnft | 163 |
| | | | | THERMAL & MOISTURE PROT | | 160 | 4 | /sqft | 163 |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | | 8110.01 | Doors: Steel with Frames | | | | | |
| | | | | H.M. Frame 18ga Interior Double | 1.00 each | 124 | 227 | 351.05 /each | 351 |
| | | | | Doors: Steel with Frames | | 124 | 227 | /each | 351 |
| | | | 8210.01 | Doors: Wood | | | | | |
| | | | | Door M Core 3-0 x 7-0 Vision | 1.00 each | 130 | 426 | 555.96 /each | 556 |
| | | | | Doors: Wood | | 130 | 426 | /each | 556 |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Int Budget w Closure | 1.00 each | 136 | 798 | 933.63 /each | 934 |
| | | | | Hardware: Finishing | | 136 | 798 | /set | 934 |
| | | | | DOORS & WINDOWS | | 390 | 1,451 | /sqft | 1,841 |
| | 9000.00 | | | FINISHES | | | | | |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Wd Door & Metal Frame | 1.00 each | 70 | 14 | 84.47 /each | 84 |
| | | | | Paint Int CMU Spray p+2ct | 118.00 sqft | 111 | 33 | 1.22 /sqft | 144 |
| | | | | Painting: Interior | | 181 | 47 | /sqft | 229 |
| | | | | FINISHES | | 181 | 47 | /sqft | 229 |
| | | | | 2I | | 2,565 | 1,958 | | 4,561 |
| | | | | 2 BUILDING CODE | | 23,625 | 15,978 | | 39,690 |

3 EXTERIOR

| | | | | | | | | | |
|--|-----------|--|---------|-------------------------------|---------------|--------|-------|-------------|--------|
| | 3A | | | | | | | | |
| | | | 2050.00 | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 53.40 cuyd | 1,100 | - | 27.17 /cuyd | 1,451 |
| | | | | Demo: General | | 1,100 | | /cuyd | 1,451 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Metal Windows | 5,764.00 sqft | 18,047 | - | 3.13 /sqft | 18,047 |
| | | | | Demo: Doors & Windows | | 18,047 | | /each | 18,047 |
| | | | | DEMOLITION | | 19,147 | | /sqft | 19,498 |
| | | | 4000.00 | MASONRY | | | | | |
| | | | 4156.00 | Access: Wall Flashing | | | | | |
| | | | | Flash Head Lead Ct. Cop 5 oz. | 951.00 sqft | 4,349 | 4,373 | 9.17 /sqft | 8,722 |
| | | | | Flash Sill Lead Ct. Cop 5 oz. | 951.00 sqft | 3,965 | 4,107 | 8.49 /sqft | 8,072 |
| | | | | Access: Wall Flashing | | 8,314 | 8,481 | /sqft | 16,794 |
| | | | | MASONRY | | 8,314 | 8,481 | /sqft | 16,794 |
| | | | 6000.00 | WOOD & PLASTICS | | | | | |
| | | | 6015.00 | Fasteners: Frame Anchors | | | | | |
| | | | | Fasteners & Misc | 1.00 lsum | - | 30 | 30.48 /lsum | 30 |
| | | | | Fasteners: Frame Anchors | | | 30 | /each | 30 |
| | | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | | Rough Bucks 2 x 6 PT Windows | 2,718.00 lnft | 10,332 | 3,070 | 4.93 /lnft | 13,402 |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|--------------------|-----------|----------|----------|--------------------------------------|------------------|----------------|-----------------|-----------------|----------------|
| | | | | Blocking: Rough Bucks | | 10,332 | 3,070 | /mbf | 13,402 |
| | | | | WOOD & PLASTICS | | 10,332 | 3,100 | /sqft | 13,432 |
| | | 7000.00 | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | | Backer Rod ½" | 2,718.00 Inft | 8,239 | 249 | 3.12 /Inft | 8,488 |
| | | | | Polyurethane Sealant 1/2" | 5,436.00 Inft | 51,789 | 2,704 | 10.02 /Inft | 54,493 |
| | | | | Sealant - Jt Filler Gaskt | | 60,028 | 2,953 | /Inft | 62,981 |
| | | 8000.00 | | THERMAL & MOISTURE PROT | | 60,028 | 2,953 | /sqft | 62,981 |
| | | | | DOORS & WINDOWS | | | | | |
| | | | 8520.01 | Window: Aluminum | | | | | |
| | | | | Custom Proj 4" .125 w Ins Gl Kynar | 5,764.00 sqft | 64,974 | 300,295 | 63.37 /sqft | 365,269 |
| | | | | Window: Aluminum | | 64,974 | 300,295 | /sqft | 365,269 |
| | | | | DOORS & WINDOWS | | 64,974 | 300,295 | /sqft | 365,269 |
| | | | | 3A | | 162,796 | 314,829 | | 477,975 |
| | 3B | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 51.30 cuyd | 1,057 | - | 27.17 /cuyd | 1,394 |
| | | | | Demo: General | | 1,057 | | /cuyd | 1,394 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Window Treatment | 5,540.00 sqft | 2,669 | - | 0.48 /sqft | 2,669 |
| | | | | Demo: Doors & Windows | | 2,669 | | /each | 2,669 |
| | | | | DEMOLITION | | 3,725 | | /sqft | 4,062 |
| | | 12000.00 | | FURNISHINGS | | | | | |
| | | | 12520.01 | Shades | | | | | |
| | | | | Vinyl Heavy Wt | 5,540.00 sqft | 6,011 | 17,881 | 4.31 /sqft | 23,892 |
| | | | | Shades | | 6,011 | 17,881 | /sqft | 23,892 |
| | | | | FURNISHINGS | | 6,011 | 17,881 | /sqft | 23,892 |
| | | | | 3B | | 9,736 | 17,881 | | 27,954 |
| | 3C | | | | | | | | |
| | | 8000.00 | | DOORS & WINDOWS | | | | | |
| | | | 8565.00 | Windows: Screens | | | | | |
| | | | | Window Screens/Wicket (Aluminum) | 704.00 sqft | 1,326 | 5,251 | 9.34 /sqft | 6,577 |
| | | | | Windows: Screens | | 1,326 | 5,251 | /each | 6,577 |
| | | | | DOORS & WINDOWS | | 1,326 | 5,251 | /sqft | 6,577 |
| | | | | 3C | | 1,326 | 5,251 | | 6,577 |
| | 3D | | | | | | | | |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9910.01 | Painting: Exterior | | | | | |
| | | | | Paint Ext Wood Door & Frame | 1.00 each | 77 | 14 | 91.35 /each | 91 |
| | | | | Painting: Exterior | | 77 | 14 | /sqft | 91 |
| | | | | FINISHES | | 77 | 14 | /sqft | 91 |
| | | | | 3D | | 77 | 14 | | 91 |
| | | | | 3 EXTERIOR | | 173,935 | 337,975 | | 512,597 |
| 5 HC ACCESS | | | | | | | | | |
| | 5A | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 6.90 cuyd | 142 | - | 27.17 /cuyd | 187 |
| | | | | Demo: General | | 142 | | /cuyd | 187 |
| | | | 2076.00 | Demo: Masonry | | | | | |
| | | | | Sawcut 6" CMU | 24.00 Inft | 679 | - | 46.49 /Inft | 1,116 |
| | | | | Tooth Jams 1 Wythe | 24.00 Inft | 741 | - | 30.89 /Inft | 741 |
| | | | | Remove CMU 6" | 120.00 sqft | 438 | - | 3.97 /sqft | 476 |
| | | | | Demo: Masonry | | 1,858 | | /cuft | 2,333 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Door | 25.00 each | 803 | - | 32.11 /each | 803 |
| | | | | Demo: Doors & Windows | | 803 | | /each | 803 |
| | | | 2088.01 | Demo: Finishes, Floors | | | | | |
| | | | | Flash Patch @ Wall Removal | 10.00 sqft | 23 | 21 | 4.41 /sqft | 44 |
| | | | | Demo: Finishes, Floors | | 23 | 21 | /sqft | 44 |
| | | | | DEMOLITION | | 2,826 | 21 | /sqft | 3,368 |
| | | 8000.00 | | DOORS & WINDOWS | | | | | |
| | | | 8210.01 | Doors: Wood | | | | | |
| | | | | Rehang Door | 25.00 each | 3,257 | 0 | 130.27 /each | 3,257 |
| | | | | Doors: Wood | | 3,257 | | /each | 3,257 |
| | | | | DOORS & WINDOWS | | 3,257 | | /sqft | 3,257 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9210.01 | Lath/Plastr: Gyp Plaster | | | | | |
| | | | | Plaster Patch @ Wall Removal | 24.00 sqft | 400 | 43 | 18.83 /sqft | 452 |
| | | | | Plaster Patch Ceiling @ Wall Removal | 10.00 sqft | 54 | 16 | 7.17 /sqft | 72 |
| | | | | Lath/Plastr: Gyp Plaster | | 454 | 59 | /sqft | 524 |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Wd Door & Metal Frame & Prep | 25.00 each | 2,106 | 394 | 99.98 /each | 2,499 |
| | | | | Painting: Interior | | 2,106 | 394 | /sqft | 2,499 |
| | | | | FINISHES | | 2,560 | 452 | /sqft | 3,023 |
| | | | | 5A | | 8,642 | 474 | | 9,647 |
| | 5B | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 35.10 cuyd | 723 | - | 27.17 /cuyd | 954 |
| | | | | Demo: General | | 723 | | /cuyd | 954 |
| | | | 2080.01 | Demo: Millwork | | | | | |
| | | | | Remove Casework | 131.00 Inft | 684 | - | 5.22 /Inft | 684 |
| | | | | Demo: Millwork | | 684 | | /sqft | 684 |
| | | | 2088.60 | Demo: Plumbing | | | | | |
| | | | | Remove Sink | 27.00 each | 3,317 | - | 122.85 /each | 3,317 |
| | | | | Demo: Plumbing | | 3,317 | | /sqft | 3,317 |
| | | | | DEMOLITION | | 4,723 | | /sqft | 4,954 |
| | | 6000.00 | | WOOD & PLASTICS | | | | | |
| | | | 6113.20 | Blocking: Misc. | | | | | |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|----------|----------|-----------------------------------|------------------|---------------|-----------------|-----------------|---------------|
| | | | 6113.20 | Blocking: Misc. | | | | | |
| | | | | Blocking 2 x 6 R.L. | 131.00 Inft | 450 | 89 | 4.11 /Inft | 539 |
| | | | | Blocking: Misc. | | 450 | 89 | /mbf | 539 |
| | | | | WOOD & PLASTICS | | 450 | 89 | /sqft | 539 |
| | | 12000.00 | | FURNISHINGS | | | | | |
| | | | 12350.00 | Casework | | | | | |
| | | | | School Casework Base & Top | 131.00 Inft | 13,191 | 32,127 | 345.94 /Inft | 45,317 |
| | | | | Casework | | 13,191 | 32,127 | /Inft | 45,317 |
| | | | | FURNISHINGS | | 13,191 | 32,127 | /sqft | 45,317 |
| | | | | 5B | | 18,364 | 32,216 | | 50,810 |
| 5C | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 3.60 cuyd | 74 | - | 27.17 /cuyd | 98 |
| | | | | Demo: General | | 74 | | /cuyd | 98 |
| | | | 2080.01 | Demo: Millwork | | | | | |
| | | | | Remove Casework | 16.00 Inft | 83 | - | 5.22 /Inft | 83 |
| | | | | Demo: Millwork | | 83 | | /sqft | 83 |
| | | | | DEMOLITION | | 158 | | /sqft | 181 |
| | | 6000.00 | | WOOD & PLASTICS | | | | | |
| | | | 6113.20 | Blocking: Misc. | | | | | |
| | | | | Blocking 2 x 6 R.L. | 16.00 Inft | 55 | 11 | 4.12 /Inft | 66 |
| | | | | Blocking: Misc. | | 55 | 11 | /mbf | 66 |
| | | | | WOOD & PLASTICS | | 55 | 11 | /sqft | 66 |
| | | 12000.00 | | FURNISHINGS | | | | | |
| | | | 12620.00 | Furniture | | | | | |
| | | | | Library Charge Desk | 16.00 Inft | 1,654 | 5,286 | 433.73 /Inft | 6,940 |
| | | | | Furniture | | 1,654 | 5,286 | /Inft | 6,940 |
| | | | | FURNISHINGS | | 1,654 | 5,286 | /sqft | 6,940 |
| | | | | 5C | | 1,866 | 5,297 | | 7,187 |
| 5D | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 0.40 cuyd | 8 | - | 27.15 /cuyd | 11 |
| | | | | Demo: General | | 8 | | /cuyd | 11 |
| | | | 2088.60 | Demo: Plumbing | | | | | |
| | | | | Remove Drinking Fountain | 2.00 each | 328 | - | 163.76 /each | 328 |
| | | | | Demo: Plumbing | | 328 | | /sqft | 328 |
| | | | | DEMOLITION | | 336 | | /sqft | 338 |
| | | | | 5D | | 336 | | | 338 |
| 5E | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2084.50 | Demo: Misc Items | | | | | |
| | | | | Remove TV | 12.00 each | 723 | - | 60.21 /each | 723 |
| | | | | Demo: Misc Items | | 723 | | /sqft | 723 |
| | | | | DEMOLITION | | 723 | | /sqft | 723 |
| | | | | 5E | | 723 | | | 723 |
| 5F | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 0.10 cuyd | 2 | - | 27.30 /cuyd | 3 |
| | | | | Demo: General | | 2 | | /cuyd | 3 |
| | | | 2077.00 | Demo: Steel | | | | | |
| | | | | Remove Steel Rail | 9.00 Inft | 90 | - | 10.04 /Inft | 90 |
| | | | | Demo: Steel | | 90 | | /each | 90 |
| | | | | DEMOLITION | | 92 | | /sqft | 93 |
| | | 5000.00 | | METALS | | | | | |
| | | | 5510.80 | Stairs: Stair Parts | | | | | |
| | | | | Stair Railing Steel 1-1/2" 6 pipe | 9.00 Inft | 534 | 877 | 159.66 /Inft | 1,437 |
| | | | | Stairs: Stair Parts | | 534 | 877 | /ft | 1,437 |
| | | | | METALS | | 534 | 877 | /sqft | 1,437 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Int Pipe Rails | 54.00 Inft | 69 | 12 | 1.50 /Inft | 81 |
| | | | | Painting: Interior | | 69 | 12 | /sqft | 81 |
| | | | | FINISHES | | 69 | 12 | /sqft | 81 |
| | | | | 5F | | 696 | 888 | | 1,611 |
| 5G | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 2.40 cuyd | 49 | - | 27.17 /cuyd | 65 |
| | | | | Demo: General | | 49 | | /cuyd | 65 |
| | | | 2084.50 | Demo: Misc Items | | | | | |
| | | | | Remove Toilet Partitions | 5.00 each | 401 | - | 80.28 /each | 401 |
| | | | | Remove Toilet Accessories | 16.00 each | 161 | - | 10.04 /each | 161 |
| | | | | Demo: Misc Items | | 562 | | /sqft | 562 |
| | | | | DEMOLITION | | 611 | | /sqft | 627 |
| | | 6000.00 | | WOOD & PLASTICS | | | | | |
| | | | 6113.20 | Blocking: Misc. | | | | | |
| | | | | Block Toilet Partition | 6.00 each | 181 | 72 | 42.06 /each | 252 |
| | | | | Block H.C. Toilet Partition | 2.00 each | 90 | 29 | 59.96 /each | 120 |
| | | | | Block Misc Toilet Accessories | 31.00 each | 561 | 156 | 23.10 /each | 716 |
| | | | | Blocking: Misc. | | 832 | 257 | /mbf | 1,088 |
| | | | | WOOD & PLASTICS | | 832 | 257 | /sqft | 1,088 |
| | | 10000.00 | | SPECIALTIES | | | | | |
| | | | 10160.02 | Toilet Partition Phenolic | | | | | |
| | | | | Toilet Partition Reg Flr Mtd | 3.00 each | 636 | 4,353 | 1,663.08 /each | 4,989 |
| | | | | Toilet Partition HC Flr Mtd | 2.00 each | 424 | 3,342 | 1,882.92 /each | 3,766 |
| | | | | Urinal Screens Wall Hung | 3.00 each | 445 | 1,395 | 613.42 /each | 1,840 |
| | | | | Toilet Partition Phenolic | | 1,505 | 9,091 | /each | 10,595 |
| | | | 10800.01 | Toilet Accessories | | | | | |
| | | | | Grab Bar 1-1/4" S.S. 36" | 4.00 each | 145 | 156 | 75.12 /each | 300 |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|---------|----------|------------------------------------|------------------|--------------|-----------------|-----------------|---------------|
| | | | 10800.01 | Toilet Accessories | | | | | |
| | | | | Mirror 18" x 30" S.S. | 4.00 each | 188 | 321 | 127.27 /each | 509 |
| | | | | Sanitary Napkin Dispenser Recessed | 1.00 each | 48 | 1,036 | 1,083.80 /each | 1,084 |
| | | | | Clothes Hook Single | 5.00 each | 100 | 96 | 39.26 /each | 196 |
| | | | | Soap Dispenser | 4.00 each | 289 | 828 | 279.46 /each | 1,118 |
| | | | | Stainless Steel Shelf | 6.00 Inft | 99 | 228 | 54.52 /Inft | 327 |
| | | | | Toilet Tissue Disp Dbl | 5.00 each | 151 | 138 | 57.62 /each | 288 |
| | | | | Towel Disp/Waste Recpt | 2.00 each | 289 | 1,355 | 821.95 /each | 1,644 |
| | | | | Toilet Accessories | | 1,309 | 4,157 | /each | 5,467 |
| | | | | SPECIALTIES | | 2,814 | 13,248 | /sqft | 16,062 |
| | | | | 5G | | 4,257 | 13,505 | | 17,778 |
| 5H | | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 30.20 cuyd | 622 | - | 27.17 /cuyd | 821 |
| | | | | Demo: General | | 622 | | /cuyd | 821 |
| | | | 2075.00 | Demo: Concrete | | | | | |
| | | | | Saw Concrete Slab to 6" | 200.00 Inft | 1,090 | - | 7.56 /Inft | 1,512 |
| | | | | Chip out Slab | 160.00 sqft | 1,978 | 14 | 14.12 /sqft | 2,259 |
| | | | | Demo: Concrete | | 3,069 | 14 | /cuyd | 3,771 |
| | | | 2076.00 | Demo: Masonry | | | | | |
| | | | | Remove CMU 6" | 2,004.00 sqft | 7,307 | - | 3.97 /sqft | 7,948 |
| | | | | Demo: Masonry | | 7,307 | | /cuft | 7,948 |
| | | | 2084.50 | Demo: Misc Items | | | | | |
| | | | | Remove Toilet Partitions | 11.00 each | 883 | - | 80.28 /each | 883 |
| | | | | Remove Urinal Screen | 3.00 each | 169 | - | 56.20 /each | 169 |
| | | | | Remove Toilet Accessories | 60.00 each | 602 | - | 10.04 /each | 602 |
| | | | | Demo: Misc Items | | 1,654 | | /sqft | 1,654 |
| | | | 2088.01 | Demo: Finishes, Floors | | | | | |
| | | | | Remove Ceramic Tile Floor | 640.00 sqft | 1,182 | - | 1.85 /sqft | 1,182 |
| | | | | Flash Patch @ Wall Removal | 167.00 sqft | 385 | 352 | 4.41 /sqft | 737 |
| | | | | Demo: Finishes, Floors | | 1,566 | 352 | /sqft | 1,919 |
| | | | 2088.50 | Demo: Finishes, Ceilings | | | | | |
| | | | | Remove Plaster Ceiling Metal Lath | 640.00 sqft | 1,439 | - | 2.25 /sqft | 1,439 |
| | | | | Demo: Finishes, Ceilings | | 1,439 | | /sqft | 1,439 |
| | | | 2088.60 | Demo: Plumbing | | | | | |
| | | | | Remove Sink | 15.00 each | 1,843 | - | 122.85 /each | 1,843 |
| | | | | Remove Water Closet | 19.00 each | 2,668 | - | 140.41 /each | 2,668 |
| | | | | Remove Urinal | 6.00 each | 1,474 | - | 245.69 /each | 1,474 |
| | | | | Demo: Plumbing | | 5,985 | | /sqft | 5,985 |
| | | | | DEMOLITION | | 21,641 | 366 | /sqft | 23,535 |
| | | 3000.00 | | CONCRETE | | | | | |
| | | | 3310.01 | Conc: Slabs On Grade | | | | | |
| | | | | Patch Conc. Slab Trench etc. | 160.00 sqft | 867 | 1,891 | 17.24 /sqft | 2,758 |
| | | | | Conc: Slabs On Grade | | 867 | 1,891 | /cuyd | 2,758 |
| | | | | CONCRETE | | 867 | 1,891 | /sqft | 2,758 |
| | | 4000.00 | | MASONRY | | | | | |
| | | | 4050.10 | Misc: Scaffold | | | | | |
| | | | | Interior Scaffold | 2,160.00 sqft | 2,402 | 906 | 1.77 /sqft | 3,822 |
| | | | | Misc: Scaffold | | 2,402 | 906 | /sqft | 3,822 |
| | | | 4050.15 | Misc: Material Handling | | | | | |
| | | | | Concrete Block | 2.43 m | - | - | 262.94 /m | 639 |
| | | | | Misc: Material Handling | | | | /m | 639 |
| | | | 4105.00 | Mortar: All Types | | | | | |
| | | | | Mortar Type "N" | 4.50 cuyd | 546 | 975 | 337.98 /cuyd | 1,521 |
| | | | | Mortar: All Types | | 546 | 975 | /cuyd | 1,521 |
| | | | 4110.01 | Mortar: Grout Fill Conc | | | | | |
| | | | | Grout Fill 3000 psi, 1/2" Gravl | 1.72 cuyd | 484 | 331 | 494.63 /cuyd | 851 |
| | | | | Grout Single Door Frame | 10.00 each | 636 | 204 | 88.73 /each | 887 |
| | | | | Mortar: Grout Fill Conc | | 1,121 | 535 | /cuyd | 1,738 |
| | | | 4157.00 | Reinforce: Vertical Wall | | | | | |
| | | | | Re-Bar #5 & #6 | 375.48 lbs | 759 | 401 | 3.09 /lbs | 1,159 |
| | | | | Reinforce: Vertical Wall | | 759 | 401 | /lbs | 1,159 |
| | | | 4158.00 | Reinforce: Horizontl Wall | | | | | |
| | | | | Horiz Wall Reinf 6" Hot Dippd | 1.62 mlf | 721 | 276 | 615.61 /mlf | 997 |
| | | | | Reinforce: Horizontl Wall | | 721 | 276 | /mlf | 997 |
| | | | 4221.20 | Conc. Block: 6" | | | | | |
| | | | | Blk 6" Standard Face Reg Wt | 2,295.00 each | 28,064 | 5,156 | 14.48 /each | 33,220 |
| | | | | Conc. Block: 6" | | 28,064 | 5,156 | /each | 33,220 |
| | | | 4221.50 | Conc. Block: 6" Lintel | | | | | |
| | | | | Lintel 6" Stand Face Reg Wt | 135.00 each | 2,508 | 887 | 26.60 /each | 3,591 |
| | | | | Conc. Block: 6" Lintel | | 2,508 | 887 | /each | 3,591 |
| | | | | MASONRY | | 36,121 | 9,134 | /sqft | 46,688 |
| | | 5000.00 | | METALS | | | | | |
| | | | 5510.35 | Misc: Bolt On Material | | | | | |
| | | | | Angle Bolted To Masonry | 644.00 lb | 2,276 | 1,939 | 6.74 /lb | 4,342 |
| | | | | Misc: Bolt On Material | | 2,276 | 1,939 | /lbs | 4,342 |
| | | | | METALS | | 2,276 | 1,939 | /sqft | 4,342 |
| | | 6000.00 | | WOOD & PLASTICS | | | | | |
| | | | 6113.20 | Blocking: Misc. | | | | | |
| | | | | Block Toilet Partition | 7.00 each | 211 | 84 | 42.05 /each | 294 |
| | | | | Block H.C. Toilet Partition | 2.00 each | 90 | 29 | 59.96 /each | 120 |
| | | | | Block Misc Toilet Accessories | 113.00 each | 2,044 | 567 | 23.10 /each | 2,611 |
| | | | | Blocking: Misc. | | 2,345 | 680 | /mbf | 3,025 |
| | | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | | Rough Bucks 2 x 6 Doors | 170.00 Inft | 426 | 115 | 3.18 /Inft | 541 |
| | | | | Blocking: Rough Bucks | | 426 | 115 | /mbf | 541 |
| | | | | WOOD & PLASTICS | | 2,770 | 796 | /sqft | 3,566 |
| | | 7000.00 | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7910.01 | Sealant - Jt Filler Gasket | | | | | |
| | | | | Polysulfide Sealant 1/4" Interior | 170.00 Inft | 1,595 | 38 | 9.61 /Inft | 1,633 |
| | | | | Sealant - Jt Filler Gasket | | 1,595 | 38 | /Inft | 1,633 |
| | | | | THERMAL & MOISTURE PROT | | 1,595 | 38 | /sqft | 1,633 |
| | | 8000.00 | | DOORS & WINDOWS | | | | | |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|-------|----------|---|------------------|----------------|-----------------|-----------------|----------------|
| | | | 8110.01 | Doors: Steel with Frames | | | | | |
| | | | | H.M. Frame 18ga Interior Single | 10.00 each | 989 | 1,728 | 271.74 /each | 2,717 |
| | | | | Doors: Steel with Frames | | 989 | 1,728 | /each | 2,717 |
| | | | 8210.01 | Doors: Wood | | | | | |
| | | | | Door M Core 3-0 x 7-0 Louver | 10.00 each | 1,380 | 4,981 | 636.08 /each | 6,361 |
| | | | | Doors: Wood | | 1,380 | 4,981 | /each | 6,361 |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Int Budget w Closure | 10.00 each | 1,356 | 7,980 | 933.63 /each | 9,336 |
| | | | | Hardware: Finishing | | 1,356 | 7,980 | /set | 9,336 |
| | | | | DOORS & WINDOWS | | 3,725 | 14,689 | /sqft | 18,414 |
| | 9000.00 | | | FINISHES | | | | | |
| | | | 9210.01 | Lath/Plastr: Gyp Plaster | | | | | |
| | | | | Plaster Patch @ Wall Removal | 228.00 sqft | 3,796 | 405 | 18.83 /sqft | 4,294 |
| | | | | Plaster Patch Ceiling @ Wall Removal | 167.00 sqft | 908 | 266 | 7.17 /sqft | 1,198 |
| | | | | Lath/Plastr: Gyp Plaster | | 4,705 | 671 | /sqft | 5,492 |
| | | | 9253.30 | GWB: Boards & Sheathing | | | | | |
| | | | | GWB 5/8" Water Resistant Clgs | 640.00 sqft | 593 | 277 | 1.36 /sqft | 871 |
| | | | | GWB: Boards & Sheathing | | 593 | 277 | /sqft | 871 |
| | | | 9254.00 | GWB: Finish Mud/Tape | | | | | |
| | | | | Labor GWB Ceiling Finish | 640.00 sqft | 713 | 49 | 1.19 /sqft | 762 |
| | | | | GWB: Finish Mud/Tape | | 713 | 49 | /sqft | 762 |
| | | | 9310.01 | Ceramic Tile | | | | | |
| | | | | Ceramic Tile Floor Grade 2 | 640.00 sqft | 8,916 | 3,887 | 20.00 /sqft | 12,802 |
| | | | | Ceramic Trim: Cove Base | 320.00 lnft | 8,199 | 1,395 | 29.98 /lnft | 9,594 |
| | | | | Ceramic Tile | | 17,115 | 5,281 | /sqft | 22,396 |
| | | | 9510.10 | Ceiling: Susp. System | | | | | |
| | | | | Susp Clg 1-1/2" Channel | 640.00 sqft | 2,149 | 1,000 | 4.92 /sqft | 3,149 |
| | | | | Ceiling: Susp. System | | 2,149 | 1,000 | /sqft | 3,149 |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Wd Door & Metal Frame | 10.00 each | 702 | 143 | 84.47 /each | 845 |
| | | | | Epoxy Paint GDW Clg | 640.00 sqft | 1,481 | 504 | 3.10 /sqft | 1,985 |
| | | | | Paint Int CMU Spray p+2ct | 1,800.00 sqft | 1,696 | 503 | 1.22 /sqft | 2,200 |
| | | | | Epoxy Paint Int CMU | 1,800.00 sqft | 4,164 | 1,510 | 3.15 /sqft | 5,674 |
| | | | | Epoxy Paint Exist Int CMU | 1,800.00 sqft | 2,622 | 1,006 | 2.02 /sqft | 3,628 |
| | | | | Painting: Interior | | 10,664 | 3,666 | /sqft | 14,331 |
| | | | | FINISHES | | 35,939 | 10,945 | /sqft | 47,000 |
| | 10000.00 | | | SPECIALTIES | | | | | |
| | | | 10160.02 | Toilet Partition Phenolic | | | | | |
| | | | | Toilet Partition Reg Flr Mtd | 7.00 each | 1,484 | 10,158 | 1,663.08 /each | 11,642 |
| | | | | Toilet Partition HC Flr Mtd | 2.00 each | 424 | 3,342 | 1,882.92 /each | 3,766 |
| | | | | Toilet Partition Phenolic | | 1,908 | 13,500 | /each | 15,407 |
| | | | 10800.01 | Toilet Accessories | | | | | |
| | | | | Grab Bar 1-1/4" S.S. 36" | 22.00 each | 796 | 857 | 75.12 /each | 1,653 |
| | | | | Mirror 18" x 30" S.S. | 15.00 each | 705 | 1,204 | 127.26 /each | 1,909 |
| | | | | Sanitary Napkin Dispenser Recessed | 1.00 each | 48 | 1,036 | 1,083.81 /each | 1,084 |
| | | | | Clothes Hook Single | 8.00 each | 161 | 154 | 39.26 /each | 314 |
| | | | | Soap Dispenser | 15.00 each | 1,085 | 3,107 | 279.46 /each | 4,192 |
| | | | | Stainless Steel Shelf | 23.00 lnft | 379 | 875 | 54.51 /lnft | 1,254 |
| | | | | Toilet Tissue Disp Dbl | 18.00 each | 542 | 495 | 57.62 /each | 1,037 |
| | | | | Towel Dispenser Surface Mtd | 9.00 each | 407 | 484 | 99.03 /each | 891 |
| | | | | Towel Disp/Waste Recpt | 2.00 each | 289 | 1,355 | 821.95 /each | 1,644 |
| | | | | Toilet Accessories | | 4,412 | 9,566 | /each | 13,977 |
| | | | | SPECIALTIES | | 6,319 | 23,066 | /sqft | 29,385 |
| | | | | 5H | | 111,253 | 62,863 | | 177,321 |
| 5K | | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 5.30 cuyd | 109 | - | 27.17 /cuyd | 144 |
| | | | | Shore - Screw Jack | 12.00 each | 12,770 | 820 | 1,196.92 /each | 14,363 |
| | | | | Demo: General | | 12,879 | 820 | /cuyd | 14,507 |
| | | | 2076.00 | Demo: Masonry | | | | | |
| | | | | Cut Out Opng 6" CMU | 84.00 sqft | 2,396 | - | 31.03 /sqft | 2,606 |
| | | | | Sawcut 6" CMU | 96.00 lnft | 2,716 | - | 46.49 /lnft | 4,463 |
| | | | | Tooth Jamb's 1 Wythe | 85.00 lnft | 2,626 | - | 30.89 /lnft | 2,626 |
| | | | | Demo: Masonry | | 7,737 | | /cuft | 9,695 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Door & Frame Int Single | 12.00 each | 1,349 | - | 127.52 /each | 1,530 |
| | | | | Demo: Doors & Windows | | 1,349 | | /each | 1,530 |
| | | | | DEMOLITION | | 21,965 | 820 | /sqft | 25,732 |
| | 4000.00 | | | MASONRY | | | | | |
| | | | 4110.01 | Mortar: Grout Fill Conc | | | | | |
| | | | | Grout Single Door Frame | 12.00 each | 764 | 245 | 88.73 /each | 1,065 |
| | | | | Mortar: Grout Fill Conc | | 764 | 245 | /cuyd | 1,065 |
| | | | | MASONRY | | 764 | 245 | /sqft | 1,065 |
| | 6000.00 | | | WOOD & PLASTICS | | | | | |
| | | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | | Rough Bucks 2 x 6 Doors | 204.00 lnft | 511 | 138 | 3.18 /lnft | 649 |
| | | | | Blocking: Rough Bucks | | 511 | 138 | /mbf | 649 |
| | | | | WOOD & PLASTICS | | 511 | 138 | /sqft | 649 |
| | 7000.00 | | | THERMAL & MOISTURE PROT | | | | | |
| | | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | | Polysulfide Sealant 1/4" Interior | 204.00 lnft | 1,914 | 45 | 9.61 /lnft | 1,959 |
| | | | | Sealant - Jt Filler Gaskt | | 1,914 | 45 | /lnft | 1,959 |
| | | | | THERMAL & MOISTURE PROT | | 1,914 | 45 | /sqft | 1,959 |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | | 8110.01 | Doors: Steel with Frames | | | | | |
| | | | | H.M. Frame 18ga Interior Single | 12.00 each | 1,187 | 2,074 | 271.74 /each | 3,261 |
| | | | | Doors: Steel with Frames | | 1,187 | 2,074 | /each | 3,261 |
| | | | 8210.01 | Doors: Wood | | | | | |
| | | | | Door M Core 3-0 x 7-0 Vision | 12.00 each | 1,563 | 5,108 | 555.95 /each | 6,671 |
| | | | | Doors: Wood | | 1,563 | 5,108 | /each | 6,671 |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Int Budget w Closure | 12.00 each | 1,628 | 9,576 | 933.63 /each | 11,204 |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|-----------------------|----------|----------|----------|---|------------------|----------------|-----------------|-----------------|----------------|
| | | | | Hardware: Finishing | | 1,628 | 9,576 | /set | 11,204 |
| | | | | DOORS & WINDOWS | | 4,378 | 16,758 | /sqft | 21,136 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9920.01 | Painting: Interior | | | | | |
| | | | | Paint Wd Door & Metal Frame | 12.00 each | 842 | 172 | /each | 1,014 |
| | | | | Painting: Interior | | 842 | 172 | /sqft | 1,014 |
| | | | | FINISHES | | 842 | 172 | /sqft | 1,014 |
| | | | | 5K | | 30,374 | 18,178 | | 51,555 |
| | 5L | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 0.60 cuyd | 12 | - | 27.18 /cuyd | 16 |
| | | | | Demo: General | | 12 | | /cuyd | 16 |
| | | | 2075.00 | Demo: Concrete | | | | | |
| | | | | Saw Concrete Slab to 6" | 24.00 Inft | 131 | - | 7.56 /Inft | 181 |
| | | | | Chip out Slab | 35.00 sqft | 433 | 3 | 14.12 /sqft | 494 |
| | | | | Demo: Concrete | | 564 | 3 | /cuyd | 676 |
| | | | | DEMOLITION | | 576 | 3 | /sqft | 692 |
| | | 14000.00 | | CONVEYING SYSTEMS | | | | | |
| | | | 14405.00 | Lifts | | | | | |
| | | | | Lift Commercial | 1.00 each | 2,989 | 15,345 | 18,491.40 /each | 18,491 |
| | | | | Lifts | | 2,989 | 15,345 | /each | 18,491 |
| | | | | CONVEYING SYSTEMS | | 2,989 | 15,345 | /sqft | 18,491 |
| | | | | 5L | | 3,565 | 15,348 | | 19,183 |
| | 5N | | | | | | | | |
| | | 3000.00 | | CONCRETE | | | | | |
| | | | 3131.00 | Forms: Ramps | | | | | |
| | | | | Ramp Forms 2 use | 214.00 Inft | 1,693 | 381 | 9.69 /Inft | 2,073 |
| | | | | Forms: Ramps | | 1,693 | 381 | /Inft | 2,073 |
| | | | 3225.00 | Rebar: WWM @ Ramp/Misc | | | | | |
| | | | | Wiremesh - Ramp 6x6 6/6 | 1.76 sqs | 122 | 90 | 119.99 /sqs | 211 |
| | | | | Rebar: WWM @ Ramp/Misc | | 122 | 90 | /sqs | 211 |
| | | | 3309.50 | Conc: Ramps | | | | | |
| | | | | Ramp Conc 4000 psi | 3.26 cuyd | 150 | 462 | 196.65 /cuyd | 641 |
| | | | | Conc: Ramps | | 150 | 462 | /cuyd | 641 |
| | | | 3375.00 | Finish: Protect & Cure | | | | | |
| | | | | Cure Conc w/burlap Ramp | 1.76 sqs | 45 | 21 | 37.43 /sqs | 66 |
| | | | | Finish: Protect & Cure | | 45 | 21 | /sqs | 66 |
| | | | 3380.01 | Finish: General | | | | | |
| | | | | Broom/Float Finish Ramp | 176.00 sqft | 155 | - | 0.88 /sqft | 155 |
| | | | | Finish: General | | 155 | | /sqft | 155 |
| | | | | CONCRETE | | 2,165 | 953 | /sqft | 3,147 |
| | | | | 5N | | 2,165 | 953 | | 3,147 |
| | 5P | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Hardware | 2.00 each | 90 | - | 45.22 /each | 90 |
| | | | | Demo: Doors & Windows | | 90 | | /each | 90 |
| | | | | DEMOLITION | | 90 | | /sqft | 90 |
| | | 8000.00 | | DOORS & WINDOWS | | | | | |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Ext Budget | 2.00 each | 452 | 2,407 | 1,429.40 /each | 2,859 |
| | | | | Hardware: Finishing | | 452 | 2,407 | /set | 2,859 |
| | | | | DOORS & WINDOWS | | 452 | 2,407 | /sqft | 2,859 |
| | | | | 5P | | 543 | 2,407 | | 2,949 |
| | 5Q | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2075.00 | Demo: Concrete | | | | | |
| | | | | Remove Locker Base | 8.00 Inft | 136 | - | 20.38 /Inft | 163 |
| | | | | Demo: Concrete | | 136 | | /cuyd | 163 |
| | | | 2084.50 | Demo: Misc Items | | | | | |
| | | | | Relocate Lockers | 8.00 each | 826 | - | 103.24 /each | 826 |
| | | | | Demo: Misc Items | | 826 | | /sqft | 826 |
| | | | | DEMOLITION | | 962 | | /sqft | 989 |
| | | | | 5Q | | 962 | | | 989 |
| | 5T | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 5.50 cuyd | 113 | - | 27.17 /cuyd | 149 |
| | | | | Demo: General | | 113 | | /cuyd | 149 |
| | | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | | Remove Hardware | 151.00 each | 6,827 | - | 45.21 /each | 6,827 |
| | | | | Demo: Doors & Windows | | 6,827 | | /each | 6,827 |
| | | | | DEMOLITION | | 6,940 | | /sqft | 6,976 |
| | | 8000.00 | | DOORS & WINDOWS | | | | | |
| | | | 8710.01 | Hardware: Finishing | | | | | |
| | | | | Finishing Hardware Ext Budget | 20.00 each | 4,521 | 24,067 | 1,429.40 /each | 28,588 |
| | | | | Finishing Hardware Int Budget w Closure | 131.00 each | 17,768 | 104,537 | 933.63 /each | 122,305 |
| | | | | Hardware: Finishing | | 22,289 | 128,604 | /set | 150,893 |
| | | | | DOORS & WINDOWS | | 22,289 | 128,604 | /sqft | 150,893 |
| | | | | 5T | | 29,229 | 128,604 | | 157,869 |
| | | | | 5 HC ACCESS | | 212,973 | 280,733 | | 501,107 |
| 6 FINISHES GEN | | | | | | | | | |
| | 6A | | | | | | | | |
| | | 2050.00 | | DEMOLITION | | | | | |
| | | | 2071.01 | Demo: General | | | | | |
| | | | | General Disposal | 8.20 cuyd | 169 | - | 27.17 /cuyd | 223 |
| | | | | Demo: General | | 169 | | /cuyd | 223 |
| | | | 2088.50 | Demo: Finishes, Ceilings | | | | | |
| | | | | Remove Acoust Tile | 880.00 sqft | 1,272 | - | 1.45 /sqft | 1,272 |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|---------|----------|-------------------------------------|------------------|----------------|-----------------|-----------------|----------------|
| | | | | Demo: Finishes, Ceilings | | 1,272 | | /sqft | 1,272 |
| | | | | DEMOLITION | | 1,441 | | /sqft | 1,494 |
| | | 9000.00 | | FINISHES | | | | | |
| | | | 9510.50 | Ceiling: 2x4 Tile | | | | | |
| | | | | MinFbr Tegulr Std 2x4 3/4" < 250 sf | 880.00 sqft | 2,868 | 2,995 | 6.66 /sqft | 5,862 |
| | | | | Ceiling: 2x4 Tile | | 2,868 | 2,995 | /sqft | 5,862 |
| | | | | FINISHES | | 2,868 | 2,995 | /sqft | 5,862 |
| | | | | 6A | | 4,308 | 2,995 | | 7,357 |
| | | 6B | | | | | | | |
| | | | 4000.00 | MASONRY | | | | | |
| | | | | Masonry Restoration | | | | | |
| | | | 4520.01 | Cut & Repoint CMU Hard Mortar | 150.00 lnft | 1,552 | 208 | 14.56 /lnft | 2,183 |
| | | | | Cut & Repoint Brick Soft Mortr | 150.00 sqft | 1,083 | 108 | 9.88 /sqft | 1,482 |
| | | | | Remove Individual Brick Allow | 1,013.00 each | 68,109 | - | 85.38 /each | 86,486 |
| | | | | Patch Individual Brick Allow | 1,013.00 each | 18,134 | 1,460 | 19.34 /each | 19,594 |
| | | | | Remove CMU 8" Allow | 169.00 each | 10,078 | - | 64.87 /each | 10,963 |
| | | | | Patch in 8" CMU Allow | 169.00 each | 5,028 | 451 | 32.42 /each | 5,479 |
| | | | | Masonry Restoration | | 103,984 | 2,227 | /m | 126,187 |
| | | | | MASONRY | | 103,984 | 2,227 | /sqft | 126,187 |
| | | | | 6B | | 103,984 | 2,227 | | 126,187 |
| | | 6E | | | | | | | |
| | | | 2050.00 | DEMOLITION | | | | | |
| | | | | Demo: General | | | | | |
| | | | 2071.01 | General Disposal | 0.20 cuyd | 4 | - | 27.15 /cuyd | 5 |
| | | | | Demo: General | | 4 | | /cuyd | 5 |
| | | | 2088.70 | Demo: Mechanical | | | | | |
| | | | | Remove Louvers | 5.00 sqft | 57 | - | 11.48 /sqft | 57 |
| | | | | Demo: Mechanical | | 57 | | /sqft | 57 |
| | | | | DEMOLITION | | 62 | | /sqft | 63 |
| | | | 5000.00 | METALS | | | | | |
| | | | | Misc: Lintels | | | | | |
| | | | 5510.05 | Stl Angles 1000 - 2000 lbs | 49.00 lb | 92 | 72 | 3.34 /lb | 164 |
| | | | | Misc: Lintels | | 92 | 72 | /lbs | 164 |
| | | | | METALS | | 92 | 72 | /sqft | 164 |
| | | | 6000.00 | WOOD & PLASTICS | | | | | |
| | | | | Blocking: Rough Bucks | | | | | |
| | | | 6113.40 | 2 x 6 PT Louvers | 5.00 lnft | 13 | 6 | 3.82 /lnft | 19 |
| | | | | Blocking: Rough Bucks | | 13 | 6 | /mbf | 19 |
| | | | | WOOD & PLASTICS | | 13 | 6 | /sqft | 19 |
| | | | 7000.00 | THERMAL & MOISTURE PROT | | | | | |
| | | | | Sealant - Jt Filler Gaskt | | | | | |
| | | | 7910.01 | Backer Rod 1/2" | 12.00 lnft | 36 | 1 | 3.12 /lnft | 37 |
| | | | | Polysulfide Sealant 1/4" Interior | 24.00 lnft | 225 | 5 | 9.61 /lnft | 231 |
| | | | | Sealant - Jt Filler Gaskt | | 262 | 6 | /lnft | 268 |
| | | | | THERMAL & MOISTURE PROT | | 262 | 6 | /sqft | 268 |
| | | | 9000.00 | FINISHES | | | | | |
| | | | | Painting: Interior | | | | | |
| | | | 9920.01 | Paint Louvers | 5.00 sqft | 9 | 2 | 2.06 /sqft | 10 |
| | | | | Painting: Interior | | 9 | 2 | /sqft | 10 |
| | | | | FINISHES | | 9 | 2 | /sqft | 10 |
| | | | 15500.00 | HVAC SYSTEMS | | | | | |
| | | | | Louvers/Filters | | | | | |
| | | | 15856.00 | Fixed Blade Stormproof | 5.00 sqft | 192 | 221 | 82.62 /sqft | 413 |
| | | | | Louvers/Filters | | 192 | 221 | /sqft | 413 |
| | | | | HVAC SYSTEMS | | 192 | 221 | /sqft | 413 |
| | | | | 6E | | 629 | 306 | | 937 |
| | | 6H | | | | | | | |
| | | | 9000.00 | FINISHES | | | | | |
| | | | | Painting: Interior | | | | | |
| | | | 9920.01 | Paint Exist Int CMU Spray 2 ct | 1,059.00 sqft | 454 | 188 | 0.61 /sqft | 642 |
| | | | | Painting: Interior | | 454 | 188 | /sqft | 642 |
| | | | | FINISHES | | 454 | 188 | /sqft | 642 |
| | | | | 6H | | 454 | 188 | | 642 |
| | | 6J | | | | | | | |
| | | | 8000.00 | DOORS & WINDOWS | | | | | |
| | | | | Glass: All Types | | | | | |
| | | | 8811.00 | Reglaze Insulated Tinted Glass | 84.00 sqft | 4,855 | 2,343 | 85.69 /sqft | 7,198 |
| | | | | Glass: All Types | | 4,855 | 2,343 | /sqft | 7,198 |
| | | | | DOORS & WINDOWS | | 4,855 | 2,343 | /sqft | 7,198 |
| | | | | 6J | | 4,855 | 2,343 | | 7,198 |
| | | 6KK | | | | | | | |
| | | | 9000.00 | FINISHES | | | | | |
| | | | | Painting: Interior | | | | | |
| | | | 9920.01 | Paint Exist Int CMU Spray 2 ct | 59,468.00 sqft | 25,476 | 10,579 | 0.61 /sqft | 36,055 |
| | | | | Painting: Interior | | 25,476 | 10,579 | /sqft | 36,055 |
| | | | | FINISHES | | 25,476 | 10,579 | /sqft | 36,055 |
| | | | | 6KK | | 25,476 | 10,579 | | 36,055 |
| | | 6L | | | | | | | |
| | | | 4000.00 | MASONRY | | | | | |
| | | | | Access: Control Joint | | | | | |
| | | | 4155.00 | Control Jnt Rubber 8" Wall | 36.00 lnft | 140 | 133 | 7.59 /lnft | 273 |
| | | | | Access: Control Joint | | 140 | 133 | /lnft | 273 |
| | | | | MASONRY | | 140 | 133 | /sqft | 273 |
| | | | 7000.00 | THERMAL & MOISTURE PROT | | | | | |
| | | | | Sealant - Jt Filler Gaskt | | | | | |
| | | | 7910.01 | Backer Rod 1/2" | 36.00 lnft | 109 | 3 | 3.12 /lnft | 112 |
| | | | | Polyurethane Sealant 1/2" | 36.00 lnft | 343 | 18 | 10.02 /lnft | 361 |
| | | | | Rake Out Masonry Jt. Filler | 36.00 lnft | 106 | 7 | 4.98 /lnft | 179 |
| | | | | Sealant - Jt Filler Gaskt | | 558 | 29 | /lnft | 652 |
| | | | | THERMAL & MOISTURE PROT | | 558 | 29 | /sqft | 652 |

| Location | Bid Item | Group | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|------------|----------|-------|---------------------------------------|------------------|----------------|-----------------|-----------------|----------------|
| | | | | | | 698 | 162 | | 926 |
| | 6LL | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | 2071.01 | | Demo: General | | | | | |
| | | | | General Disposal | 554.90 cuyd | 11,429 | - | 27.17 /cuyd | 15,076 |
| | | | | Demo: General | | 11,429 | | /cuyd | 15,076 |
| | | 2088.50 | | Demo: Finishes, Ceilings | | | | | |
| | | | | Rem. Acoust Tile & Grid | 58,931.00 sqft | 70,967 | - | 1.20 /sqft | 70,967 |
| | | | | Demo: Finishes, Ceilings | | 70,967 | | /sqft | 70,967 |
| | | | | DEMOLITION | | 82,396 | | /sqft | 86,043 |
| | 9000.00 | | | FINISHES | | | | | |
| | | 9510.50 | | Ceiling: 2x4 Tile | | | | | |
| | | | | MinFbr Tegulr Std 2x4 3/4" 250-500 sf | 58,931.00 sqft | 116,390 | 193,595 | 5.26 /sqft | 309,985 |
| | | | | Ceiling: 2x4 Tile | | 116,390 | 193,595 | /sqft | 309,985 |
| | | | | FINISHES | | 116,390 | 193,595 | /sqft | 309,985 |
| | | | | 6LL | | 198,785 | 193,595 | | 396,028 |
| | 6M | | | | | | | | |
| | 2050.00 | | | DEMOLITION | | | | | |
| | | 2071.01 | | Demo: General | | | | | |
| | | | | General Disposal | 2.10 cuyd | 43 | - | 27.17 /cuyd | 57 |
| | | | | Demo: General | | 43 | | /cuyd | 57 |
| | | 2084.01 | | Demo: Doors & Windows | | | | | |
| | | | | Remove Window Treatment | 224.00 sqft | 108 | - | 0.48 /sqft | 108 |
| | | | | Demo: Doors & Windows | | 108 | | /each | 108 |
| | | | | DEMOLITION | | 151 | | /sqft | 165 |
| | 12000.00 | | | FURNISHINGS | | | | | |
| | | 12510.01 | | Blinds | | | | | |
| | | | | Horiz 1" Alum Avg | 224.00 sqft | 324 | 1,622 | 8.69 /sqft | 1,946 |
| | | | | Blinds | | 324 | 1,622 | /sqft | 1,946 |
| | | | | FURNISHINGS | | 324 | 1,622 | /sqft | 1,946 |
| | | | | 6M | | 475 | 1,622 | | 2,111 |
| | 6T | | | | | | | | |
| | 8000.00 | | | DOORS & WINDOWS | | | | | |
| | | 8811.00 | | Glass: All Types | | | | | |
| | | | | Reglaze Insulated Tinted Glass | 16.00 sqft | 925 | 446 | 85.69 /sqft | 1,371 |
| | | | | Glass: All Types | | 925 | 446 | /sqft | 1,371 |
| | | | | DOORS & WINDOWS | | 925 | 446 | /sqft | 1,371 |
| | | | | 6T | | 925 | 446 | | 1,371 |
| | | | | 6 FINISHES GEN | | 340,590 | 214,463 | | 578,811 |

Estimate Totals

| | | | |
|-----------|------------------|------------------|-----|
| Labor | 752,048 | 7,905.513 | hrs |
| Material | 852,369 | | |
| Equipment | 31,934 | 1,566.307 | hrs |
| | 1,636,351 | 1,636,351 | |
| | Total | 1,636,351 | |

ESTABROOK ELEMENTARY SCHOOL RENOVATION
STUDY ESTIMATE - 11-22-08
LEXINGTON, MA

Project name **Estabrook E.S.**

Lexington
MA

Estimator *Essential Estimating*

| Location | Labor Amount | Material Amount | Sub Amount | Equip Amount | Total Amount |
|-----------------|--------------|-----------------|------------|--------------|--------------|
| 1 LIFE SAFETY | 1,085 | 4,812 | | | 5,896 |
| 2 BUILDING CODE | 12,357 | 9,278 | | 279 | 21,915 |
| 3 EXTERIOR | 191,961 | 328,054 | | 9,008 | 529,023 |
| 4 HAZARDOUS MAT | 345,724 | 141,176 | 3,697 | 46,148 | 558,765 |
| 5 HC ACCESS | 199,308 | 300,502 | | 6,684 | 506,494 |
| 6 FINISHES GEN | 63,591 | 38,845 | | 1,254 | 103,689 |

Estimate Totals

| | | | |
|--------------|------------------|-----------|-----|
| Labor | 814,026 | 9,223.716 | hrs |
| Material | 822,666 | | |
| Subcontract | 3,697 | | |
| Equipment | 63,373 | 1,419.281 | hrs |
| Other | 22,020 | | |
| | <u>1,725,782</u> | | |
| | 1,725,782 | | |
| Total | 1,725,782 | | |

| Location | Bid Item | Description | Labor Amount | Material Amount | Sub Amount | Equip Amount | Total Amount |
|------------------------|------------|------------------------|----------------|-----------------|--------------|---------------|----------------|
| 1 LIFE SAFETY | | | | | | | |
| | <u>1D</u> | | <u>1,085</u> | <u>4,812</u> | | | <u>5,896</u> |
| | | 1 LIFE SAFETY | 1,085 | 4,812 | | | 5,896 |
| 2 BUILDING CODE | | | | | | | |
| | <u>2D</u> | | <u>260</u> | <u>70</u> | | | <u>331</u> |
| | <u>2H</u> | | <u>109</u> | | | <u>4</u> | <u>113</u> |
| | <u>2I</u> | | <u>11,988</u> | <u>9,207</u> | | <u>276</u> | <u>21,471</u> |
| | | 2 BUILDING CODE | 12,357 | 9,278 | | 279 | 21,915 |
| 3 EXTERIOR | | | | | | | |
| | <u>3A</u> | | <u>124,059</u> | <u>290,932</u> | | <u>330</u> | <u>415,321</u> |
| | <u>3B</u> | | <u>9,531</u> | <u>17,506</u> | | <u>330</u> | <u>27,368</u> |
| | <u>3C</u> | | <u>949</u> | <u>3,758</u> | | | <u>4,707</u> |
| | <u>3E</u> | | <u>27,063</u> | | | <u>8,001</u> | <u>35,064</u> |
| | <u>3P</u> | | <u>436</u> | <u>55</u> | | | <u>491</u> |
| | <u>3Q</u> | | <u>4,076</u> | <u>334</u> | | | <u>4,410</u> |
| | <u>3R</u> | | <u>25,847</u> | <u>15,469</u> | | <u>348</u> | <u>41,664</u> |
| | | 3 EXTERIOR | 191,961 | 328,054 | | 9,008 | 529,023 |
| 4 HAZARDOUS MAT | | | | | | | |
| | <u>4D</u> | | <u>328,862</u> | <u>139,724</u> | <u>2,773</u> | <u>46,148</u> | <u>535,838</u> |
| | <u>4E</u> | | <u>10,528</u> | <u>1,301</u> | <u>462</u> | | <u>15,072</u> |
| | <u>4F</u> | | <u>6,335</u> | <u>150</u> | <u>462</u> | | <u>7,855</u> |
| | | 4 HAZARDOUS MAT | 345,724 | 141,176 | 3,697 | 46,148 | 558,765 |
| 5 HC ACCESS | | | | | | | |
| | <u>5A</u> | | <u>11,721</u> | <u>6,196</u> | | <u>871</u> | <u>18,787</u> |
| | <u>5B</u> | | <u>18,448</u> | <u>39,825</u> | | <u>237</u> | <u>58,510</u> |
| | <u>5C</u> | | <u>1,399</u> | <u>3,971</u> | | <u>18</u> | <u>5,388</u> |
| | <u>5CC</u> | | <u>2,968</u> | <u>1,554</u> | | <u>70</u> | <u>4,592</u> |
| | <u>5D</u> | | <u>833</u> | | | <u>5</u> | <u>837</u> |
| | <u>5E</u> | | <u>60</u> | | | | <u>60</u> |
| | <u>5F</u> | | <u>610</u> | <u>754</u> | | <u>22</u> | <u>1,386</u> |
| | <u>5G</u> | | <u>10,599</u> | <u>30,436</u> | | <u>38</u> | <u>41,074</u> |
| | <u>5H</u> | | <u>87,333</u> | <u>53,969</u> | | <u>2,774</u> | <u>144,076</u> |
| | <u>5K</u> | | <u>15,582</u> | <u>8,820</u> | | <u>1,960</u> | <u>26,362</u> |
| | <u>5L</u> | | <u>3,338</u> | <u>15,341</u> | | <u>230</u> | <u>18,908</u> |
| | <u>5N</u> | | <u>5,300</u> | <u>7,454</u> | | <u>192</u> | <u>12,945</u> |
| | <u>5Q</u> | | <u>4,717</u> | | | <u>140</u> | <u>4,857</u> |
| | <u>5R</u> | | <u>823</u> | <u>12,347</u> | | <u>3</u> | <u>13,172</u> |
| | <u>5T</u> | | <u>26,769</u> | <u>117,808</u> | | <u>34</u> | <u>144,610</u> |
| | <u>5W</u> | | <u>8,809</u> | <u>2,026</u> | | <u>93</u> | <u>10,928</u> |
| | | 5 HC ACCESS | 199,308 | 300,502 | | 6,684 | 506,494 |
| 6 FINISHES GEN | | | | | | | |
| | <u>6A</u> | | <u>744</u> | <u>517</u> | | <u>9</u> | <u>1,270</u> |
| | <u>6B</u> | | <u>16,873</u> | <u>2,493</u> | | <u>588</u> | <u>19,954</u> |
| | <u>6CC</u> | | <u>677</u> | <u>1,197</u> | | | <u>1,874</u> |
| | <u>6D</u> | | <u>1,335</u> | <u>133</u> | | <u>359</u> | <u>1,828</u> |
| | <u>6F</u> | | <u>890</u> | <u>75</u> | | <u>23</u> | <u>988</u> |
| | <u>6KK</u> | | <u>25,211</u> | <u>10,470</u> | | | <u>35,680</u> |
| | <u>6L</u> | | <u>640</u> | <u>148</u> | | <u>60</u> | <u>848</u> |
| | <u>6M</u> | | <u>2,202</u> | <u>7,530</u> | | <u>63</u> | <u>9,795</u> |
| | <u>6MM</u> | | <u>396</u> | <u>173</u> | | | <u>568</u> |

| Location | Bid Item | Description | Labor Amount | Material Amount | Sub Amount | Equip Amount | Total Amount |
|----------|------------|-----------------------|---------------|-----------------|------------|--------------|----------------|
| | | | <u>6,451</u> | <u>8,922</u> | | <u>1</u> | <u>15,374</u> |
| | <u>6P</u> | | <u>4,259</u> | <u>6,061</u> | | <u>90</u> | <u>10,410</u> |
| | <u>6Q</u> | | <u>1,619</u> | <u>393</u> | | <u>2</u> | <u>2,014</u> |
| | <u>6QQ</u> | | <u>91</u> | <u>36</u> | | | <u>127</u> |
| | <u>6R</u> | | <u>148</u> | <u>36</u> | | <u>4</u> | <u>187</u> |
| | <u>6S</u> | | <u>1,398</u> | <u>149</u> | | <u>33</u> | <u>1,580</u> |
| | <u>6U</u> | | <u>93</u> | <u>38</u> | | | <u>131</u> |
| | <u>6YY</u> | | <u>267</u> | <u>107</u> | | <u>21</u> | <u>396</u> |
| | <u>6ZZ</u> | | <u>296</u> | <u>367</u> | | <u>1</u> | <u>664</u> |
| | | 6 FINISHES GEN | 63,591 | 38,845 | | 1,254 | 103,689 |

Estimate Totals

| | | | |
|--------------|------------------|------------------|-----|
| Labor | 814,026 | 9,223.716 | hrs |
| Material | 822,666 | | |
| Subcontract | 3,697 | | |
| Equipment | 63,373 | 1,419.281 | hrs |
| Other | <u>22,020</u> | | |
| | 1,725,782 | 1,725,782 | |
| Total | 1,725,782 | | |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|------------------------|-----------|-------|---|------------------|-----------------------|-----------------------|-----------------|-----------------------|
| 1 LIFE SAFETY | | | | | | | | |
| | 1D | | | | | | | |
| | 2084.01 | | Remove Hardware | 4.00 each | 181 | - | 45.19 /each | 181 |
| | 8710.01 | | Finishing Hardware Ext Budget | 4.00 each | 904 | 4,812 | 1,428.88 /each | 5,716 |
| | | | <u>1D</u> | | <u>1,085</u> | <u>4,812</u> | | <u>5,896</u> |
| | | | 1 LIFE SAFETY | | 1,085 | 4,812 | | 5,896 |
| 2 BUILDING CODE | | | | | | | | |
| | 2D | | | | | | | |
| | 7270.00 | | Firesafing | 72.00 lnft | 260 | 70 | 4.59 /lnft | 331 |
| | | | <u>2D</u> | | <u>260</u> | <u>70</u> | | <u>331</u> |
| | 2H | | | | | | | |
| | 2071.01 | | General Disposal | 0.60 cuyd | 12 | - | 27.17 /cuyd | 16 |
| | 2084.01 | | Remove Door | 3.00 each | 96 | - | 32.10 /each | 96 |
| | | | <u>2H</u> | | <u>109</u> | | | <u>113</u> |
| | 2I | | | | | | | |
| | 4050.10 | | Interior Scaffold | 480.00 sqft | 534 | 201 | 1.77 /sqft | 849 |
| | 4050.15 | | Concrete Block | 0.39 m | - | - | 262.84 /m | 104 |
| | 4105.00 | | Mortar Type "N" | 0.73 cuyd | 89 | 158 | 337.86 /cuyd | 247 |
| | 4110.01 | | Grout Fill 3000 psi, 1/2" Gravl | 0.44 cuyd | 124 | 85 | 494.86 /cuyd | 218 |
| | 4110.01 | | Grout Single Door Frame | 3.00 each | 191 | 61 | 88.70 /each | 266 |
| | 4110.01 | | Grout Double Door Frame | 1.00 each | 85 | 29 | 120.01 /each | 120 |
| | 4157.00 | | Re-Bar #5 & #6 | 100.13 lbs | 202 | 107 | 3.09 /lbs | 309 |
| | 4158.00 | | Horiz Wall Reinf 6" Hot Dippd | 0.21 mlf | 93 | 36 | 615.80 /mlf | 129 |
| | 4221.20 | | Blk 6" Stand Face Reg Wt - Infill | 363.00 each | 6,587 | 862 | 20.52 /each | 7,449 |
| | 4221.50 | | Lintel 6" Stand Face Lt Wt | 34.00 each | 79 | 44 | 3.63 /each | 123 |
| | 5510.35 | | Angle Bolted To Masonry | 143.00 lb | 505 | 430 | 6.74 /lb | 964 |
| | 6113.40 | | Rough Bucks 2 x 6 PT Doors | 71.00 lnft | 178 | 80 | 3.63 /lnft | 258 |
| | 7910.01 | | Polysulfide Sealant 1/4" Interior | 71.00 lnft | 666 | 16 | 9.60 /lnft | 682 |
| | 8110.01 | | H.M. Frame 18ga Interior Single | 3.00 each | 297 | 518 | 271.64 /each | 815 |
| | 8110.01 | | H.M. Frame 18ga Interior Double | 1.00 each | 124 | 227 | 350.92 /each | 351 |
| | 8210.01 | | Door M Core 3-0 x 7-0 Vision | 5.00 each | 651 | 2,128 | 555.75 /each | 2,779 |
| | 8710.01 | | Finishing Hardware Int Budget w Closure | 5.00 each | 678 | 3,989 | 933.29 /each | 4,666 |
| | 9920.01 | | Paint Wd Door & Metal Frame | 5.00 each | 351 | 71 | 84.43 /each | 422 |
| | 9920.01 | | Paint Int CMU Spray p+2ct | 590.00 sqft | 556 | 165 | 1.22 /sqft | 721 |
| | | | <u>2I</u> | | <u>11,988</u> | <u>9,207</u> | | <u>21,471</u> |
| | | | 2 BUILDING CODE | | 12,357 | 9,278 | | 21,915 |
| 3 EXTERIOR | | | | | | | | |
| | 3A | | | | | | | |
| | 2071.01 | | General Disposal | 50.20 cuyd | 1,034 | - | 27.16 /cuyd | 1,363 |
| | 2084.01 | | Remove Metal Windows | 5,426.00 sqft | 16,982 | - | 3.13 /sqft | 16,982 |
| | 4156.00 | | Flash Head Lead Ct. Cop 5 oz. | 553.00 sqft | 2,528 | 2,542 | 9.17 /sqft | 5,070 |
| | 4156.00 | | Flash Sill Lead Ct. Cop 5 oz. | 550.00 sqft | 2,292 | 2,375 | 8.49 /sqft | 4,667 |
| | 6113.40 | | Rough Bucks 2 x 6 PT Windows | 1,549.00 lnft | 5,886 | 1,749 | 4.93 /lnft | 7,635 |
| | 7910.01 | | Backer Rod 1/2" | 1,549.00 lnft | 4,694 | 142 | 3.12 /lnft | 4,836 |
| | 7910.01 | | Polyurethane Sealant 1/2" | 3,098.00 lnft | 29,503 | 1,540 | 10.02 /lnft | 31,044 |
| | 8520.01 | | Custom Proj 4" .125 w Ins Gl Kynar | 5,426.00 sqft | 61,140 | 282,585 | 63.35 /sqft | 343,725 |
| | | | <u>3A</u> | | <u>124,059</u> | <u>290,932</u> | | <u>415,321</u> |
| | 3B | | | | | | | |
| | 2071.01 | | General Disposal | 50.20 cuyd | 1,034 | - | 27.16 /cuyd | 1,363 |
| | 2084.01 | | Remove Window Treatment | 5,426.00 sqft | 2,613 | - | 0.48 /sqft | 2,613 |
| | 12520.01 | | Vinyl Heavy Wt | 5,426.00 sqft | 5,885 | 17,506 | 4.31 /sqft | 23,392 |
| | | | <u>3B</u> | | <u>9,531</u> | <u>17,506</u> | | <u>27,368</u> |
| | 3C | | | | | | | |
| | 8565.00 | | Window Screens/Wicket (Aluminum) | 504.00 sqft | 949 | 3,758 | 9.34 /sqft | 4,707 |
| | | | <u>3C</u> | | <u>949</u> | <u>3,758</u> | | <u>4,707</u> |
| | 3E | | | | | | | |
| | 2060.00 | | Small Building Temp | 45,312.00 cuft | 10,602 | - | 0.36 /cuft | 16,370 |
| | 2060.00 | | Disposal Building | 295.30 cuyd | 2,580 | - | 11.88 /cuyd | 3,507 |
| | 2075.00 | | Remove Conc Walls 8" | 832.00 sqft | 13,881 | - | 18.25 /sqft | 15,187 |
| | | | <u>3E</u> | | <u>27,063</u> | | | <u>35,064</u> |
| | 3P | | | | | | | |
| | 4520.01 | | ReGrout Stone Hard Mortar | 57.00 sqft | 436 | 55 | 8.61 /sqft | 491 |
| | | | <u>3P</u> | | <u>436</u> | <u>55</u> | | <u>491</u> |
| | 3Q | | | | | | | |
| | 9910.01 | | Scrape & Prep Ext Misc Surfaces Lintels | 1,095.00 sqft | 1,782 | - | 1.63 /sqft | 1,782 |
| | 9910.01 | | Paint Ext Misc Exposed Metal Lintels | 1,095.00 sqft | 2,294 | 334 | 2.40 /sqft | 2,628 |
| | | | <u>3Q</u> | | <u>4,076</u> | <u>334</u> | | <u>4,410</u> |
| | 3R | | | | | | | |
| | 2071.01 | | General Disposal | 52.90 cuyd | 1,089 | - | 27.16 /cuyd | 1,437 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|------------------------|----------|-------|---|------------------|----------------|-----------------|-----------------|----------------|
| 3R | | | | | | | | |
| | 2078.00 | | Remove Wall Sheathing | 2,856.00 sqft | 1,834 | - | 0.64 /sqft | 1,834 |
| | 2079.00 | | Remove Aluminum Siding Verticle | 2,856.00 sqft | 4,584 | - | 1.61 /sqft | 4,584 |
| | 6116.00 | | Wall Sheath 1/2" Cdx Plywood | 2,856.00 sqft | 3,706 | 1,980 | 1.99 /sqft | 5,685 |
| | 7211.00 | | Insul Fibrgls 6" Foil 1 side | 2,856.00 sqft | 2,065 | 2,279 | 1.52 /sqft | 4,344 |
| | 7420.01 | | Siding Steel Zinc Alloy 22 ga | 2,856.00 sqft | 12,570 | 11,210 | 8.33 /sqft | 23,779 |
| | | | 3R | | 25,847 | 15,469 | | 41,664 |
| | | | 3 EXTERIOR | | 191,961 | 328,054 | | 529,023 |
| 4 HAZARDOUS MAT | | | | | | | | |
| 4D | | | | | | | | |
| | 2073.00 | | Remove Vinyl Asbestos Tile | 34,789.00 sqft | 80,280 | - | 2.31 /sqft | 80,280 |
| | 2073.00 | | Vacuum Cleaner 16 gal | 2.00 each | - | 2,152 | 1,075.89 /each | 2,152 |
| | 2073.00 | | Final Cleaning | 34,789.00 sqft | 8,920 | - | 0.26 /sqft | 8,920 |
| | 2073.00 | | Testing | 6.00 day | - | - | 462.14 /day | 2,773 |
| | 2073.00 | | Collect & Bulk Mat'l Bulk 3cf bags | 3,149.00 bags | 19,647 | 3,240 | 7.27 /bags | 22,887 |
| | 2073.00 | | Cart Bags | 3,149.00 bags | 10,765 | - | 3.42 /bags | 10,765 |
| | 2073.00 | | Disposal Minimum | 323.00 cuyd | - | - | 56.75 /cuyd | 18,331 |
| | 2088.01 | | Shotblast Floor | 34,789.00 sqft | 30,700 | - | 1.39 /sqft | 48,359 |
| | 3326.00 | | Leveling Compound | 34,789.00 sqft | 132,908 | 65,424 | 6.52 /sqft | 226,821 |
| | 9660.01 | | Floor Vinyl Composition Tile 1/8" | 34,789.00 sqft | 37,036 | 64,178 | 2.91 /sqft | 101,214 |
| | 9660.01 | | Floor Resil Base 4" | 5,928.00 lnft | 8,606 | 4,731 | 2.25 /lnft | 13,337 |
| | | | 4D | | 328,862 | 139,724 | | 535,838 |
| 4E | | | | | | | | |
| | 2073.00 | | Remove Vinyl Asbestos Tile | 2,624.00 sqft | 6,055 | - | 2.31 /sqft | 6,055 |
| | 2073.00 | | Vacuum Cleaner 16 gal | 1.00 each | - | 1,076 | 1,075.89 /each | 1,076 |
| | 2073.00 | | Final Cleaning | 2,624.00 sqft | 673 | - | 0.26 /sqft | 673 |
| | 2073.00 | | Testing | 1.00 day | - | - | 462.13 /day | 462 |
| | 2073.00 | | Collect & Bulk Mat'l Bulk 3cf bags | 219.00 bags | 1,366 | 225 | 7.27 /bags | 1,592 |
| | 2073.00 | | Cart Bags | 219.00 bags | 749 | - | 3.42 /bags | 749 |
| | 2073.00 | | Disposal Minimum | 49.00 cuyd | - | - | 56.75 /cuyd | 2,781 |
| | 2088.01 | | Remove Carpet & Pad | 2,624.00 sqft | 1,685 | - | 0.64 /sqft | 1,685 |
| | | | 4E | | 10,528 | 1,301 | | 15,072 |
| 4F | | | | | | | | |
| | 2073.00 | | Remove Asbestos Ceil | 1,746.00 sqft | 4,477 | - | 2.56 /sqft | 4,477 |
| | 2073.00 | | Final Cleaning | 1,746.00 sqft | 448 | - | 0.26 /sqft | 448 |
| | 2073.00 | | Testing | 1.00 day | - | - | 462.14 /day | 462 |
| | 2073.00 | | Collect & Bulk Mat'l Bulk 3cf bags | 146.00 bags | 911 | 150 | 7.27 /bags | 1,061 |
| | 2073.00 | | Cart Bags | 146.00 bags | 499 | - | 3.42 /bags | 499 |
| | 2073.00 | | Disposal Minimum | 16.00 cuyd | - | - | 56.75 /cuyd | 908 |
| | | | 4F | | 6,335 | 150 | | 7,855 |
| | | | 4 HAZARDOUS MAT | | 345,724 | 141,176 | | 558,765 |
| 5 HC ACCESS | | | | | | | | |
| 5A | | | | | | | | |
| | 2071.01 | | General Disposal | 3.30 cuyd | 68 | - | 27.16 /cuyd | 90 |
| | 2076.00 | | Cut Out Opng 4" CMU | 28.00 sqft | 755 | - | 29.34 /sqft | 821 |
| | 2076.00 | | Sawcut 6" CMU | 32.00 lnft | 905 | - | 46.47 /lnft | 1,487 |
| | 2076.00 | | Tooth Jambs 1 Wythe | 28.00 lnft | 865 | - | 30.88 /lnft | 865 |
| | 2076.00 | | Remove CMU 6" | 72.00 sqft | 262 | - | 3.97 /sqft | 285 |
| | 2084.01 | | Remove Door | 19.00 each | 610 | - | 32.10 /each | 610 |
| | 2084.01 | | Remove Door & Frame Int Single | 8.00 each | 899 | - | 126.93 /each | 1,015 |
| | 2088.01 | | Flash Patch @ Wall Removal | 6.00 sqft | 14 | 13 | 4.41 /sqft | 26 |
| | 4050.15 | | Concrete Block | 0.10 m | - | - | 262.70 /m | 25 |
| | 4105.00 | | Mortar Type "N" | 0.18 cuyd | 22 | 39 | 337.89 /cuyd | 61 |
| | 4110.01 | | Grout Double Door Frame | 4.00 each | 342 | 114 | 120.22 /each | 481 |
| | 4158.00 | | Horiz Wall Reinf 6" Hot Dippd | 0.10 mlf | 44 | 17 | 615.40 /mlf | 62 |
| | 4221.20 | | Blk 6" Stand Face Reg Wt - Infill | 96.00 each | 1,742 | 228 | 20.52 /each | 1,970 |
| | 6113.40 | | Rough Bucks 2 x 6 PT Doors | 68.00 lnft | 170 | 77 | 3.63 /lnft | 247 |
| | 7910.01 | | Polysulfide Sealant 1/4" Interior | 68.00 lnft | 638 | 15 | 9.60 /lnft | 653 |
| | 8110.01 | | H.M. Frame 18ga Interior Single | 4.00 each | 396 | 691 | 271.64 /each | 1,087 |
| | 8210.01 | | Rehang Door | 17.00 each | 2,214 | 0 | 130.22 /each | 2,214 |
| | 8210.01 | | Door M Core 3-0 x 7-0 Vision | 4.00 each | 521 | 1,702 | 555.75 /each | 2,223 |
| | 8710.01 | | Finishing Hardware Int Budget w Closure | 4.00 each | 542 | 3,191 | 933.29 /each | 3,733 |
| | 9210.01 | | Plaster Patch @ Wall Removal | 24.00 sqft | 399 | 43 | 18.81 /sqft | 451 |
| | 9210.01 | | Plaster Patch Ceiling @ Wall Removal | 6.00 sqft | 33 | 10 | 7.17 /sqft | 43 |
| | 9920.01 | | Paint Wd Door & Metal Frame | 4.00 each | 281 | 57 | 84.43 /each | 338 |
| | | | 5A | | 11,721 | 6,196 | | 18,787 |
| 5B | | | | | | | | |
| | 2071.01 | | General Disposal | 36.00 cuyd | 741 | - | 27.16 /cuyd | 978 |
| | 2080.01 | | Remove Casework | 162.00 lnft | 845 | - | 5.22 /lnft | 845 |
| | 6113.20 | | Blocking 2 x 6 R.L. | 162.00 lnft | 556 | 110 | 4.11 /lnft | 666 |
| | 12350.00 | | School Casework Base & Top | 162.00 lnft | 16,306 | 39,715 | 345.81 /lnft | 56,021 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|------------|----------|------------------------------------|------------------|----------------------|----------------------|-----------------|----------------------|
| | | | | | <u>18,448</u> | <u>39,825</u> | | <u>58,510</u> |
| | 5C | | | | | | | |
| | | 2071.01 | General Disposal | 2.70 cuyd | 56 | - | 27.16 /cuyd | 73 |
| | | 2080.01 | Remove Casework | 12.00 lnft | 63 | - | 5.22 /lnft | 63 |
| | | 6113.20 | Blocking 2 x 6 R.L. | 12.00 lnft | 41 | 8 | 4.11 /lnft | 49 |
| | | 12620.00 | Library Charge Desk | 12.00 lnft | 1,240 | 3,963 | 433.57 /lnft | 5,203 |
| | | | <u>5C</u> | | <u>1,399</u> | <u>3,971</u> | | <u>5,388</u> |
| | 5CC | | | | | | | |
| | | 2071.01 | General Disposal | 1.40 cuyd | 29 | - | 26.94 /cuyd | 38 |
| | | 2075.00 | Remove Stair 4' | 5.00 risr | 223 | - | 48.44 /risr | 242 |
| | | 2077.00 | Remove Steel Rail | 20.00 lnft | 201 | - | 10.03 /lnft | 201 |
| | | 3136.00 | Stair Forms | 88.00 sqft | 1,564 | 360 | 21.87 /sqft | 1,925 |
| | | 3215.10 | Step-Stair Rebar #5 | 0.01 ton | 24 | 23 | 4,728.00 /ton | 47 |
| | | 3228.00 | Wiremesh @ Steps 6x6 6/6 | 0.50 sqs | 36 | 25 | 122.02 /sqs | 61 |
| | | 3314.00 | Stair/Step Conc 4000 psi | 2.40 cuyd | 85 | 325 | 177.64 /cuyd | 426 |
| | | 3375.00 | Cure Conc w/burlap Ext Stair | 0.50 sqs | 13 | 6 | 37.42 /sqs | 19 |
| | | 3380.01 | Stair Finish | 50.00 sqft | 135 | 0 | 2.71 /sqft | 136 |
| | | 3380.01 | Rub Risers | 25.00 lnft | 102 | 2 | 4.14 /lnft | 103 |
| | | 5510.80 | Stair Railing Steel 1-1/2" 2 pipe | 20.00 lnft | 506 | 804 | 66.71 /lnft | 1,334 |
| | | 9920.01 | Paint Int Pipe Rails | 40.00 lnft | 51 | 9 | 1.50 /lnft | 60 |
| | | | <u>5CC</u> | | <u>2,968</u> | <u>1,554</u> | | <u>4,592</u> |
| | 5D | | | | | | | |
| | | 2071.01 | General Disposal | 0.70 cuyd | 14 | - | 27.16 /cuyd | 19 |
| | | 2088.60 | Remove Drinking Fountain | 5.00 each | 818 | - | 163.69 /each | 818 |
| | | | <u>5D</u> | | <u>833</u> | | | <u>837</u> |
| | 5E | | | | | | | |
| | | 2084.50 | Remove TV | 1.00 each | 60 | - | 60.19 /each | 60 |
| | | | <u>5E</u> | | <u>60</u> | | | <u>60</u> |
| | 5F | | | | | | | |
| | | 2071.01 | General Disposal | 0.20 cuyd | 4 | - | 27.15 /cuyd | 5 |
| | | 2077.00 | Remove Steel Rail | 16.00 lnft | 161 | - | 10.03 /lnft | 161 |
| | | 5510.80 | Stair Railing Steel 1-1/2" 2 pipe | 9.00 lnft | 228 | 362 | 66.75 /lnft | 601 |
| | | 5510.80 | Stair Railing Galv 1-1/2" 2 pipe | 7.00 lnft | 177 | 385 | 81.62 /lnft | 571 |
| | | 9920.01 | Paint Int Pipe Rails | 32.00 lnft | 41 | 7 | 1.50 /lnft | 48 |
| | | | <u>5F</u> | | <u>610</u> | <u>754</u> | | <u>1,386</u> |
| | 5G | | | | | | | |
| | | 2071.01 | General Disposal | 5.80 cuyd | 119 | - | 27.16 /cuyd | 158 |
| | | 2084.50 | Remove Toilet Partitions | 11.00 each | 883 | - | 80.25 /each | 883 |
| | | 2084.50 | Remove Urinal Screen | 1.00 each | 56 | - | 56.18 /each | 56 |
| | | 2084.50 | Remove Toilet Accessories | 45.00 each | 451 | - | 10.03 /each | 451 |
| | | 6113.20 | Block Toilet Partition | 14.00 each | 421 | 167 | 42.04 /each | 589 |
| | | 6113.20 | Block H.C. Toilet Partition | 4.00 each | 181 | 59 | 59.93 /each | 240 |
| | | 6113.20 | Block Misc Toilet Accessories | 87.00 each | 1,573 | 437 | 23.09 /each | 2,009 |
| | | 10160.02 | Toilet Partition Reg Flr Mtd | 7.00 each | 1,483 | 10,154 | 1,662.48 /each | 11,637 |
| | | 10160.02 | Toilet Partition HC Flr Mtd | 4.00 each | 847 | 6,681 | 1,882.23 /each | 7,529 |
| | | 10160.02 | Urinal Screens Wall Hung | 7.00 each | 1,038 | 3,254 | 613.20 /each | 4,292 |
| | | 10800.01 | Grab Bar 1-1/4" S.S. 36" | 16.00 each | 578 | 623 | 75.09 /each | 1,201 |
| | | 10800.01 | Mirror 18" x 30" S.S. | 10.00 each | 470 | 802 | 127.22 /each | 1,272 |
| | | 10800.01 | Sanitary Napkin Dispenser Recessed | 2.00 each | 96 | 2,070 | 1,083.42 /each | 2,167 |
| | | 10800.01 | Clothes Hook Single | 11.00 each | 221 | 211 | 39.25 /each | 432 |
| | | 10800.01 | Soap Dispenser | 10.00 each | 723 | 2,070 | 279.36 /each | 2,794 |
| | | 10800.01 | Stainless Steel Shelf | 15.00 lnft | 247 | 571 | 54.49 /lnft | 817 |
| | | 10800.01 | Toilet Tissue Disp Dbl | 15.00 each | 451 | 413 | 57.60 /each | 864 |
| | | 10800.01 | Towel Dispenser Surface Mtd | 4.00 each | 181 | 215 | 98.99 /each | 396 |
| | | 10800.01 | Towel Disp/Waste Recpt | 4.00 each | 578 | 2,708 | 821.65 /each | 3,287 |
| | | | <u>5G</u> | | <u>10,599</u> | <u>30,436</u> | | <u>41,074</u> |
| | 5H | | | | | | | |
| | | 2071.01 | General Disposal | 54.10 cuyd | 1,114 | - | 27.16 /cuyd | 1,469 |
| | | 2075.00 | Saw Concrete Slab to 6" | 206.00 lnft | 1,123 | - | 7.56 /lnft | 1,557 |
| | | 2075.00 | Chip out Slab | 178.00 sqft | 2,200 | 16 | 14.11 /sqft | 2,512 |
| | | 2076.00 | Remove CMU 6" | 1,596.00 sqft | 5,817 | - | 3.97 /sqft | 6,328 |
| | | 2084.50 | Remove Toilet Partitions | 7.00 each | 562 | - | 80.25 /each | 562 |
| | | 2084.50 | Remove Urinal Screen | 1.00 each | 56 | - | 56.18 /each | 56 |
| | | 2084.50 | Remove Toilet Accessories | 47.00 each | 471 | - | 10.03 /each | 471 |
| | | 2088.01 | Remove Ceramic Tile Floor | 640.00 sqft | 1,181 | - | 1.85 /sqft | 1,181 |
| | | 2088.01 | Flash Patch @ Wall Removal | 133.00 sqft | 306 | 280 | 4.41 /sqft | 587 |
| | | 2088.50 | Remove Plaster Ceiling Metal Lath | 640.00 sqft | 1,438 | - | 2.25 /sqft | 1,438 |
| | | 2088.60 | Remove Sink | 11.00 each | 1,351 | - | 122.80 /each | 1,351 |
| | | 2088.60 | Remove Water Closet | 10.00 each | 1,404 | - | 140.36 /each | 1,404 |
| | | 2088.60 | Remove Urinal | 4.00 each | 982 | - | 245.60 /each | 982 |
| | | 3310.01 | Patch Conc. Slab Trench etc. | 206.00 sqft | 1,116 | 2,434 | 17.23 /sqft | 3,550 |
| | | 4050.10 | Interior Scaffold | 1,596.00 sqft | 1,774 | 669 | 1.77 /sqft | 2,823 |
| | | 4050.15 | Concrete Block | 1.47 m | - | - | 262.85 /m | 386 |
| | | 4105.00 | Mortar Type "N" | 2.73 cuyd | 331 | 591 | 337.85 /cuyd | 922 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|-----------|----------|-------|--|------------------|---------------|-----------------|-----------------|----------------|
| 5H | | | | | | | | |
| | 4110.01 | | Grout Fill 3000 psi, 1/2" Gravl | 1.28 cuyd | 360 | 246 | 494.43 /cuyd | 633 |
| | 4110.01 | | Grout Single Door Frame | 7.00 each | 445 | 143 | 88.69 /each | 621 |
| | 4157.00 | | Re-Bar #5 & #6 | 287.87 lbs | 582 | 307 | 3.09 /lbs | 889 |
| | 4158.00 | | Horiz Wall Reinf 6" Hot Dippd | 1.10 mlf | 489 | 188 | 615.38 /mlf | 677 |
| | 4221.20 | | Blk 6" Standard Face Reg Wt | 1,355.00 each | 16,563 | 3,043 | 14.47 /each | 19,606 |
| | 4221.50 | | Lintel 6" Stand Face Reg Wt | 118.00 each | 2,192 | 775 | 26.59 /each | 3,138 |
| | 5510.35 | | Angle Bolted To Masonry | 486.00 lb | 1,717 | 1,462 | 6.74 /lb | 3,275 |
| | 6113.20 | | Block Toilet Partition | 7.00 each | 211 | 84 | 42.04 /each | 294 |
| | 6113.20 | | Block H.C. Toilet Partition | 4.00 each | 181 | 59 | 59.93 /each | 240 |
| | 6113.20 | | Block Misc Toilet Accessories | 78.00 each | 1,410 | 391 | 23.09 /each | 1,801 |
| | 6113.40 | | Rough Bucks 2 x 6 Doors | 129.00 lnft | 323 | 87 | 3.18 /lnft | 410 |
| | 7910.01 | | Polysulfide Sealant 1/4" Interior | 129.00 lnft | 1,210 | 29 | 9.60 /lnft | 1,239 |
| | 8110.01 | | H.M. Frame 18ga Interior Single | 7.00 each | 692 | 1,209 | 271.64 /each | 1,902 |
| | 8210.01 | | Door M Core 3-0 x 7-0 Louver | 7.00 each | 965 | 3,486 | 635.84 /each | 4,451 |
| | 8710.01 | | Finishing Hardware Int Budget w Closure | 7.00 each | 949 | 5,584 | 933.29 /each | 6,533 |
| | 9210.01 | | Plaster Patch @ Wall Removal | 168.00 sqft | 2,796 | 298 | 18.81 /sqft | 3,160 |
| | 9210.01 | | Plaster Patch Ceiling @ Wall Removal | 133.00 sqft | 723 | 212 | 7.17 /sqft | 953 |
| | 9253.30 | | GWB 5/8" Water Resistant Clgs | 640.00 sqft | 593 | 277 | 1.36 /sqft | 870 |
| | 9254.00 | | Labor GWB Ceiling Finish | 640.00 sqft | 713 | 49 | 1.19 /sqft | 761 |
| | 9310.01 | | Ceramic Tile Floor Grade 2 | 640.00 sqft | 8,912 | 3,885 | 20.00 /sqft | 12,797 |
| | 9310.01 | | Ceramic Trim: Cove Base | 266.00 lnft | 6,813 | 1,159 | 29.97 /lnft | 7,972 |
| | 9510.10 | | Susp Clg 1-1/2" Channel | 640.00 sqft | 2,148 | 1,000 | 4.92 /sqft | 3,148 |
| | 9920.01 | | Paint Wd Door & Metal Frame | 7.00 each | 491 | 100 | 84.43 /each | 591 |
| | 9920.01 | | Epoxy Paint GDW Clg | 640.00 sqft | 1,480 | 504 | 3.10 /sqft | 1,984 |
| | 9920.01 | | Paint Int CMU Spray p+2ct | 1,183.00 sqft | 1,114 | 331 | 1.22 /sqft | 1,445 |
| | 9920.01 | | Epoxy Paint Int CMU | 1,183.00 sqft | 2,736 | 992 | 3.15 /sqft | 3,727 |
| | 9920.01 | | Epoxy Paint Exist Int CMU | 2,660.00 sqft | 3,873 | 1,487 | 2.02 /sqft | 5,360 |
| | 10160.02 | | Toilet Partition Reg Flr Mtd | 3.00 each | 636 | 4,352 | 1,662.48 /each | 4,987 |
| | 10160.02 | | Toilet Partition HC Flr Mtd | 4.00 each | 847 | 6,681 | 1,882.23 /each | 7,529 |
| | 10160.02 | | Urinal Screens Wall Hung | 4.00 each | 593 | 1,860 | 613.20 /each | 2,453 |
| | 10800.01 | | Grab Bar 1-1/4" S.S. 36" | 14.00 each | 506 | 545 | 75.09 /each | 1,051 |
| | 10800.01 | | Mirror 18" x 30" S.S. | 11.00 each | 517 | 882 | 127.22 /each | 1,399 |
| | 10800.01 | | Sanitary Napkin Dispenser Recessed | 2.00 each | 96 | 2,070 | 1,083.42 /each | 2,167 |
| | 10800.01 | | Clothes Hook Single | 7.00 each | 140 | 134 | 39.24 /each | 275 |
| | 10800.01 | | Soap Dispenser | 11.00 each | 795 | 2,278 | 279.36 /each | 3,073 |
| | 10800.01 | | Stainless Steel Shelf | 17.00 lnft | 280 | 647 | 54.49 /lnft | 926 |
| | 10800.01 | | Toilet Tissue Disp Dbl | 10.00 each | 301 | 275 | 57.60 /each | 576 |
| | 10800.01 | | Towel Dispenser Surface Mtd | 3.00 each | 136 | 161 | 98.99 /each | 297 |
| | 10800.01 | | Towel Disp/Waste Recpt | 4.00 each | 578 | 2,708 | 821.65 /each | 3,287 |
| 5H | | | | | 87,333 | 53,969 | | 144,076 |
| 5K | | | | | | | | |
| | 2071.01 | | General Disposal | 2.20 cuyd | 45 | - | 27.16 /cuyd | 60 |
| | 2071.01 | | Shore - Screw Jack | 5.00 each | 5,319 | 342 | 1,196.45 /each | 5,982 |
| | 2076.00 | | Cut Out Opng 6" CMU | 35.00 sqft | 998 | - | 31.01 /sqft | 1,085 |
| | 2076.00 | | Cut Out Brick & Block | 14.00 sqft | 805 | - | 62.55 /sqft | 876 |
| | 2076.00 | | Sawcut 6" CMU | 33.00 lnft | 933 | - | 46.47 /lnft | 1,534 |
| | 2076.00 | | Sawcut 16" CMU | 16.00 lnft | 1,207 | - | 123.93 /lnft | 1,983 |
| | 2076.00 | | Tooth Jambs 1 Wythe | 28.00 lnft | 865 | - | 30.88 /lnft | 865 |
| | 2076.00 | | Tooth Jambs 2 Wythes | 14.00 lnft | 863 | - | 61.61 /lnft | 863 |
| | 2084.01 | | Remove Door & Frame Int Single | 2.00 each | 225 | - | 127.47 /each | 255 |
| | 2084.01 | | Remove Door & Frame Ext Single | 2.00 each | 257 | - | 145.68 /each | 291 |
| | 4110.01 | | Grout Single Door Frame | 5.00 each | 318 | 102 | 88.70 /each | 443 |
| | 6113.40 | | Rough Bucks 2 x 6 Doors | 51.00 lnft | 128 | 35 | 3.18 /lnft | 162 |
| | 6113.40 | | Rough Bucks 2 x 6 PT Doors | 34.00 lnft | 85 | 38 | 3.63 /lnft | 123 |
| | 7910.01 | | Backer Rod 1/2" | 34.00 lnft | 103 | 3 | 3.12 /lnft | 106 |
| | 7910.01 | | Polysulfide Sealant 1/4" Interior | 51.00 lnft | 478 | 11 | 9.60 /lnft | 490 |
| | 7910.01 | | Polyurethane Sealant 1/2" | 68.00 lnft | 648 | 34 | 10.02 /lnft | 681 |
| | 8110.01 | | H.M. Frame 16ga Galv Single | 2.00 each | 198 | 412 | 304.67 /each | 609 |
| | 8110.01 | | H.M. Frame 18ga Interior Single | 3.00 each | 297 | 518 | 271.64 /each | 815 |
| | 8110.01 | | H.M. Door Ins 16ga Galv 3-0 x 7-0 Vision | 2.00 each | 199 | 1,179 | 688.74 /each | 1,377 |
| | 8210.01 | | Door M Core 3-0 x 7-0 Vision | 3.00 each | 391 | 1,277 | 555.75 /each | 1,667 |
| | 8710.01 | | Finishing Hardware Ext Budget | 2.00 each | 452 | 2,406 | 1,428.88 /each | 2,858 |
| | 8710.01 | | Finishing Hardware Int Budget w Closure | 3.00 each | 407 | 2,393 | 933.29 /each | 2,800 |
| | 9910.01 | | Paint Ext Door & Frame | 2.00 each | 154 | 28 | 91.31 /each | 183 |
| | 9920.01 | | Paint Wd Door & Metal Frame | 3.00 each | 210 | 43 | 84.43 /each | 253 |
| 5K | | | | | 15,582 | 8,820 | | 26,362 |
| 5L | | | | | | | | |
| | 2071.01 | | General Disposal | 0.20 cuyd | 4 | - | 27.10 /cuyd | 5 |
| | 2075.00 | | Saw Concrete Slab to 6" | 18.00 lnft | 98 | - | 7.56 /lnft | 136 |
| | 2075.00 | | Chip out Slab | 20.00 sqft | 247 | 2 | 14.11 /sqft | 282 |
| | 14405.00 | | Lift Commercial | 1.00 each | 2,988 | 15,339 | 18,484.69 /each | 18,485 |
| 5L | | | | | 3,338 | 15,341 | | 18,908 |
| 5N | | | | | | | | |
| | 3131.00 | | Ramp Forms 2 use | 176.00 lnft | 1,392 | 313 | 9.69 /lnft | 1,705 |
| | 3225.00 | | Wiremesh - Ramp 6x6 6/6 | 2.80 sqs | 193 | 142 | 119.96 /sqs | 336 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|-----------------------|----------|-------|---|------------------|----------------|-----------------|-----------------|----------------|
| 5N | | | | | | | | |
| | 3309.50 | | Ramp Conc 4000 psi | 5.19 cuyd | 239 | 736 | 197.25 /cuyd | 1,024 |
| | 3375.00 | | Cure Conc w/burlap Ramp | 2.80 sqs | 72 | 33 | 37.41 /sqs | 105 |
| | 3380.01 | | Broom/Float Finish Ramp | 280.00 sqft | 247 | - | 0.88 /sqft | 247 |
| | 5510.80 | | Stair Railing Galv 1-1/2" 2 pipe | 112.00 lnft | 2,832 | 6,167 | 81.62 /lnft | 9,141 |
| | 9910.01 | | Paint Ext Stair Hand 1 Rail | 224.00 lnft | 326 | 63 | 1.74 /lnft | 389 |
| | | | 5N | | 5,300 | 7,454 | | 12,945 |
| 5Q | | | | | | | | |
| | 2071.01 | | General Disposal | 1.40 cuyd | 29 | - | 27.16 /cuyd | 38 |
| | 2075.00 | | Remove Locker Base | 39.00 lnft | 663 | - | 20.37 /lnft | 795 |
| | 2084.50 | | Relocate Lockers | 39.00 each | 4,025 | - | 103.20 /each | 4,025 |
| | | | 5Q | | 4,717 | | | 4,857 |
| 5R | | | | | | | | |
| | 2071.01 | | General Disposal | 0.40 cuyd | 8 | - | 26.90 /cuyd | 11 |
| | 2084.50 | | Remove Kitchen Serve | 12.00 lnft | 173 | - | 14.45 /lnft | 173 |
| | 11400.01 | | Serving Line | 12.00 lnft | 641 | 12,347 | 1,082.34 /lnft | 12,988 |
| | | | 5R | | 823 | 12,347 | | 13,172 |
| 5T | | | | | | | | |
| | 2071.01 | | General Disposal | 5.10 cuyd | 105 | - | 27.16 /cuyd | 139 |
| | 2084.01 | | Remove Hardware | 136.00 each | 6,146 | - | 45.19 /each | 6,146 |
| | 8710.01 | | Finishing Hardware Ext Budget | 23.00 each | 5,197 | 27,667 | 1,428.88 /each | 32,864 |
| | 8710.01 | | Finishing Hardware Int Budget w Closure | 113.00 each | 15,320 | 90,141 | 933.29 /each | 105,461 |
| | | | 5T | | 26,769 | 117,808 | | 144,610 |
| 5W | | | | | | | | |
| | 4050.15 | | Concrete Block | 0.11 m | - | - | 262.79 /m | 29 |
| | 4050.15 | | Brick | 0.66 m | - | - | 88.30 /m | 58 |
| | 4105.00 | | Mortar Type "N" | 0.61 cuyd | 74 | 132 | 337.84 /cuyd | 206 |
| | 4105.00 | | Mortar Color | 18.00 lbs | - | 215 | 11.95 /lbs | 215 |
| | 4110.01 | | Grout Fill 3000 psi, 1/2" Gravl | 0.29 cuyd | 82 | 56 | 494.76 /cuyd | 143 |
| | 4156.00 | | Flash Sill Lead Ct. Cop 5 oz. | 49.00 sqft | 204 | 212 | 8.49 /sqft | 416 |
| | 4156.10 | | Weepholes - Metal | 25.00 each | 92 | 28 | 4.80 /each | 120 |
| | 4157.00 | | Re-Bar #5 & #6 | 75.10 lbs | 152 | 80 | 3.09 /lbs | 232 |
| | 4158.00 | | Horiz Wall Reinf 8" Hot Dippd | 0.10 mlf | 59 | 17 | 781.33 /mlf | 77 |
| | 4159.00 | | Brick Anchors Z Ties 8" | 55.00 each | 87 | 10 | 1.77 /each | 98 |
| | 4202.00 | | Standard Size Face Brick Infill | 0.66 m | 5,340 | 669 | 9,104.71 /m | 6,009 |
| | 4220.00 | | Blk 8" Stand Face Reg Wt - Infill | 111.00 each | 2,014 | 326 | 21.08 /each | 2,340 |
| | 4710.10 | | Clean Brick - General | 0.98 sqs | 281 | 7 | 293.24 /sqs | 287 |
| | 7186.00 | | Ashphalt Ct. Troweled 1/8" | 98.00 sqft | 225 | 77 | 3.08 /sqft | 302 |
| | 7212.00 | | Extruded Polystyrene 2.0" | 98.00 sqft | 106 | 171 | 2.83 /sqft | 277 |
| | 9920.01 | | Paint Int CMU Spray p+2ct | 98.00 sqft | 92 | 27 | 1.22 /sqft | 120 |
| | | | 5W | | 8,809 | 2,026 | | 10,928 |
| | | | 5 HC ACCESS | | 199,308 | 300,502 | | 506,494 |
| 6 FINISHES GEN | | | | | | | | |
| 6A | | | | | | | | |
| | 2071.01 | | General Disposal | 1.40 cuyd | 29 | - | 27.16 /cuyd | 38 |
| | 2088.50 | | Remove Acoust Tile | 152.00 sqft | 220 | - | 1.45 /sqft | 220 |
| | 9510.50 | | MinFbr Tegulr Std 2x4 3/4" < 250 sf | 152.00 sqft | 495 | 517 | 6.66 /sqft | 1,012 |
| | | | 6A | | 744 | 517 | | 1,270 |
| 6B | | | | | | | | |
| | 2071.01 | | General Disposal | 2.40 cuyd | 49 | - | 26.92 /cuyd | 65 |
| | 2076.00 | | Remove Brick Veneer | 200.00 sqft | 1,027 | - | 5.80 /sqft | 1,161 |
| | 4050.10 | | Exterior Scaffold | 200.00 sqft | 296 | 84 | 2.25 /sqft | 449 |
| | 4105.00 | | Mortar Type "N" | 0.70 cuyd | 85 | 152 | 337.84 /cuyd | 236 |
| | 4105.00 | | Mortar Color | 56.00 lbs | - | 669 | 11.95 /lbs | 669 |
| | 4159.00 | | Brick Anchors Z Ties 8" | 113.00 each | 179 | 21 | 1.77 /each | 200 |
| | 4202.00 | | Standard Size Face Brick Infill | 1.35 m | 10,922 | 1,369 | 9,104.42 /m | 12,291 |
| | 4520.01 | | Cut & Repoint CMU Hard Mortar | 68.00 lnft | 703 | 94 | 14.55 /lnft | 989 |
| | 4520.01 | | Remove CMU 8" Allow | 34.00 each | 2,027 | - | 64.85 /each | 2,205 |
| | 4520.01 | | Patch in 8" CMU Allow | 34.00 each | 1,011 | 91 | 32.41 /each | 1,102 |
| | 4710.10 | | Clean Brick - General | 2.00 sqs | 573 | 14 | 293.22 /sqs | 586 |
| | | | 6B | | 16,873 | 2,493 | | 19,954 |
| 6CC | | | | | | | | |
| | 3328.00 | | Patch Concrete Wall | 50.00 sqft | 677 | 1,197 | 37.49 /sqft | 1,874 |
| | | | 6CC | | 677 | 1,197 | | 1,874 |
| 6D | | | | | | | | |
| | 4520.01 | | Cut & Repoint Brick Soft Mortr | 185.00 sqft | 1,335 | 133 | 9.88 /sqft | 1,828 |
| | | | 6D | | 1,335 | 133 | | 1,828 |
| 6F | | | | | | | | |
| | 2071.01 | | General Disposal | 0.20 cuyd | 4 | - | 27.15 /cuyd | 5 |
| | 2079.00 | | Remove Soffit & Trim | 20.00 sqft | 90 | - | 4.49 /sqft | 90 |
| | 7240.00 | | Ext Cement Bd Finish System Soffit Infill | 20.00 sqft | 766 | 72 | 42.98 /sqft | 860 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|------------|-------|-------------------------------------|------------------|---------------|-----------------|-----------------|----------------|
| | 6F | | | | | | | |
| | 9910.01 | | Paint Ext Soffit 3 ct Infill | 20.00 sqft | 31 | 3 | 1.67 /sqft | 33 |
| | | | 6F | | 890 | 75 | | 988 |
| | 6KK | | | | | | | |
| | 9920.01 | | Paint Exist Int CMU Spray 2 ct | 58,873.00 sqft | 25,211 | 10,470 | 0.61 /sqft | 35,680 |
| | | | 6KK | | 25,211 | 10,470 | | 35,680 |
| | 6L | | | | | | | |
| | 4155.00 | | Control Jnt Rubber 8" Wall | 33.00 Inft | 129 | 122 | 7.59 /Inft | 250 |
| | 7910.01 | | Backer Rod ½" | 33.00 Inft | 100 | 3 | 3.12 /Inft | 103 |
| | 7910.01 | | Polyurethane Sealant 1/2" | 33.00 Inft | 314 | 16 | 10.02 /Inft | 331 |
| | 7910.01 | | Rake Out Masonry Jt. Filler | 33.00 Inft | 97 | 7 | 4.97 /Inft | 164 |
| | | | 6L | | 640 | 148 | | 848 |
| | 6M | | | | | | | |
| | 2071.01 | | General Disposal | 9.60 cuyd | 198 | - | 27.16 /cuyd | 261 |
| | 2084.01 | | Remove Window Treatment | 1,040.00 sqft | 501 | - | 0.48 /sqft | 501 |
| | 12510.01 | | Horiz 1" Alum Avg | 1,040.00 sqft | 1,504 | 7,530 | 8.69 /sqft | 9,034 |
| | | | 6M | | 2,202 | 7,530 | | 9,795 |
| | 6MM | | | | | | | |
| | 8110.01 | | H.M. Frame Repair Allow | 2.00 each | 396 | 173 | 284.16 /each | 568 |
| | | | 6MM | | 396 | 173 | | 568 |
| | 6N | | | | | | | |
| | 2071.01 | | General Disposal | 0.20 cuyd | 4 | - | 27.00 /cuyd | 5 |
| | 2084.50 | | Remove Basketball Backstops | 2.00 each | 1,284 | - | 642.01 /each | 1,284 |
| | 11490.01 | | Basketball Backboard Clg Swing | 2.00 each | 5,163 | 8,922 | 7,042.46 /each | 14,085 |
| | | | 6N | | 6,451 | 8,922 | | 15,374 |
| | 6P | | | | | | | |
| | 2071.01 | | General Disposal | 14.20 cuyd | 292 | - | 26.92 /cuyd | 382 |
| | 2088.50 | | Rem. Acoust Tile & Grid | 1,534.00 sqft | 1,847 | - | 1.20 /sqft | 1,847 |
| | 9510.50 | | Mylar Faced Std 2x4 3/4" 250-500 sf | 1,534.00 sqft | 2,120 | 6,061 | 5.33 /sqft | 8,181 |
| | | | 6P | | 4,259 | 6,061 | | 10,410 |
| | 6Q | | | | | | | |
| | 2071.01 | | General Disposal | 0.30 cuyd | 6 | - | 26.93 /cuyd | 8 |
| | 2088.01 | | Remove Expansion Joint | 16.00 Inft | 1,284 | - | 80.25 /Inft | 1,284 |
| | 5810.01 | | Embedded Floor Joint 2" Alum | 16.00 Inft | 329 | 393 | 45.12 /Inft | 722 |
| | | | 6Q | | 1,619 | 393 | | 2,014 |
| | 6QQ | | | | | | | |
| | 8520.01 | | Fasten Window Hardware Replacement | 40.00 sqft | 91 | 36 | 3.19 /sqft | 127 |
| | | | 6QQ | | 91 | 36 | | 127 |
| | 6R | | | | | | | |
| | 9210.01 | | Plaster Patch Ceiling | 20.00 sqft | 129 | 32 | 8.21 /sqft | 164 |
| | 9920.01 | | Paint GDW Infill Roller p + 2ct | 20.00 sqft | 19 | 4 | 1.15 /sqft | 23 |
| | | | 6R | | 148 | 36 | | 187 |
| | 6S | | | | | | | |
| | 9210.01 | | Plaster Patch @ Case Removal | 84.00 sqft | 1,398 | 149 | 18.81 /sqft | 1,580 |
| | | | 6S | | 1,398 | 149 | | 1,580 |
| | 6U | | | | | | | |
| | 9910.01 | | Paint Exist Metal Panel 2 ct | 228.00 sqft | 93 | 38 | 0.57 /sqft | 131 |
| | | | 6U | | 93 | 38 | | 131 |
| | 6YY | | | | | | | |
| | 2071.01 | | General Disposal | 0.40 cuyd | 8 | - | 26.90 /cuyd | 11 |
| | 2077.00 | | Remove Steel Floor | 20.00 sqft | 162 | - | 8.81 /sqft | 176 |
| | 3230.01 | | Wiremesh-Corroform 6x6 6/6 Infill | 0.20 sqs | 21 | 11 | 163.35 /sqs | 33 |
| | 3319.00 | | Conc @ Curruform 4000 psi Infill | 0.24 cuyd | 15 | 34 | 215.08 /cuyd | 52 |
| | 3375.00 | | Cure Conc w/burlap Elv. Slab Infill | 0.20 sqs | 8 | 2 | 54.50 /sqs | 11 |
| | 3380.01 | | Broom/Float Finish Elv. Slab Infill | 20.00 sqft | 27 | - | 1.36 /sqft | 27 |
| | 5312.10 | | Slab Form 1-1/2" 20 ga Galv infill | 20.00 sqft | 26 | 59 | 4.32 /sqft | 86 |
| | | | 6YY | | 267 | 107 | | 396 |
| | 6ZZ | | | | | | | |
| | 2071.01 | | General Disposal | 0.20 cuyd | 4 | - | 26.95 /cuyd | 5 |
| | 2084.01 | | Remove Int Bi-Fold Door | 1.00 each | 46 | - | 45.82 /each | 46 |
| | 8350.01 | | Door Bifold | 1.00 each | 135 | 151 | 286.01 /each | 286 |
| | 8710.01 | | Residential Hardware Int Budget | 1.00 set | 46 | 201 | 247.04 /set | 247 |
| | 9920.01 | | Paint Wd Door & Frame | 1.00 each | 65 | 15 | 79.78 /each | 80 |
| | | | 6ZZ | | 296 | 367 | | 664 |
| | | | 6 FINISHES GEN | | 63,591 | 38,845 | | 103,689 |

Estimate Totals

Estimate Totals

| | | | |
|-------------|---------------|-----------|-----|
| Labor | 814,026 | 9,223.716 | hrs |
| Material | 822,666 | | |
| Subcontract | 3,697 | | |
| Equipment | 63,373 | 1,419.281 | hrs |
| Other | <u>22,020</u> | | |
| | 1,725,782 | 1,725,782 | |
| | Total | 1,725,782 | |

HASTINGS ELEMENTARY SCHOOL RENOVATION
STUDY ESTIMATE - 11-25-08
LEXINGTON, MA

Project name **Hastings E.S.**
Lexington
MA

Architect **TDPC**

Estimator *Essential Estimating*

| Location | Labor Amount | Material Amount | Sub Amount | Equip Amount | Total Amount |
|-----------------|--------------|-----------------|------------|--------------|--------------|
| 1 LIFE SAFETY | 1,381 | 5,094 | | 19 | 6,494 |
| 2 BUILDING CODE | 6,281 | 8,179 | | 166 | 14,626 |
| 3 EXTERIOR | 347,701 | 452,507 | | 19,351 | 819,559 |
| 4 HAZARDOUS MAT | 198,164 | 119,574 | 1,387 | 25,462 | 354,577 |
| 5 HC ACCESS | 136,301 | 275,016 | | 3,673 | 414,990 |
| 6 FINISHES GEN | 167,151 | 37,872 | | 22,234 | 227,256 |

Estimate Totals

| | | | |
|--------------|------------------|------------------|-----|
| Labor | 856,978 | 9,163.423 | hrs |
| Material | 898,242 | | |
| Subcontract | 1,387 | | |
| Equipment | 70,905 | 2,319.138 | hrs |
| Other | 9,991 | | |
| | <u>1,837,503</u> | 1,837,503 | |
| Total | | 1,837,503 | |

| Location | Bid Item | Description | Labor Amount | Material Amount | Sub Amount | Equip Amount | Total Amount |
|------------------------|------------|------------------------|----------------|-----------------|--------------|---------------|----------------|
| 1 LIFE SAFETY | | | | | | | |
| | <u>1D</u> | | <u>1,085</u> | <u>4,813</u> | | | <u>5,897</u> |
| | <u>1E</u> | | <u>296</u> | <u>282</u> | | <u>19</u> | <u>597</u> |
| | | 1 LIFE SAFETY | 1,381 | 5,094 | | 19 | 6,494 |
| 2 BUILDING CODE | | | | | | | |
| | <u>2A</u> | | <u>176</u> | <u>301</u> | | | <u>477</u> |
| | <u>2I</u> | | <u>4,467</u> | <u>3,065</u> | | <u>166</u> | <u>7,699</u> |
| | <u>3F</u> | | <u>1,637</u> | <u>4,813</u> | | | <u>6,450</u> |
| | | 2 BUILDING CODE | 6,281 | 8,179 | | 166 | 14,626 |
| 3 EXTERIOR | | | | | | | |
| | <u>3A</u> | | <u>211,542</u> | <u>406,656</u> | | <u>480</u> | <u>618,678</u> |
| | <u>3B</u> | | <u>12,219</u> | <u>22,441</u> | | <u>423</u> | <u>35,083</u> |
| | <u>3C</u> | | <u>181</u> | <u>716</u> | | | <u>897</u> |
| | <u>3E</u> | | <u>49,352</u> | | | <u>16,499</u> | <u>65,851</u> |
| | <u>3L</u> | | <u>67,553</u> | <u>21,955</u> | | <u>1,948</u> | <u>91,456</u> |
| | <u>3P</u> | | <u>4,077</u> | <u>512</u> | | | <u>4,589</u> |
| | <u>3Q</u> | | <u>2,778</u> | <u>227</u> | | | <u>3,005</u> |
| | | 3 EXTERIOR | 347,701 | 452,507 | | 19,351 | 819,559 |
| 4 HAZARDOUS MAT | | | | | | | |
| | <u>4B</u> | | <u>65</u> | <u>3</u> | | | <u>68</u> |
| | <u>4C</u> | | <u>20,275</u> | <u>43,766</u> | | <u>251</u> | <u>64,293</u> |
| | <u>4D</u> | | <u>177,824</u> | <u>75,804</u> | <u>1,387</u> | <u>25,211</u> | <u>290,217</u> |
| | | 4 HAZARDOUS MAT | 198,164 | 119,574 | 1,387 | 25,462 | 354,577 |
| 5 HC ACCESS | | | | | | | |
| | <u>5A</u> | | <u>8,857</u> | <u>463</u> | | <u>927</u> | <u>10,247</u> |
| | <u>5B</u> | | <u>2,419</u> | <u>4,426</u> | | <u>26</u> | <u>6,871</u> |
| | <u>5D</u> | | <u>1,167</u> | | | <u>7</u> | <u>1,173</u> |
| | <u>5E</u> | | <u>241</u> | | | | <u>241</u> |
| | <u>5F</u> | | <u>6,811</u> | <u>7,734</u> | | <u>260</u> | <u>14,805</u> |
| | <u>5G</u> | | <u>17,480</u> | <u>56,451</u> | | <u>51</u> | <u>73,982</u> |
| | <u>5H</u> | | <u>54,961</u> | <u>27,792</u> | | <u>1,757</u> | <u>84,510</u> |
| | <u>5L</u> | | <u>6,920</u> | <u>30,689</u> | | <u>503</u> | <u>38,113</u> |
| | <u>5N</u> | | <u>3,928</u> | <u>2,795</u> | | <u>90</u> | <u>6,813</u> |
| | <u>5Q</u> | | <u>251</u> | | | <u>10</u> | <u>261</u> |
| | <u>5R</u> | | <u>326</u> | | | <u>3</u> | <u>329</u> |
| | <u>5T</u> | | <u>32,850</u> | <u>144,641</u> | | <u>39</u> | <u>177,530</u> |
| | <u>5V</u> | | <u>91</u> | <u>25</u> | | | <u>116</u> |
| | | 5 HC ACCESS | 136,301 | 275,016 | | 3,673 | 414,990 |
| 6 FINISHES GEN | | | | | | | |
| | <u>6A</u> | | <u>5,208</u> | <u>3,620</u> | | <u>65</u> | <u>8,893</u> |
| | <u>6AA</u> | | <u>615</u> | <u>65</u> | | | <u>680</u> |
| | <u>6B</u> | | <u>109,587</u> | <u>2,854</u> | | <u>21,493</u> | <u>133,933</u> |
| | <u>6BB</u> | | <u>828</u> | <u>1,838</u> | | <u>4</u> | <u>2,670</u> |
| | <u>6CC</u> | | <u>135</u> | <u>239</u> | | | <u>375</u> |
| | <u>6D</u> | | <u>1,372</u> | <u>137</u> | | <u>369</u> | <u>1,877</u> |
| | <u>6DD</u> | | <u>72</u> | <u>22</u> | | | <u>94</u> |
| | <u>6E</u> | | <u>4,382</u> | <u>2,353</u> | | <u>11</u> | <u>6,745</u> |
| | <u>6GG</u> | | <u>1,626</u> | <u>2,874</u> | | | <u>4,499</u> |
| | <u>6HH</u> | | <u>820</u> | | | | <u>820</u> |
| | <u>6JJ</u> | | <u>115</u> | <u>507</u> | | <u>6</u> | <u>628</u> |
| | <u>6KK</u> | | <u>22,519</u> | <u>9,351</u> | | | <u>31,870</u> |
| | <u>6MM</u> | | <u>198</u> | <u>86</u> | | | <u>284</u> |
| | <u>6NN</u> | | <u>663</u> | <u>459</u> | | <u>4</u> | <u>1,126</u> |
| | <u>6P</u> | | <u>2,943</u> | <u>4,189</u> | | <u>62</u> | <u>7,194</u> |
| | <u>6PP</u> | | <u>139</u> | <u>108</u> | | | <u>247</u> |
| | <u>6RR</u> | | <u>3,190</u> | <u>4,592</u> | | <u>18</u> | <u>7,800</u> |
| | <u>6SS</u> | | <u>1,055</u> | <u>76</u> | | | <u>1,131</u> |

| Location | Bid Item | Description | Labor Amount | Material Amount | Sub Amount | Equip Amount | Total Amount |
|----------|-----------|-----------------------|----------------|-----------------|------------|---------------|----------------|
| | | | <u>1,132</u> | <u>2,016</u> | | <u>25</u> | <u>3,173</u> |
| | <u>6W</u> | | <u>2,244</u> | <u>126</u> | | | <u>2,370</u> |
| | <u>6X</u> | | <u>1,326</u> | <u>691</u> | | <u>15</u> | <u>2,032</u> |
| | <u>6Y</u> | | <u>798</u> | <u>926</u> | | <u>8</u> | <u>1,733</u> |
| | <u>6Z</u> | | <u>6,185</u> | <u>742</u> | | <u>155</u> | <u>7,081</u> |
| | | 6 FINISHES GEN | 167,151 | 37,872 | | 22,234 | 227,256 |

Estimate Totals

| | | | | |
|--------------|------------------|------------------|-----------|-----|
| Labor | 856,978 | | 9,163.423 | hrs |
| Material | 898,241 | | | |
| Subcontract | 1,387 | | | |
| Equipment | 70,905 | | 2,319.138 | hrs |
| Other | <u>9,991</u> | | | |
| | 1,837,502 | 1,837,502 | | |
| Total | 1,837,502 | | | |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|------------------------|-----------|-------|---|------------------|----------------|-----------------|-----------------|----------------|
| 1 LIFE SAFETY | | | | | | | | |
| | 1D | | | | | | | |
| | 2084.01 | | Remove Hardware | 4.00 each | 181 | - | 45.20 /each | 181 |
| | 8710.01 | | Finishing Hardware Ext Budget | 4.00 each | 904 | 4,813 | 1,429.15 /each | 5,717 |
| | | | 1D | | 1,085 | 4,813 | | 5,897 |
| | 1E | | | | | | | |
| | 7145.00 | | Cement W.P. 1 ct 1/8" | 105.00 sqft | 296 | 282 | 5.68 /sqft | 597 |
| | | | 1E | | 296 | 282 | | 597 |
| | | | 1 LIFE SAFETY | | 1,381 | 5,094 | | 6,494 |
| 2 BUILDING CODE | | | | | | | | |
| | 2A | | | | | | | |
| | 2084.01 | | Remove Hardware | 1.00 each | 45 | - | 45.20 /each | 45 |
| | 8710.01 | | Door Closers | 1.00 each | 131 | 301 | 431.93 /each | 432 |
| | | | 2A | | 176 | 301 | | 477 |
| | 2I | | | | | | | |
| | 2071.01 | | General Disposal | 2.60 cuyd | 54 | - | 26.93 /cuyd | 70 |
| | 2088.01 | | Flash Patch @ Wall Removal | 22.00 sqft | 51 | 46 | 4.41 /sqft | 97 |
| | 2088.21 | | Remove Stud GWB Partition | 220.00 sqft | 825 | - | 3.75 /sqft | 825 |
| | 4050.10 | | Interior Scaffold | 220.00 sqft | 245 | 92 | 1.77 /sqft | 389 |
| | 4050.15 | | Concrete Block | 0.20 m | - | - | 243.90 /m | 49 |
| | 4105.00 | | Mortar Type "N" | 0.36 cuyd | 44 | 78 | 337.92 /cuyd | 122 |
| | 4110.01 | | Grout Fill 3000 psi, 1/2" Gravl | 0.78 cuyd | 220 | 150 | 494.53 /cuyd | 386 |
| | 4110.01 | | Grout Single Door Frame | 1.00 each | 64 | 20 | 88.70 /each | 89 |
| | 4157.00 | | Re-Bar #5 & #6 | 150.00 lbs | 303 | 160 | 3.09 /lbs | 463 |
| | 4158.00 | | Horiz Wall Reinf 6" Hot Dippd | 0.16 mlf | 71 | 27 | 615.44 /mlf | 98 |
| | 4221.20 | | Blk 6" 2 hr Stand Face Reg Wt | 78.00 each | 1,013 | 221 | 15.81 /each | 1,233 |
| | 4221.50 | | Lintel 6" Stand Face Lt Wt | 18.00 each | 42 | 24 | 3.63 /each | 65 |
| | 5510.35 | | Angle Bolted To Masonry | 86.00 lb | 304 | 259 | 6.74 /lb | 580 |
| | 6113.40 | | Rough Bucks 2 x 6 PT Doors | 17.00 lnft | 43 | 19 | 3.63 /lnft | 62 |
| | 7910.01 | | Polysulfide Sealant 1/4" Interior | 17.00 lnft | 159 | 4 | 9.60 /lnft | 163 |
| | 8110.01 | | H.M. Frame 18ga Interior Single | 1.00 each | 99 | 173 | 271.69 /each | 272 |
| | 8110.01 | | H.M. Door 18ga 3-0 x 7-0 Vision Lab | 1.00 each | 88 | 853 | 940.94 /each | 941 |
| | 8710.01 | | Finishing Hardware Int Budget w Closure | 1.00 each | 136 | 798 | 933.46 /each | 933 |
| | 9210.01 | | Plaster Patch @ Wall Removal | 20.00 sqft | 333 | 36 | 18.82 /sqft | 376 |
| | 9210.01 | | Plaster Patch Ceiling @ Wall Removal | 22.00 sqft | 120 | 35 | 7.17 /sqft | 158 |
| | 9920.01 | | Paint Metal Door & Frame | 1.00 each | 58 | 13 | 71.26 /each | 71 |
| | 9920.01 | | Paint Int CMU Spray p+2ct | 210.00 sqft | 198 | 59 | 1.22 /sqft | 257 |
| | | | 2I | | 4,467 | 3,065 | | 7,699 |
| | 3F | | | | | | | |
| | 2084.01 | | Remove Door | 4.00 each | 128 | - | 32.11 /each | 128 |
| | 2084.01 | | Remove Hardware | 4.00 each | 181 | - | 45.20 /each | 181 |
| | 8110.01 | | Re-Hang Door | 4.00 each | 424 | 0 | 106.05 /each | 424 |
| | 8710.01 | | Finishing Hardware Ext Budget | 4.00 each | 904 | 4,813 | 1,429.15 /each | 5,717 |
| | | | 3F | | 1,637 | 4,813 | | 6,450 |
| | | | 2 BUILDING CODE | | 6,281 | 8,179 | | 14,626 |
| 3 EXTERIOR | | | | | | | | |
| | 3A | | | | | | | |
| | 2071.01 | | General Disposal | 73.10 cuyd | 1,505 | - | 27.16 /cuyd | 1,986 |
| | 2084.01 | | Remove Metal Windows | 6,954.00 sqft | 21,769 | - | 3.13 /sqft | 21,769 |
| | 2084.01 | | Remove Translucent Panels | 936.00 sqft | 2,930 | - | 3.13 /sqft | 2,930 |
| | 4156.00 | | Flash Head Lead Ct. Cop 5 oz. | 1,168.00 sqft | 5,340 | 5,370 | 9.17 /sqft | 10,710 |
| | 4156.00 | | Flash Sill Lead Ct. Cop 5 oz. | 1,168.00 sqft | 4,869 | 5,044 | 8.49 /sqft | 9,913 |
| | 6015.00 | | Fastners & Misc | 1.00 lsum | - | 36 | 35.58 /lsum | 36 |
| | 6113.40 | | Rough Bucks 2 x 6 PT Windows | 3,152.00 lnft | 11,980 | 3,559 | 4.93 /lnft | 15,539 |
| | 7410.04 | | Translucent Panel System | 936.00 sqft | 15,175 | 26,994 | 45.05 /sqft | 42,169 |
| | 7910.01 | | Backer Rod 1/2" | 3,152.00 lnft | 9,553 | 289 | 3.12 /lnft | 9,842 |
| | 7910.01 | | Polyurethane Sealant 1/2" | 6,304.00 lnft | 60,047 | 3,135 | 10.02 /lnft | 63,182 |
| | 8520.01 | | Custom Proj 4" .125 w Ins Gl Kynar | 6,954.00 sqft | 78,374 | 362,230 | 63.36 /sqft | 440,603 |
| | | | 3A | | 211,542 | 406,656 | | 618,678 |
| | 3B | | | | | | | |
| | 2071.01 | | General Disposal | 64.40 cuyd | 1,326 | - | 27.16 /cuyd | 1,749 |
| | 2084.01 | | Remove Window Treatment | 6,954.00 sqft | 3,349 | - | 0.48 /sqft | 3,349 |
| | 12520.01 | | Vinyl Heavy Wt | 6,954.00 sqft | 7,544 | 22,441 | 4.31 /sqft | 29,985 |
| | | | 3B | | 12,219 | 22,441 | | 35,083 |
| | 3C | | | | | | | |
| | 8565.00 | | Window Screens/Wicket (Aluminum) | 96.00 sqft | 181 | 716 | 9.34 /sqft | 897 |
| | | | 3C | | 181 | 716 | | 897 |
| | 3E | | | | | | | |
| | 2060.00 | | Small Building Wood | 100,160.00 cuft | 23,441 | - | 0.36 /cuft | 35,733 |
| | 2060.00 | | Disposal Building | 857.00 cuyd | 7,488 | - | 11.77 /cuyd | 10,082 |
| | 2075.00 | | Remove Conc Walls 8" | 1,104.00 sqft | 18,423 | - | 18.15 /sqft | 20,035 |
| | | | 3E | | 49,352 | | | 65,851 |
| | 3L | | | | | | | |
| | 2071.01 | | General Disposal | 27.80 cuyd | 572 | - | 26.93 /cuyd | 749 |
| | 2076.00 | | Remove Brick & Block Wall | 751.00 sqft | 7,300 | - | 10.55 /sqft | 7,921 |
| | 4050.10 | | Exterior Scaffold | 751.00 sqft | 1,113 | 315 | 2.25 /sqft | 1,687 |
| | 4050.10 | | Interior Scaffold | 751.00 sqft | 835 | 315 | 1.76 /sqft | 1,322 |
| | 4050.15 | | Concrete Block | 1.00 m | - | - | 243.88 /m | 244 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|------------------------|----------|---|-------------|------------------|----------------|-----------------|-----------------|----------------|
| 3L | | | | | | | | |
| | 4050.15 | Brick | | 4.00 m | - | - | 81.94 /m | 328 |
| | 4105.00 | Mortar Type "N" | | 3.75 cuyd | 455 | 812 | 337.92 /cuyd | 1,267 |
| | 4105.00 | Mortar Color | | 114.00 lbs | - | 1,362 | 11.95 /lbs | 1,362 |
| | 4110.01 | Grout Fill 3000 psi, 1/2" Gravl | | 2.71 cuyd | 763 | 521 | 493.87 /cuyd | 1,338 |
| | 4156.00 | Flash Head Lead Ct. Cop 5 oz. | | 32.00 sqft | 146 | 147 | 9.17 /sqft | 293 |
| | 4156.00 | Flash Sill Lead Ct. Cop 5 oz. | | 32.00 sqft | 133 | 138 | 8.49 /sqft | 272 |
| | 4156.00 | Flash Shelf Lead Ct. Cop 5 oz. | | 41.00 sqft | 149 | 170 | 7.77 /sqft | 318 |
| | 4156.10 | Weepholes - Metal | | 21.00 each | 78 | 23 | 4.80 /each | 101 |
| | 4157.00 | Re-Bar #7 & #8 | | 676.56 lb | 1,074 | 702 | 2.63 /lb | 1,776 |
| | 4158.00 | Horiz Wall Reinf 8" Hot Dippd | | 0.49 mlf | 296 | 87 | 781.60 /mlf | 383 |
| | 4159.00 | Brick Anchors Z Ties 8" | | 333.00 each | 529 | 62 | 1.77 /each | 591 |
| | 4202.00 | Standard Size Face Brick Infill | | 3.99 m | 32,288 | 4,046 | 9,106.21 /m | 36,334 |
| | 4220.00 | Blk 8" Stand Face Reg Wt - Infill | | 610.00 each | 11,072 | 1,790 | 21.09 /each | 12,862 |
| | 4221.45 | Lintel 8" Stand Face Reg Wt | | 55.00 each | 1,073 | 429 | 28.72 /each | 1,580 |
| | 4710.10 | Clean Brick - General | | 5.91 sqs | 1,693 | 40 | 293.28 /sqs | 1,733 |
| | 5510.05 | Stl Angles 1000 - 2000 lbs | | 287.00 lb | 538 | 419 | 3.34 /lb | 958 |
| | 5510.35 | Angle Bolted To Masonry | | 86.00 lb | 304 | 259 | 6.74 /lb | 580 |
| | 6113.40 | Rough Bucks 2 x 6 PT Windows | | 94.00 lnft | 357 | 106 | 4.93 /lnft | 463 |
| | 6413.00 | Window Stools (Wood) | | 32.00 lnft | 213 | 241 | 14.20 /lnft | 454 |
| | 6413.00 | Apron At Stools | | 32.00 lnft | 105 | 85 | 5.94 /lnft | 190 |
| | 7186.00 | Ashphalt Ct. Sprayed 2 cts. | | 591.00 sqft | 1,297 | 278 | 2.67 /sqft | 1,576 |
| | 7212.00 | Extruded Polystyrene 2.0" | | 591.00 sqft | 641 | 1,029 | 2.83 /sqft | 1,670 |
| | 7910.01 | Backer Rod 1/2" | | 94.00 lnft | 285 | 9 | 3.12 /lnft | 294 |
| | 7910.01 | Polyurethane Sealant 1/2" | | 188.00 lnft | 1,791 | 93 | 10.02 /lnft | 1,884 |
| | 8520.01 | Custom Proj 4" .125 w Ins Gl Kynar | | 160.00 sqft | 1,803 | 8,334 | 63.36 /sqft | 10,138 |
| | 9920.01 | Paint Wood Sill | | 32.00 lnft | 107 | 5 | 3.51 /lnft | 112 |
| | 9920.01 | Paint Wood Apron | | 32.00 lnft | 96 | 4 | 3.11 /lnft | 100 |
| | 9920.01 | Paint Int CMU Spray p+2ct | | 473.00 sqft | 446 | 132 | 1.22 /sqft | 578 |
| | | 3L | | | 67,553 | 21,955 | | 91,456 |
| 3P | | | | | | | | |
| | 4520.01 | ReGrout Stone Hard Mortar | | 533.00 sqft | 4,077 | 512 | 8.61 /sqft | 4,589 |
| | | 3P | | | 4,077 | 512 | | 4,589 |
| 3Q | | | | | | | | |
| | 9910.01 | Scrape & Prep Ext Misc Surfaces Lintels | | 746.00 sqft | 1,214 | - | 1.63 /sqft | 1,214 |
| | 9910.01 | Paint Ext Misc Exposed Metal Lintels | | 746.00 sqft | 1,563 | 227 | 2.40 /sqft | 1,791 |
| | | 3Q | | | 2,778 | 227 | | 3,005 |
| | | 3 EXTERIOR | | | 347,701 | 452,507 | | 819,559 |
| 4 HAZARDOUS MAT | | | | | | | | |
| 4B | | | | | | | | |
| | 2073.00 | Remove Asbestos Shelf | | 4.00 sqft | 65 | 3 | 16.92 /sqft | 68 |
| | | 4B | | | 65 | 3 | | 68 |
| 4C | | | | | | | | |
| | 2071.01 | General Disposal | | 39.60 cuyd | 815 | - | 26.93 /cuyd | 1,066 |
| | 2080.01 | Remove Casework | | 178.00 lnft | 929 | - | 5.22 /lnft | 929 |
| | 6113.20 | Blocking 2 x 6 R.L. | | 178.00 lnft | 611 | 121 | 4.11 /lnft | 732 |
| | 12350.00 | School Casework Base & Top | | 178.00 lnft | 17,920 | 43,646 | 345.87 /lnft | 61,565 |
| | | 4C | | | 20,275 | 43,766 | | 64,293 |
| 4D | | | | | | | | |
| | 2073.00 | Remove Vinyl Asbestos Tile | | 19,002.00 sqft | 43,858 | - | 2.31 /sqft | 43,858 |
| | 2073.00 | Vacuum Cleaner 16 gal | | 1.00 each | - | 1,076 | 1,076.10 /each | 1,076 |
| | 2073.00 | Final Cleaning | | 19,002.00 sqft | 4,873 | - | 0.26 /sqft | 4,873 |
| | 2073.00 | Testing | | 3.00 day | - | - | 462.23 /day | 1,387 |
| | 2073.00 | Collect & Bulk Mat'l Bulk 3cf bags | | 1,584.00 bags | 9,885 | 1,630 | 7.27 /bags | 11,515 |
| | 2073.00 | Cart Bags | | 1,584.00 bags | 5,416 | - | 3.42 /bags | 5,416 |
| | 2073.00 | Disposal Minimum | | 176.00 cuyd | - | - | 56.77 /cuyd | 9,991 |
| | 2088.01 | Shotblast Floor | | 19,002.00 sqft | 16,772 | - | 1.39 /sqft | 26,419 |
| | 3326.00 | Leveling Compound | | 19,002.00 sqft | 72,610 | 35,742 | 6.52 /sqft | 123,915 |
| | 9660.01 | Floor Vinyl Composition Tile 1/8" | | 19,002.00 sqft | 20,234 | 35,061 | 2.91 /sqft | 55,294 |
| | 9660.01 | Floor Resil Base 4" | | 2,876.00 lnft | 4,176 | 2,296 | 2.25 /lnft | 6,472 |
| | | 4D | | | 177,824 | 75,804 | | 290,217 |
| | | 4 HAZARDOUS MAT | | | 198,164 | 119,574 | | 354,577 |
| 5 HC ACCESS | | | | | | | | |
| 5A | | | | | | | | |
| | 2071.01 | General Disposal | | 47.00 cuyd | 968 | - | 27.16 /cuyd | 1,277 |
| | 2076.00 | Cut Out Opng 4" CMU | | 40.00 sqft | 1,079 | - | 29.35 /sqft | 1,174 |
| | 2076.00 | Sawcut 4" CMU | | 40.00 lnft | 754 | - | 30.99 /lnft | 1,240 |
| | 2076.00 | Tooth Jams 1 Wythe | | 40.00 lnft | 1,235 | - | 30.89 /lnft | 1,235 |
| | 2084.01 | Remove Door | | 13.00 each | 417 | - | 32.11 /each | 417 |
| | 2084.50 | Remove Lockers | | 8.00 each | 184 | - | 22.96 /each | 184 |
| | 2088.01 | Flash Patch @ Wall Removal | | 4.00 sqft | 9 | 8 | 4.41 /sqft | 18 |
| | 4050.10 | Interior Scaffold | | 40.00 sqft | 44 | 17 | 1.77 /sqft | 71 |
| | 4050.15 | Concrete Block | | 0.05 m | - | - | 244.00 /m | 11 |
| | 4105.00 | Mortar Type "N" | | 0.06 cuyd | 7 | 13 | 338.00 /cuyd | 20 |
| | 4110.01 | Grout Fill 3000 psi, 1/2" Gravl | | 0.03 cuyd | 8 | 6 | 497.30 /cuyd | 15 |
| | 4157.00 | Re-Bar #5 & #6 | | 41.72 lbs | 84 | 45 | 3.09 /lbs | 129 |
| | 4158.00 | Horiz Wall Reinf 4" Hot Dippd | | 0.03 mlf | 13 | 4 | 568.30 /mlf | 17 |
| | 4221.25 | Blk 4" Standard Face Reg Wt | | 45.00 each | 516 | 71 | 13.04 /each | 587 |
| | 8210.01 | Rehang Door | | 13.00 each | 1,693 | - | 130.24 /each | 1,693 |
| | 9210.01 | Plaster Patch @ Wall Removal | | 40.00 sqft | 666 | 71 | 18.83 /sqft | 753 |
| | 9210.01 | Plaster Patch Ceiling @ Wall Removal | | 4.00 sqft | 22 | 6 | 7.17 /sqft | 29 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|-----------|----------|-----------|---|------------------|---------------|-----------------|-----------------|---------------|
| 5A | | | | | | | | |
| | 9920.01 | | Paint Wd Door & Metal Frame & Prep | 13.00 each | 1,095 | 205 | 99.96 /each | 1,299 |
| | 9920.01 | | Paint Int CMU Spray p+2ct | 64.00 sqft | 60 | 18 | 1.22 /sqft | 78 |
| | | 5A | | | 8,857 | 463 | | 10,247 |
| 5B | | | | | | | | |
| | 2071.01 | | General Disposal | 4.00 cuyd | 82 | - | 27.17 /cuyd | 109 |
| | 2080.01 | | Remove Casework | 18.00 lnft | 94 | - | 5.22 /lnft | 94 |
| | 2088.60 | | Remove Sink | 3.00 each | 368 | - | 122.82 /each | 368 |
| | 6113.20 | | Blocking 2 x 6 R.L. | 18.00 lnft | 62 | 12 | 4.11 /lnft | 74 |
| | 12350.00 | | School Casework Base & Top | 18.00 lnft | 1,812 | 4,414 | 345.87 /lnft | 6,226 |
| | | 5B | | | 2,419 | 4,426 | | 6,871 |
| 5D | | | | | | | | |
| | 2071.01 | | General Disposal | 1.00 cuyd | 21 | - | 27.16 /cuyd | 27 |
| | 2088.60 | | Remove Drinking Fountain | 7.00 each | 1,146 | - | 163.72 /each | 1,146 |
| | | 5D | | | 1,167 | | | 1,173 |
| 5E | | | | | | | | |
| | 2084.50 | | Remove TV | 4.00 each | 241 | - | 60.20 /each | 241 |
| | | 5E | | | 241 | | | 241 |
| 5F | | | | | | | | |
| | 2071.01 | | General Disposal | 1.10 cuyd | 23 | - | 27.16 /cuyd | 30 |
| | 2077.00 | | Remove Steel Rail | 116.00 lnft | 1,164 | - | 10.03 /lnft | 1,164 |
| | 5510.80 | | Stair Railing Steel 1-1/2" 2 pipe | 9.00 lnft | 228 | 362 | 66.77 /lnft | 601 |
| | 5510.80 | | Stair Railing Galv 1-1/2" 2 pipe | 9.00 lnft | 228 | 496 | 81.63 /lnft | 735 |
| | 5510.80 | | Stair Railing Steel 1-1/2" 6 pipe | 62.00 lnft | 3,676 | 6,038 | 159.64 /lnft | 9,897 |
| | 5510.80 | | Wall Rail Steel 1-1/2" 1 pipe | 36.00 lnft | 922 | 743 | 47.56 /lnft | 1,712 |
| | 9920.01 | | Paint Int Pipe Rails | 444.00 lnft | 571 | 96 | 1.50 /lnft | 666 |
| | | 5F | | | 6,811 | 7,734 | | 14,805 |
| 5G | | | | | | | | |
| | 2071.01 | | General Disposal | 7.80 cuyd | 161 | - | 27.16 /cuyd | 212 |
| | 2084.50 | | Remove Toilet Partitions | 14.00 each | 1,124 | - | 80.27 /each | 1,124 |
| | 2084.50 | | Remove Toilet Accessories | 71.00 each | 712 | - | 10.03 /each | 712 |
| | 6113.20 | | Block Toilet Partition | 24.00 each | 723 | 287 | 42.05 /each | 1,009 |
| | 6113.20 | | Block H.C. Toilet Partition | 8.00 each | 362 | 118 | 59.94 /each | 480 |
| | 6113.20 | | Block Misc Toilet Accessories | 138.00 each | 2,495 | 693 | 23.10 /each | 3,188 |
| | 10160.02 | | Toilet Partition Reg Flr Mtd | 13.00 each | 2,755 | 18,861 | 1,662.79 /each | 21,616 |
| | 10160.02 | | Toilet Partition HC Flr Mtd | 8.00 each | 1,695 | 13,365 | 1,882.59 /each | 15,061 |
| | 10160.02 | | Urinal Screens Wall Hung | 11.00 each | 1,632 | 5,115 | 613.31 /each | 6,746 |
| | 10800.01 | | Grab Bar 1-1/4" S.S. 36" | 16.00 each | 579 | 623 | 75.10 /each | 1,202 |
| | 10800.01 | | Mirror 18" x 30" S.S. | 20.00 each | 940 | 1,605 | 127.24 /each | 2,545 |
| | 10800.01 | | Sanitary Napkin Dispenser Recessed | 4.00 each | 193 | 4,142 | 1,083.62 /each | 4,334 |
| | 10800.01 | | Clothes Hook Single | 19.00 each | 381 | 365 | 39.25 /each | 746 |
| | 10800.01 | | Soap Dispenser | 20.00 each | 1,446 | 4,142 | 279.41 /each | 5,588 |
| | 10800.01 | | Stainless Steel Shelf | 30.00 lnft | 494 | 1,142 | 54.50 /lnft | 1,635 |
| | 10800.01 | | Toilet Tissue Disp Dbl | 21.00 each | 632 | 578 | 57.61 /each | 1,210 |
| | 10800.01 | | Towel Disp/Waste Recept | 8.00 each | 1,157 | 5,417 | 821.81 /each | 6,574 |
| | | 5G | | | 17,480 | 56,451 | | 73,982 |
| 5H | | | | | | | | |
| | 2071.01 | | General Disposal | 21.20 cuyd | 437 | - | 27.16 /cuyd | 576 |
| | 2075.00 | | Saw Concrete Slab to 6" | 92.00 lnft | 501 | - | 7.56 /lnft | 695 |
| | 2075.00 | | Chip out Slab | 64.00 sqft | 791 | 6 | 14.11 /sqft | 903 |
| | 2076.00 | | Remove CMU 6" | 710.00 sqft | 2,588 | - | 3.97 /sqft | 2,816 |
| | 2084.50 | | Remove Toilet Accessories | 28.00 each | 281 | - | 10.03 /each | 281 |
| | 2088.01 | | Remove Ceramic Tile Floor | 168.00 sqft | 310 | - | 1.85 /sqft | 310 |
| | 2088.01 | | Flash Patch @ Wall Removal | 71.00 sqft | 164 | 150 | 4.41 /sqft | 313 |
| | 2088.50 | | Remove Plaster Ceiling Metal Lath | 168.00 sqft | 378 | - | 2.25 /sqft | 378 |
| | 2088.60 | | Remove Sink | 7.00 each | 860 | - | 122.82 /each | 860 |
| | 2088.60 | | Remove Water Closet | 7.00 each | 983 | - | 140.39 /each | 983 |
| | 3310.01 | | Patch Conc. Slab Trench etc. | 92.00 sqft | 499 | 1,087 | 17.23 /sqft | 1,586 |
| | 4050.10 | | Interior Scaffold | 1,120.00 sqft | 1,245 | 470 | 1.77 /sqft | 1,982 |
| | 4050.15 | | Concrete Block | 2.00 m | - | - | 243.89 /m | 488 |
| | 4105.00 | | Mortar Type "N" | 1.98 cuyd | 240 | 429 | 337.92 /cuyd | 669 |
| | 4110.01 | | Grout Fill 3000 psi, 1/2" Gravl | 0.93 cuyd | 262 | 179 | 494.65 /cuyd | 460 |
| | 4110.01 | | Grout Single Door Frame | 7.00 each | 445 | 143 | 88.71 /each | 621 |
| | 4157.00 | | Re-Bar #5 & #6 | 198.17 lbs | 400 | 211 | 3.09 /lbs | 612 |
| | 4158.00 | | Horiz Wall Reinf 6" Hot Dippd | 0.80 mlf | 356 | 136 | 615.49 /mlf | 492 |
| | 4221.20 | | Blk 6" Standard Face Reg Wt | 971.00 each | 11,872 | 2,181 | 14.47 /each | 14,053 |
| | 4221.50 | | Lintel 6" Stand Face Reg Wt | 100.00 each | 1,858 | 657 | 26.60 /each | 2,660 |
| | 5510.35 | | Angle Bolted To Masonry | 400.00 lb | 1,413 | 1,204 | 6.74 /lb | 2,696 |
| | 6113.20 | | Block Misc Toilet Accessories | 53.00 each | 958 | 266 | 23.10 /each | 1,224 |
| | 6113.40 | | Rough Bucks 2 x 6 Doors | 119.00 lnft | 298 | 81 | 3.18 /lnft | 379 |
| | 7910.01 | | Polysulfide Sealant 1/4" Interior | 119.00 lnft | 1,116 | 26 | 9.60 /lnft | 1,143 |
| | 8110.01 | | H.M. Frame 18ga Interior Single | 7.00 each | 692 | 1,209 | 271.69 /each | 1,902 |
| | 8210.01 | | Door M Core 3-0 x 7-0 Louver | 7.00 each | 966 | 3,486 | 635.96 /each | 4,452 |
| | 8710.01 | | Finishing Hardware Int Budget w Closure | 7.00 each | 949 | 5,585 | 933.46 /each | 6,534 |
| | 9210.01 | | Plaster Patch @ Wall Removal | 120.00 sqft | 1,998 | 213 | 18.83 /sqft | 2,260 |
| | 9210.01 | | Plaster Patch Ceiling @ Wall Removal | 71.00 sqft | 386 | 113 | 7.17 /sqft | 509 |
| | 9253.30 | | GWB 5/8" Water Resistant Clgs | 448.00 sqft | 415 | 194 | 1.36 /sqft | 609 |
| | 9254.00 | | Labor GWB Ceiling Finish | 448.00 sqft | 499 | 34 | 1.19 /sqft | 533 |
| | 9310.01 | | Ceramic Tile Floor Grade 2 | 448.00 sqft | 6,240 | 2,720 | 20.00 /sqft | 8,960 |
| | 9310.01 | | Ceramic Trim: Cove Base | 224.00 lnft | 5,738 | 976 | 29.98 /lnft | 6,714 |
| | 9510.10 | | Susp Clg 1-1/2" Channel | 448.00 sqft | 1,504 | 700 | 4.92 /sqft | 2,204 |
| | 9920.01 | | Paint Wd Door & Metal Frame | 7.00 each | 491 | 100 | 84.45 /each | 591 |
| | 9920.01 | | Epoxy Paint GDW Clg | 448.00 sqft | 1,036 | 353 | 3.10 /sqft | 1,389 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|-----------------------|----------|-------|---|------------------|----------------|-----------------|-----------------|----------------|
| 5H | | | | | | | | |
| | 9920.01 | | Paint Int CMU Spray p+2ct | 749.00 sqft | 706 | 209 | 1.22 /sqft | 915 |
| | 9920.01 | | Epoxy Paint Int CMU | 749.00 sqft | 1,732 | 628 | 3.15 /sqft | 2,360 |
| | 9920.01 | | Epoxy Paint Exist Int CMU | 896.00 sqft | 1,305 | 501 | 2.02 /sqft | 1,806 |
| | 10800.01 | | Grab Bar 1-1/4" S.S. 36" | 14.00 each | 506 | 545 | 75.10 /each | 1,051 |
| | 10800.01 | | Mirror 18" x 30" S.S. | 7.00 each | 329 | 562 | 127.24 /each | 891 |
| | 10800.01 | | Soap Dispenser | 7.00 each | 506 | 1,450 | 279.41 /each | 1,956 |
| | 10800.01 | | Stainless Steel Shelf | 11.00 Inft | 181 | 419 | 54.50 /Inft | 600 |
| | 10800.01 | | Toilet Tissue Disp Dbl | 7.00 each | 211 | 193 | 57.61 /each | 403 |
| | 10800.01 | | Towel Dispenser Surface Mtd | 7.00 each | 316 | 377 | 99.01 /each | 693 |
| | | | 5H | | 54,961 | 27,792 | | 84,510 |
| 5L | | | | | | | | |
| | 2071.01 | | General Disposal | 0.50 cuyd | 10 | - | 27.18 /cuyd | 14 |
| | 2075.00 | | Saw Concrete Slab to 6" | 44.00 Inft | 240 | - | 7.56 /Inft | 333 |
| | 2075.00 | | Chip out Slab | 56.00 sqft | 692 | 5 | 14.11 /sqft | 790 |
| | 14405.00 | | Lift Commercial | 2.00 each | 5,978 | 30,684 | 18,488.17 /each | 36,976 |
| | | | 5L | | 6,920 | 30,689 | | 38,113 |
| 5N | | | | | | | | |
| | 3131.00 | | Ramp Forms 2 use | 296.00 Inft | 2,341 | 527 | 9.69 /Inft | 2,867 |
| | 3225.00 | | Wiremesh - Ramp 6x6 6/6 | 4.24 sqs | 293 | 216 | 119.99 /sqs | 509 |
| | 3309.50 | | Ramp Conc 4000 psi | 7.85 cuyd | 361 | 1,113 | 196.62 /cuyd | 1,543 |
| | 3375.00 | | Cure Conc w/burlap Ramp | 4.24 sqs | 109 | 50 | 37.42 /sqs | 159 |
| | 3380.01 | | Broom/Float Finish Ramp | 424.00 sqft | 373 | - | 0.88 /sqft | 373 |
| | 5510.80 | | Stair Railing Galv 1-1/2" 2 pipe | 16.00 Inft | 405 | 881 | 81.63 /Inft | 1,306 |
| | 9910.01 | | Paint Ext Stair Hand 1 Rail | 32.00 Inft | 47 | 9 | 1.74 /Inft | 56 |
| | | | 5N | | 3,928 | 2,795 | | 6,813 |
| 5Q | | | | | | | | |
| | 2071.01 | | General Disposal | 0.50 cuyd | 10 | - | 27.18 /cuyd | 14 |
| | 2075.00 | | Remove Locker Base | 2.00 Inft | 34 | - | 20.38 /Inft | 41 |
| | 2084.50 | | Relocate Lockers | 2.00 each | 206 | - | 103.23 /each | 206 |
| | | | 5Q | | 251 | | | 261 |
| 5R | | | | | | | | |
| | 2071.01 | | General Disposal | 0.40 cuyd | 8 | - | 26.93 /cuyd | 11 |
| | 2084.50 | | Remove Kitchen Serve | 22.00 Inft | 318 | - | 14.45 /Inft | 318 |
| | | | 5R | | 326 | | | 329 |
| 5T | | | | | | | | |
| | 2071.01 | | General Disposal | 6.00 cuyd | 124 | - | 27.16 /cuyd | 163 |
| | 2084.01 | | Remove Hardware | 163.00 each | 7,368 | - | 45.20 /each | 7,368 |
| | 8710.01 | | Finishing Hardware Ext Budget | 36.00 each | 8,136 | 43,313 | 1,429.15 /each | 51,449 |
| | 8710.01 | | Finishing Hardware Int Budget w Closure | 127.00 each | 17,222 | 101,328 | 933.46 /each | 118,550 |
| | | | 5T | | 32,850 | 144,641 | | 177,530 |
| 5V | | | | | | | | |
| | 15250.00 | | Fiberglass 1" Pipe | 16.00 Inft | 91 | 25 | 7.24 /Inft | 116 |
| | | | 5V | | 91 | 25 | | 116 |
| | | | 5 HC ACCESS | | 136,301 | 275,016 | | 414,990 |
| 6 FINISHES GEN | | | | | | | | |
| 6A | | | | | | | | |
| | 2071.01 | | General Disposal | 9.90 cuyd | 204 | - | 27.17 /cuyd | 269 |
| | 2088.50 | | Remove Acoust Tile | 1,064.00 sqft | 1,537 | - | 1.45 /sqft | 1,537 |
| | 9510.50 | | MinFbr Tegulr Std 2x4 3/4" < 250 sf | 1,064.00 sqft | 3,467 | 3,620 | 6.66 /sqft | 7,087 |
| | | | 6A | | 5,208 | 3,620 | | 8,893 |
| 6AA | | | | | | | | |
| | 9910.01 | | Paint Exist Fascia 2 ct | 290.00 Inft | 403 | 41 | 1.53 /Inft | 443 |
| | 9910.01 | | Paint Exist Ext Soffit 2 ct | 216.00 sqft | 212 | 25 | 1.10 /sqft | 237 |
| | | | 6AA | | 615 | 65 | | 680 |
| 6B | | | | | | | | |
| | 4520.01 | | Cut & Repoint CMU Hard Mortar | 339.00 Inft | 3,506 | 469 | 14.55 /Inft | 4,933 |
| | 4520.01 | | Cut & Repoint Brick Soft Mortr | 658.00 sqft | 4,751 | 474 | 9.88 /sqft | 6,501 |
| | 4520.01 | | Remove Individual Brick Allow | 1,013.00 each | 68,097 | - | 85.36 /each | 86,470 |
| | 4520.01 | | Patch Individual Brick Allow | 1,013.00 each | 18,131 | 1,459 | 19.34 /each | 19,590 |
| | 4520.01 | | Remove CMU 8" Allow | 169.00 each | 10,076 | - | 64.86 /each | 10,961 |
| | 4520.01 | | Patch in 8" CMU Allow | 169.00 each | 5,027 | 451 | 32.41 /each | 5,478 |
| | | | 6B | | 109,587 | 2,854 | | 133,933 |
| 6BB | | | | | | | | |
| | 2071.01 | | General Disposal | 0.60 cuyd | 12 | - | 27.15 /cuyd | 16 |
| | 2080.05 | | Remove Fascia | 63.00 Inft | 248 | - | 3.93 /Inft | 248 |
| | 7620.30 | | Fascia Copper 12" | 63.00 Inft | 568 | 1,838 | 38.19 /Inft | 2,406 |
| | | | 6BB | | 828 | 1,838 | | 2,670 |
| 6CC | | | | | | | | |
| | 3328.00 | | Patch Concrete Wall | 10.00 sqft | 135 | 239 | 37.50 /sqft | 375 |
| | | | 6CC | | 135 | 239 | | 375 |
| 6D | | | | | | | | |
| | 4520.01 | | Cut & Repoint Brick Soft Mortr | 190.00 sqft | 1,372 | 137 | 9.88 /sqft | 1,877 |
| | | | 6D | | 1,372 | 137 | | 1,877 |
| 6DD | | | | | | | | |
| | 2079.00 | | Remove Trim to 6" Window | 8.00 Inft | 8 | - | 1.05 /Inft | 8 |
| | 6450.85 | | Window Trim Select | 8.00 Inft | 49 | 20 | 8.62 /Inft | 69 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|------------|-------|---|------------------|---------------|-----------------|-----------------|---------------|
| | 6DD | | | | | | | |
| | 9910.01 | | Paint Ext Wood Trim | 8.00 sqft | 14 | 2 | 2.04 /sqft | 16 |
| | | | 6DD | | 72 | 22 | | 94 |
| | 6E | | | | | | | |
| | 2071.01 | | General Disposal | 1.60 cuyd | 33 | - | 27.17 /cuyd | 43 |
| | 2088.70 | | Remove Louvers | 43.00 sqft | 494 | - | 11.48 /sqft | 494 |
| | 5510.05 | | Stl Angles 1000 - 2000 lbs | 221.00 lb | 415 | 323 | 3.34 /lb | 738 |
| | 6113.40 | | 2 x 6 PT Louvers | 70.00 lnft | 188 | 79 | 3.82 /lnft | 267 |
| | 7910.01 | | Backer Rod ½" | 70.00 lnft | 212 | 6 | 3.12 /lnft | 219 |
| | 7910.01 | | Polysulfide Sealant 1/4" Interior | 140.00 lnft | 1,313 | 31 | 9.60 /lnft | 1,344 |
| | 9920.01 | | Paint Louvers | 43.00 sqft | 74 | 15 | 2.06 /sqft | 88 |
| | 15856.00 | | Fixed Blade Stormproof | 43.00 sqft | 1,654 | 1,898 | 82.61 /sqft | 3,552 |
| | | | 6E | | 4,382 | 2,353 | | 6,745 |
| | 6GG | | | | | | | |
| | 3328.00 | | Patch Concrete Wall | 120.00 sqft | 1,626 | 2,874 | 37.50 /sqft | 4,499 |
| | | | 6GG | | 1,626 | 2,874 | | 4,499 |
| | 6HH | | | | | | | |
| | 7620.30 | | Refasten Fascia | 61.00 lnft | 820 | 0 | 13.45 /lnft | 820 |
| | | | 6HH | | 820 | | | 820 |
| | 6JJ | | | | | | | |
| | 5516.00 | | Grate Weld StlGlv 3/4 x 1/8 | 30.00 sqft | 115 | 507 | 20.94 /sqft | 628 |
| | | | 6JJ | | 115 | 507 | | 628 |
| | 6KK | | | | | | | |
| | 9920.01 | | Paint Exist Int CMU Spray 2 ct | 52,576.00 sqft | 22,519 | 9,352 | 0.61 /sqft | 31,870 |
| | | | 6KK | | 22,519 | 9,352 | | 31,870 |
| | 6MM | | | | | | | |
| | 8110.01 | | H.M. Frame Repair Allow | 1.00 each | 198 | 86 | 284.22 /each | 284 |
| | | | 6MM | | 198 | 86 | | 284 |
| | 6NN | | | | | | | |
| | 2071.01 | | General Disposal | 0.60 cuyd | 12 | - | 27.15 /cuyd | 16 |
| | 2088.01 | | Remove Wood Floor | 60.00 sqft | 136 | - | 2.26 /sqft | 136 |
| | 9560.01 | | Patch Wood Floor | 60.00 sqft | 385 | 404 | 13.16 /sqft | 789 |
| | 9560.01 | | Sand & Finish Floor | 60.00 sqft | 130 | 55 | 3.08 /sqft | 185 |
| | | | 6NN | | 663 | 459 | | 1,126 |
| | 6P | | | | | | | |
| | 2071.01 | | General Disposal | 9.80 cuyd | 202 | - | 26.93 /cuyd | 264 |
| | 2088.50 | | Rem. Acoust Tile & Grid | 1,060.00 sqft | 1,276 | - | 1.20 /sqft | 1,276 |
| | 9510.50 | | Mylar Faced Std 2x4 3/4" 250-500 sf | 1,060.00 sqft | 1,465 | 4,189 | 5.33 /sqft | 5,654 |
| | | | 6P | | 2,943 | 4,189 | | 7,194 |
| | 6PP | | | | | | | |
| | 5510.05 | | Stl Angles 1000 - 2000 lbs | 74.00 lb | 139 | 108 | 3.34 /lb | 247 |
| | | | 6PP | | 139 | 108 | | 247 |
| | 6RR | | | | | | | |
| | 2071.01 | | General Disposal | 2.70 cuyd | 56 | - | 27.16 /cuyd | 73 |
| | 2079.00 | | Remove Exterior Metal Panels | 288.00 sqft | 462 | - | 1.61 /sqft | 462 |
| | 7410.00 | | Alluminum Wall Panel | 288.00 sqft | 2,672 | 4,592 | 25.22 /sqft | 7,264 |
| | | | 6RR | | 3,190 | 4,592 | | 7,800 |
| | 6SS | | | | | | | |
| | 4710.10 | | Clean Exist Brick Bio Growth | 3.00 sqs | 1,055 | 76 | 376.92 /sqs | 1,131 |
| | | | 6SS | | 1,055 | 76 | | 1,131 |
| | 6V | | | | | | | |
| | 2071.01 | | General Disposal | 4.00 cuyd | 82 | - | 26.92 /cuyd | 108 |
| | 2088.01 | | Remove Carpet & Pad | 432.00 sqft | 277 | - | 0.64 /sqft | 277 |
| | 9660.01 | | Floor Resil Base 4" | 84.00 lnft | 122 | 67 | 2.25 /lnft | 189 |
| | 9685.00 | | Carpet Commercial 32oz | 48.00 sqyd | 651 | 1,949 | 54.15 /sqyd | 2,599 |
| | | | 6V | | 1,132 | 2,016 | | 3,173 |
| | 6W | | | | | | | |
| | 4710.10 | | Clean Masonry from Water Damage | 219.00 sqft | 2,244 | 126 | 10.82 /sqft | 2,370 |
| | | | 6W | | 2,244 | 126 | | 2,370 |
| | 6X | | | | | | | |
| | 2071.01 | | General Disposal | 2.40 cuyd | 49 | - | 26.92 /cuyd | 65 |
| | 2078.00 | | Remove Ceiling Framing | 264.00 sqft | 593 | - | 2.25 /sqft | 593 |
| | 2088.50 | | Rem. Acoust Tile & Grid | 264.00 sqft | 318 | - | 1.20 /sqft | 318 |
| | 9510.50 | | MinFbr SqEdge Std 2x4 3/4" 250 - 500 sf | 264.00 sqft | 365 | 691 | 4.00 /sqft | 1,056 |
| | | | 6X | | 1,326 | 691 | | 2,032 |
| | 6Y | | | | | | | |
| | 2071.01 | | General Disposal | 1.20 cuyd | 25 | - | 27.17 /cuyd | 33 |
| | 2080.05 | | Remove Gutter/Downspouts | 62.00 lnft | 149 | - | 2.41 /lnft | 149 |
| | 7620.15 | | Downspout Copper Circular 5" | 26.00 lnft | 252 | 590 | 32.39 /lnft | 842 |
| | 7620.15 | | Gutter Copper 1/2 Round 5" | 36.00 lnft | 373 | 336 | 19.68 /lnft | 709 |
| | | | 6Y | | 798 | 926 | | 1,733 |
| | 6Z | | | | | | | |
| | 2071.01 | | General Disposal | 1.80 cuyd | 37 | - | 27.17 /cuyd | 49 |
| | 2079.00 | | Remove Soffit & Trim | 198.00 sqft | 890 | - | 4.50 /sqft | 890 |
| | 7240.00 | | Ext Cement Bd Finish System Soffit | 198.00 sqft | 5,054 | 717 | 29.87 /sqft | 5,914 |
| | 9910.01 | | Paint Ext Soffit 3 ct | 198.00 sqft | 204 | 25 | 1.16 /sqft | 229 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------------|----------|-------|-------------|------------------|--------------|-----------------|-----------------|--------------|
| | | | | | <u>6.185</u> | <u>742</u> | | <u>7.081</u> |
| 6 FINISHES GEN | | | | | 167,151 | 37,872 | | 227,256 |

Estimate Totals

| | | | |
|-------------|--------------|-----------|-----|
| Labor | 856,978 | 9,163.423 | hrs |
| Material | 898,242 | | |
| Subcontract | 1,387 | | |
| Equipment | 70,905 | 2,319.138 | hrs |
| Other | <u>9,991</u> | | |
| | 1,837,503 | 1,837,503 | |
| Total | | 1,837,503 | |

Elementary Schools - Structural Report for Hasting School

Lim Consultants, Inc.

90 Hamilton St., Cambridge MA 02139

617/577-9200 ■ FAX 617/577-8252 ■ jharbage@limconsultants.com

Date: Dec. 17, 2008

To: Mr. Daniel Colli
Design Partnership of Cambridge
500 Rutherford Avenue
Charlestown, MA 02129

Re: Hastings Elementary School, Lexington, MA

Dear Mr. Colli,

At your request, we visited the above-mentioned project on 11/25/08 and again on 12/9/08 in order to observe cracks in the masonry wall of the building. Our comments with regard to these observations follow. Photographs and a key to their location (SK-A) are also enclosed.

The area of interest is the west (exterior) wall of the north wing of the building. Severe cracks were observed on the interior (CMU) and exterior (brick) surfaces of this wall at the North end, immediately below the roof (photos 7 and 15). Similar cracking of considerably less magnitude were observed at the South end of this same wall (photos 13 and 14). Vertical cracks were also observed between the west (exterior) wall and intersecting cross walls (photos 8, 9, 10, 11 and 12). Returning to the North end of the West wall, slight cracking was also seen on the exterior at the west end of the North elevation, just below the roof and right around the corner from the severe cracks mentioned above (photo 17). Again, at the North end of the West wall, cracks similar to those described above but of lesser magnitude appear have developed in the exterior brick veneer Just below the second floor directly below the more severe cracking above (photo 16).

A second visit to the site revealed the existence of an expansion joint between the North and South wings of the building at the location shown on the key plan (see SK-A). It was also determined that the second level and flat portions of the roof were constructed of continuous cast in place concrete slabs. These slabs may turn down so as to form a spandrel capable of spanning the long openings in the exterior walls. At this time we confirmed that the wall in question is approximately 135 feet long and does not contain any control joints. This visit also included access to the roof and the opportunity to observe and photograph distressed area described above in greater detail (photo 22, 23, 24, 26 and 27).

We have spoken to Mr. Shawn Newell at the Lexington school department. He informed us that some record drawings of the Hasting School are available. Mr. Newell offered to email us a list of these drawings. We will forward this list along to you as soon as it is received.

Lim Consultants, Inc.

90 Hamilton St., Cambridge MA 02139

617/577-9200 ■ FAX 617/577-8252 ■ jharbage@limconsultants.com

Page 2

At this time, It is our opinion that safety of the building occupants is not an immediate concern. For the present, we recommend that the conditions described herein be monitored on a regular basis so that any changes impacting safety can be promptly brought to your attention.


With regard to cause, there is little evidence that foundation settlement plays a significant part in the cause of these cracks. Rather, it appears that their cause is the result of lateral movement due to seasonal expansion and contraction combined with and possibly long term effects of concrete and/or masonry shrinkage. At present, we do not know whether the expansion joint is effective. Hence we cannot be more specific with respect to cause at this time or to make recommendations for final and durable repairs. Rather, we suggest the following actions for your consideration. Of first importance is a commitment to regular inspections so that safety can be assured while a final solution of this problem is developed. Also of importance is the need to seal these cracks on the exterior face of the building so that additional deterioration is minimized. This sealant need only be considered temporary in nature and should be sufficiently pliable so as to not introduce additional restraints to the free movement of the structure at the distressed areas.

Other recommendations for your consideration are as follows.



1. Provide means of observing seasonal variations in crack size due to temperature change.
2. Map in greater detail the relative movements of the structure.
3. Review existing record drawings
4. Consider value of more intrusive investigation if questions remain regarding construction details after a thorough review of drawings. This work would best be done during periods when the school is not in session.

Armed with this information, it should be possible to determine the cause of this problem with greater specificity and develop a lasting remedial recommendation. Thank you for giving us the opportunity to work with you in connection with this problem.

Sincerely yours,



John Harbage, P.E.
Lim Consultants



ELEVATION - WEST WALL OF NORTH WING

SK-A

DEC. 17, 2000



1



2



3



4



5



6



7



8



9



10



11



12




13



14



15



16



17



18



19



20



21



22



23



24



25



26



27



28




29



30



31



32



33



34



35



36

High School – E/P/FP Report

**Lexington Elem. Schools
Master Plan Study**

Lexington High School

Executive Summary – Electrical

This facility was recently renovated during the early 2000's and consists of 325,848sq.ft. The existing electrical systems due to their recent installation are in good condition. Remote building services interconnect to main building and run underground.

Existing Conditions

- Exterior parking area lighting consists of 400 watt metal halide fixtures on 30' round tapered poles. Roadways have 18' poles with 175 watt metal halide fixtures. Exterior lighting is controlled with mechanical time clocks for "ON and OFF". Building mounted 250 watt metal halide floods also exist.
- There is no automated lighting control system for facility.
- Electrical distribution consists of an underground primary service of 13.8kv to a 1000kva pad mounted transformer, utility owned. Secondary service runs underground to a 2500 ampere, 277/480V, 3Ø, 4W switchboard located in Building C. Feeders for the remainder of the buildings are fed from this switchboard and run underground. Building "G" has a 1600 ampere switchboard which in turn also feeds a 400 ampere distribution panel in Building "J". Building "H" is fed directly from Building "C" switchboard with a 400 ampere feeder. Boiler Room switchgear is currently being replaced due to water damage as a result of a water heater rupture.
- The emergency system consists of a 600kw exterior generator housed in a walk-in sound attenuated enclosure. The generator is diesel fired fed from a remote underground fuel tank. The generator is a Kohler Model #600ROZD4. The generator has a separation of 6 ½' from the pad mounted transformer. Building "C" has two automatic transfer switches housed in same emergency room. One switch, 225 amps is for emergency lighting for entire facility. The second 250 amp transfer switch is for stand-by loads. A system of emergency by-pass relay cabinets exist. Exit signs appear to have fair coverage.
- Fire alarm system consists of a voice evacuation, addressable system with the fire command center located in Building "D" for the main building consisting of Buildings A, B, C, D, E, and F. The manufacturer is Simplex 4120 Series. A radio master box #6122 transmits alarms to fire department. Buildings G, H, and J each have their own fire command center and share a second radio master box located in the "J" Building to transmit alarms to fire department. Fire alarm system meets ADA Standards. Smokes exist in egress corridors. Elevators have recall. Manual pull stations have tamper resistant covers. Sprinkler system is supervised. Toilets have strobes. Classrooms have speaker/strobes. Facility appears to have good coverage of speaker/strobes. Auditorium fire curtain appears to be connected to fire alarm.

- Corridor lighting consists of 2 x 4 recessed 18 cell parabolics with three (3) T8 lamps and electronic ballasts controlled with local key switches.
Classroom lighting consists of recessed parabolics controlled with two (2) switches. There is no occupancy sensor.
Auditorium lighting consists of recessed cans with 250W Halogen lamps. There are four (4) connector strips for theatrical lighting. Stage has a Colortran 96 dimmer rack.
Kitchen lighting is with wraparound fixtures.
Cafeteria lighting consist of suspended 30" round indirect luminaries.
Gymnasium and field house have 2 x 4 fluorescent high bays with four (4) T5HO lamps with lens and wireguard. Gym lights are controlled with switches and occupancy sensors. Field house lights are breaker controlled.
There are no lighting occupancy sensors in this facility to turn lights OFF when space is unoccupied with the exception of the gymnasium.
- Security system consists of a Detection System Inc. DS7 400X zoned system. Each building has its own control panel and remote keypads. Dual tech sensors exist in corridors.
Exterior doors and all auditorium doors are alarmed. Facility is connected to a remote central station.
- Classrooms have a Category 5 Network. Classrooms have 1 to 4 data drops and one (1) CATV drop. School has a wireless network. There is no central UPS for head end equipment.
- Paging/Intercom/Master Clock is a Simplex 5100 Series with rack mounted equipment. There is corridor flush mounted speakers. Classrooms have a wall phone with a clock/speaker.
- There is no lightning protection system.
- There is a 4kw photovoltaic system mounted on roof.
- Gymnasium power is connected to the generator.

Proposed System Priorities:

Priority 1 - Immediate Needs

- Emergency closet near kitchen has contactor very loud, near failure condition.
» **\$1,000.00**
- One hood light fixture missing protective globe.
» **\$100.00**

- Served by two (2) open recessed cans, need lens.
» **\$500.00**
- 60A/2P breaker for photovoltaic system is not GFI. Breaker to be changed to GFI type.
» **\$750.00**

Priority 2: 1 – 5 Year

- Exterior lighting not controlled with photocell “ON”, timeclocks only. Photocell needs to be added to system.
» **\$5,000.00**
- Selective kitchen loads including refrigeration should be reconnected to the generator.
» **\$25,000.00**
- Provide automated lighting control system for common area lighting and exterior lighting.
» **\$100,000.00**

**Lexington Elem. Schools
Master Plan Study**

Lexington High School

Executive Summary - Plumbing/Fire Protection

The Lexington High School has received minimal maintenance on the plumbing systems and equipment over its occupied years. There has been two separate renovations to the school one in 2000 and another in 2004. Even with adequate maintenance, systems will gradually deteriorate due to scale and poor water conditions. Most of the systems have been replaced recently and are working adequately at this time.

Fixtures:

- Fixtures are a mix of original fixtures and new fixtures installed as part of the 2000 renovation. The majority of the fixture do meet the accessibility code as well as the water conservation requirements of the Plumbing Code.
- The water closets are generally wall hung vitreous china, flush valve type with siphon jet action.
- The urinals are wall hung vitreous china, flush valve type with blow out action.
- The lavatories are wall hung vitreous china. The faucets are hot and cold water controls.
- The drinking fountains are generally wall hung stainless, bi-level electric water coolers with recessed coolers.

Water System:

- There are two separate domestic water services located within the facility. The first domestic water service enters the main Boiler Room located in building D. This service entering the building is 4 in. and is complete with a water meter as well as a pressure reducing valve with by-pass and reduced pressure backflow preventer. The pressure reducing valve pressure is set to reduce the incoming 100 psi down to the set pressure 80 psi.
- The domestic hot water for the core of the school is supplied from a new plate and frame heat exchanger which fed off of the heating boilers. There are four new 200 gallon storage tanks being installed due to a failure of the original storage tanks. The domestic hot water for the three outer buildings of the school is supplied from a 250 gall gas fired PVI tank type water heater which is located in the Boiler Room in Building G. The non-potable hot water for the science classrooms is supplied from a separate 250 gallon gas fired PVI tank type water heater which is located in the Boiler Room of Building G.

- There is a master thermostatic mixing valve on the domestic hot water system prior to being distributed to the building hot water system. There is a separate 140 degree F. hot water supplied to the Kitchen which also includes a thermostatic mixing valve.

Drainage System:

- The sanitary and storm drainage systems are piped with cast iron. The exposed piping is visibly in good condition.
- The sanitary drainage system is piped to a municipal sewer system.
- The roof is generally flat and is drained by roof drains and a roof drainage system, which exits the building and connects to a municipal storm drainage system.
- There are 2 acid neutralization systems in the school. The first system is dedicated to the science classroom drainage. The second system is dedicated to the photograph drainage. Each of the systems includes a mixing tank with mixer, base and acid storage tanks, injection pumps and pH monitoring. These systems appear to have minimal or no maintenance since their installation. The base storage tank was empty and the acid storage tank was approximately half full. The acid injection pump appeared to be not operating. The pH monitoring system was reading a pH level of 4.5 at discharge and this should have a pH level around 7.

Natural Gas System:

- The building has two separate gas services. The first service enters the Boiler Room in Building D and provides fuel for heating, domestic hot water and cooking. The second service enters the Boiler Room in Building G and supplies fuel for heating, domestic hot water and the science classrooms..

Kitchen:

- The kitchen equipment is all generally original new and is in good working order.
- There is a grease trap in the kitchen that appears to be dedicated for the 3-pot sink. All other fixtures appear to go to a dedicated kitchen waste drainage system.

Fire Protection:

- The school is protected by a combination standpipe/sprinkler system.
- The core of the school is supplied by an 8" fire service with a Double Check Valve Assembly located in the Boiler Room of Building D. There are three separate alarm valves which are then broken down by zone control assemblies.
- The three outer buildings each have separate fire services which service the buildings. The outer buildings also have multiple zones associated with it.

- There are areas throughout the school that sprinkler protection is obstructed by ductwork. Approximately 5 percent of the school appears to have sprinkler coverage deficiencies.

Proposed System Priorities

Priority 1 – Immediate Needs and Requirements:

- Provide proper maintenance of the ph neutralization systems so they may operate as designed and discharge waste at an acceptable level.
 - » **\$2,500.00**
- Provide modifications to the existing fire protection sprinkler system to eliminate sprinkler coverage deficiencies.
 - » **\$10,000.00**

Priority 2 – 5 Year Requirements:

- All plumbing fixtures will be replaced with new water conserving type fixtures capable of saving approximately 30% of overall water usage of the building.
 - » **\$60,000.00**

Priority 3 – 10 Year Requirements:

- A new gas fired water heater boiler will be provided for the core buildings of the school independent of the heating boilers to eliminate the need for the heating boilers to fire during non-heating months.
 - » **\$25,000.00**

High School – Base Renovation Cost Estimate

**LEXINGTON HIGH SCHOOL RENOVATION
STUDY ESTIMATE - 1-1-09
LEXINGTON, MA**

Project name **Lexington High school**
Lexington
MA

Architect **TDPC**

Estimator *Essential Estimating*

| Location | Labor Amount | Material Amount | Sub Amount | Equip Amount | Total Amount |
|------------------------|----------------|-----------------|------------|---------------|----------------|
| 1 LIFE SAFETY | 1,776 | 1,669 | | 6 | 3,450 |
| 2 BUILDING CODE | 69,238 | 190,957 | | 3,877 | 264,072 |
| 3 EXTERIOR | 466,289 | 493,805 | | 647 | 960,741 |
| 4 HAZARDOUS MAT | 808 | 38 | | | 846 |
| 5 HC ACCESS | 411,368 | 458,780 | | 13,010 | 883,158 |
| 6 FINISHES GEN | 111,008 | 53,820 | | 4,053 | 168,882 |

Estimate Totals

| | | | |
|--------------|------------------|------------------|-----|
| Labor | 1,060,487 | 10,544.202 | hrs |
| Material | 1,199,070 | | |
| Equipment | 21,593 | 1,166.657 | hrs |
| | 2,281,150 | 2,281,150 | |
| Total | 2,281,150 | | |

| Location | Bid Item | Description | Labor Amount | Material Amount | Sub Amount | Equip Amount | Total Amount |
|------------------------|-------------|------------------------|----------------|-----------------|------------|---------------|----------------|
| 1 LIFE SAFETY | | | | | | | |
| | <u>1A</u> | | <u>630</u> | <u>865</u> | | | <u>1,495</u> |
| | <u>1F</u> | | <u>1,145</u> | <u>804</u> | | <u>6</u> | <u>1,955</u> |
| | | 1 LIFE SAFETY | 1,776 | 1,669 | | 6 | 3,450 |
| 2 BUILDING CODE | | | | | | | |
| | <u>2C</u> | | <u>372</u> | <u>1,341</u> | | <u>1</u> | <u>1,714</u> |
| | <u>2I</u> | | <u>13,746</u> | <u>20,161</u> | | | <u>33,907</u> |
| | <u>2K</u> | | <u>566</u> | <u>69</u> | | <u>16</u> | <u>651</u> |
| | <u>2L</u> | | <u>650</u> | | | <u>38</u> | <u>688</u> |
| | <u>2P</u> | | <u>72</u> | | | <u>3</u> | <u>75</u> |
| | <u>2R</u> | | <u>53,724</u> | <u>169,257</u> | | <u>3,819</u> | <u>226,800</u> |
| | <u>2S</u> | | <u>107</u> | <u>129</u> | | | <u>236</u> |
| | | 2 BUILDING CODE | 69,238 | 190,957 | | 3,877 | 264,072 |
| 3 EXTERIOR | | | | | | | |
| | <u>3A</u> | | <u>283,437</u> | <u>389,215</u> | | <u>420</u> | <u>673,072</u> |
| | <u>3B</u> | | <u>4,054</u> | <u>7,442</u> | | <u>141</u> | <u>11,637</u> |
| | <u>3G</u> | | <u>666</u> | <u>473</u> | | | <u>1,140</u> |
| | <u>3H</u> | | <u>171,578</u> | <u>82,805</u> | | | <u>254,382</u> |
| | <u>3J</u> | | <u>4,129</u> | <u>12,847</u> | | <u>87</u> | <u>17,062</u> |
| | <u>3K</u> | | <u>376</u> | <u>30</u> | | | <u>406</u> |
| | <u>3M</u> | | <u>1,973</u> | <u>984</u> | | | <u>2,957</u> |
| | <u>3P</u> | | <u>77</u> | <u>10</u> | | | <u>86</u> |
| | | 3 EXTERIOR | 466,289 | 493,805 | | 647 | 960,741 |
| 4 HAZARDOUS MAT | | | | | | | |
| | <u>4B</u> | | <u>808</u> | <u>38</u> | | | <u>846</u> |
| | | 4 HAZARDOUS MAT | 808 | 38 | | | 846 |
| 5 HC ACCESS | | | | | | | |
| | <u>5A</u> | | <u>70,969</u> | <u>13,012</u> | | <u>4,631</u> | <u>88,612</u> |
| | <u>5AA</u> | | <u>809</u> | <u>197</u> | | <u>1</u> | <u>1,006</u> |
| | <u>5B</u> | | <u>55,777</u> | <u>122,336</u> | | <u>649</u> | <u>178,762</u> |
| | <u>5BB</u> | | <u>636</u> | <u>14,590</u> | | | <u>15,226</u> |
| | <u>5D</u> | | <u>1,834</u> | | | <u>11</u> | <u>1,845</u> |
| | <u>5E</u> | | <u>963</u> | | | | <u>963</u> |
| | <u>5F</u> | | <u>23,698</u> | <u>26,491</u> | | <u>932</u> | <u>51,121</u> |
| | <u>5G</u> | | <u>28,289</u> | <u>70,540</u> | | <u>67</u> | <u>98,896</u> |
| | <u>5GG</u> | | <u>3,917</u> | <u>20,327</u> | | <u>35</u> | <u>24,279</u> |
| | <u>5H</u> | | <u>146,871</u> | <u>87,933</u> | | <u>4,038</u> | <u>238,843</u> |
| | <u>5HH</u> | | <u>3,843</u> | <u>212</u> | | <u>3</u> | <u>4,057</u> |
| | <u>5JJ</u> | | <u>1,124</u> | | | | <u>1,124</u> |
| | <u>5K</u> | | <u>2,425</u> | <u>1,515</u> | | <u>233</u> | <u>4,172</u> |
| | <u>5L</u> | | <u>3,401</u> | <u>15,346</u> | | <u>241</u> | <u>18,988</u> |
| | <u>5M</u> | | <u>21,671</u> | <u>34,993</u> | | <u>880</u> | <u>57,544</u> |
| | <u>5MM</u> | | <u>2,583</u> | <u>426</u> | | <u>99</u> | <u>3,108</u> |
| | <u>5N</u> | | <u>20,418</u> | <u>17,700</u> | | <u>1,092</u> | <u>39,211</u> |
| | <u>5NNN</u> | | <u>17,848</u> | <u>24,000</u> | | <u>74</u> | <u>41,922</u> |
| | <u>5P</u> | | <u>454</u> | <u>2,001</u> | | <u>1</u> | <u>2,456</u> |
| | <u>5X</u> | | <u>1,824</u> | <u>3,934</u> | | <u>24</u> | <u>5,782</u> |
| | <u>5Z</u> | | <u>2,015</u> | <u>3,225</u> | | | <u>5,240</u> |
| | | 5 HC ACCESS | 411,368 | 458,780 | | 13,010 | 883,158 |
| 6 FINISHES GEN | | | | | | | |

| Location | Bid Item | Description | Labor Amount | Material Amount | Sub Amount | Equip Amount | Total Amount |
|----------|-------------|-----------------------|----------------|-----------------|------------|--------------|----------------|
| | | | <u>23,772</u> | | | <u>313</u> | <u>24,085</u> |
| | <u>6AAA</u> | | <u>728</u> | <u>193</u> | | | <u>922</u> |
| | <u>6B</u> | | <u>18,082</u> | <u>588</u> | | <u>2,213</u> | <u>20,883</u> |
| | <u>6BBB</u> | | <u>181</u> | <u>97</u> | | | <u>277</u> |
| | <u>6CC</u> | | <u>312</u> | <u>551</u> | | | <u>862</u> |
| | <u>6CCC</u> | | <u>426</u> | <u>362</u> | | <u>3</u> | <u>791</u> |
| | <u>6D</u> | | <u>3,480</u> | <u>347</u> | | <u>935</u> | <u>4,763</u> |
| | <u>6E</u> | | <u>548</u> | <u>266</u> | | <u>1</u> | <u>815</u> |
| | <u>6G</u> | | <u>203</u> | <u>72</u> | | <u>1</u> | <u>277</u> |
| | <u>6GGG</u> | | <u>302</u> | <u>44</u> | | | <u>346</u> |
| | <u>6H</u> | | <u>3,034</u> | <u>612</u> | | | <u>3,647</u> |
| | <u>6HH</u> | | <u>834</u> | | | | <u>834</u> |
| | <u>6HHH</u> | | <u>1,278</u> | <u>1,221</u> | | <u>7</u> | <u>2,505</u> |
| | <u>6JJJ</u> | | <u>102</u> | <u>6</u> | | | <u>108</u> |
| | <u>6KKK</u> | | <u>1,123</u> | <u>2,000</u> | | <u>23</u> | <u>3,146</u> |
| | <u>6L</u> | | <u>4,152</u> | <u>960</u> | | <u>390</u> | <u>5,503</u> |
| | <u>6LLL</u> | | <u>692</u> | <u>526</u> | | <u>5</u> | <u>1,222</u> |
| | <u>6MM</u> | | <u>6,596</u> | <u>17,160</u> | | <u>89</u> | <u>23,846</u> |
| | <u>6MMM</u> | | <u>111</u> | <u>16</u> | | | <u>128</u> |
| | <u>6NNN</u> | | <u>82</u> | <u>16</u> | | | <u>99</u> |
| | <u>6OOO</u> | | <u>2,127</u> | <u>2,936</u> | | | <u>5,062</u> |
| | <u>6PPP</u> | | <u>352</u> | <u>803</u> | | | <u>1,154</u> |
| | <u>6Q</u> | | <u>1,407</u> | <u>608</u> | | <u>3</u> | <u>2,018</u> |
| | <u>6QQQ</u> | | <u>279</u> | <u>14</u> | | | <u>293</u> |
| | <u>6SS</u> | | <u>1,006</u> | <u>73</u> | | | <u>1,078</u> |
| | <u>6SSS</u> | | <u>6,003</u> | <u>2,109</u> | | | <u>8,112</u> |
| | <u>6UU</u> | | <u>4,434</u> | <u>5,846</u> | | <u>16</u> | <u>10,296</u> |
| | <u>6UUU</u> | | <u>2,097</u> | <u>622</u> | | | <u>2,719</u> |
| | <u>6VV</u> | | <u>1,202</u> | <u>380</u> | | <u>29</u> | <u>1,611</u> |
| | <u>6VVV</u> | | <u>271</u> | | | | <u>271</u> |
| | <u>6W</u> | | <u>1,025</u> | <u>57</u> | | | <u>1,082</u> |
| | <u>6WW</u> | | <u>692</u> | <u>75</u> | | <u>17</u> | <u>784</u> |
| | <u>6WW</u> | | <u>43</u> | <u>24</u> | | <u>6</u> | <u>72</u> |
| | <u>W</u> | | | | | | |
| | <u>6XXX</u> | | <u>96</u> | <u>154</u> | | | <u>249</u> |
| | <u>6Y</u> | | <u>294</u> | <u>545</u> | | <u>1</u> | <u>841</u> |
| | <u>6YYY</u> | | <u>22</u> | <u>164</u> | | | <u>186</u> |
| | <u>6ZZZ</u> | | <u>23,622</u> | <u>14,372</u> | | | <u>37,994</u> |
| | | 6 FINISHES GEN | 111,008 | 53,820 | | 4,053 | 168,882 |

Estimate Totals

| | | | |
|--------------|------------------|------------------|-----|
| Labor | 1,060,486 | 10,544.202 | hrs |
| Material | 1,199,070 | | |
| Equipment | <u>21,593</u> | 1,166.657 | hrs |
| | <u>2,281,149</u> | <u>2,281,149</u> | |
| Total | 2,281,149 | | |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|------------------------|-----------|----------|---|------------------|--------------|-----------------|-----------------|--------------|
| 1 LIFE SAFETY | | | | | | | | |
| | 1A | | | | | | | |
| | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | Remove Door | 2.00 each | 96 | - | 48.17 /each | 96 |
| | | | Demo: Doors & Windows | | 96 | | /each | 96 |
| | | 8210.01 | Doors: Wood | | | | | |
| | | | Re Hang Door | 2.00 each | 261 | 851 | 555.91 /each | 1,112 |
| | | | Doors: Wood | | 261 | 851 | /each | 1,112 |
| | | 9920.01 | Painting: Interior | | | | | |
| | | | Refinish & Stain Exist Door | 2.00 each | 273 | 14 | 143.56 /each | 287 |
| | | | Painting: Interior | | 273 | 14 | /sqft | 287 |
| | | | 1A | | 630 | 865 | | 1,495 |
| | 1F | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.90 cuyd | 19 | - | 26.93 /cuyd | 24 |
| | | | Demo: General | | 19 | | /cuyd | 24 |
| | | 2084.50 | Demo: Misc Items | | | | | |
| | | | Remove Fire Ext Cabinet | 4.00 each | 321 | - | 80.28 /each | 321 |
| | | | Demo: Misc Items | | 321 | | /sqft | 321 |
| | | 6113.20 | Blocking: Misc. | | | | | |
| | | | Blocking 2 x 6 R.L. | 24.00 lnft | 82 | 16 | 4.11 /lnft | 99 |
| | | | Blocking: Misc. | | 82 | 16 | /mbf | 99 |
| | | 10523.00 | Fire Extinguishers | | | | | |
| | | | Fire Ext Cabinet | 4.00 each | 723 | 788 | 377.77 /each | 1,511 |
| | | | Fire Extinguishers | | 723 | 788 | /each | 1,511 |
| | | | 1F | | 1,145 | 804 | | 1,955 |
| | | | 1 LIFE SAFETY | | 1,776 | 1,669 | | 3,450 |
| 2 BUILDING CODE | | | | | | | | |
| | 2C | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.20 cuyd | 4 | - | 27.00 /cuyd | 5 |
| | | | Demo: General | | 4 | | /cuyd | 5 |
| | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | Remove Door | 1.00 each | 32 | - | 32.10 /each | 32 |
| | | | Demo: Doors & Windows | | 32 | | /each | 32 |
| | | 8210.01 | Doors: Wood | | | | | |
| | | | Birch Solid Core 3-0 x 7-0 Vision | 1.00 each | 130 | 529 | 658.83 /each | 659 |
| | | | Doors: Wood | | 130 | 529 | /each | 659 |
| | | 8710.01 | Hardware: Finishing | | | | | |
| | | | Finishing Hardware Int Budget w Closure | 1.00 each | 136 | 798 | 933.57 /each | 934 |
| | | | Hardware: Finishing | | 136 | 798 | /set | 934 |
| | | 9920.01 | Painting: Interior | | | | | |
| | | | Paint Wd Door & Metal Frame | 1.00 each | 70 | 14 | 84.46 /each | 84 |
| | | | Painting: Interior | | 70 | 14 | /sqft | 84 |
| | | | 2C | | 372 | 1,341 | | 1,714 |
| | 2I | | | | | | | |
| | | 6015.00 | Fasteners: Frame Anchors | | | | | |
| | | | Fastners & Misc | 1.00 lsum | - | 1 | 1.27 /lsum | 1 |
| | | | Fasteners: Frame Anchors | | | 1 | /each | 1 |
| | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | Rough Bucks 2 x 6 Doors | 153.00 lnft | 383 | 104 | 3.18 /lnft | 487 |
| | | | Blocking: Rough Bucks | | 383 | 104 | /mbf | 487 |
| | | 8110.01 | Doors: Steel with Frames | | | | | |
| | | | H.M. Frame 18ga Interior Single | 9.00 each | 890 | 1,555 | 271.72 /each | 2,446 |
| | | | H.M. Door 18ga 3-0 x 7-0 Vision Lab | 9.00 each | 796 | 7,673 | 941.02 /each | 8,469 |
| | | | Doors: Steel with Frames | | 1,686 | 9,228 | /each | 10,915 |
| | | 8710.01 | Hardware: Finishing | | | | | |
| | | | Finishing Hardware Int Budget w Closure | 9.00 each | 1,221 | 7,181 | 933.56 /each | 8,402 |
| | | | Hardware: Finishing | | 1,221 | 7,181 | /set | 8,402 |
| | | 9252.10 | GWB Int Frame: S Studs | | | | | |
| | | | S Stud 600 x 12' 20 ga | 89.00 each | 2,511 | 1,225 | 41.98 /each | 3,736 |
| | | | GWB Int Frame: S Studs | | 2,511 | 1,225 | /each | 3,736 |
| | | 9252.30 | GWB Int Frame: Track | | | | | |
| | | | Track: Standard 20 ga 6.00 " | 184.00 lnft | 932 | 219 | 6.25 /lnft | 1,150 |
| | | | GWB Int Frame: Track | | 932 | 219 | /lnft | 1,150 |
| | | 9253.10 | GWB: Fasteners | | | | | |
| | | | Misc. Accessories | 1.00 lsum | 269 | 99 | 367.96 /lsum | 368 |
| | | | GWB: Fasteners | | 269 | 99 | /each | 368 |
| | | 9253.30 | GWB: Boards & Sheathing | | | | | |
| | | | GWB 5/8" Walls | 3,660.00 sqft | 3,054 | 1,279 | 1.18 /sqft | 4,333 |
| | | | GWB: Boards & Sheathing | | 3,054 | 1,279 | /sqft | 4,333 |
| | | 9254.00 | GWB: Finish Mud/Tape | | | | | |
| | | | Acoustic Sealant | 153.00 lnft | 353 | 6 | 2.35 /lnft | 359 |
| | | | Labor GWB Wall Finish | 1,482.00 sqft | 1,270 | 113 | 0.93 /sqft | 1,383 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|-----------|----------|-------|---|------------------|---------------|-----------------|-----------------|----------------|
| | | | GWB: Finish Mud/Tape | | 1,623 | 119 | /sqft | 1,742 |
| | 9510.60 | | Ceiling: 2x2 Tile | | | | | |
| | | | Patch MinFbr SqEdge Std 2x2 3/4" < 250 sf | 92.00 sqft | 400 | 289 | 7.48 /sqft | 688 |
| | | | Ceiling: 2x2 Tile | | 400 | 289 | /sqft | 688 |
| | 9920.01 | | Painting: Interior | | | | | |
| | | | Paint Metal Door & Frame | 9.00 each | 526 | 115 | 71.26 /each | 641 |
| | | | Paint GDW Wall Roller p + 2ct | 1,482.00 sqft | 1,143 | 301 | 0.97 /sqft | 1,444 |
| | | | Painting: Interior | | 1,669 | 417 | /sqft | 2,085 |
| | | | 2I | | 13,746 | 20,161 | | 33,907 |
| 2K | | | | | | | | |
| | 2071.01 | | Demo: General | | | | | |
| | | | General Disposal | 0.20 cuyd | 4 | - | 26.95 /cuyd | 5 |
| | | | Demo: General | | 4 | | /cuyd | 5 |
| | 2084.01 | | Demo: Doors & Windows | | | | | |
| | | | Remove Door & Frame Int Single | 1.00 each | 112 | - | 126.97 /each | 127 |
| | | | Demo: Doors & Windows | | 112 | | /each | 127 |
| | 4105.00 | | Mortar: All Types | | | | | |
| | | | Mortar Type "N" | 0.04 cuyd | 5 | 9 | 338.00 /cuyd | 14 |
| | | | Mortar: All Types | | 5 | 9 | /cuyd | 14 |
| | 4158.00 | | Reinforce: Horizontl Wall | | | | | |
| | | | Horiz Wall Reinf 6" Hot Dippd | 0.02 mlf | 9 | 3 | 615.00 /mlf | 12 |
| | | | Reinforce: Horizontl Wall | | 9 | 3 | /mlf | 12 |
| | 4221.20 | | Conc. Block: 6" | | | | | |
| | | | Blk 6" Stand Face Reg Wt - Infill | 24.00 each | 436 | 57 | 20.53 /each | 493 |
| | | | Conc. Block: 6" | | 436 | 57 | /each | 493 |
| | | | 2K | | 566 | 69 | | 651 |
| 2L | | | | | | | | |
| | 2071.01 | | Demo: General | | | | | |
| | | | General Disposal | 0.70 cuyd | 14 | - | 26.93 /cuyd | 19 |
| | | | Demo: General | | 14 | | /cuyd | 19 |
| | 2084.01 | | Demo: Doors & Windows | | | | | |
| | | | Remove Door Frame Int Double | 2.00 each | 257 | - | 145.11 /each | 290 |
| | | | Remove Transom or Borrowed Lite | 56.00 sqft | 379 | - | 6.77 /sqft | 379 |
| | | | Demo: Doors & Windows | | 636 | | /each | 669 |
| | | | 2L | | 650 | | | 688 |
| 2P | | | | | | | | |
| | 2071.01 | | Demo: General | | | | | |
| | | | General Disposal | 0.40 cuyd | 8 | - | 26.95 /cuyd | 11 |
| | | | Demo: General | | 8 | | /cuyd | 11 |
| | 2084.01 | | Demo: Doors & Windows | | | | | |
| | | | Remove Screen Door | 2.00 each | 64 | - | 32.11 /each | 64 |
| | | | Demo: Doors & Windows | | 64 | | /each | 64 |
| | | | 2P | | 72 | | | 75 |
| 2R | | | | | | | | |
| | 2071.01 | | Demo: General | | | | | |
| | | | General Disposal | 15.50 cuyd | 319 | - | 26.93 /cuyd | 417 |
| | | | Demo: General | | 319 | | /cuyd | 417 |
| | 2077.00 | | Demo: Steel | | | | | |
| | | | Remove Metal Stair 4' | 90.00 risr | 9,843 | - | 130.75 /risr | 11,767 |
| | | | Remove Steel Rail | 230.00 lnft | 2,308 | - | 10.04 /lnft | 2,308 |
| | | | Demo: Steel | | 12,151 | | /each | 14,075 |
| | 5510.80 | | Stairs: Stair Parts | | | | | |
| | | | Custom Steel Stairs 5'-0" | 90.00 risr | 16,201 | 88,510 | 1,172.09 /risr | 105,488 |
| | | | Wall Rail Steel 1-1/2" 1 pipe | 85.00 lnft | 2,178 | 1,755 | 47.52 /lnft | 4,039 |
| | | | Ornamental Steel Well Rail Mid | 140.00 lnft | 11,704 | 35,959 | 344.49 /lnft | 48,229 |
| | | | Landing Steel Pan | 270.00 sqft | 7,335 | 42,403 | 185.50 /sqft | 50,086 |
| | | | Stairs: Stair Parts | | 37,417 | 168,627 | /flt | 207,841 |
| | 9920.01 | | Painting: Interior | | | | | |
| | | | Paint Stair Assembly | 718.00 sqft | 2,584 | 420 | 4.18 /sqft | 3,003 |
| | | | Paint Int Pipe Rails | 975.00 lnft | 1,253 | 211 | 1.50 /lnft | 1,464 |
| | | | Painting: Interior | | 3,836 | 630 | /sqft | 4,467 |
| | | | 2R | | 53,724 | 169,257 | | 226,800 |
| 2S | | | | | | | | |
| | 6113.20 | | Blocking: Misc. | | | | | |
| | | | Blocking 2 x 4 R.L. | 6.00 lnft | 17 | 3 | 3.26 /lnft | 20 |
| | | | Blocking: Misc. | | 17 | 3 | /mbf | 20 |
| | 10523.00 | | Fire Extinguishers | | | | | |
| | | | Fire Blanket | 1.00 each | 90 | 126 | 216.21 /each | 216 |
| | | | Fire Extinguishers | | 90 | 126 | /each | 216 |
| | | | 2S | | 107 | 129 | | 236 |
| | | | 2 BUILDING CODE | | 69,238 | 190,957 | | 264,072 |

3 EXTERIOR

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|-----------|----------|-------|---|------------------|----------------|-----------------|-----------------|----------------|
| 3A | | | | | | | | |
| | 2071.01 | | Demo: General | | | | | |
| | | | General Disposal | 63.90 cuyd | 1,316 | - | 27.17 /cuyd | 1,736 |
| | | | Demo: General | | 1,316 | | /cuyd | 1,736 |
| | 2084.01 | | Demo: Doors & Windows | | | | | |
| | | | Remove Metal Windows | 6,906.00 sqft | 21,621 | - | 3.13 /sqft | 21,621 |
| | | | Demo: Doors & Windows | | 21,621 | | /each | 21,621 |
| | 4156.00 | | Access: Wall Flashing | | | | | |
| | | | Flash Head Lead Ct. Cop 5 oz. | 1,650.00 sqft | 7,544 | 7,587 | 9.17 /sqft | 15,132 |
| | | | Flash Sill Lead Ct. Cop 5 oz. | 1,650.00 sqft | 6,879 | 7,126 | 8.49 /sqft | 14,005 |
| | | | Access: Wall Flashing | | 14,423 | 14,713 | /sqft | 29,136 |
| | 6015.00 | | Fasteners: Frame Anchors | | | | | |
| | | | Fastners & Misc | 1.00 lsum | - | 66 | 66.07 /lsum | 66 |
| | | | Fasteners: Frame Anchors | | | 66 | /each | 66 |
| | 6113.40 | | Blocking: Rough Bucks | | | | | |
| | | | Rough Bucks 2 x 6 PT Windows | 5,898.00 lnft | 22,419 | 6,661 | 4.93 /lnft | 29,080 |
| | | | Blocking: Rough Bucks | | 22,419 | 6,661 | /mbf | 29,080 |
| | 7910.01 | | Sealant - Jt Filler Gaskt | | | | | |
| | | | Backer Rod ½" | 5,898.00 lnft | 17,878 | 540 | 3.12 /lnft | 18,418 |
| | | | Polyurethane Sealant 1/2" | 11,796.00 lnft | 112,373 | 5,866 | 10.02 /lnft | 118,239 |
| | | | Sealant - Jt Filler Gaskt | | 130,250 | 6,407 | /lnft | 136,657 |
| | 8520.01 | | Window: Aluminum | | | | | |
| | | | Custom Proj 4" .125 w Ins Gl Kynar | 6,906.00 sqft | 77,841 | 359,766 | 63.37 /sqft | 437,608 |
| | | | Window: Aluminum | | 77,841 | 359,766 | /sqft | 437,608 |
| | 9910.01 | | Painting: Exterior | | | | | |
| | | | Scrape & Prep Ext Misc Surfaces Lintels | 1,650.00 sqft | 2,686 | - | 1.63 /sqft | 2,686 |
| | | | Paint Ext Misc Exposed Metal Lintels | 1,650.00 sqft | 3,458 | 503 | 2.40 /sqft | 3,962 |
| | | | Paint Exist Ext Soffit 2 ct | 9,608.00 sqft | 9,422 | 1,099 | 1.10 /sqft | 10,520 |
| | | | Painting: Exterior | | 15,566 | 1,602 | /sqft | 17,168 |
| 3A | | | | | 283,437 | 389,215 | | 673,072 |
| 3B | | | | | | | | |
| | 2071.01 | | Demo: General | | | | | |
| | | | General Disposal | 21.40 cuyd | 441 | - | 27.17 /cuyd | 581 |
| | | | Demo: General | | 441 | | /cuyd | 581 |
| | 2084.01 | | Demo: Doors & Windows | | | | | |
| | | | Remove Window Treatment | 2,307.00 sqft | 1,111 | - | 0.48 /sqft | 1,111 |
| | | | Demo: Doors & Windows | | 1,111 | | /each | 1,111 |
| | 12520.01 | | Shades | | | | | |
| | | | Vinyl Heavy Wt | 2,306.00 sqft | 2,502 | 7,442 | 4.31 /sqft | 9,944 |
| | | | Shades | | 2,502 | 7,442 | /sqft | 9,944 |
| 3B | | | | | 4,054 | 7,442 | | 11,637 |
| 3G | | | | | | | | |
| | 6015.00 | | Fasteners: Frame Anchors | | | | | |
| | | | Fastners & Misc | 1.00 lsum | - | 1 | 1.26 /lsum | 1 |
| | | | Fasteners: Frame Anchors | | | 1 | /each | 1 |
| | 6113.40 | | Blocking: Rough Bucks | | | | | |
| | | | Rough Bucks 2 x 6 PT Windows | 14.00 lnft | 53 | 16 | 4.93 /lnft | 69 |
| | | | Blocking: Rough Bucks | | 53 | 16 | /mbf | 69 |
| | 6413.00 | | I Trim: Dr & Window Matrl | | | | | |
| | | | Window Stools (Wood) | 6.00 lnft | 40 | 45 | 14.20 /lnft | 85 |
| | | | Apron At Stools | 6.00 lnft | 20 | 16 | 5.94 /lnft | 36 |
| | | | I Trim: Dr & Window Matrl | | 60 | 61 | /lnft | 121 |
| | 7910.01 | | Sealant - Jt Filler Gaskt | | | | | |
| | | | Backer Rod ½" | 14.00 lnft | 42 | 1 | 3.12 /lnft | 44 |
| | | | Polyurethane Sealant 1/2" | 28.00 lnft | 267 | 14 | 10.02 /lnft | 281 |
| | | | Sealant - Jt Filler Gaskt | | 309 | 15 | /lnft | 324 |
| | 8520.01 | | Window: Aluminum | | | | | |
| | | | Aluminum Sill Sash Jambs | 14.00 lnft | 206 | 378 | 41.74 /lnft | 584 |
| | | | Window: Aluminum | | 206 | 378 | /sqft | 584 |
| | 9920.01 | | Painting: Interior | | | | | |
| | | | Paint Wood Sill | 6.00 lnft | 20 | 1 | 3.51 /lnft | 21 |
| | | | Paint Wood Apron | 6.00 lnft | 18 | 1 | 3.11 /lnft | 19 |
| | | | Painting: Interior | | 38 | 2 | /sqft | 40 |
| 3G | | | | | 666 | 473 | | 1,140 |
| 3H | | | | | | | | |
| | 8811.00 | | Glass: All Types | | | | | |
| | | | Reglaze Insulated Tinted Glass | 2,969.00 sqft | 171,578 | 82,805 | 85.68 /sqft | 254,382 |
| | | | Glass: All Types | | 171,578 | 82,805 | /sqft | 254,382 |
| 3H | | | | | 171,578 | 82,805 | | 254,382 |
| 3J | | | | | | | | |
| | 2071.01 | | Demo: General | | | | | |
| | | | General Disposal | 1.10 cuyd | 23 | - | 27.16 /cuyd | 30 |
| | | | Demo: General | | 23 | | /cuyd | 30 |
| | 2084.01 | | Demo: Doors & Windows | | | | | |
| | | | Remove Door & Frame Ext Double | 3.00 each | 450 | - | 170.04 /each | 510 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|------------------------|-----------|-------|--|------------------|----------------|-----------------|-----------------|----------------|
| | | | Demo: Doors & Windows | | 450 | | /each | 510 |
| | 4110.01 | | Mortar: Grout Fill Conc | | | | | |
| | | | Grout Double Door Frame | 3.00 each | 256 | 86 | 120.26 /each | 361 |
| | | | Mortar: Grout Fill Conc | | 256 | 86 | /cuyd | 361 |
| | 4156.00 | | Access: Wall Flashing | | | | | |
| | | | Flash Head Lead Ct. Cop 5 oz. | 18.00 sqft | 82 | 83 | 9.17 /sqft | 165 |
| | | | Access: Wall Flashing | | 82 | 83 | /sqft | 165 |
| | 6113.40 | | Blocking: Rough Bucks | | | | | |
| | | | Rough Bucks 2 x 6 PT Doors | 20.00 lnft | 50 | 23 | 3.63 /lnft | 73 |
| | | | Blocking: Rough Bucks | | 50 | 23 | /mbf | 73 |
| | 7910.01 | | Sealant - Jt Filler Gaskt | | | | | |
| | | | Backer Rod ½" | 20.00 lnft | 61 | 2 | 3.12 /lnft | 62 |
| | | | Polyurethane Sealant 1/2" | 40.00 lnft | 381 | 20 | 10.02 /lnft | 401 |
| | | | Sealant - Jt Filler Gaskt | | 442 | 22 | /lnft | 463 |
| | 8110.01 | | Doors: Steel with Frames | | | | | |
| | | | H.M. Frame 16ga Galv Double | 3.00 each | 371 | 739 | 370.08 /each | 1,110 |
| | | | H.M. Door Ins 16ga Galv 3-0 x 7-0 Hlf Gl | 6.00 each | 636 | 4,589 | 870.96 /each | 5,226 |
| | | | Doors: Steel with Frames | | 1,007 | 5,329 | /each | 6,336 |
| | 8710.01 | | Hardware: Finishing | | | | | |
| | | | Finishing Hardware Ext Budget | 6.00 each | 1,356 | 7,220 | 1,429.30 /each | 8,576 |
| | | | Hardware: Finishing | | 1,356 | 7,220 | /set | 8,576 |
| | 9910.01 | | Painting: Exterior | | | | | |
| | | | Paint Ext Door & Frame | 6.00 each | 463 | 85 | 91.34 /each | 548 |
| | | | Painting: Exterior | | 463 | 85 | /sqft | 548 |
| | | | 3J | | 4,129 | 12,847 | | 17,062 |
| | 3K | | | | | | | |
| | 4520.01 | | Masonry Restoration | | | | | |
| | | | Patch Individual Brick | 21.00 each | 376 | 30 | 19.34 /each | 406 |
| | | | Masonry Restoration | | 376 | 30 | /m | 406 |
| | | | 3K | | 376 | 30 | | 406 |
| | 3M | | | | | | | |
| | 7620.20 | | Sheetmetal: Soffits | | | | | |
| | | | Soffit Aluminum | 163.00 sqft | 1,973 | 984 | 18.14 /sqft | 2,957 |
| | | | Sheetmetal: Soffits | | 1,973 | 984 | /sqft | 2,957 |
| | | | 3M | | 1,973 | 984 | | 2,957 |
| | 3P | | | | | | | |
| | 4520.01 | | Masonry Restoration | | | | | |
| | | | ReGrout Stone Hard Mortar | 10.00 sqft | 77 | 10 | 8.61 /sqft | 86 |
| | | | Masonry Restoration | | 77 | 10 | /m | 86 |
| | | | 3P | | 77 | 10 | | 86 |
| | | | 3 EXTERIOR | | 466,289 | 493,805 | | 960,741 |
| 4 HAZARDOUS MAT | | | | | | | | |
| | 4B | | | | | | | |
| | 2073.00 | | Demo: Asbestos Removal | | | | | |
| | | | Remove Asbestos Shelf | 50.00 sqft | 808 | 38 | 16.92 /sqft | 846 |
| | | | Demo: Asbestos Removal | | 808 | 38 | /sqft | 846 |
| | | | 4B | | 808 | 38 | | 846 |
| | | | 4 HAZARDOUS MAT | | 808 | 38 | | 846 |
| 5 HC ACCESS | | | | | | | | |
| | 5A | | | | | | | |
| | 2071.01 | | Demo: General | | | | | |
| | | | General Disposal | 39.80 cuyd | 820 | - | 27.17 /cuyd | 1,081 |
| | | | Demo: General | | 820 | | /cuyd | 1,081 |
| | 2076.00 | | Demo: Masonry | | | | | |
| | | | Cut Out Opng 4" CMU | 434.00 sqft | 11,709 | - | 29.35 /sqft | 12,737 |
| | | | Sawcut 4" CMU | 188.00 lnft | 3,545 | - | 30.99 /lnft | 5,826 |
| | | | Tooth Jamb 1 Wythe | 203.00 lnft | 6,270 | - | 30.89 /lnft | 6,270 |
| | | | Remove CMU 4" | 396.00 sqft | 1,283 | - | 3.53 /sqft | 1,396 |
| | | | Demo: Masonry | | 22,808 | | /cuft | 26,230 |
| | 2080.01 | | Demo: Millwork | | | | | |
| | | | Remove Tall Cabinet | 39.00 lnft | 751 | - | 19.27 /lnft | 751 |
| | | | Remove Casework | 3.00 lnft | 16 | - | 5.22 /lnft | 16 |
| | | | Remove Display Case | 9.00 lnft | 87 | - | 9.63 /lnft | 87 |
| | | | Demo: Millwork | | 854 | | /sqft | 854 |
| | 2084.01 | | Demo: Doors & Windows | | | | | |
| | | | Remove Door | 80.00 each | 2,569 | - | 32.11 /each | 2,569 |
| | | | Remove Door & Frame Int Single | 4.00 each | 450 | - | 127.51 /each | 510 |
| | | | Demo: Doors & Windows | | 3,018 | | /each | 3,079 |
| | 2084.50 | | Demo: Misc Items | | | | | |
| | | | Remove Lockers | 22.00 each | 505 | - | 22.96 /each | 505 |
| | | | Demo: Misc Items | | 505 | | /sqft | 505 |
| | 2088.01 | | Demo: Finishes, Floors | | | | | |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|------------|------------|---|------------------|---------------|-----------------|-----------------|---------------|
| | | 2088.01 | Demo: Finishes, Floors | | | | | |
| | | | Flash Patch @ Wall Removal | 95.00 sqft | 219 | 200 | 4.41 /sqft | 419 |
| | | | Demo: Finishes, Floors | | 219 | 200 | /sqft | 419 |
| | | 4050.10 | Misc: Scaffold | | | | | |
| | | | Interior Scaffold | 828.00 sqft | 921 | 347 | 1.77 /sqft | 1,465 |
| | | | Misc: Scaffold | | 921 | 347 | /sqft | 1,465 |
| | | 4050.15 | Misc: Material Handling | | | | | |
| | | | Concrete Block | 2.00 m | - | - | 243.91 /m | 488 |
| | | | Misc: Material Handling | | | | /m | 488 |
| | | 4105.00 | Mortar: All Types | | | | | |
| | | | Mortar Type "N" | 0.24 cuyd | 29 | 52 | 337.96 /cuyd | 81 |
| | | | Mortar: All Types | | 29 | 52 | /cuyd | 81 |
| | | 4110.01 | Mortar: Grout Fill Conc | | | | | |
| | | | Grout Fill 3000 psi, 1/2" Gravl | 0.91 cuyd | 256 | 175 | 494.68 /cuyd | 450 |
| | | | Grout Single Door Frame | 4.00 each | 255 | 82 | 88.72 /each | 355 |
| | | | Mortar: Grout Fill Conc | | 511 | 257 | /cuyd | 805 |
| | | 4157.00 | Reinforce: Vertical Wall | | | | | |
| | | | Re-Bar #5 & #6 | 262.84 lbs | 531 | 280 | 3.09 /lbs | 811 |
| | | | Reinforce: Vertical Wall | | 531 | 280 | /lbs | 811 |
| | | 4158.00 | Reinforce: Horizontl Wall | | | | | |
| | | | Horiz Wall Reinf 4" Hot Dippd | 0.77 mlf | 345 | 92 | 567.25 /mlf | 437 |
| | | | Reinforce: Horizontl Wall | | 345 | 92 | /mlf | 437 |
| | | 4221.25 | Conc. Block: 4" | | | | | |
| | | | Blk 4" Standard Face Reg Wt | 1,158.00 each | 13,284 | 1,821 | 13.04 /each | 15,104 |
| | | | Conc. Block: 4" | | 13,284 | 1,821 | /each | 15,104 |
| | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | Polysulfide Sealant 1/4" Interior | 68.00 lnft | 638 | 15 | 9.60 /lnft | 653 |
| | | | Sealant - Jt Filler Gaskt | | 638 | 15 | /lnft | 653 |
| | | 8110.01 | Doors: Steel with Frames | | | | | |
| | | | H.M. Frame 18ga Interior Single | 4.00 each | 396 | 691 | 271.73 /each | 1,087 |
| | | | Doors: Steel with Frames | | 396 | 691 | /each | 1,087 |
| | | 8210.01 | Doors: Wood | | | | | |
| | | | Rehang Door | 80.00 each | 10,421 | 0 | 130.26 /each | 10,421 |
| | | | Door M Core 3-0 x 7-0 Vision | 4.00 each | 521 | 1,703 | 555.91 /each | 2,224 |
| | | | Doors: Wood | | 10,942 | 1,703 | /each | 12,644 |
| | | 8710.01 | Hardware: Finishing | | | | | |
| | | | Finishing Hardware Int Budget w Closure | 4.00 each | 542 | 3,192 | 933.56 /each | 3,734 |
| | | | Hardware: Finishing | | 542 | 3,192 | /set | 3,734 |
| | | 9210.01 | Lath/Plastr: Gyp Plaster | | | | | |
| | | | Plaster Patch @ Wall Removal | 364.00 sqft | 6,060 | 646 | 18.83 /sqft | 6,855 |
| | | | Plaster Patch Ceiling @ Wall Removal | 110.00 sqft | 598 | 175 | 7.17 /sqft | 789 |
| | | | Lath/Plastr: Gyp Plaster | | 6,658 | 821 | /sqft | 7,644 |
| | | 9253.10 | GWB: Fasteners | | | | | |
| | | | Misc. Accessories | 1.00 lsum | 83 | 29 | 112.66 /lsum | 113 |
| | | | GWB: Fasteners | | 83 | 29 | /each | 113 |
| | | 9920.01 | Painting: Interior | | | | | |
| | | | Paint Wd Door & Metal Frame & Prep | 11.00 each | 926 | 173 | 99.97 /each | 1,100 |
| | | | Refinish & Stain Exist Door | 37.00 each | 5,055 | 256 | 143.56 /each | 5,312 |
| | | | Paint Int CMU Spray p+2ct | 1,658.00 sqft | 1,562 | 463 | 1.22 /sqft | 2,026 |
| | | | Painting: Interior | | 7,544 | 893 | /sqft | 8,437 |
| | | 12380.01 | Display Casework | | | | | |
| | | | Display case 7" h Doors | 9.00 lnft | 321 | 2,619 | 326.66 /lnft | 2,940 |
| | | | Display Casework | | 321 | 2,619 | /lnft | 2,940 |
| | | 5A | | | 70,969 | 13,012 | | 88,612 |
| | 5AA | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.10 cuyd | 2 | - | 27.30 /cuyd | 3 |
| | | | Demo: General | | 2 | | /cuyd | 3 |
| | | 2088.01 | Demo: Finishes, Floors | | | | | |
| | | | Remove Expansion Joint | 8.00 lnft | 642 | - | 80.28 /lnft | 642 |
| | | | Demo: Finishes, Floors | | 642 | | /sqft | 642 |
| | | 5810.01 | Expansion Joint | | | | | |
| | | | Embedded Floor Joint 2" Alum | 8.00 lnft | 164 | 197 | 45.13 /lnft | 361 |
| | | | Expansion Joint | | 164 | 197 | /lnft | 361 |
| | | 5AA | | | 809 | 197 | | 1,006 |
| | 5B | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 98.70 cuyd | 2,033 | - | 27.17 /cuyd | 2,681 |
| | | | Demo: General | | 2,033 | | /cuyd | 2,681 |
| | | 2080.01 | Demo: Millwork | | | | | |
| | | | Remove Casework | 397.00 lnft | 2,072 | - | 5.22 /lnft | 2,072 |
| | | | Demo: Millwork | | 2,072 | | /sqft | 2,072 |
| | | 2088.60 | Demo: Plumbing | | | | | |
| | | | Remove Sink | 47.00 each | 5,773 | - | 122.84 /each | 5,773 |
| | | | Demo: Plumbing | | 5,773 | | /sqft | 5,773 |
| | | 6015.00 | Fasteners: Frame Anchors | | | | | |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|------------|----------|-------------------------------------|------------------|---------------|-----------------|-----------------|----------------|
| | | 6015.00 | Fasteners: Frame Anchors | | | | | |
| | | | Fastners & Misc | 1.00 lsum | - | 3 | 2.53 /lsum | 3 |
| | | | Fasteners: Frame Anchors | | | 3 | /each | 3 |
| | | 6113.20 | Blocking: Misc. | | | | | |
| | | | Blocking 2 x 6 R.L. | 409.00 lnft | 1,405 | 277 | 4.11 /lnft | 1,682 |
| | | | Blocking: Misc. | | 1,405 | 277 | /mbf | 1,682 |
| | | 6410.00 | I Trim: Cabinets | | | | | |
| | | | Modify HC Casework | 5.00 lnft | 945 | 820 | 352.85 /lnft | 1,764 |
| | | | I Trim: Cabinets | | 945 | 820 | /lnft | 1,764 |
| | | 11600.00 | Equip: Laboratory/Science | | | | | |
| | | | Science Casework Base & Top | 236.00 lnft | 24,089 | 72,867 | 410.83 /lnft | 96,956 |
| | | | Science Casework Lecture Bench | 60.00 lnft | 8,082 | 20,660 | 479.04 /lnft | 28,742 |
| | | | Equip: Laboratory/Science | | 32,172 | 93,527 | /lnft | 125,699 |
| | | 12350.00 | Casework | | | | | |
| | | | School Casework Base & Top | 113.00 lnft | 11,377 | 27,711 | 345.91 /lnft | 39,088 |
| | | | Casework | | 11,377 | 27,711 | /lnft | 39,088 |
| | | | 5B | | 55,777 | 122,336 | | 178,762 |
| | 5BB | | | | | | | |
| | | 9510.60 | Ceiling: 2x2 Tile | | | | | |
| | | | MinFbr Tegulr Std 2x2 3/4" < 250 sf | 64.00 sqft | 190 | 251 | 6.89 /sqft | 441 |
| | | | Ceiling: 2x2 Tile | | 190 | 251 | /sqft | 441 |
| | | 9660.01 | Flooring Resilient Tile | | | | | |
| | | | Radial Rubber Floor 3/16" | 64.00 sqft | 446 | 582 | 16.07 /sqft | 1,028 |
| | | | Flooring Resilient Tile | | 446 | 582 | /sqft | 1,028 |
| | | 14001.00 | Elevators | | | | | |
| | | | Controls Auto | 2.00 lsum | - | 10,099 | 5,049.38 /lsum | 10,099 |
| | | | Walls Stainless Steel | 1.00 lsum | - | 3,658 | 3,658.07 /lsum | 3,658 |
| | | | Elevators | | | 13,757 | /each | 13,757 |
| | | | 5BB | | 636 | 14,590 | | 15,226 |
| | 5D | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 1.60 cuyd | 33 | - | 27.17 /cuyd | 43 |
| | | | Demo: General | | 33 | | /cuyd | 43 |
| | | 2088.60 | Demo: Plumbing | | | | | |
| | | | Remove Drinking Fountain | 11.00 each | 1,801 | - | 163.74 /each | 1,801 |
| | | | Demo: Plumbing | | 1,801 | | /sqft | 1,801 |
| | | | 5D | | 1,834 | | | 1,845 |
| | 5E | | | | | | | |
| | | 2084.50 | Demo: Misc Items | | | | | |
| | | | Remove TV | 16.00 each | 963 | - | 60.21 /each | 963 |
| | | | Demo: Misc Items | | 963 | | /sqft | 963 |
| | | | 5E | | 963 | | | 963 |
| | 5F | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 3.20 cuyd | 66 | - | 27.17 /cuyd | 87 |
| | | | Demo: General | | 66 | | /cuyd | 87 |
| | | 2077.00 | Demo: Steel | | | | | |
| | | | Remove Steel Rail | 342.00 lnft | 3,432 | - | 10.04 /lnft | 3,432 |
| | | | Demo: Steel | | 3,432 | | /each | 3,432 |
| | | 5510.80 | Stairs: Stair Parts | | | | | |
| | | | Stair Railing Galv 1-1/2" 2 pipe | 32.00 lnft | 809 | 1,763 | 81.64 /lnft | 2,613 |
| | | | Stair Railing Steel 1-1/2" 6 pipe | 210.00 lnft | 12,454 | 20,452 | 159.65 /lnft | 33,527 |
| | | | Wall Rail Steel 1-1/2" 1 pipe | 100.00 lnft | 2,562 | 2,065 | 47.56 /lnft | 4,756 |
| | | | Retrofit Top Rail | 88.00 lnft | 2,430 | 1,884 | 50.38 /lnft | 4,433 |
| | | | Stairs: Stair Parts | | 18,254 | 26,164 | /flt | 45,329 |
| | | 9910.01 | Painting: Exterior | | | | | |
| | | | Paint Ext Stair Pipe 2 Rails | 32.00 lnft | 85 | 15 | 3.13 /lnft | 100 |
| | | | Painting: Exterior | | 85 | 15 | /sqft | 100 |
| | | 9920.01 | Painting: Interior | | | | | |
| | | | Paint Int Pipe Rails | 1,448.00 lnft | 1,861 | 313 | 1.50 /lnft | 2,174 |
| | | | Painting: Interior | | 1,861 | 313 | /sqft | 2,174 |
| | | | 5F | | 23,698 | 26,491 | | 51,121 |
| | 5G | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 10.20 cuyd | 210 | - | 27.17 /cuyd | 277 |
| | | | Demo: General | | 210 | | /cuyd | 277 |
| | | 2084.50 | Demo: Misc Items | | | | | |
| | | | Remove Toilet Partitions | 6.00 each | 482 | - | 80.28 /each | 482 |
| | | | Remove Toilet Accessories | 216.00 each | 2,167 | - | 10.04 /each | 2,167 |
| | | | Demo: Misc Items | | 2,649 | | /sqft | 2,649 |
| | | 6015.00 | Fasteners: Frame Anchors | | | | | |
| | | | Fastners & Misc | 1.00 lsum | - | 18 | 17.79 /lsum | 18 |
| | | | Fasteners: Frame Anchors | | | 18 | /each | 18 |
| | | 6113.20 | Blocking: Misc. | | | | | |
| | | | Block Toilet Partition | 3.00 each | 90 | 36 | 42.05 /each | 126 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|------------|----------|------------------------------------|------------------|---------------|-----------------|-----------------|---------------|
| | | 6113.20 | Blocking: Misc. | | | | | |
| | | | Block H.C. Toilet Partition | 3.00 each | 136 | 44 | 59.95 /each | 180 |
| | | | Block Misc Toilet Accessories | 347.00 each | 6,275 | 1,742 | 23.10 /each | 8,016 |
| | | | Blocking: Misc. | | 6,501 | 1,822 | /mbf | 8,322 |
| | | 10160.02 | Toilet Partition Phenolic | | | | | |
| | | | Toilet Partition HC Fir Mtd | 15.00 each | 3,179 | 25,063 | 1,882.78 /each | 28,242 |
| | | | Toilet Partition Phenolic | | 3,179 | 25,063 | /each | 28,242 |
| | | 10800.01 | Toilet Accessories | | | | | |
| | | | Grab Bar 1-1/4" S.S. 36" | 20.00 each | 723 | 779 | 75.11 /each | 1,502 |
| | | | Mirror 18" x 30" S.S. | 60.00 each | 2,821 | 4,814 | 127.25 /each | 7,635 |
| | | | Sanitary Napkin Dispenser Recessed | 8.00 each | 386 | 8,284 | 1,083.73 /each | 8,670 |
| | | | Clothes Hook Single | 46.00 each | 923 | 883 | 39.26 /each | 1,806 |
| | | | Soap Dispenser | 60.00 each | 4,340 | 12,427 | 279.44 /each | 16,766 |
| | | | Stainless Steel Shelf | 90.00 lnft | 1,481 | 3,425 | 54.51 /lnft | 4,906 |
| | | | Toilet Tissue Disp Dbl | 71.00 each | 2,138 | 1,953 | 57.62 /each | 4,091 |
| | | | Towel Dispenser Surface Mtd | 17.00 each | 769 | 915 | 99.02 /each | 1,683 |
| | | | Towel Disp/Waste Recpt | 15.00 each | 2,170 | 10,158 | 821.89 /each | 12,328 |
| | | | Toilet Accessories | | 15,750 | 43,638 | /each | 59,388 |
| | | | 5G | | 28,289 | 70,540 | | 98,896 |
| | 5GG | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 5.30 cuyd | 109 | - | 27.17 /cuyd | 144 |
| | | | Demo: General | | 109 | | /cuyd | 144 |
| | | 2080.01 | Demo: Millwork | | | | | |
| | | | Remove Casework | 34.00 lnft | 177 | - | 5.22 /lnft | 177 |
| | | | Demo: Millwork | | 177 | | /sqft | 177 |
| | | 6113.20 | Blocking: Misc. | | | | | |
| | | | Blocking 2 x 6 R.L. | 34.00 lnft | 117 | 23 | 4.11 /lnft | 140 |
| | | | Blocking: Misc. | | 117 | 23 | /mbf | 140 |
| | | 12620.00 | Furniture | | | | | |
| | | | Reception Desk | 34.00 lnft | 3,514 | 20,304 | 700.53 /lnft | 23,818 |
| | | | Furniture | | 3,514 | 20,304 | /lnft | 23,818 |
| | | | 5GG | | 3,917 | 20,327 | | 24,279 |
| | 5H | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 92.00 cuyd | 1,895 | - | 27.17 /cuyd | 2,499 |
| | | | Demo: General | | 1,895 | | /cuyd | 2,499 |
| | | 2075.00 | Demo: Concrete | | | | | |
| | | | Saw Concrete Slab to 6" | 236.00 lnft | 1,287 | - | 7.56 /lnft | 1,784 |
| | | | Chip out Slab | 208.00 sqft | 2,571 | 19 | 14.12 /sqft | 2,936 |
| | | | Demo: Concrete | | 3,858 | 19 | /cuyd | 4,720 |
| | | 2076.00 | Demo: Masonry | | | | | |
| | | | Remove CMU 6" | 2,352.00 sqft | 8,575 | - | 3.97 /sqft | 9,328 |
| | | | Demo: Masonry | | 8,575 | | /cuft | 9,328 |
| | | 2084.50 | Demo: Misc Items | | | | | |
| | | | Remove Toilet Partitions | 17.00 each | 1,365 | - | 80.28 /each | 1,365 |
| | | | Remove Urinal Screen | 10.00 each | 562 | - | 56.19 /each | 562 |
| | | | Remove Toilet Accessories | 66.00 each | 662 | - | 10.04 /each | 662 |
| | | | Demo: Misc Items | | 2,589 | | /sqft | 2,589 |
| | | 2088.01 | Demo: Finishes, Floors | | | | | |
| | | | Remove Ceramic Tile Floor | 1,416.00 sqft | 2,614 | - | 1.85 /sqft | 2,614 |
| | | | Flash Patch @ Wall Removal | 196.00 sqft | 451 | 413 | 4.41 /sqft | 865 |
| | | | Demo: Finishes, Floors | | 3,066 | 413 | /sqft | 3,479 |
| | | 2088.50 | Demo: Finishes, Ceilings | | | | | |
| | | | Remove Plaster Ceiling Metal Lath | 1,416.00 sqft | 3,183 | - | 2.25 /sqft | 3,183 |
| | | | Demo: Finishes, Ceilings | | 3,183 | | /sqft | 3,183 |
| | | 2088.60 | Demo: Plumbing | | | | | |
| | | | Remove Sink | 18.00 each | 2,211 | - | 122.84 /each | 2,211 |
| | | | Remove Water Closet | 17.00 each | 2,387 | - | 140.40 /each | 2,387 |
| | | | Remove Urinal | 7.00 each | 1,720 | - | 245.68 /each | 1,720 |
| | | | Demo: Plumbing | | 6,318 | | /sqft | 6,318 |
| | | 3310.01 | Conc: Slabs On Grade | | | | | |
| | | | Patch Conc. Slab Trench etc. | 208.00 sqft | 1,127 | 2,458 | 17.24 /sqft | 3,585 |
| | | | Conc: Slabs On Grade | | 1,127 | 2,458 | /cuyd | 3,585 |
| | | 4050.10 | Misc: Scaffold | | | | | |
| | | | Interior Scaffold | 2,352.00 sqft | 2,615 | 986 | 1.77 /sqft | 4,162 |
| | | | Misc: Scaffold | | 2,615 | 986 | /sqft | 4,162 |
| | | 4050.15 | Misc: Material Handling | | | | | |
| | | | Concrete Block | 3.00 m | - | - | 243.91 /m | 732 |
| | | | Misc: Material Handling | | | | /m | 732 |
| | | 4105.00 | Mortar: All Types | | | | | |
| | | | Mortar Type "N" | 4.51 cuyd | 547 | 977 | 337.95 /cuyd | 1,524 |
| | | | Mortar: All Types | | 547 | 977 | /cuyd | 1,524 |
| | | 4110.01 | Mortar: Grout Fill Conc | | | | | |
| | | | Grout Fill 3000 psi, 1/2" Gravl | 1.94 cuyd | 546 | 373 | 494.59 /cuyd | 960 |
| | | | Grout Single Door Frame | 7.00 each | 445 | 143 | 88.72 /each | 621 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|-------|---|------------------|--------------|-----------------|-----------------|--------------|
| | | | Mortar: Grout Fill Conc | | 992 | 516 | /cuyd | 1,581 |
| | 4157.00 | | Reinforce: Vertical Wall | | | | | |
| | | | Re-Bar #5 & #6 | 425.54 lbs | 860 | 454 | 3.09 /lbs | 1,314 |
| | | | Reinforce: Vertical Wall | | 860 | 454 | /lbs | 1,314 |
| | 4158.00 | | Reinforce: Horizontl Wall | | | | | |
| | | | Horiz Wall Reinf 6" Hot Dippd | 1.64 mlf | 730 | 280 | 615.57 /mlf | 1,010 |
| | | | Reinforce: Horizontl Wall | | 730 | 280 | /mlf | 1,010 |
| | 4221.20 | | Conc. Block: 6" | | | | | |
| | | | Blk 6" Standard Face Reg Wt | 2,274.00 each | 27,805 | 5,108 | 14.47 /each | 32,914 |
| | | | Conc. Block: 6" | | 27,805 | 5,108 | /each | 32,914 |
| | 4221.50 | | Conc. Block: 6" Lintel | | | | | |
| | | | Lintel 6" Stand Face Reg Wt | 162.00 each | 3,010 | 1,064 | 26.60 /each | 4,309 |
| | | | Conc. Block: 6" Lintel | | 3,010 | 1,064 | /each | 4,309 |
| | 5510.35 | | Misc: Bolt On Material | | | | | |
| | | | Angle Bolted To Masonry | 715.00 lb | 2,527 | 2,152 | 6.74 /lb | 4,820 |
| | | | Misc: Bolt On Material | | 2,527 | 2,152 | /lbs | 4,820 |
| | 6113.20 | | Blocking: Misc. | | | | | |
| | | | Block Toilet Partition | 17.00 each | 512 | 203 | 42.05 /each | 715 |
| | | | Block H.C. Toilet Partition | 7.00 each | 316 | 103 | 59.95 /each | 420 |
| | | | Block Misc Toilet Accessories | 101.00 each | 1,826 | 507 | 23.10 /each | 2,333 |
| | | | Blocking: Misc. | | 2,655 | 813 | /mbf | 3,468 |
| | 6113.40 | | Blocking: Rough Bucks | | | | | |
| | | | Rough Bucks 2 x 6 Doors | 129.00 lnft | 323 | 87 | 3.18 /lnft | 410 |
| | | | Blocking: Rough Bucks | | 323 | 87 | /mbf | 410 |
| | 7910.01 | | Sealant - Jt Filler Gaskt | | | | | |
| | | | Polysulfide Sealant 1/4" Interior | 129.00 lnft | 1,210 | 29 | 9.60 /lnft | 1,239 |
| | | | Sealant - Jt Filler Gaskt | | 1,210 | 29 | /lnft | 1,239 |
| | 8110.01 | | Doors: Steel with Frames | | | | | |
| | | | H.M. Frame 18ga Interior Single | 7.00 each | 692 | 1,210 | 271.72 /each | 1,902 |
| | | | Doors: Steel with Frames | | 692 | 1,210 | /each | 1,902 |
| | 8210.01 | | Doors: Wood | | | | | |
| | | | Door M Core 3-0 x 7-0 Louver | 7.00 each | 966 | 3,487 | 636.03 /each | 4,452 |
| | | | Doors: Wood | | 966 | 3,487 | /each | 4,452 |
| | 8710.01 | | Hardware: Finishing | | | | | |
| | | | Finishing Hardware Int Budget w Closure | 7.00 each | 949 | 5,586 | 933.56 /each | 6,535 |
| | | | Hardware: Finishing | | 949 | 5,586 | /set | 6,535 |
| | 9210.01 | | Lath/Plastr: Gyp Plaster | | | | | |
| | | | Plaster Patch @ Wall Removal | 168.00 sqft | 2,797 | 298 | 18.83 /sqft | 3,164 |
| | | | Plaster Patch Ceiling @ Wall Removal | 188.00 sqft | 1,022 | 300 | 7.17 /sqft | 1,349 |
| | | | Lath/Plastr: Gyp Plaster | | 3,819 | 598 | /sqft | 4,512 |
| | 9253.10 | | GWB: Fasteners | | | | | |
| | | | Misc. Accessories | 1.00 lsum | 334 | 123 | 457.00 /lsum | 457 |
| | | | GWB: Fasteners | | 334 | 123 | /each | 457 |
| | 9253.30 | | GWB: Boards & Sheathing | | | | | |
| | | | GWB 5/8" Water Resistant Clgs | 1,416.00 sqft | 1,313 | 614 | 1.36 /sqft | 1,926 |
| | | | GWB: Boards & Sheathing | | 1,313 | 614 | /sqft | 1,926 |
| | 9254.00 | | GWB: Finish Mud/Tape | | | | | |
| | | | Labor GWB Ceiling Finish | 1,416.00 sqft | 1,577 | 108 | 1.19 /sqft | 1,685 |
| | | | GWB: Finish Mud/Tape | | 1,577 | 108 | /sqft | 1,685 |
| | 9310.01 | | Ceramic Tile | | | | | |
| | | | Ceramic Tile Floor Grade 2 | 1,416.00 sqft | 19,724 | 8,599 | 20.00 /sqft | 28,323 |
| | | | Ceramic Trim: Cove Base | 376.00 lnft | 9,633 | 1,639 | 29.98 /lnft | 11,272 |
| | | | Ceramic Tile | | 29,358 | 10,237 | /sqft | 39,595 |
| | 9510.10 | | Ceiling: Susp. System | | | | | |
| | | | Susp Clg 1-1/2" Channel | 1,416.00 sqft | 4,754 | 2,213 | 4.92 /sqft | 6,967 |
| | | | Ceiling: Susp. System | | 4,754 | 2,213 | /sqft | 6,967 |
| | 9920.01 | | Painting: Interior | | | | | |
| | | | Paint Wd Door & Metal Frame | 7.00 each | 491 | 100 | 84.46 /each | 591 |
| | | | Epoxy Paint GDW Clg | 1,416.00 sqft | 3,275 | 1,115 | 3.10 /sqft | 4,391 |
| | | | Paint Int CMU Spray p+2ct | 3,313.00 sqft | 3,122 | 926 | 1.22 /sqft | 4,048 |
| | | | Epoxy Paint Int CMU | 3,473.00 sqft | 8,034 | 2,912 | 3.15 /sqft | 10,946 |
| | | | Epoxy Paint Exist Int CMU | 3,460.00 sqft | 5,039 | 1,934 | 2.02 /sqft | 6,974 |
| | | | Painting: Interior | | 19,961 | 6,988 | /sqft | 26,950 |
| | 10160.02 | | Toilet Partition Phenolic | | | | | |
| | | | Toilet Partition Reg Flr Mtd | 10.00 each | 2,119 | 14,510 | 1,662.96 /each | 16,630 |
| | | | Toilet Partition HC Fir Mtd | 7.00 each | 1,484 | 11,696 | 1,882.78 /each | 13,179 |
| | | | Urinal Screens Wall Hung | 7.00 each | 1,038 | 3,255 | 613.38 /each | 4,294 |
| | | | Toilet Partition Phenolic | | 4,641 | 29,461 | /each | 34,103 |
| | 10800.01 | | Toilet Accessories | | | | | |
| | | | Grab Bar 1-1/4" S.S. 36" | 14.00 each | 506 | 545 | 75.11 /each | 1,052 |
| | | | Mirror 18" x 30" S.S. | 18.00 each | 846 | 1,444 | 127.25 /each | 2,291 |
| | | | Soap Dispenser | 18.00 each | 1,302 | 3,728 | 279.44 /each | 5,030 |
| | | | Stainless Steel Shelf | 27.00 lnft | 444 | 1,027 | 54.51 /lnft | 1,472 |
| | | | Toilet Tissue Disp Dbl | 17.00 each | 512 | 468 | 57.62 /each | 979 |
| | | | Towel Disp/Waste Recpt | 7.00 each | 1,013 | 4,741 | 821.89 /each | 5,753 |
| | | | Toilet Accessories | | 4,623 | 11,953 | /each | 16,577 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|------------|----------|---|------------------|-----------------------|----------------------|-----------------|-----------------------|
| | | | | | <u>146,871</u> | <u>87,933</u> | | <u>238,843</u> |
| | 5HH | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.40 cuyd | 8 | - | 27.18 /cuyd | 11 |
| | | | Demo: General | | 8 | | /cuyd | 11 |
| | | 2088.01 | Demo: Finishes, Floors | | | | | |
| | | | Remove Expansion Joint | 45.00 lnft | 3,612 | - | 80.28 /lnft | 3,612 |
| | | | Demo: Finishes, Floors | | 3,612 | | /sqft | 3,612 |
| | | 9685.00 | Flooring Carpet | | | | | |
| | | | Vinyl Reducer Strip | 45.00 lnft | 222 | 212 | 9.65 /lnft | 434 |
| | | | Flooring Carpet | | 222 | 212 | /sqyd | 434 |
| | | | <u>5HH</u> | | <u>3,843</u> | <u>212</u> | | <u>4,057</u> |
| | 5JJ | | | | | | | |
| | | 2084.50 | Demo: Misc Items | | | | | |
| | | | Relocate Fire Blanket | 4.00 each | 1,124 | - | 280.97 /each | 1,124 |
| | | | Demo: Misc Items | | 1,124 | | /sqft | 1,124 |
| | | | <u>5JJ</u> | | <u>1,124</u> | | | <u>1,124</u> |
| | 5K | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.10 cuyd | 2 | - | 27.20 /cuyd | 3 |
| | | | Shore - Screw Jack | 1.00 each | 1,064 | 68 | 1,196.83 /each | 1,197 |
| | | | Demo: General | | 1,066 | 68 | /cuyd | 1,200 |
| | | 2076.00 | Demo: Masonry | | | | | |
| | | | Cut Out Opng 6" CMU | 7.00 sqft | 200 | - | 31.02 /sqft | 217 |
| | | | Sawcut 6" CMU | 8.00 lnft | 226 | - | 46.49 /lnft | 372 |
| | | | Tooth Jamb 1 Wythe | 7.00 lnft | 216 | - | 30.89 /lnft | 216 |
| | | | Demo: Masonry | | 642 | | /cuft | 805 |
| | | 4110.01 | Mortar: Grout Fill Conc | | | | | |
| | | | Grout Single Door Frame | 1.00 each | 64 | 20 | 88.71 /each | 89 |
| | | | Mortar: Grout Fill Conc | | 64 | 20 | /cuyd | 89 |
| | | 6113.20 | Blocking: Misc. | | | | | |
| | | | Blocking 2 x 6 R.L. | 17.00 lnft | 58 | 12 | 4.11 /lnft | 70 |
| | | | Blocking: Misc. | | 58 | 12 | /mbf | 70 |
| | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | Polysulfide Sealant 1/4" Interior | 17.00 lnft | 159 | 4 | 9.61 /lnft | 163 |
| | | | Sealant - Jt Filler Gaskt | | 159 | 4 | /lnft | 163 |
| | | 8110.01 | Doors: Steel with Frames | | | | | |
| | | | H.M. Frame 18ga Interior Single | 1.00 each | 99 | 173 | 271.72 /each | 272 |
| | | | Doors: Steel with Frames | | 99 | 173 | /each | 272 |
| | | 8210.01 | Doors: Wood | | | | | |
| | | | Door M Core 3-0 x 7-0 Vision | 1.00 each | 130 | 426 | 555.91 /each | 556 |
| | | | Doors: Wood | | 130 | 426 | /each | 556 |
| | | 8710.01 | Hardware: Finishing | | | | | |
| | | | Finishing Hardware Int Budget w Closure | 1.00 each | 136 | 798 | 933.57 /each | 934 |
| | | | Hardware: Finishing | | 136 | 798 | /set | 934 |
| | | 9920.01 | Painting: Interior | | | | | |
| | | | Paint Wd Door & Metal Frame | 1.00 each | 70 | 14 | 84.46 /each | 84 |
| | | | Painting: Interior | | 70 | 14 | /sqft | 84 |
| | | | <u>5K</u> | | <u>2,425</u> | <u>1,515</u> | | <u>4,172</u> |
| | 5L | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.30 cuyd | 6 | - | 27.13 /cuyd | 8 |
| | | | Demo: General | | 6 | | /cuyd | 8 |
| | | 2075.00 | Demo: Concrete | | | | | |
| | | | Saw Concrete Slab to 6" | 20.00 lnft | 109 | - | 7.56 /lnft | 151 |
| | | | Chip out Slab | 24.00 sqft | 297 | 2 | 14.12 /sqft | 339 |
| | | | Demo: Concrete | | 406 | 2 | /cuyd | 490 |
| | | 14405.00 | Lifts | | | | | |
| | | | Lift Commercial | 1.00 each | 2,989 | 15,344 | 18,490.09 /each | 18,490 |
| | | | Lifts | | 2,989 | 15,344 | /each | 18,490 |
| | | | <u>5L</u> | | <u>3,401</u> | <u>15,346</u> | | <u>18,988</u> |
| | 5M | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 2.80 cuyd | 58 | - | 27.16 /cuyd | 76 |
| | | | Demo: General | | 58 | | /cuyd | 76 |
| | | 2077.00 | Demo: Steel | | | | | |
| | | | Remove Steel Rail | 304.00 lnft | 3,051 | - | 10.04 /lnft | 3,051 |
| | | | Demo: Steel | | 3,051 | | /each | 3,051 |
| | | 5510.80 | Stairs: Stair Parts | | | | | |
| | | | Wall Rail Steel 1-1/2" 1 pipe | 134.00 lnft | 3,433 | 2,767 | 47.56 /lnft | 6,373 |
| | | | Wall Railing Steel 1-1/2" 2 Pipe | 70.00 lnft | 2,528 | 2,691 | 76.35 /lnft | 5,344 |
| | | | Wall Rail Steel Galv 1-1/2" 2 pipe | 80.00 lnft | 2,907 | 3,624 | 83.43 /lnft | 6,674 |
| | | | Ornamental Steel Well Rail Mid | 100.00 lnft | 8,360 | 25,685 | 344.64 /lnft | 34,464 |
| | | | Stairs: Stair Parts | | 17,227 | 34,766 | /flt | 52,855 |
| | | 9910.01 | Painting: Exterior | | | | | |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|------------|---------|--------------------------------------|------------------|---------------|-----------------|-----------------|---------------|
| | | 9910.01 | Painting: Exterior | | | | | |
| | | | Paint Ext Stair Pipe 2 Rails | 80.00 Inft | 212 | 38 | 3.13 /Inft | 250 |
| | | | Painting: Exterior | | 212 | 38 | /sqft | 250 |
| | | 9920.01 | Painting: Interior | | | | | |
| | | | Paint Int Pipe Rails | 874.00 Inft | 1,123 | 189 | 1.50 /Inft | 1,312 |
| | | | Painting: Interior | | 1,123 | 189 | /sqft | 1,312 |
| | | | 5M | | 21,671 | 34,993 | | 57,544 |
| | 5MM | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.70 cuyd | 14 | - | 27.16 /cuyd | 19 |
| | | | Demo: General | | 14 | | /cuyd | 19 |
| | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | Remove Door & Frame Int Single | 4.00 each | 450 | - | 127.51 /each | 510 |
| | | | Demo: Doors & Windows | | 450 | | /each | 510 |
| | | 4050.15 | Misc: Material Handling | | | | | |
| | | | Concrete Block | 0.10 m | - | - | 262.81 /m | 25 |
| | | | Misc: Material Handling | | | | /m | 25 |
| | | 4105.00 | Mortar: All Types | | | | | |
| | | | Mortar Type "N" | 0.27 cuyd | 33 | 58 | 338.00 /cuyd | 91 |
| | | | Mortar: All Types | | 33 | 58 | /cuyd | 91 |
| | | 4110.01 | Mortar: Grout Fill Conc | | | | | |
| | | | Grout Fill 3000 psi, 1/2" Gravl | 0.43 cuyd | 121 | 83 | 494.80 /cuyd | 213 |
| | | | Mortar: Grout Fill Conc | | 121 | 83 | /cuyd | 213 |
| | | 4157.00 | Reinforce: Vertical Wall | | | | | |
| | | | Re-Bar #5 & #6 | 29.20 lbs | 59 | 31 | 3.09 /lbs | 90 |
| | | | Reinforce: Vertical Wall | | 59 | 31 | /lbs | 90 |
| | | 4158.00 | Reinforce: Horizontal Wall | | | | | |
| | | | Horiz Wall Reinf 8" Hot Dipd | 0.07 mlf | 42 | 13 | 782.70 /mlf | 55 |
| | | | Reinforce: Horizontal Wall | | 42 | 13 | /mlf | 55 |
| | | 4221.15 | Conc. Block: 8" | | | | | |
| | | | Blk 8" Standard Face Reg Wt - Infill | 96.00 each | 1,864 | 241 | 21.92 /each | 2,105 |
| | | | Conc. Block: 8" | | 1,864 | 241 | /each | 2,105 |
| | | | 5MM | | 2,583 | 426 | | 3,108 |
| | 5N | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 7.50 cuyd | 154 | - | 27.17 /cuyd | 204 |
| | | | Demo: General | | 154 | | /cuyd | 204 |
| | | 2075.00 | Demo: Concrete | | | | | |
| | | | Saw Concrete Slab to 6" | 32.00 Inft | 174 | - | 7.56 /Inft | 242 |
| | | | Remove Slab on Grade | 454.00 sqft | 3,126 | - | 7.51 /sqft | 3,411 |
| | | | Remove Ramp | 178.00 sqft | 1,860 | - | 11.40 /sqft | 2,030 |
| | | | Demo: Concrete | | 5,161 | | /cuyd | 5,682 |
| | | 3131.00 | Forms: Ramps | | | | | |
| | | | Ramp Forms 2 use | 504.00 Inft | 3,986 | 897 | 9.69 /Inft | 4,883 |
| | | | Forms: Ramps | | 3,986 | 897 | /Inft | 4,883 |
| | | 3136.00 | Forms: Stairs | | | | | |
| | | | Stair Forms | 63.00 sqft | 1,120 | 258 | 21.88 /sqft | 1,378 |
| | | | Forms: Stairs | | 1,120 | 258 | /sqft | 1,378 |
| | | 3215.10 | Rebar: Steps & Stairs | | | | | |
| | | | Step-Stair Rebar #5 | 0.01 ton | 24 | 23 | 4,729.00 /ton | 47 |
| | | | Rebar: Steps & Stairs | | 24 | 23 | /ton | 47 |
| | | 3225.00 | Rebar: WWM @ Ramp/Misc | | | | | |
| | | | Wiremesh - Ramp 6x6 6/6 | 14.54 sqs | 1,005 | 740 | 120.00 /sqs | 1,745 |
| | | | Rebar: WWM @ Ramp/Misc | | 1,005 | 740 | /sqs | 1,745 |
| | | 3228.00 | Rebar: Wiremesh @ Steps | | | | | |
| | | | Wiremesh @ Steps 6x6 6/6 | 0.50 sqs | 36 | 25 | 122.06 /sqs | 61 |
| | | | Rebar: Wiremesh @ Steps | | 36 | 25 | /sqs | 61 |
| | | 3309.50 | Conc: Ramps | | | | | |
| | | | Ramp Conc 4000 psi | 26.93 cuyd | 1,238 | 3,818 | 196.97 /cuyd | 5,304 |
| | | | Conc: Ramps | | 1,238 | 3,818 | /cuyd | 5,304 |
| | | 3314.00 | Conc: Stairs & Steps | | | | | |
| | | | Stair/Step Conc 4000 psi | 1.40 cuyd | 49 | 189 | 177.94 /cuyd | 249 |
| | | | Conc: Stairs & Steps | | 49 | 189 | /cuyd | 249 |
| | | 3375.00 | Finish: Protect & Cure | | | | | |
| | | | Cure Conc w/burlap Ext Stair | 0.40 sqs | 10 | 5 | 37.45 /sqs | 15 |
| | | | Cure Conc w/burlap Ramp | 14.54 sqs | 374 | 171 | 37.43 /sqs | 544 |
| | | | Finish: Protect & Cure | | 384 | 175 | /sqs | 559 |
| | | 3380.01 | Finish: General | | | | | |
| | | | Broom/Float Finish Ramp | 1,390.00 sqft | 1,224 | - | 0.88 /sqft | 1,224 |
| | | | Stair Finish | 40.00 sqft | 108 | 0 | 2.71 /sqft | 109 |
| | | | Rub Risers | 15.00 Inft | 61 | 1 | 4.14 /Inft | 62 |
| | | | Finish: General | | 1,393 | 1 | /sqft | 1,395 |
| | | 5510.80 | Stairs: Stair Parts | | | | | |
| | | | Stair Railing Galv 1-1/2" 2 pipe | 208.00 Inft | 5,260 | 11,457 | 81.64 /Inft | 16,981 |
| | | | Stairs: Stair Parts | | 5,260 | 11,457 | /ft | 16,981 |
| | | 9910.01 | Painting: Exterior | | | | | |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|-----------------------|-------------|--------------------|--|------------------|----------------|-----------------|-----------------|----------------|
| | | 9910.01 | Painting: Exterior | | | | | |
| | | | Paint Ext Stair Hand 1 Rail | 416.00 lnft | 606 | 116 | 1.74 /lnft | 722 |
| | | | Painting: Exterior | | 606 | 116 | /sqft | 722 |
| | | 5N | | | 20,418 | 17,700 | | 39,211 |
| | 5NNN | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 11.70 cuyd | 241 | - | 26.93 /cuyd | 315 |
| | | | Demo: General | | 241 | | /cuyd | 315 |
| | | 2084.50 | Demo: Misc Items | | | | | |
| | | | Remove Lockers | 37.00 each | 849 | - | 22.96 /each | 849 |
| | | | Remove Benches | 409.00 lnft | 4,104 | - | 10.04 /lnft | 4,104 |
| | | | Demo: Misc Items | | 4,954 | | /sqft | 4,954 |
| | | 6113.20 | Blocking: Misc. | | | | | |
| | | | Blocking 2 x 6 R.L. | 37.00 lnft | 127 | 25 | 4.11 /lnft | 152 |
| | | | Blocking: Misc. | | 127 | 25 | /mbf | 152 |
| | | 10505.90 | Lockers | | | | | |
| | | | Locker HC Single Tier 6' | 37.00 each | 5,473 | 11,659 | 463.04 /each | 17,132 |
| | | | Locker: Bench | 409.00 lnft | 7,053 | 12,316 | 47.36 /lnft | 19,369 |
| | | | Lockers | | 12,526 | 23,975 | /each | 36,502 |
| | | 5NNN | | | 17,848 | 24,000 | | 41,922 |
| | 5P | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.10 cuyd | 2 | - | 27.10 /cuyd | 3 |
| | | | Demo: General | | 2 | | /cuyd | 3 |
| | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | Remove Hardware | 2.00 each | 90 | - | 45.21 /each | 90 |
| | | | Demo: Doors & Windows | | 90 | | /each | 90 |
| | | 8710.01 | Hardware: Finishing | | | | | |
| | | | Finishing Hardware Ext Budget | 1.00 each | 226 | 1,203 | 1,429.30 /each | 1,429 |
| | | | Finishing Hardware Int Budget w Closure | 1.00 each | 136 | 798 | 933.56 /each | 934 |
| | | | Hardware: Finishing | | 362 | 2,001 | /set | 2,363 |
| | | 5P | | | 454 | 2,001 | | 2,456 |
| | 5X | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 3.60 cuyd | 74 | - | 27.17 /cuyd | 98 |
| | | | Demo: General | | 74 | | /cuyd | 98 |
| | | 2080.01 | Demo: Millwork | | | | | |
| | | | Remove Casework | 16.00 lnft | 83 | - | 5.22 /lnft | 83 |
| | | | Demo: Millwork | | 83 | | /sqft | 83 |
| | | 6113.20 | Blocking: Misc. | | | | | |
| | | | Blocking 2 x 6 R.L. | 16.00 lnft | 55 | 11 | 4.11 /lnft | 66 |
| | | | Blocking: Misc. | | 55 | 11 | /mbf | 66 |
| | | 12350.00 | Casework | | | | | |
| | | | School Casework Base & Top | 16.00 lnft | 1,611 | 3,924 | 345.91 /lnft | 5,535 |
| | | | Casework | | 1,611 | 3,924 | /lnft | 5,535 |
| | | 5X | | | 1,824 | 3,934 | | 5,782 |
| | 5Z | | | | | | | |
| | | 12620.00 | Furniture | | | | | |
| | | | Modify Reception Desk | 6.00 lnft | 2,015 | 3,225 | 873.35 /lnft | 5,240 |
| | | | Furniture | | 2,015 | 3,225 | /lnft | 5,240 |
| | | 5Z | | | 2,015 | 3,225 | | 5,240 |
| | | 5 HC ACCESS | | | 411,368 | 458,780 | | 883,158 |
| 6 FINISHES GEN | | | | | | | | |
| | 6A | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 47.60 cuyd | 980 | - | 27.17 /cuyd | 1,293 |
| | | | Demo: General | | 980 | | /cuyd | 1,293 |
| | | 2088.50 | Demo: Finishes, Ceilings | | | | | |
| | | | Remove Acoust Tile | 5,135.00 sqft | 11,130 | - | 2.17 /sqft | 11,130 |
| | | | Demo: Finishes, Ceilings | | 11,130 | | /sqft | 11,130 |
| | | 9510.60 | Ceiling: 2x2 Tile | | | | | |
| | | | Re-Install & Clean 2x2 3/4" 250 - 500 sf | 5,135.00 sqft | 11,662 | | 2.27 /sqft | 11,662 |
| | | | Ceiling: 2x2 Tile | | 11,662 | | /sqft | 11,662 |
| | | 6A | | | 23,772 | | | 24,085 |
| | 6AAA | | | | | | | |
| | | 2088.21 | Demo: Finishes, Walls | | | | | |
| | | | Rem Ceramic Tile But No Studs | 40.00 sqft | 87 | - | 2.17 /sqft | 87 |
| | | | Demo: Finishes, Walls | | 87 | | /sqft | 87 |
| | | 9310.01 | Ceramic Tile | | | | | |
| | | | Patch Ceramic Wall Tile | 40.00 sqft | 642 | 193 | 20.88 /sqft | 835 |
| | | | Ceramic Tile | | 642 | 193 | /sqft | 835 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|-------------|----------|-----------------------------------|------------------|----------------------|-------------------|-----------------|----------------------|
| | | | | | <u>728</u> | <u>193</u> | | <u>922</u> |
| | 6B | | | | | | | |
| | | 4520.01 | Masonry Restoration | | | | | |
| | | | Cut & Repoint CMU Hard Mortar | 110.00 Inft | 1,138 | 152 | 14.55 /Inft | 1,601 |
| | | | Cut & Repoint Brick Soft Mortr | 10.00 sqft | 72 | 7 | 9.88 /sqft | 99 |
| | | | Remove Individual Brick Allow | 68.00 each | 4,572 | - | 85.37 /each | 5,805 |
| | | | Patch Individual Brick Allow | 68.00 each | 1,217 | 98 | 19.34 /each | 1,315 |
| | | | Remove CMU 8" Allow | 124.00 each | 7,394 | - | 64.87 /each | 8,043 |
| | | | Patch in 8" CMU Allow | 124.00 each | 3,689 | 331 | 32.42 /each | 4,020 |
| | | | Masonry Restoration | | 18,082 | 588 | /m | 20,883 |
| | | | <u>6B</u> | | <u>18,082</u> | <u>588</u> | | <u>20,883</u> |
| | 6BBB | | | | | | | |
| | | 8710.01 | Hardware: Finishing | | | | | |
| | | | Sound Seal | 2.00 each | 181 | 97 | 138.70 /each | 277 |
| | | | Hardware: Finishing | | 181 | 97 | /set | 277 |
| | | | <u>6BBB</u> | | <u>181</u> | <u>97</u> | | <u>277</u> |
| | 6CC | | | | | | | |
| | | 3328.00 | Conc: Restoration | | | | | |
| | | | Patch Concrete Wall | 23.00 sqft | 312 | 551 | 37.50 /sqft | 862 |
| | | | Conc: Restoration | | 312 | 551 | /sqft | 862 |
| | | | <u>6CC</u> | | <u>312</u> | <u>551</u> | | <u>862</u> |
| | 6CCC | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.50 cuyd | 10 | - | 27.18 /cuyd | 14 |
| | | | Demo: General | | 10 | | /cuyd | 14 |
| | | 2080.05 | Demo: Roofing | | | | | |
| | | | Remove Base Flashing | 54.00 sqft | 214 | - | 3.97 /sqft | 214 |
| | | | Demo: Roofing | | 214 | | /sqft | 214 |
| | | 7515.10 | Membrane: Base Flashing | | | | | |
| | | | Base Flashing Premier | 54.00 sqft | 202 | 362 | 10.43 /sqft | 563 |
| | | | Membrane: Base Flashing | | 202 | 362 | /Inft | 563 |
| | | | <u>6CCC</u> | | <u>426</u> | <u>362</u> | | <u>791</u> |
| | 6D | | | | | | | |
| | | 4520.01 | Masonry Restoration | | | | | |
| | | | Cut & Repoint Brick Soft Mortr | 482.00 sqft | 3,480 | 347 | 9.88 /sqft | 4,763 |
| | | | Masonry Restoration | | 3,480 | 347 | /m | 4,763 |
| | | | <u>6D</u> | | <u>3,480</u> | <u>347</u> | | <u>4,763</u> |
| | 6E | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.20 cuyd | 4 | - | 27.20 /cuyd | 5 |
| | | | Demo: General | | 4 | | /cuyd | 5 |
| | | 2088.70 | Demo: Mechanical | | | | | |
| | | | Remove Louvers | 4.00 sqft | 46 | - | 11.48 /sqft | 46 |
| | | | Demo: Mechanical | | 46 | | /sqft | 46 |
| | | 5510.05 | Misc: Lintels | | | | | |
| | | | Stl Angles 1000 - 2000 lbs | 49.00 lb | 92 | 72 | 3.34 /lb | 164 |
| | | | Misc: Lintels | | 92 | 72 | /lbs | 164 |
| | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | 2 x 6 PT Louvers | 10.00 Inft | 27 | 11 | 3.82 /Inft | 38 |
| | | | Blocking: Rough Bucks | | 27 | 11 | /mbf | 38 |
| | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | Backer Rod 1/2" | 10.00 Inft | 30 | 1 | 3.12 /Inft | 31 |
| | | | Polysulfide Sealant 1/4" Interior | 20.00 Inft | 188 | 4 | 9.61 /Inft | 192 |
| | | | Sealant - Jt Filler Gaskt | | 218 | 5 | /Inft | 223 |
| | | 9920.01 | Painting: Interior | | | | | |
| | | | Paint Louvers | 4.00 sqft | 7 | 1 | 2.06 /sqft | 8 |
| | | | Painting: Interior | | 7 | 1 | /sqft | 8 |
| | | 15856.00 | Louvers/Filters | | | | | |
| | | | Fixed Blade Stormproof | 4.00 sqft | 154 | 177 | 82.62 /sqft | 330 |
| | | | Louvers/Filters | | 154 | 177 | /sqft | 330 |
| | | | <u>6E</u> | | <u>548</u> | <u>266</u> | | <u>815</u> |
| | 6G | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.20 cuyd | 4 | - | 27.20 /cuyd | 5 |
| | | | Demo: General | | 4 | | /cuyd | 5 |
| | | 2079.00 | Demo: Exterior Finishes | | | | | |
| | | | Remove Soffit & Trim | 12.00 sqft | 54 | - | 4.50 /sqft | 54 |
| | | | Demo: Exterior Finishes | | 54 | | /sqft | 54 |
| | | 7620.20 | Sheetmetal: Soffits | | | | | |
| | | | Soffit Aluminum | 12.00 sqft | 145 | 72 | 18.14 /sqft | 218 |
| | | | Sheetmetal: Soffits | | 145 | 72 | /sqft | 218 |
| | | | <u>6G</u> | | <u>203</u> | <u>72</u> | | <u>277</u> |
| | 6GGG | | | | | | | |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|---------|---|------------------|--------------|-----------------|-----------------|--------------|
| | | 9910.01 | Painting: Exterior | | | | | |
| | | | Paint Ext Misc Exposed Metal | 144.00 sqft | 302 | 44 | 2.40 /sqft | 346 |
| | | | Painting: Exterior | | 302 | 44 | /sqft | 346 |
| | | | 6GGG | | 302 | 44 | | 346 |
| | 6H | | | | | | | |
| | | 9920.01 | Painting: Interior | | | | | |
| | | | Paint Exist Conc Wall roller 2ct | 5,648.00 sqft | 2,769 | 502 | 0.58 /sqft | 3,272 |
| | | | Paint Exist Int CMU Spray 2 ct | 619.00 sqft | 265 | 110 | 0.61 /sqft | 375 |
| | | | Painting: Interior | | 3,034 | 612 | /sqft | 3,647 |
| | | | 6H | | 3,034 | 612 | | 3,647 |
| | 6HH | | | | | | | |
| | | 7620.30 | Sheetmetal: Fascia | | | | | |
| | | | Refasten Fascia | 62.00 lnft | 834 | 0 | 13.45 /lnft | 834 |
| | | | Sheetmetal: Fascia | | 834 | | /lnft | 834 |
| | | | 6HH | | 834 | | | 834 |
| | 6HHH | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 1.00 cuyd | 21 | - | 27.17 /cuyd | 27 |
| | | | Demo: General | | 21 | | /cuyd | 27 |
| | | 2080.05 | Demo: Roofing | | | | | |
| | | | Remove Shingles | 10.00 sqft | 10 | - | 0.97 /sqft | 10 |
| | | | Remove Gravel Stop | 98.00 lnft | 385 | - | 3.93 /lnft | 385 |
| | | | Demo: Roofing | | 395 | | /sq | 395 |
| | | 7310.00 | Shingles: Asphalt | | | | | |
| | | | Patch Premium Class C 300-385 lb | 0.10 sqs | 53 | 14 | 669.90 /sqs | 67 |
| | | | Shingles: Asphalt | | 53 | 14 | /sqs | 67 |
| | | 7312.10 | Shingles: Felt | | | | | |
| | | | Patch Roofing Felt 60 lb. | 0.11 sq | 5 | 4 | 83.00 /sq | 9 |
| | | | Shingles: Felt | | 5 | 4 | /sqs | 9 |
| | | 7620.30 | Sheetmetal: Fascia | | | | | |
| | | | Fascia Alum 12" Dur Fin | 98.00 lnft | 804 | 1,203 | 20.48 /lnft | 2,007 |
| | | | Sheetmetal: Fascia | | 804 | 1,203 | /lnft | 2,007 |
| | | | 6HHH | | 1,278 | 1,221 | | 2,505 |
| | 6JJJ | | | | | | | |
| | | 4710.10 | Cleaning: Masonry | | | | | |
| | | | Clean Brick - Acid Graffiti | 10.00 sqft | 102 | 6 | 10.82 /sqft | 108 |
| | | | Cleaning: Masonry | | 102 | 6 | /sq | 108 |
| | | | 6JJJ | | 102 | 6 | | 108 |
| | 6KKK | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.20 cuyd | 4 | - | 27.15 /cuyd | 5 |
| | | | Demo: General | | 4 | | /cuyd | 5 |
| | | 2084.01 | Demo: Doors & Windows | | | | | |
| | | | Remove Door & Frame Ext Single | 1.00 each | 128 | - | 145.73 /each | 146 |
| | | | Demo: Doors & Windows | | 128 | | /each | 146 |
| | | 4110.01 | Mortar: Grout Fill Conc | | | | | |
| | | | Grout Single Door Frame | 1.00 each | 64 | 20 | 88.71 /each | 89 |
| | | | Mortar: Grout Fill Conc | | 64 | 20 | /cuyd | 89 |
| | | 4156.00 | Access: Wall Flashing | | | | | |
| | | | Flash Head Lead Ct. Cop 5 oz. | 3.00 sqft | 14 | 14 | 9.17 /sqft | 28 |
| | | | Access: Wall Flashing | | 14 | 14 | /sqft | 28 |
| | | 6113.40 | Blocking: Rough Bucks | | | | | |
| | | | Rough Bucks 2 x 6 PT Doors | 17.00 lnft | 43 | 19 | 3.63 /lnft | 62 |
| | | | Blocking: Rough Bucks | | 43 | 19 | /mbf | 62 |
| | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |
| | | | Backer Rod ½" | 17.00 lnft | 52 | 2 | 3.12 /lnft | 53 |
| | | | Polyurethane Sealant 1/2" | 34.00 lnft | 324 | 17 | 10.02 /lnft | 341 |
| | | | Sealant - Jt Filler Gaskt | | 375 | 18 | /lnft | 394 |
| | | 8110.01 | Doors: Steel with Frames | | | | | |
| | | | H.M. Frame 16ga Galv Single | 1.00 each | 99 | 206 | 304.76 /each | 305 |
| | | | H.M. Door Ins 16ga Galv 3-0 x 7-0 Flush | 1.00 each | 93 | 504 | 597.14 /each | 597 |
| | | | Doors: Steel with Frames | | 192 | 710 | /each | 902 |
| | | 8710.01 | Hardware: Finishing | | | | | |
| | | | Finishing Hardware Ext Budget | 1.00 each | 226 | 1,203 | 1,429.29 /each | 1,429 |
| | | | Hardware: Finishing | | 226 | 1,203 | /set | 1,429 |
| | | 9910.01 | Painting: Exterior | | | | | |
| | | | Paint Ext Door & Frame | 1.00 each | 77 | 14 | 91.34 /each | 91 |
| | | | Painting: Exterior | | 77 | 14 | /sqft | 91 |
| | | | 6KKK | | 1,123 | 2,000 | | 3,146 |
| | 6L | | | | | | | |
| | | 4155.00 | Access: Control Joint | | | | | |
| | | | Control Jnt Rubber 8" Wall | 214.00 lnft | 834 | 791 | 7.59 /lnft | 1,625 |
| | | | Access: Control Joint | | 834 | 791 | /lnft | 1,625 |
| | | 7910.01 | Sealant - Jt Filler Gaskt | | | | | |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|-------|--|------------------|--------------|-----------------|-----------------|---------------|
| | 7910.01 | | Sealant - Jt Filler Gaskt | | | | | |
| | | | Backer Rod ½" | 214.00 Inft | 649 | 20 | 3.12 /Inft | 668 |
| | | | Polyurethane Sealant 1/2" | 214.00 Inft | 2,039 | 106 | 10.02 /Inft | 2,145 |
| | | | Rake Out Masonry Jt. Filler | 214.00 Inft | 631 | 44 | 4.98 /Inft | 1,065 |
| | | | Sealant - Jt Filler Gaskt | | 3,318 | 170 | /Inft | 3,878 |
| | | | 6L | | 4,152 | 960 | | 5,503 |
| | 6LLL | | | | | | | |
| | 2071.01 | | Demo: General | | | | | |
| | | | General Disposal | 0.70 cuyd | 14 | - | 27.16 /cuyd | 19 |
| | | | Demo: General | | 14 | | /cuyd | 19 |
| | 2079.00 | | Demo: Exterior Finishes | | | | | |
| | | | Remove Exterior Metal Panels | 72.00 sqft | 116 | - | 1.61 /sqft | 116 |
| | | | Demo: Exterior Finishes | | 116 | | /sqft | 116 |
| | 7410.00 | | Metal Facing Panels | | | | | |
| | | | Metal Facing Panel Ins 18ga | 72.00 sqft | 562 | 526 | 15.11 /sqft | 1,088 |
| | | | Metal Facing Panels | | 562 | 526 | /sqft | 1,088 |
| | | | 6LLL | | 692 | 526 | | 1,222 |
| | 6MM | | | | | | | |
| | 2071.01 | | Demo: General | | | | | |
| | | | General Disposal | 1.50 cuyd | 31 | - | 27.17 /cuyd | 41 |
| | | | Demo: General | | 31 | | /cuyd | 41 |
| | 2084.01 | | Demo: Doors & Windows | | | | | |
| | | | Remove Door | 2.00 each | 64 | - | 32.11 /each | 64 |
| | | | Remove Door & Frame Ext Double | 3.00 each | 450 | - | 170.04 /each | 510 |
| | | | Demo: Doors & Windows | | 514 | | /each | 574 |
| | 4110.01 | | Mortar: Grout Fill Conc | | | | | |
| | | | Grout Double Door Frame | 3.00 each | 256 | 86 | 120.25 /each | 361 |
| | | | Mortar: Grout Fill Conc | | 256 | 86 | /cuyd | 361 |
| | 4156.00 | | Access: Wall Flashing | | | | | |
| | | | Flash Head Lead Ct. Cop 5 oz. | 18.00 sqft | 82 | 83 | 9.17 /sqft | 165 |
| | | | Access: Wall Flashing | | 82 | 83 | /sqft | 165 |
| | 6015.00 | | Fasteners: Frame Anchors | | | | | |
| | | | Fastners & Misc | 1.00 lsum | - | 1 | 1.27 /lsum | 1 |
| | | | Fasteners: Frame Anchors | | | 1 | /each | 1 |
| | 6113.40 | | Blocking: Rough Bucks | | | | | |
| | | | Rough Bucks 2 x 6 PT Doors | 60.00 Inft | 150 | 68 | 3.63 /Inft | 218 |
| | | | Blocking: Rough Bucks | | 150 | 68 | /mbf | 218 |
| | 7910.01 | | Sealant - Jt Filler Gaskt | | | | | |
| | | | Backer Rod ½" | 60.00 Inft | 182 | 6 | 3.12 /Inft | 187 |
| | | | Polyurethane Sealant 1/2" | 120.00 Inft | 1,143 | 60 | 10.02 /Inft | 1,203 |
| | | | Sealant - Jt Filler Gaskt | | 1,325 | 65 | /Inft | 1,390 |
| | 8110.01 | | Doors: Steel with Frames | | | | | |
| | | | H.M. Frame 16ga Galv Double | 3.00 each | 371 | 739 | 370.08 /each | 1,110 |
| | | | H.M. Frame Repair Allow | 3.00 each | 594 | 259 | 284.24 /each | 853 |
| | | | H.M. Door Ins 16ga Galv 3-0 x 7-0 Hlf Gl | 8.00 each | 848 | 6,119 | 870.96 /each | 6,968 |
| | | | Doors: Steel with Frames | | 1,813 | 7,118 | /each | 8,931 |
| | 8710.01 | | Hardware: Finishing | | | | | |
| | | | Finishing Hardware Ext Budget | 8.00 each | 1,808 | 9,626 | 1,429.30 /each | 11,434 |
| | | | Hardware: Finishing | | 1,808 | 9,626 | /set | 11,434 |
| | 9910.01 | | Painting: Exterior | | | | | |
| | | | Paint Ext Door & Frame | 8.00 each | 617 | 114 | 91.34 /each | 731 |
| | | | Painting: Exterior | | 617 | 114 | /sqft | 731 |
| | | | 6MM | | 6,596 | 17,160 | | 23,846 |
| | 6MMM | | | | | | | |
| | 9910.01 | | Painting: Exterior | | | | | |
| | | | Paint Col Cover | 108.00 Inft | 111 | 16 | 1.18 /Inft | 127 |
| | | | Painting: Exterior | | 111 | 16 | /sqft | 127 |
| | | | 6MMM | | 111 | 16 | | 127 |
| | 6NNN | | | | | | | |
| | 9920.01 | | Painting: Interior | | | | | |
| | | | Paint Louvers | 48.00 sqft | 82 | 16 | 2.06 /sqft | 99 |
| | | | Painting: Interior | | 82 | 16 | /sqft | 99 |
| | | | 6NNN | | 82 | 16 | | 99 |
| | 6000 | | | | | | | |
| | 10430.01 | | Signs | | | | | |
| | | | Interior Custom | 49.00 each | 2,127 | 2,936 | 103.31 /each | 5,062 |
| | | | Signs | | 2,127 | 2,936 | /each | 5,062 |
| | | | 6000 | | 2,127 | 2,936 | | 5,062 |
| | 6PPP | | | | | | | |
| | 6113.20 | | Blocking: Misc. | | | | | |
| | | | Blocking 2 x 6 R.L. | 16.00 Inft | 55 | 11 | 4.11 /Inft | 66 |
| | | | Blocking: Misc. | | 55 | 11 | /mbf | 66 |
| | 11164.00 | | Equip: Dock | | | | | |
| | | | Dock Bumpers | 16.00 Inft | 297 | 792 | 68.03 /Inft | 1,088 |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|-------------|----------|--|------------------|--------------|-----------------|-----------------|---------------|
| | | | Equip: Dock | | 297 | 792 | /each | 1,088 |
| | | | 6PPP | | 352 | 803 | | 1,154 |
| | 6Q | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.40 cuyd | 8 | - | 27.18 /cuyd | 11 |
| | | | Demo: General | | 8 | | /cuyd | 11 |
| | | 2077.00 | Demo: Steel | | | | | |
| | | | Remove Wall Expansion Joint | 48.00 lnft | 381 | - | 7.95 /lnft | 381 |
| | | | Demo: Steel | | 381 | | /each | 381 |
| | | 5810.01 | Expansion Joint | | | | | |
| | | | Embedded Wall Expansion Joint | 48.00 lnft | 1,017 | 608 | 33.86 /lnft | 1,625 |
| | | | Expansion Joint | | 1,017 | 608 | /lnft | 1,625 |
| | | | 6Q | | 1,407 | 608 | | 2,018 |
| | 6QQQ | | | | | | | |
| | | 6113.20 | Blocking: Misc. | | | | | |
| | | | Blocking 2 x 4 R.L. | 30.00 lnft | 84 | 14 | 3.26 /lnft | 98 |
| | | | Blocking: Misc. | | 84 | 14 | /mbf | 98 |
| | | 10110.01 | Chalkboards/Tackboards | | | | | |
| | | | Refasten Markerboard Alum Fr | 40.00 sqft | 130 | 0 | 3.25 /sqft | 130 |
| | | | Tackboard Alum Fr | 20.00 sqft | 65 | 0 | 3.25 /sqft | 65 |
| | | | Chalkboards/Tackboards | | 195 | | /sqft | 195 |
| | | | 6QQQ | | 279 | 14 | | 293 |
| | 6SS | | | | | | | |
| | | 4710.10 | Cleaning: Masonry | | | | | |
| | | | Clean Exist Brick Bio Growth | 2.86 sqs | 1,006 | 73 | 376.96 /sqs | 1,078 |
| | | | Cleaning: Masonry | | 1,006 | 73 | /sqs | 1,078 |
| | | | 6SS | | 1,006 | 73 | | 1,078 |
| | 6SSS | | | | | | | |
| | | 9560.01 | Flooring Wood Strip | | | | | |
| | | | Refinish Wood Floor Mid | 1,824.00 sqft | 6,003 | 2,109 | 4.45 /sqft | 8,112 |
| | | | Flooring Wood Strip | | 6,003 | 2,109 | /sqft | 8,112 |
| | | | 6SSS | | 6,003 | 2,109 | | 8,112 |
| | 6UU | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 2.60 cuyd | 54 | - | 26.93 /cuyd | 70 |
| | | | Demo: General | | 54 | | /cuyd | 70 |
| | | 2088.01 | Demo: Finishes, Floors | | | | | |
| | | | Remove Rec Floor Matt | 284.00 sqft | 1,505 | - | 5.30 /sqft | 1,505 |
| | | | Demo: Finishes, Floors | | 1,505 | | /sqft | 1,505 |
| | | 12690.01 | Floor Mats | | | | | |
| | | | Entrance Mat Rec 3/8" w Frame | 284.00 sqft | 2,876 | 5,846 | 30.71 /sqft | 8,722 |
| | | | Floor Mats | | 2,876 | 5,846 | /sqft | 8,722 |
| | | | 6UU | | 4,434 | 5,846 | | 10,296 |
| | 6UUU | | | | | | | |
| | | 9920.01 | Painting: Interior | | | | | |
| | | | Paint Exist GDW Roller 2ct | 4,080.00 sqft | 2,097 | 622 | 0.67 /sqft | 2,719 |
| | | | Painting: Interior | | 2,097 | 622 | /sqft | 2,719 |
| | | | 6UUU | | 2,097 | 622 | | 2,719 |
| | 6VV | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 4.40 cuyd | 91 | - | 27.17 /cuyd | 120 |
| | | | Demo: General | | 91 | | /cuyd | 120 |
| | | 2088.01 | Demo: Finishes, Floors | | | | | |
| | | | Remove Rubber Base | 476.00 lnft | 420 | - | 0.88 /lnft | 420 |
| | | | Demo: Finishes, Floors | | 420 | | /sqft | 420 |
| | | 9660.01 | Flooring Resilient Tile | | | | | |
| | | | Floor Resil Base 4" | 476.00 lnft | 691 | 380 | 2.25 /lnft | 1,071 |
| | | | Flooring Resilient Tile | | 691 | 380 | /sqft | 1,071 |
| | | | 6VV | | 1,202 | 380 | | 1,611 |
| | 6VVV | | | | | | | |
| | | 8710.01 | Hardware: Finishing | | | | | |
| | | | Adjust Finishing Hardware Int Budget w Closure | 4.00 each | 271 | 0 | 67.81 /each | 271 |
| | | | Hardware: Finishing | | 271 | | /set | 271 |
| | | | 6VVV | | 271 | | | 271 |
| | 6W | | | | | | | |
| | | 4710.10 | Cleaning: Masonry | | | | | |
| | | | Clean Masonry from Water Damage | 100.00 sqft | 1,025 | 57 | 10.82 /sqft | 1,082 |
| | | | Cleaning: Masonry | | 1,025 | 57 | /sqs | 1,082 |
| | | | 6W | | 1,025 | 57 | | 1,082 |
| | 6WW | | | | | | | |
| | | 9210.01 | Lath/Plastr: Gyp Plaster | | | | | |

| Location | Bid Item | Phase | Description | Takeoff Quantity | Labor Amount | Material Amount | Total Cost/Unit | Total Amount |
|----------|----------|----------|---|------------------|----------------|-----------------|-----------------|----------------|
| | | 9210.01 | Lath/Plastr: Gyp Plaster | | | | | |
| | | | Plaster Patch Wall | 41.00 sqft | 683 | 73 | 18.83 /sqft | 772 |
| | | | Lath/Plastr: Gyp Plaster | | 683 | 73 | /sqft | 772 |
| | | 9253.10 | GWB: Fasteners | | | | | |
| | | | Misc. Accessories | 1.00 lsum | 9 | 3 | 11.81 /lsum | 12 |
| | | | GWB: Fasteners | | 9 | 3 | /each | 12 |
| | | | 6WWW | | 692 | 75 | | 784 |
| | 6WWW | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.10 cuyd | 2 | - | 27.20 /cuyd | 3 |
| | | | Demo: General | | 2 | | /cuyd | 3 |
| | | 2088.01 | Demo: Finishes, Floors | | | | | |
| | | | Remove Vinyl Tile | 6.00 sqft | 8 | - | 1.28 /sqft | 8 |
| | | | Demo: Finishes, Floors | | 8 | | /sqft | 8 |
| | | 3326.00 | Conc: Slurry Coat | | | | | |
| | | | Leveling Compound | 6.00 sqft | 23 | 11 | 6.55 /sqft | 39 |
| | | | Conc: Slurry Coat | | 23 | 11 | /sqft | 39 |
| | | 9660.01 | Flooring Resilient Tile | | | | | |
| | | | Patch Floor Vinyl Composition Tile 1/8" | 6.00 sqft | 10 | 13 | 3.73 /sqft | 22 |
| | | | Flooring Resilient Tile | | 10 | 13 | /sqft | 22 |
| | | | 6WWW | | 43 | 24 | | 72 |
| | 6XXX | | | | | | | |
| | | 6113.20 | Blocking: Misc. | | | | | |
| | | | Blocking 2 x 6 R.L. | 2.00 lnft | 7 | 1 | 4.12 /lnft | 8 |
| | | | Blocking: Misc. | | 7 | 1 | /mbf | 8 |
| | | 10505.90 | Lockers | | | | | |
| | | | Locker Single Tier 6' | 2.00 each | 89 | 152 | 120.62 /each | 241 |
| | | | Lockers | | 89 | 152 | /each | 241 |
| | | | 6XXX | | 96 | 154 | | 249 |
| | 6Y | | | | | | | |
| | | 2071.01 | Demo: General | | | | | |
| | | | General Disposal | 0.20 cuyd | 4 | - | 27.15 /cuyd | 5 |
| | | | Demo: General | | 4 | | /cuyd | 5 |
| | | 2080.05 | Demo: Roofing | | | | | |
| | | | Remove Gutter/Downspouts | 24.00 lnft | 58 | - | 2.41 /lnft | 58 |
| | | | Demo: Roofing | | 58 | | /sqft | 58 |
| | | 7620.15 | Sheetmetal: Guttr DwnSpt | | | | | |
| | | | Downspout Copper Circular 5" | 24.00 lnft | 232 | 545 | 32.39 /lnft | 777 |
| | | | Sheetmetal: Guttr DwnSpt | | 232 | 545 | /lnft | 777 |
| | | | 6Y | | 294 | 545 | | 841 |
| | 6YYY | | | | | | | |
| | | 8210.01 | Doors: Wood | | | | | |
| | | | Door Louver | 1.00 each | 22 | 164 | 185.51 /each | 186 |
| | | | Doors: Wood | | 22 | 164 | /each | 186 |
| | | | 6YYY | | 22 | 164 | | 186 |
| | 6ZZZ | | | | | | | |
| | | 9660.01 | Flooring Resilient Tile | | | | | |
| | | | Patch Synthetic Gym Floor 1/2" | 2,000.00 sqft | 21,879 | 13,926 | 17.90 /sqft | 35,805 |
| | | | Flooring Resilient Tile | | 21,879 | 13,926 | /sqft | 35,805 |
| | | 9920.01 | Painting: Interior | | | | | |
| | | | Paint Floor Lines | 1,849.00 lnft | 1,742 | 446 | 1.18 /lnft | 2,189 |
| | | | Painting: Interior | | 1,742 | 446 | /sqft | 2,189 |
| | | | 6ZZZ | | 23,622 | 14,372 | | 37,994 |
| | | | 6 FINISHES GEN | | 111,008 | 53,820 | | 168,882 |

Estimate Totals

| | | | |
|--------------|------------------|------------------|-----|
| Labor | 1,060,487 | 10,544.202 | hrs |
| Material | 1,199,070 | | |
| Equipment | 21,593 | 1,166.657 | hrs |
| | 2,281,150 | 2,281,150 | |
| Total | 2,281,150 | | |

High School – Food Service Report



December 26, 2008

Mr. David Finney
Design Partnership of Cambridge, Inc.
500 Rutherford Avenue
Charlestown, Massachusetts 02129

Re: Lexington High School Kitchen
Foodservice Facilities Site Evaluation

Introduction

Crabtree McGrath Associates, Inc., a consulting group specializing in foodservice facilities planning and design has been retained by Design Partnership of Cambridge to provide an analysis and recommendations for future modifications to the existing kitchen and serving facilities.

Foodservice Findings

CMA toured the existing kitchen and serving areas on Friday, December 12, 2008 to evaluate the site and operating conditions. The facility is organized into a central kitchen with two serving areas. Serving area one labeled "Com One" is directly adjacent to the kitchen. Serving area two labels as "Com two" is remote to the kitchen but within approximately fifty feet to the kitchen. Both serving areas were renovated about the year 2000.

Serving Areas

- Com one has a pizza service station that lacks the proper temperature maintenance equipment or sneeze guards. Upon closer inspection we found the counter can be easily modified to accommodate the addition of equipment needed to properly serve meals at this service station.
 - In general Com one is in good order. The ceiling finishes, lighting, and wall finished are adequate but some consideration may want to be given to cosmetic repair at certain counters in addition to repairing the pizza serving station.
- Com two has a hot well counter designated to warm and serve hot meals. The hot food wells have since failed and are in need of replacement.
 - In general Com two is in good order but there may be the need for additional hand sinks and the cosmetic upgrade of counters. The ceiling finishes, lighting, and wall finished appear to be adequate though replacement of the hot wells is needed.

F O O D F A C I L I T I E S P L A N N E R S

153 Andover Street, Suite 209, Danvers, Massachusetts 01923 phone: 978.762.6464 fax: 978.762.6245
mail@crabtree-mcgrath.com

Main Kitchen

Unlike the serving areas the kitchen has never been renovated save the replacement of a few pieces of kitchen equipment and the addition of a walk-in refrigerated freezer. Below is a listing of other deficiencies and considerations for review.

- The ceiling in all areas of the kitchen is open to mechanical equipment above. Pipes, motors, ductwork, and plumbing are visible. As this condition is impossible to keep clean the kitchen is in violation of the public health code. The health code requires that the kitchen ceiling be smooth, washable, and free of unnecessary obstructions.
- Food prep sinks are not code compliant. The health code requires that food prep sinks be indirectly drained meaning air gaps need to be present between the sink drain and the sanitary plumbing system. Some sinks do not have the proper code compliant faucets and the construction of other prep counters and tables are showing signs of failure and corrosion. All counters should be replaced with new counters of fully welded construction and made of 100% stainless steel.
- The office is located deep within the kitchen. This does not allow for oversight of the receiving area and the kitchen operation. Additionally, student wishing to conduct business with the kitchen staff must enter the kitchen environment to reach the office and conduct transactions. This condition increases the potential for injury to non-kitchen personnel. The office should be relocated to an area that allows for the oversight of the receiving area and kitchen and to eliminate the need for non-foodservice staff entering the food production area.
- The dry storage rooms are fragmented into three separate areas. In order to realize a more efficient storage facility storage rooms should be consolidated to one area. Currently in certain storage rooms sanitary lines are running overhead of the food storage and this is in violation of the health code. Lighting fixtures are open to the room and are required to be protected by a shatterproof lens. Lastly, in each room refitting the rooms with new shelving can increase the density of storage and efficiency of used area.
- The pot washing area placement is inconvenient and is an all-manual operation. The modern pot washing area utilizes a ware washing machine. The machine reduces labor costs, uses less water to wash, and cleans and sanitizes the ware more effectively.
- Cooking Line and General Kitchen Conditions
 - The existing exhaust ventilation system is outdated and unable to support newer cooking equipment and is not constructed to current NFPA standards.
 - The length and width of the hood should extend at least 6” beyond the edge of the cooking equipment and 12”-14” over the front of convection ovens.
 - There should be at least 6” of over hood hang on the backside of the equipment.
 - Cooking equipment - convection ovens, steamer and kettles are all aged and in need of replacement and appear to be original to the kitchen. The cooking equipment should be replaced with functional, newer energy efficient units.
 - The cooking equipment in the center of the kitchen is mounted on a fixed curb, which inhibits moving the equipment for cleaning, service, and maintenance. We

recommend removing the curb and mounting all of the equipment on either 6” stainless steel legs or on casters where possible.

- The steam kettles require floor trough in front of them to ease in cleaning and as an efficient way to drain off water from the kettles.
- Sixty-quart mixer - appears to be original equipment. The unit should be retrofitted with safety guards that are common and required on newer units to protect against injury.
- Hand sinks - Additional hand sinks are required. There should be at least one additional hand sink. The health department for hand washing does not approve preparation hand sinks.
- The walk in coolers should be consolidated from four separate units into two total units. Currently each of the four units has a condenser and a unit cooler running 24 hours per day year round consuming more energy than necessary. Throughout the years walk-in freezers were added to compensate for population growth. To consolidate these units would translate into an immediate saving in electrical consumption and drastically increase operational efficiency and inventory control. Additionally, newer motors and monitoring systems will further reduce the amount of energy used to maintain the systems.
 - Two of the older walk-in coolers are constructed of wood. This is a violation of the health code since surfaces in the kitchen must be non absorbent and easy to clean. Wood surfaces in a kitchen environment do not meet this criterion. Additionally the R-value of the aged walls does not meet the efficiency standards of today.
 - One of the older walk-in cooler floors has failed and corrosion is visible. The floor has been replaced once already and the unit will need to be replaced. Rather than unit replacement consolidation is recommended during replacement.
- Floor surfaces - as observed during our visit the floor is showing serious wear in some areas. We found surfaces to be different in parts of the kitchen with unsealed concrete in the receiving area. The floor should be a monolithic assembly with coved corners where the floor meets all walls to facilitate ease of cleaning.

Ways a renovation would conserve energy

- **Open burner ranges** – These units have a minimum of five standing pilot lights. These pilots continue to consume energy even when the units are not in use. We recommend a brand that offers an electronic pilot igniter. The igniter makes it easy to light pilots and encourages staff to totally shut the unit down at the end of the day in an effort to conserve natural gas. *For example a four-burner unit consumes on average 4000 to 6000 btu's per hour, that's more than 21 million btu's per year at an idle operating cost of \$249. Additionally, in locations where the code requires the gas to be shut down at the hood when the fan is not running the pilot igniters make it easy to relight pilots at the beginning of each day. Garland and US range are the only quality manufacturers that offer this option but within the next six months others will begin offering the igniter option. The upgrade to the ignition system has a pay-back period of approximately 15 months.

**The calculation is based on the assumption that the unit is idle for ten hours per day with five pilots burning at a total hourly consumption of 6000 btu's at 365 days per year. This*

equals 21,900,000 btu's per year of idle time consumption. One therm is equal to 100,000 btu's and in New England the cost per therm is \$1.14 with an expected increase of 5% in 2009.

- **Walk -in refrigerated rooms** - The mechanical refrigeration systems for these rooms are controlled with simple time clock defrosts at the freezer coils. It works well but it is not an intelligent system. We recommend utilizing a Smart Defrost system that is designed to defrost the refrigerated room only when they are needed. Typical time clock controlled electric defrost systems have four defrosts per day. Using a Smart Defrost system can reduce the number of defrosts from none to two per day. This system represents an average savings of 75% in energy. In addition to the smart defrost we recommend the use of PSC or ECM motors in all refrigeration room blower coils. These motors last longer and represent a 72% energy consumption reduction, and run quieter than traditional motors.
- **The Exhaust hoods** - Today there are new technologies on the market that allow us to realize savings without restricting the type of hood availability. These systems are called Energy Management Systems or EMS. What EMS controls do is modulate the speed of the exhaust and MAU fan motors with variable frequency drives (VFD's). In simple terms the control system senses heat at the exhaust duct and increase or decreases the amount of exhaust rate based on demand rather than running at 100% capacity 100% of the time. EMS systems have been shown to significantly reduce the energy consumption and electrical demands associated with operating the hood systems. On average this represents a 62% reduction in electrical demand. In addition to electrical energy savings there would be an energy savings gained from the reduced heating load at the make up air units. Typically the average fan speed associated airflow of the MAU will drop 30% resulting in a significant amount of air that does not need to be heated. The average pay back for these systems is less than one year and in most cases the cost is immediately reimbursed by the local gas and power utility.
- **Hood Lights** - By replacing the incandescent light bulbs in exhaust hoods significant reductions in energy usage can be realized. Incandescent bulbs transform about 85% of energy they use into heat. The life spans of these lights are approximately 750 to 1000 hours. Consider the constant vibration at the hood and this is reduced even further. The initial cost of a 60 watt incandescent bulb is about 50 cents each and assuming the typical hood has eight lights in it we can calculate that these eight bulbs will cost about \$525 dollars per year to operate.

Compact fluorescent lights CFL's are much more efficient. They convert only about 25% of energy put into them into heat. The lifespan of a CFL is 7,500 to 10,000 hours but the initial cost is about \$10 each. This initial high cost is quickly recovered since the cost to operate CFL is about \$160 per year. Compact fluorescents should be specified for all new hoods going forward but consider the savings if the change was implemented to include all existing hoods system wide.

- **Low-Flow Pre-Rinse Spray Valves** - A low-flow pre-rinse spray valve is one of the easiest and most cost effective energy saving devices available to the foodservice operator. In addition to minimizing water consumption, water heating energy and sewer charges are also reduced. Replacing a typical spray valve that flows up to three gallons of water per minute with a low-flow unit can yield the same result with less water.

Conclusion

It is our recommendation that the kitchen be renovated to meet current standards for health and safety. The kitchen should be fitted with energy efficient kitchen equipment that will dramatically reduce the cost of operation. Additionally, improving ergonomics will reduce the cost of labor and free time to better deploy labor. Replacement of work counters, sinks, and cooking equipment will improved safety and overall staff moral as well as increase productivity and efficient flow considering the disorganized flow from storage to prep and finally through to cooking. We feel there is enough existing space available in order to reorganize the kitchen portion of this facility.

Lastly, much of this work would be required as part of a renovation due to the many non-code compliant conditions that exist.

Respectfully,

John Sousa

Crabtree McGrath Associates, Inc.

High School – Site Scope Memo



WARNER LARSON
LANDSCAPE ARCHITECTS

11 March 2009

Mr. David Finney
The Design Partnership of Cambridge
Hood Business Park
500 Rutherford Ave.
Charlestown, MA 02129-1647

Re: Lexington School Study
Lexington, MA

Dear Mr. Finney:

Below is a brief memo addressing existing site conditions observed at the Lexington High School site. During the course of the study, we received input from the Committee and a neighborhood group regarding site issues. A conceptual site plan has been prepared indicating a conceptual design approach which attempts to address the issues raised and improve the identity, circulation, aesthetics, scale and character of the Lexington High School grounds.

Site Evaluation

The existing High School is built on a site that leaves little room for expansion. The site is relatively flat and is bounded on all sides by roads, residential properties or playfields. The northerly portion of the site is further limited by the existence of wetlands, in some places as close as 50 feet +/- from the buildings.

The school consists of three separate buildings linked by exterior walkways and a court yard giving a campus like affect. Students are required to go from building to building for class changes, which can be uncomfortable in the harsh N.E. winters. The campus design also creates security issues that must be addressed.

The vehicular circulation consists of one and two way drives leading to large undefined paved parking areas. There seems to be no identifiable main vehicular entrance to the School. Vehicular circulation on the site is confusing due to a lack of definition. Delivery and service is exposed to the southerly parking and dumpsters are disbursed around the campus. There seems to be no main front entrance to the School.

Proposed Conditions

The proposed additions to the building, in additions to satisfying the educational program for the High School, provide unity and definition to the site and improve accessibility between the buildings. With the buildings connected, pedestrian access between buildings will be improved and better security will be provided.

The building addition proposed on the easterly side of the school links two buildings. The one way drive will continue to be used as a student drop off area with some adjustments. Due to floor levels and accessibility issues, the drive will be reconstructed in the same horizontal alignment, but will transition to a slightly higher elevation to facilitate accessibility.

There are wetland issues relating to the proposed construction in this area. Any proposed construction that falls within 100 feet of a wetland will require a Notice of Intent be filed with the Conservation commission. There is also a 25 foot setback from a wetland line which defines a no disturb zone and a 50 foot setback for structures. While these setbacks are compromised in a couple locations as shown on the plan, the construction may be permitted since the existing site improvements have already been developed and the drive will be rebuilt no closer to the wetland. Similarly, The new building will be designed so that it is not any closer to the wetland edge than the existing building.

After a discussion with the Conservation Commission Director, we understand that the Commission may request additional wetland mitigation to satisfy the Conditions of the previous construction.

The southerly parking lot has been redesigned to provide better definition of traffic flow, better delineation of parking spaces and identification of a pedestrian entrance into the main entrance courtyard.

The drive from Waltham Street has been redesigned to provide a controlled intersection at the corner of the school. The flow of traffic will lead cars toward the pedestrian entrance to the main courtyard.

11 March 2009
Lexington School Study
Page 3

No site design revisions were proposed to the Worthen Road parking area since that area was recently upgraded. Some improvements to the student drop off and bus loading and unloading area were proposed to provide scale, character and interest to the only main entrance that can be seen from a Town road.

Additional planting has been added to provide a better sense of scale, character and definition to the campus.

Respectfully Submitted,

A handwritten signature in cursive script that reads "Gary Larson". The signature is written in black ink and is positioned above the printed name.

Gary Larson, ASLA, RLA